			Pi	operty Detail Form		
Agency:	AUDITOR'S OFFICE / AUI	DITOR'S OFFICE				
Property:	State Auditor's Office (Old	Shodair Hospital Bld)				
Property Address:	840 Helena Ave HELENA					
Property ID:	34010					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings: 2	29764	
Year built:		blank		Number of stories:	3	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior mason	y walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Office			
Provide a brief description	on of operations:		blank			
Storage height of wareho	oused products:		blank			
Are flammable and combustible liquids stored in a cut-off room?		null				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank	
ndicate the Alarm Cover	ages provided for your fac	ility:		blank		
Are alarms connected to	a constantly attended loca	ation?		null		
s there a watchman serv	ice?	null		What is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire extingu	iishers?	null		Are they serviced annually?	null	
Are there any hose statio	ons?	null		Is there a fire private fire brigade?	null	
requency of training rec	eived by the private fire b	rigade:				
Type of public fire depart	ment:	null		Distance:	blank	
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
s there a body of water r	nearby?	null	Descri	otion:		
How far is the body of wa	ater from major buildings?					
Previous history of flood	ing?	null	Descri	otion:		
Any property damage los	sses in the past 3 years:	null	Descri	otion:		

			Pi	operty Detail Form		
Agency:	AUDITOR'S OFFICE / AUI	DITOR'S OFFICE				
Property:	State Auditor's Office (Old	Shodair Hospital Bld)				
Property Address:	840 Helena Ave HELENA					
Property ID:	34010					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings: 2	29764	
Year built:		blank		Number of stories:	3	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior mason	y walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Office			
Provide a brief description	on of operations:		blank			
Storage height of wareho	oused products:		blank			
Are flammable and combustible liquids stored in a cut-off room?		null				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank	
ndicate the Alarm Cover	ages provided for your fac	ility:		blank		
Are alarms connected to	a constantly attended loca	ation?		null		
s there a watchman serv	ice?	null		What is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire extingu	iishers?	null		Are they serviced annually?	null	
Are there any hose statio	ons?	null		Is there a fire private fire brigade?	null	
requency of training rec	eived by the private fire b	rigade:				
Type of public fire depart	ment:	null		Distance:	blank	
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
s there a body of water r	nearby?	null	Descri	otion:		
How far is the body of wa	ater from major buildings?					
Previous history of flood	ing?	null	Descri	otion:		
Any property damage los	sses in the past 3 years:	null	Descri	otion:		

			Prope	rty Detail Form				
Agency:	BOARD OF PUBLIC EDUC	ATION / BOARD OF PUBLIC EDUC	ATION, SCH	OOL FOR THE DEAF & BLIND				
Property:	Academic Building							
Property Address:	3911 Central Ave. GREAT	FALLS						
Property ID:	1							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	46478			
Year built:		1972		Number of stories:	1			
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Cor	ncrete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board			
Do major interior masonr	ry walls (fire walls) extend a	above the roofline?		N				
Occupancy:								
Occupancy Type:			Government	tal Building				
Provide a brief description of operations:		ADMIN/OFF	ICES/LIBRARY/CONFERENCE RM/STORAGE/MECHANIC	AL RM				
Storage height of warehoused products:		18-20 IN. BE	8-20 IN. BELOW CEILING					
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ						
Protection:								
Are there any automatic	sprinklers?	Υ	Wha	at are the design densities for each area?		NOT AVAILABLE		
The water supply for auto	omatic sprinklers is?	Public	Hov	w many hydrants are located within 500 feet of buildings?	?	4		
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	tion?	Υ					
ls there a watchman serv	rice?	N	Wha	at is the frequency of rounds?				
Are watchman recording	rounds?		N					
Are there any fire extingu	uishers?	Υ	Are	they serviced annually?		Υ		
Are there any hose statio	ons?	N	ls th	here a fire private fire brigade?		N		
Frequency of training rec	ceived by the private fire br	igade:						
Type of public fire depart	tment:	Paid	Dist	tance:		5 BLOCKS		
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	1					
Describe the Occupancy	of those buildings(s) nearl	y (within 100 feet):	RESIDENTIA	AL COTTAGE 1/STUDENTS				
ls there a body of water r	nearby?	N	Description	:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Description	:				
Any property damage los	sses in the past 3 years:	Υ	Description	ı:	LOST TRANSF LIFT SERVING	ORMER/DAMAGED PLATFORM BASEMENT		

			Prope	erty Detail Form				
Agency:	BOARD OF PUBLIC EDUC	CATION / BOARD OF PUBLIC EDUC	ATION, SCH	HOOL FOR THE DEAF & BLIND				
Property:	Boiler House							
Property Address:	3911 Central Ave. GREAT	FALLS						
Property ID:	3							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	3000			
Year built:		1952		Number of stories:	1			
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry			
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Power Plan	ut				
Provide a brief description	on of operations:		Contains bo	pilers and storage rooms				
Storage height of warehoused products:		6 feet belov	feet below ceiling					
Are flammable and combustible liquids stored in a cut-off room?			Υ					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ						
Protection:								
Are there any automatic	sprinklers?	N	Wh	nat are the design densities for each area?				
The water supply for auto	omatic sprinklers is?		Но	w many hydrants are located within 500 feet of buildings?	2			
Indicate the Alarm Cover	ages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ation?	N					
ls there a watchman serv	ice?	N	Wh	nat is the frequency of rounds?				
Are watchman recording	rounds?		N					
Are there any fire extingu	iishers?	Υ	Are	e they serviced annually?	Υ			
Are there any hose statio	ons?	N	ls t	there a fire private fire brigade?	N			
Frequency of training rec	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid	Dis	stance:	5 blocks			
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	2					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Classroom;	Residential Cottage				
Is there a body of water r	nearby?	N	Description	n:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Description	n:				
Any property damage los	sses in the past 3 years:	N	Description	n:				

								- 3 -	
			Pro	perty D	etail Form				
Agency:	BOARD OF PUBLIC EDUC	CATION / BOARD OF PUBLIC EDUC	CATION, S	CHOOL F	FOR THE DEAF & BLIND				
Property:	Classroom Building								
Property Address:	3911 Central Ave. GREAT	FALLS							
Property ID:	4								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	9072			
Year built:		1960			Number of stories:	1			
Construction of roof:		Wood Joists			Construction of floors:	Poured Concr	rete		
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry			
Do major interior masonry walls (fire walls) extend above the roofline?		above the roofline?			N				
Occupancy:									
Occupancy Type:			Governm	nental Bui	ilding				
Provide a brief description of operations:			Classroo	om buildin	ng				
Storage height of warehoused products:			6 feet be	6 feet below ceiling					
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic	sprinklers?	Υ	,	What are	e the design densities for each area?				
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?	•	2		
Indicate the Alarm Cover	ages provided for your fac	ility:		Smoke D	etectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
Are alarms connected to	a constantly attended loca	ation?		Υ					
ls there a watchman serv	rice?	N	,	What is t	the frequency of rounds?				
Are watchman recording	rounds?			N					
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N		
Frequency of training red	ceived by the private fire b	rigade:							
Type of public fire depart	tment:	Paid		Distance	):		5 blocks		
Exposure:									
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	2						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Boiler Ho	ouse; Res	sidential Cottage				
Is there a body of water r	nearby?	N	Descript	tion:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Description:						
Any property damage los	sses in the past 3 years:	N	Descript	tion:					

								. ago
			Pro	perty D	etail Form			
Agency:	BOARD OF PUBLIC EDUC	CATION / BOARD OF PUBLIC EDUC	CATION, S	CHOOL F	FOR THE DEAF & BLIND			
Property:	Food Service Building							
Property Address:	3911 Central Ave. GREAT	FALLS						
Property ID:	6							
Construction:								
Total number of insured I	ouildings:	1			Total square footage of insured buildings:	5603		
ear built:		1983			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Poured Concr	rete	
Construction of exterior v	walls:	Masonry			Construction of interior walls:	Masonry		
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Governm	nental Bui	lding			
Provide a brief description of operations:		blank						
Storage height of warehoused products:		2-3 feet b	below ceil	ling				
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	Υ	,	What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?	Public	How many hydrants are located within 500 feet of buildings?					
ndicate the Alarm Cover	ages provided for your fac	ility:	Sprinkler Waterflow, Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Valve Tamper					
Are alarms connected to	a constantly attended loca	ation?	Υ					
s there a watchman serv	ice?	N	,	What is t	he frequency of rounds?			
Are watchman recording	rounds?		I	N				
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N	ı	ls there a	fire private fire brigade?		N	
requency of training rec	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid	1	Distance	:		5 Blocks	
Exposure:								
low many buildings(not	part of Account) are withir	100 feet of insured buildings?	2					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Resident	tial Cottag	ges			
s there a body of water n	earby?	N	Descript	tion:				
low far is the body of wa	ter from major buildings?							
Previous history of flooding?			Description:					
Any property damage los	ses in the past 3 years:	N	Descript	tion:				

			Prop	perty Detail Form			
Agency:	BOARD OF PUBLIC EDUC	CATION / BOARD OF PUBLIC EDUC	CATION, SC	HOOL FOR THE DEAF & BLIND			
Property:	PE & Therapy Center						
Property Address:	3911 Central Ave. GREAT	FALLS					
Property ID:	8						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	27763		
Year built:		1984		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ F	Fire Doors	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Governme	ental Building			
Provide a brief description	on of operations:		GYMNASI	IUM/SWIMMING POOL/BASKET BALL COURT/BOWLING AI	LEY/WEIGHT F	RM/CONCESSION STAND	
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ					
Protection:							
Are there any automatic	sprinklers?	N	w	hat are the design densities for each area?		NOT AVAILABLE	
The water supply for aut	omatic sprinklers is?		Н	ow many hydrants are located within 500 feet of buildings	?	2	
ndicate the Alarm Cover	rages provided for your fac	cility:	Sı	moke Detectors, Sprinkler Waterflow, Sprinkler Valve Tamper			
Are alarms connected to	a constantly attended loca	ation?	N				
s there a watchman serv	vice?	N	W	hat is the frequency of rounds?			
Are watchman recording	rounds?						
Are there any fire exting	uishers?	Υ	Α	re they serviced annually?		Υ	
Are there any hose station	ons?	Υ	Is	there a fire private fire brigade?		N	
requency of training re	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	D	istance:		5 BLOCKS	
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	1				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Residentia	al Cottage			
s there a body of water	nearby?	N	Description	on:			
How far is the body of w	ater from major buildings?						
Previous history of flood	ling?	N	Description	on:			
Any property damage lo	sses in the past 3 years:	N	Description	on:			

							. ago
			Property	Detail Form			
Agency:	BOARD OF PUBLIC EDU	CATION / BOARD OF PUBLIC EDUC	CATION, SCHOO	L FOR THE DEAF & BLIND			
Property:	Residential Cottage II						
Property Address:	3911 Central Ave. GREAT	FALLS					
Property ID:	7						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	20699		
Year built:		1983		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	r walls:	Masonry		Construction of interior walls:	Gypsum Board	d	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		Υ			
Occupancy:							
Occupancy Type:			Res Apt Compl	ex			
Provide a brief description of operations:		RESIDENTIAL	HOUSING FOR SENSORY IMPAIRED STUDENTS				
Storage height of warehoused products:		18-20 IN. FROM	M CEILING				
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ					
Protection:							
Are there any automatic	sprinklers?	Υ	What a	are the design densities for each area?		NOT AVAILABLE	
The water supply for au	tomatic sprinklers is?	Public	How m	nany hydrants are located within 500 feet of buildings	s?	4	
Indicate the Alarm Cove	erages provided for your fa	cility:	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
Are alarms connected to	o a constantly attended loc	ation?	N				
Is there a watchman ser	rvice?	Υ	What i	s the frequency of rounds?		1/HOUR	
Are watchman recording	g rounds?		N				
Are there any fire exting	guishers?	Υ	Are the	ey serviced annually?		Υ	
Are there any hose stati	ions?	N	Is there	e a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:					
Type of public fire depa	rtment:	Paid	Distan	ce:		5 BLOCKS	
Exposure:							
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	2				
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):	FOOD SERVIC	E/COTTAGE 1			
Is there a body of water	nearby?	N	Description:				
How far is the body of w	vater from major buildings?	?					
Previous history of floo	ding?	N	Description:				
Any property damage lo	osses in the past 3 years:	Y	Description:		BROKEN WA' PANEL	TER LINE DAMAGED ELECT	RICAL

			Property	Detail Form					
Agency:	BOARD OF PUBLIC EDU	CATION / BOARD OF PUBLIC EDUC	CATION, SCHOO	L FOR THE DEAF & BLIND					
Property:	Residential Cottages I								
Property Address:	3911 Central Ave. GREAT	FALLS							
Property ID:	5								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	20699				
Year built:		1983		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete				
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board				
Do major interior masonry walls (fire walls) extend above the roofline?			Υ						
Occupancy:									
Occupancy Type:			Res Apt Compl	ex					
Provide a brief description of operations:			RESIDENTAL I	HOUSING FOR SENSORY IMPAIRED STUDENTS					
Storage height of warehoused products:			18-20 IN. BELC	18-20 IN. BELOW CEILING					
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ							
Protection:									
Are there any automatic	sprinklers?	Υ	What a	are the design densities for each area?	NOT AVAILA	BLE			
The water supply for auto	omatic sprinklers is?	Public	How m	nany hydrants are located within 500 feet of buildings	s? 4				
Indicate the Alarm Cover	ages provided for your fac	cility:	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Waterflow, Sprinkler Valve Tamper						
Are alarms connected to	a constantly attended loca	ation?	N						
ls there a watchman serv	ice?	Υ	What i	s the frequency of rounds?	1/HOUR				
Are watchman recording	rounds?		N						
Are there any fire extingu	iishers?	Υ	Are the	ey serviced annually?	Υ				
Are there any hose statio	ons?	N	Is ther	e a fire private fire brigade?	N				
Frequency of training red	eived by the private fire b	rigade:							
Type of public fire depart	ment:	Paid	Distan	ce:	5 BLOCKS				
Exposure:									
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	4						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	2 CLASSROOM	MS/BOILER/COTTAGE					
Is there a body of water r	nearby?	N	Description:						
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Description:						
Any property damage los	ses in the past 3 years:	Υ	Description:		WIND DAMAGE TO SHINGL	.ES			

					- 3 -
			Prope	erty Detail Form	
Agency:	BOARD OF PUBLIC EDUC	CATION / BOARD OF PUBLIC EDUC	CATION, SCH	OOL FOR THE DEAF & BLIND	
Property:	Vocational Shop Building				
Property Address:	3911 Central Ave. GREAT	FALLS			
Property ID:	2				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	8724
Year built:		1956		Number of stories:	1
Construction of roof:	onstruction of roof: Wood Joists			Construction of floors:	Poured Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry
Do major interior masonry walls (fire walls) extend above the roofline?			N		
Occupancy:					
Occupancy Type:			Governmen	ntal Building	
Provide a brief description of operations:		Office; Woo	od Shop; Storage		
Storage height of warehoused products:		6 feet below	v ceiling		
Are flammable and combustible liquids stored in a cut-off room?		N/A			
Safegaurds taken for the storage and dispensing of flammable liquids:		f flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	N	Wh	nat are the design densities for each area?	
The water supply for auto	omatic sprinklers is?	Public	Ho	w many hydrants are located within 500 feet of buildings?	? 2
Indicate the Alarm Cover	ages provided for your fac	cility:	Sm	noke Detectors	
Are alarms connected to	a constantly attended loca	ation?	N		
Is there a watchman serv	rice?	N	Wh	nat is the frequency of rounds?	
Are watchman recording	rounds?		N		
Are there any fire extingu	uishers?	Υ	Are	e they serviced annually?	Υ
Are there any hose statio	ons?	N	ls t	there a fire private fire brigade?	N
Frequency of training rec	ceived by the private fire b	rigade:			
Type of public fire depart	tment:	Paid	Dis	stance:	5 Blocks
Exposure:					
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water r	nearby?	N	Description	n:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ing?	N	Description	n:	
Any property damage los	sses in the past 3 years:	N	Description	n:	

			Pr	operty D	Petail Form		
Agency:	DEPARTMENT OF ADMIN	NISTRATION / DEPARTMENT OF AD	MINISTR	RATION			
Property:	1225 8TH						
Property Address:	1225 8th HELENA						
Property ID:	24						
Construction:							
Total number of insured	buildings:	1			Total square footage of insured buildings:	1707	
Year built:		blank			Number of stories:	2	
Construction of roof:		null			Construction of floors:	null	
Construction of exterior	walls:	null			Construction of interior walls:	null	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			null		
Occupancy:							
Occupancy Type:			Office				
Provide a brief description	n of operations:		blank				
Storage height of warehoused products:		blank					
Are flammable and combustible liquids stored in a cut-off room?		null					
Safegaurds taken for the storage and dispensing of flammable liquids:		null					
Protection:							
Are there any automatic s	sprinklers?	N		What are	the design densities for each area?		
The water supply for auto	omatic sprinklers is?		How many hydrants are located within 500 feet of buildings? blank				blank
Indicate the Alarm Cover	ages provided for your fac	cility:		blank			
Are alarms connected to	a constantly attended loca	ation?		null			
Is there a watchman serv	ice?	null		What is t	the frequency of rounds?		
Are watchman recording	rounds?						
Are there any fire extingu	ishers?	null		Are they	serviced annually?		null
Are there any hose statio	ns?	null		Is there a	a fire private fire brigade?		null
Frequency of training rec	eived by the private fire b	rigade:					
Type of public fire depart	ment:	null		Distance	н		blank
Exposure:							
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water n	earby?	null	Descrip	otion:			
How far is the body of wa	ter from major buildings?						
Previous history of flood	ing?	null	Descrip	otion:			
Any property damage los	ses in the past 3 years:	null	Descrip	otion:			

						1 49	,-		
			Prop	perty Detail Form					
Agency:	DEPARTMENT OF ADMIN	IISTRATION / DEPARTMENT OF AD	OMINISTRA	TION					
Property:	1424 9th for DNRC								
Property Address:	1424 9th HELENA								
Property ID:	18								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	28424				
Year built:		1960		Number of stories:	2				
Construction of roof:		null		Construction of floors:	Reinforced Concre	rete			
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board				
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Office						
Provide a brief description of operations:			OFFICES	OFFICES STATE GOVERNMENT					
Storage height of warehoused products:		N/A							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic	sprinklers?	Υ	W	What are the design densities for each area?					
The water supply for aut	omatic sprinklers is?	Public	н	low many hydrants are located within 500 feet of buildings?	2				
Indicate the Alarm Cove	rages provided for your fac	ility:	s	Sprinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors					
Are alarms connected to	a constantly attended loca	ation?	Υ	,					
Is there a watchman serv	vice?	Υ	W	What is the frequency of rounds?	E۷	VERY 3 HOURS			
Are watchman recording	g rounds?		Υ	,					
Are there any fire exting	uishers?	Υ	Α	are they serviced annually?	Υ				
Are there any hose static	ons?	Υ	Is	s there a fire private fire brigade?	N				
Frequency of training re	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Paid	D	Distance:	bla	ank			
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water	nearby?	N	Description	on:					
How far is the body of w	ater from major buildings?								
Previous history of floor	ding?	N	Description	on:					

							. ago
			Prop	erty Detail Form			
gency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT (	OF ADMINISTRAT	TION			
Property:	Armory PBX						
roperty Address:	1100 N. Last Chance Gul	ch HELENA					
roperty ID:							
construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	56251		
ear built:		1920		Number of stories:	4		
construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Con	ncrete	
onstruction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board		
o major interior mason	ry walls (fire walls) extend	d above the roofline?		N			
Occupancy:							
Occupancy Type:			Office				
rovide a brief descripti	on of operations:		OFFICES	STATE GOVERNMENT			
torage height of wareh	oused products:		N/A				
re flammable and com	bustible liquids stored in a	a cut-off room?	N/A				
afegaurds taken for the	e storage and dispensing	of flammable liquids:	N/A				
rotection:							
re there any automatic	sprinklers?	Υ	w	hat are the design densities for each area?			
he water supply for aut	tomatic sprinklers is?	Public	Н	ow many hydrants are located within 500 feet of buildin	gs?	2	
ndicate the Alarm Cove	rages provided for your fa	cility:	Sr	noke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflo	)W		
are alarms connected to	a constantly attended loc	cation?	Y				
s there a watchman serv	vice?	Υ	w	hat is the frequency of rounds?	,	EVERY 3 HOURS	
re watchman recording	g rounds?		Y				
are there any fire exting	uishers?	Υ	Aı	re they serviced annually?		Υ	
re there any hose static	ons?	Υ	Is	there a fire private fire brigade?	1	N	
requency of training re	ceived by the private fire I	origade:					
ype of public fire depar	rtment:	Paid	Di	stance:		blank	
xposure:							
low many buildings(not	t part of Account) are with	in 100 feet of insured building	<b>s?</b> 0				

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Description: Ν Any property damage losses in the past 3 years: N

Description:

Description:

					1 490 1
			P	roperty Detail Form	
Agency:	DEPARTMENT OF ADMIN	NISTRATION / DEPARTMENT OF AI	DMINISTI	RATION	
Property:	Aviation & Support Facility	r-Office			
Property Address:	2800 Airport Rd HELENA				
Property ID:	38				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	5920
Year built:		1960		Number of stories: 1	
Construction of roof:		Steel Deck		Construction of floors:	einforced Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	asonry w/ Fire Doors
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief description	on of operations:		Offices	5	
Storage height of warehoused products:			N/A		
Are flammable and combustible liquids stored in a cut-off room?			N/A		
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cove	rages provided for your fac	cility:		Smoke Detectors	
Are alarms connected to	a constantly attended loc	ation?		Υ	
Is there a watchman serv	vice?	null		What is the frequency of rounds?	Every 3 Hours
Are watchman recording	g rounds?			Υ	
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose static	ons?	Υ		Is there a fire private fire brigade?	N
Frequency of training re	ceived by the private fire b	rigade:			
Type of public fire depar	rtment:	Paid		Distance:	blank
Exposure:					
How many buildings(not	t part of Account) are withi	n 100 feet of insured buildings?	1		
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):	airport	hanger	
Is there a body of water	nearby?	N	Descri	ption:	
How far is the body of w	ater from major buildings?				
Previous history of flood	ding?	N	Descri	ption:	

			Pro	pperty Detail Form		
Agency:	DEPARTMENT OF ADMII	NISTRATION / DEPARTMENT OF A	DMINISTR	ATION		
Property:	Aviation & Support Facility	r-Shop				
Property Address:	2800 Airport Rd HELENA					
Property ID:						
Construction:						
Total number of insured	l buildings:	1		Total square footage of insured buildings:	25343	
Year built:		1958		Number of stories:	1	
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Co	oncrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fir	re Doors
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Garage,	Service Center		
Provide a brief description of operations:			OFFICE	S STATE GOVERNMENT		
Storage height of warehoused products:			N/A			
Are flammable and combustible liquids stored in a cut-off room?		Υ				
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	Υ			
Protection:						
Are there any automation	sprinklers?	N	,	What are the design densities for each area?		
Γhe water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		2
ndicate the Alarm Cove	rages provided for your fa	cility:		Smoke Detectors		
Are alarms connected to	o a constantly attended loc	ation?		Υ		
s there a watchman ser	vice?	Υ	,	What is the frequency of rounds?		EVERY 3 HOURS
Are watchman recording	g rounds?			Υ		
Are there any fire exting	juishers?	Υ		Are they serviced annually?		Υ
Are there any hose stati	ons?	Υ		Is there a fire private fire brigade?		N
requency of training re	eceived by the private fire b	rigade:				
Гуре of public fire depa	rtment:	Paid		Distance:		blank
Exposure:						
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	1			
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):	AIRPOR	T HANGER		
s there a body of water	nearby?	N	Descript	tion:		
How far is the body of w	ater from major buildings?	•				

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

			Pro	perty Detail Form	
gency:	DEPARTMENT OF ADMIN	IISTRATION / DEPARTMENT OF AD	DMINISTRA	ATION	
Property:	Board of Health				
roperty Address:	1301 Lockey HELENA				
roperty ID:	4				
Construction:					
otal number of insured	buildings:	1		Total square footage of insured buildings:	7852
ear built:		1919		Number of stories:	3
construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete
construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors
o major interior masoni	ry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
occupancy Type:			Office		
rovide a brief description	on of operations:		Offices		
torage height of wareho	oused products:		N/A		
are flammable and comb	oustible liquids stored in a	cut-off room?	N/A		
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A		
rotection:					
re there any automatic	sprinklers?	N	'	What are the design densities for each area?	
he water supply for auto	omatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?	4
ndicate the Alarm Cover	ages provided for your fac	ility:		Smoke Detectors	
re alarms connected to	a constantly attended loca	ition?	`	Υ	
s there a watchman serv	rice?	Υ	,	What is the frequency of rounds?	Every three hours
re watchman recording	rounds?		`	Υ	
are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ
are there any hose static	ons?	N	ı	s there a fire private fire brigade?	N
requency of training red	ceived by the private fire br	rigade:			
ype of public fire depart	tment:	Paid	I	Distance:	blank
xposure:					
low many buildings(not	part of Account) are within	100 feet of insured buildings?	1		

Office

Description:

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

						- 3
			Prop	perty Detail Form		
Agency:	DEPARTMENT OF ADMIN	IISTRATION / DEPARTMENT OF AD	MINISTRA	TION		
Property:	Boiler Plant					
Property Address:	120 N Roberts HELENA					
Property ID:	9					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	7946	
Year built:		1968		Number of stories:	2	
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Cor	ncrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fir	re Doors
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Power Pla	nt		
Provide a brief description of operations:		Heating pl	lant			
Storage height of warehoused products:		8 feet				
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	Υ			
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ				
Protection:						
Are there any automatic	sprinklers?	N	W	hat are the design densities for each area?		
The water supply for aut	omatic sprinklers is?		н	ow many hydrants are located within 500 feet of buildings?		4
Indicate the Alarm Cover	rages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ition?	nı	ull		
Is there a watchman serv	vice?	Υ	W	/hat is the frequency of rounds?		Every 3 hours
Are watchman recording	rounds?		Υ			
Are there any fire exting	uishers?	Υ	Α	re they serviced annually?		Υ
Are there any hose static	ons?	N	Is	there a fire private fire brigade?		N
Frequency of training red	ceived by the private fire br	igade:				
Type of public fire depar	tment:	Paid	D	istance:		blank
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	2			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Office buil	ding		
Is there a body of water	nearby?	N	Description	on:		
How far is the body of wa	ater from major buildings?					

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

DAMAGE TO INTERIOR FINISHES FROM FLOODING

					1 49			
			Prop	erty Detail Form				
Agency:	DEPARTMENT OF ADMII	NISTRATION / DEPARTMENT OF AI	DMINISTRAT	FION				
Property:	Capitol Building							
Property Address:	1301 E 6th HELENA							
Property ID:	10							
Construction:								
Total number of insured	l buildings:	1		Total square footage of insured buildings:	184564			
Year built:		1889		Number of stories:	4			
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete			
Construction of exterior	r walls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ Fire Doors			
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Governme	ntal Building				
Provide a brief description of operations:			OFFICES	OFFICES STATE GOVERNMENT				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			Υ					
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	Υ	W	hat are the design densities for each area?				
The water supply for au	tomatic sprinklers is?	Public	Н	ow many hydrants are located within 500 feet of buildings	? 4			
Indicate the Alarm Cove	erages provided for your fac	cility:	Sp	orinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors,	Burglar Alarms (Door Contacts)			
Are alarms connected to	o a constantly attended loc	ation?	Υ					
Is there a watchman ser	vice?	null	W	hat is the frequency of rounds?	Υ			
Are watchman recording	g rounds?							
Are there any fire exting	guishers?	Υ	Ar	re they serviced annually?	Υ			
Are there any hose state	ions?	N	Is	there a fire private fire brigade?	Υ			
Frequency of training re	eceived by the private fire b	rigade:						
Type of public fire depa	rtment:	Paid	Di	istance:	blank			
Exposure:								
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	1					
Describe the Occupancy of those buildings(s) nearby (within 100 feet):		BOILER P	LANT					
Is there a body of water	nearby?	N	Description	on:				
How far is the body of w	vater from major buildings?							
Previous history of floo	ding?	Υ	Description	on:	GROUNDWATER FLOODING - MINOR			

Description:

			Prope	erty Detail Form	
gency:	DEPARTMENT OF ADMIN	ISTRATION / DEPARTMENT OF AD	OMINISTRATI	ON	
roperty:	Cogswell Building				
roperty Address:	1401 Lockey HELENA				
roperty ID:	2				
onstruction:					
otal number of insured	buildings:	1		Total square footage of insured buildings:	96726
ear built:		1955		Number of stories:	3
onstruction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete
onstruction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board
o major interior masonr	ry walls (fire walls) extend a	above the roofline?		N	
ccupancy:					
ccupancy Type:			Laboratory		
rovide a brief description of operations:			OFFICES -	STATE GOVERNMENT	
torage height of wareho	oused products:		N/A		
re flammable and comb	oustible liquids stored in a c	cut-off room?	Υ		
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ		
rotection:					
re there any automatic	sprinklers?	N	Wh	at are the design densities for each area?	
he water supply for auto	omatic sprinklers is?	Public	Hov	w many hydrants are located within 500 feet of buildings?	4
dicate the Alarm Cover	ages provided for your faci	ility:	Spr	rinkler Waterflow, Smoke Detectors, Sprinkler Valve Tamper	
re alarms connected to	a constantly attended loca	tion?	Υ		
there a watchman serv	rice?	Υ	Wh	at is the frequency of rounds?	EVERY 3 HOURS
re watchman recording	rounds?		Υ		
re there any fire extingu	uishers?	Υ	Are	they serviced annually?	Υ
re there any hose statio	ons?	Υ	ls t	here a fire private fire brigade?	N
requency of training rec	ceived by the private fire br	igade:			
ype of public fire depart	tment:	Paid	Dis	stance:	blank
xposure:					
ow many buildings/not	part of Account) are within	100 feet of insured buildings?	0		

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

							Page	
			Prope	rty Detail Form				
Agency:	DEPARTMENT OF ADMIN	NISTRATION / DEPARTMENT OF AI	DMINISTRATI	ON				
Property:	DPHHS Headquarters Bld	g, Sanders Street						
Property Address:	111 N Sanders HELENA							
Property ID:	5							
Construction:								
Total number of insure	d buildings:	1		Total square footage of insured buildings:	47464			
Year built:		1975		Number of stories:	4			
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Con	ncrete		
Construction of exterio	or walls:	Glass and Steel Curtain		Construction of interior walls:	Gypsum Board			
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Office					
Provide a brief description of operations:			OFFICES S	OFFICES STATE GOVERNMENT				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A					
Protection:								
Are there any automati	c sprinklers?	Υ	Wh	at are the design densities for each area?				
The water supply for au	utomatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?	?	3		
Indicate the Alarm Cov	erages provided for your fac	cility:	Sme	oke Detectors				
Are alarms connected to	to a constantly attended loc	ation?	Υ					
Is there a watchman se	rvice?	Υ	Wh	at is the frequency of rounds?	ĺ	EVERY 3 HOURS		
Are watchman recording	ng rounds?		Υ					
Are there any fire extin	guishers?	Υ	Are	they serviced annually?	,	Υ		
Are there any hose stat	tions?	Υ	ls ti	here a fire private fire brigade?	į	N		
Frequency of training r	eceived by the private fire b	rigade:						
Type of public fire depart	artment:	Paid	Dis	tance:	ļ	blank		
Exposure:								
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	1					
Describe the Occupano	cy of those buildings(s) near	rby (within 100 feet):	OFFICES					
Is there a body of water	r nearby?	N	Description	:				
How far is the body of	water from major buildings?	?						
Previous history of floo	oding?	N	Description	ı:				

							- 3 -
			Pr	roperty Detail Form			
Agency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT OF A	.DMINISTF	RATION			
Property:	Executive Residence						
Property Address:	2 Carson HELENA						
Property ID:	1						
Construction:							
Total number of insured	l buildings:	1		Total square footage of insured buildings:	12259		
Year built:		1960		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced (	Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry		
Do major interior masor	nry walls (fire walls) extend	d above the roofline?		N			
Occupancy:							
Occupancy Type:			Res Ap	ot Complex			
Provide a brief descript	on of operations:		Govern	nors home			
Storage height of wareh	oused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	e storage and dispensing	of flammable liquids:	N/A				
Protection:							
Are there any automation	sprinklers?	N		What are the design densities for each area?			
Γhe water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of building	gs?	3	
ndicate the Alarm Cove	rages provided for your fa	cility:		Burglar Alarms (Door Contacts), Burglar Alarms (Motion Dete	ction), Smoke De	etectors	
Are alarms connected to	a constantly attended lo	cation?		Υ			
s there a watchman ser	vice?	Υ		What is the frequency of rounds?		Every 3 hours	
Are watchman recording	g rounds?			Υ			
Are there any fire exting	juishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a fire private fire brigade?		N	
requency of training re	eceived by the private fire	origade:					
Гуре of public fire depa	rtment:	Paid		Distance:		blank	
Exposure:							
How many buildings(no	t part of Account) are with	in 100 feet of insured buildings?	1				
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):	Private	residence			
s there a body of water	nearby?	N	Descri	ption:			
How far is the body of w	ater from major buildings	?					

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

							i age	
			Prope	rty Detail Form				
Agency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT OF A	DMINISTRATIO	ON				
Property:	FWP-1420 6TH AVE							
Property Address:	1420 E 6th HELENA							
Property ID:	16							
Construction:								
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	22966			
Year built:		1965		Number of stories:	2			
Construction of roof:		Steel Deck		Construction of floors:	Reinforced C	concrete		
Construction of exterio	or walls:	Glass and Steel Curtain		Construction of interior walls:	Gypsum Boar	rd		
Do major interior maso	onry walls (fire walls) extend	I above the roofline?		N				
Occupancy:								
Occupancy Type:			Office					
Provide a brief descrip	tion of operations:		OFFICES S	OFFICES STATE GOVERNMENT				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for t	he storage and dispensing o	of flammable liquids:	N/A					
Protection:								
Are there any automat	ic sprinklers?	N	Wha	at are the design densities for each area?				
The water supply for a	utomatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings	s?	2		
Indicate the Alarm Cov	erages provided for your fa	cility:	Smo	oke Detectors				
Are alarms connected	to a constantly attended loc	cation?	Υ					
Is there a watchman se	ervice?	Υ	Wha	at is the frequency of rounds?		<b>EVERY 3 HOURS</b>		
Are watchman recordi	ng rounds?		Υ					
Are there any fire extir	guishers?	Υ	Are	they serviced annually?		Υ		
Are there any hose sta	tions?	Υ	ls ti	here a fire private fire brigade?		N		
Frequency of training	received by the private fire b	origade:						
Type of public fire dep	artment:	Paid	Dis	tance:		blank		
Exposure:								
How many buildings(n	ot part of Account) are with	in 100 feet of insured buildings?	1					
Describe the Occupan	cy of those buildings(s) nea	rby (within 100 feet):	OFFICES					
Is there a body of water	r nearby?	N	Description	:				
How far is the body of	water from major buildings	?						
Previous history of flo	oding?	N	Description	:				
Any property damage	losses in the past 3 years:	N	Description	:				

							Page 2
			Pı	roperty Detail Form			
Agency:	DEPARTMENT OF ADM	INISTRATION / DEPARTMENT OF A	.DMINISTI	RATION			
Property:	Grounds Maintenance sh	ор					
Property Address:	425 N. Roberts HELENA						
Property ID:							
Construction:							
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	3309		
Year built:		blank		Number of stories:	1		
Construction of roof:		null		Construction of floors:	null		
Construction of exterio	or walls:	null		Construction of interior walls:	null		
Do major interior maso	onry walls (fire walls) extend	d above the roofline?		null			
Occupancy:							
Occupancy Type:			Garage	e, Service Center			
Provide a brief descrip	otion of operations:		blank				
Storage height of ware	ehoused products:		blank				
Are flammable and combustible liquids stored in a cut-off room?		null					
Safegaurds taken for t	he storage and dispensing	of flammable liquids:	null				
Protection:							
Are there any automat	ic sprinklers?	N		What are the design densities for each area?			
The water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		blank	
Indicate the Alarm Cov	verages provided for your fa	acility:		blank			
Are alarms connected	to a constantly attended lo	cation?		null			
Is there a watchman se	ervice?	null		What is the frequency of rounds?			
Are watchman recordi	ng rounds?						
Are there any fire extir	nguishers?	null		Are they serviced annually?		null	
Are there any hose sta	tions?	null		Is there a fire private fire brigade?		null	
Frequency of training	received by the private fire	brigade:					
Type of public fire dep	artment:	null		Distance:		blank	
Exposure:							
How many buildings(n	ot part of Account) are with	in 100 feet of insured buildings?	blank				
Describe the Occupan	cy of those buildings(s) nea	arby (within 100 feet):					
Is there a body of water	er nearby?	null	Descri	ption:			
How far is the body of	water from major buildings	?					

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: null

null

						Page
			Pro	operty Detail Form		
Agency:	DEPARTMENT OF ADMIN	NISTRATION / DEPARTMENT OF A	ADMINISTR	ATION		
Property:	Justice Building					
Property Address:	215 N Sanders HELENA					
Property ID:	12					
Construction:						
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	98850	
Year built:		1982		Number of stories:	4	
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete	
Construction of exterio	or walls:	Glass and Steel Curtain		Construction of interior walls:	Gypsum Board	
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Library			
Provide a brief description of operations:			OFFICE	S STATE GOVERNMENT		
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for t	he storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automat	ic sprinklers?	N		What are the design densities for each area?		
Γhe water supply for a	utomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	? 3	
ndicate the Alarm Cov	verages provided for your fac	cility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected	to a constantly attended loca	ation?		Υ		
s there a watchman so	ervice?	Υ		What is the frequency of rounds?	EVERY 3 HOURS	
Are watchman recordi	ng rounds?			Υ		
Are there any fire extir	nguishers?	Υ		Are they serviced annually?	Υ	
Are there any hose sta	itions?	Υ		Is there a fire private fire brigade?	N	
requency of training	received by the private fire b	rigade:				
Type of public fire dep	artment:	Paid		Distance:	blank	
Exposure:						
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	2			
Describe the Occupan	cy of those buildings(s) near	by (within 100 feet):	OFFICE	S		
s there a body of wate	er nearby?	N	Descrip	tion:		
How far is the body of	water from major buildings?	•				
Previous history of flo	odina?	N	Descrip	tion:		

							i age
			Prop	erty Detail Form			
Agency:	DEPARTMENT OF ADMII	NISTRATION / DEPARTMENT OF A	DMINISTRAT	FION			
Property:	Labor & Industry (Walt Su	llivan)					
Property Address:	1315 Lockey HELENA						
Property ID:	3						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	51235		
Year built:		1959		Number of stories:	4		
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Conc	crete	
Construction of exterio	r walls:	Glass and Steel Curtain		Construction of interior walls:	Gypsum Board		
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Office				
Provide a brief descript	tion of operations:		OFFICES	STATE GOVERNMENT			
Storage height of warel	housed products:		N/A				
Are flammable and com	nbustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automatic	c sprinklers?	N	W	hat are the design densities for each area?			
The water supply for au	utomatic sprinklers is?		Н	ow many hydrants are located within 500 feet of buildings?	? 3	3	
Indicate the Alarm Cove	erages provided for your fa	cility:	Sr	moke Detectors			
Are alarms connected t	o a constantly attended loc	ation?	Υ				
Is there a watchman se	rvice?	Υ	W	hat is the frequency of rounds?	E	EVERY 3 HOURS	
Are watchman recording	g rounds?		Υ				
Are there any fire exting	guishers?	Υ	Ar	re they serviced annually?	Y	<b>,</b>	
Are there any hose stat	ions?	Υ	Is	there a fire private fire brigade?	N	1	
Frequency of training re	eceived by the private fire b	rigade:					
Type of public fire depart	artment:	Paid	Di	stance:	b	lank	
Exposure:							
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	3				
Describe the Occupano	y of those buildings(s) nea	rby (within 100 feet):	OFFICES				
Is there a body of water	nearby?	N	Descriptio	on:			
How far is the body of v	water from major buildings?	?					

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

							Page
			Pro	operty Detail Form			
Agency:	DEPARTMENT OF ADM	INISTRATION / DEPARTMENT OF A	DMINISTR	RATION			
Property:	Metcalf Building						
Property Address:	1520 E 6th HELENA						
Property ID:	13						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	91379		
Year built:		1982		Number of stories:	3		
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Cor	ncrete	
Construction of exterio	or walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board	ı	
Do major interior maso	onry walls (fire walls) exten	nd above the roofline?		N			
Occupancy:							
Occupancy Type:			Office				
Provide a brief descrip	tion of operations:		OFFICE	ES STATE GOVERNMENT			
Storage height of ware	housed products:		N/A				
Are flammable and cor	mbustible liquids stored in	a cut-off room?	N/A				
Safegaurds taken for the	he storage and dispensing	of flammable liquids:	N/A				
Protection:							
Are there any automati	ic sprinklers?	Υ		What are the design densities for each area?			
The water supply for a	utomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings	?	3	
Indicate the Alarm Cov	erages provided for your f	acility:		${\bf Smoke\ Detectors,\ Sprinkler\ Valve\ Tamper,\ Sprinkler\ Waterflow}$			
Are alarms connected	to a constantly attended lo	ocation?		Υ			
Is there a watchman se	ervice?	Υ		What is the frequency of rounds?		EVERY 3 HOURS	
Are watchman recording	ng rounds?			Υ			
Are there any fire extin	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose sta	tions?	Υ		Is there a fire private fire brigade?		N	
Frequency of training I	received by the private fire	brigade:					
Type of public fire dep	artment:	Paid		Distance:		blank	
Exposure:							
How many buildings(n	ot part of Account) are with	hin 100 feet of insured buildings?	1				
Describe the Occupand	cy of those buildings(s) ne	arby (within 100 feet):	OFFICE	<b></b>			
Is there a body of water	r nearby?	N	Descrip	otion:			
How far is the body of	water from major buildings	s?					

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

			Prop	perty Detail Form		
Agency:	DEPARTMENT OF ADMII	NISTRATION / DEPARTMENT OF A	DMINISTRA	TION		
Property:	Mitchell Building					
Property Address:	125 N Roberts HELENA					
Property ID:	6					
Construction:						
Total number of insured	l buildings:	1		Total square footage of insured buildings:	130005	
Year built:		1949		Number of stories:	5	
Construction of roof:		null		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descripti	on of operations:		OFFICES	STATE GOVERNMENT		
Storage height of warehoused products:			N/A			
Are flammable and combustible liquids stored in a cut-off room?			N/A			
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N	W	hat are the design densities for each area?		
The water supply for au	tomatic sprinklers is?		н	ow many hydrants are located within 500 feet of buildings?	4	
ndicate the Alarm Cove	rages provided for your fac	cility:	S	moke Detectors		
Are alarms connected to	o a constantly attended loc	ation?	Υ			
s there a watchman ser	vice?	Υ	W	/hat is the frequency of rounds?	EVERY 3 HC	URS
Are watchman recording	g rounds?		Υ			
Are there any fire exting	juishers?	Υ	Α	re they serviced annually?	Υ	
Are there any hose stati	ons?	Υ	Is	there a fire private fire brigade?	N	
Frequency of training re	eceived by the private fire b	rigade:				
Type of public fire depa	rtment:	Paid	D	istance:	blank	
Exposure:						
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	2			
Describe the Occupancy	y of those buildings(s) near	rby (within 100 feet):	OFFICES			
s there a body of water	nearby?	N	Description	on:		
How far is the body of w	ater from major buildings?					
Previous history of floo	ding?	N	Description	on:		
Any property damage lo	sses in the past 3 years:	N	Description	on:		

					Page A
			Pr	operty Detail Form	
Agency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT OF A	DMINIST	RATION	
Property:	Montana Lottery, Leased				
Property Address:	2525 N. Montana Ave. HE	LENA			
Property ID:	61010				
Construction:					
Total number of insure	d buildings:	1		Total square footage of insured buildings:	14340
Year built:		1975		Number of stories:	1
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete
Construction of exterio	r walls:	Wood Frame		Construction of interior walls:	Gypsum Board
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief descript	tion of operations:		Offices		
Storage height of warel	noused products:		20 feet		
Are flammable and con	nbustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for th	ne storage and dispensing o	f flammable liquids:	N/A		
Protection:					
Are there any automatic	c sprinklers?	N		What are the design densities for each area?	Majority is open
The water supply for au	utomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	1
Indicate the Alarm Cov	erages provided for your fac	cility:		Burglar Alarms (Beams), Burglar Alarms (Door Contacts), Burglar Smoke Detectors, Sprinkler Valve Tamper	Alarms (Motion Detection), Fire Pump Alarms,
Are alarms connected t	o a constantly attended loc	ation?		Υ	
Is there a watchman se	rvice?	N		What is the frequency of rounds?	
Are watchman recording	g rounds?				
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ
Are there any hose stat	ions?	Υ		Is there a fire private fire brigade?	N
Frequency of training r	eceived by the private fire b	rigade:			
Type of public fire depart	artment:	Paid		Distance:	2 miles
Exposure:					
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	4		
Describe the Occupano	y of those buildings(s) near	by (within 100 feet):	Retail a	and security business	
Is there a body of water	nearby?	N	Descri	ption:	
How far is the body of	water from major buildings?	•			

Description:

Previous history of flooding?

			Pr	operty Detail Form	
Agency:	DEPARTMENT OF ADMIN	NISTRATION / DEPARTMENT OF AD	OMINISTE	RATION	
Property:	Offices - 1410/1412 8TH				
Property Address:	1410/1412 8th HELENA				
Property ID:	32				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings: 38	962
Year built:		blank		Number of stories: 2	
Construction of roof:		Wood Joists		Construction of floors:	/ood Timber
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	ypsum Board
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief description	on of operations:		offices		
Storage height of wareho	oused products:		n/a		
Are flammable and comb	Are flammable and combustible liquids stored in a cut-off room?  N/A				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank
Indicate the Alarm Cover	ages provided for your fac	cility:		Smoke Detectors	
Are alarms connected to	a constantly attended loca	ation?		null	
Is there a watchman serv	rice?	null		What is the frequency of rounds?	
Are watchman recording	rounds?				
Are there any fire extingu	iishers?	Υ		Are they serviced annually?	Υ
Are there any hose statio	ons?	null		Is there a fire private fire brigade?	null
Frequency of training red	eived by the private fire b	rigade:			
Type of public fire depart	ment:	Paid		Distance:	blank
Exposure:					
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water r	nearby?	Υ	Descrip	otion:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ing?	Υ	Descrip	otion:	

DAMAGE TO BOILER FROM FLOODING

						. ago
			Pro	operty Detail Form		
Agency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT OF A	DMINISTR	ATION		
Property:	Old Liquor Warehouse					
Property Address:	920 Front HELENA					
Property ID:	35					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	60627	
Year built:		1930		Number of stories:	2	
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete	
Construction of exterio	r walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descript	ion of operations:		OFFICE	S GOVERNMENT		
Storage height of warel	noused products:		8 FT.			
Are flammable and com	nbustible liquids stored in a	cut-off room?	Υ			
Safegaurds taken for th	e storage and dispensing	of flammable liquids:	Υ			
Protection:						
Are there any automatic	c sprinklers?	Υ		What are the design densities for each area?		
The water supply for au	itomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	? 3	
Indicate the Alarm Cove	erages provided for your fa	cility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected t	o a constantly attended loo	eation?		Υ		
Is there a watchman se	rvice?	Υ		What is the frequency of rounds?	EVERY 3 HOURS	
Are watchman recording	g rounds?			Υ		
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stat	ions?	Υ		Is there a fire private fire brigade?	N	
Frequency of training re	eceived by the private fire b	origade:				
Type of public fire depart	artment:	Paid		Distance:	blank	
Exposure:						
How many buildings(no	ot part of Account) are with	in 100 feet of insured buildings?	2			
Describe the Occupano	y of those buildings(s) nea	rby (within 100 feet):	OFFICE	S/HOTEL		
Is there a body of water	nearby?	N	Descrip	tion:		
How far is the body of v	water from major buildings	?				
Previous history of floo	ding?	Υ	Descrip	tion:	MINOR GROUNDWATER FLOODING	

Description:

			Pro	operty D	Detail Form			
Agency:	DEPARTMENT OF ADMIN	NISTRATION / DEPARTMENT OF AL	DMINISTR	RATION				
Property:	Old Livestock Building							
Property Address:	1310 Lockey HELENA							
Property ID:	7							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	7713		
Year built:		1919			Number of stories:	3		
Construction of roof:		Reinforced Concrete			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ Fir	re Doors	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief descripti	on of operations:		Offices					
Storage height of wareh	oused products:		N/A					
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?			
The water supply for aut	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?	1	3	
Indicate the Alarm Cove	rages provided for your fac	cility:		Smoke D	Detectors			
Are alarms connected to	a constantly attended loca	ation?		Υ				
ls there a watchman ser	vice?	Υ		What is t	the frequency of rounds?		Every 3 hours	
Are watchman recording	g rounds?			Υ				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:						
Type of public fire depar	rtment:	Paid		Distance	e:		blank	
Exposure:								
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Descrip	otion:				
How far is the body of w	ater from major buildings?	,						
Previous history of flood	ding?	N	Descrip	otion:				
Any property damage lo	sses in the past 3 years:	N	Descrip	otion:				

					- 3 -
			Pro	operty Detail Form	
Agency:	DEPARTMENT OF ADMIN	IISTRATION / DEPARTMENT OF AD	MINISTR	RATION	
Property:	OPI 1300 Superintendent of	of Public Instruction			
Property Address:	1300 11th Ave. HELENA				
Property ID:	17				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings: 20	0125
Year built:		1970		Number of stories: 2	
Construction of roof:		Steel Deck		Construction of floors: W	ood Timber
Construction of exterior	walls:	Wood Frame		Construction of interior walls: G	ypsum Board
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief description	on of operations:		OFFICE	ES STATE GOVERNMENT	
Storage height of warehoused products:			N/A		
Are flammable and combustible liquids stored in a cut-off room?  N/A					
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cover	ages provided for your fac	sility:		Smoke Detectors	
Are alarms connected to	a constantly attended loca	ation?		Υ	
Is there a watchman serv	ice?	Υ		What is the frequency of rounds?	EVERY 3 HOURS
Are watchman recording	rounds?			Υ	
Are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose station	ons?	Υ		Is there a fire private fire brigade?	Υ
Frequency of training red	eived by the private fire b	rigade:			
Type of public fire depart	ment:	Paid		Distance:	blank
Exposure:					
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water r	nearby?	N	Descrip	otion:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ing?	N	Descrip	otion:	

21138

**EVERY 3 HOURS** 

2

	Property Detail Fo
Agency:	DEPARTMENT OF ADMINISTRATION / DEPARTMENT OF ADMINISTRATION
Property:	OPI Building 1227
Property Address:	1227 11th Avenue HELENA

34 **Property ID:** 

Cons	tructior	١.	
Cons	uruction	1	

Total number of insured buildings: 1

Total square footage of insured buildings: 1968 Number of stories:

Construction of roof: Steel Deck Construction of floors: Wood Timber Construction of exterior walls: Masonry Construction of interior walls: Gypsum Board

Do major interior masonry walls (fire walls) extend above the roofline?

## Occupancy:

Year built:

**Occupancy Type:** Office

Provide a brief description of operations: OFFICES STATE GOVENMENT

Storage height of warehoused products: N/A Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids: N/A

## Protection:

Ν Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? How many hydrants are located within 500 feet of buildings? 2

Indicate the Alarm Coverages provided for your facility: **Smoke Detectors** 

Are alarms connected to a constantly attended location?

Is there a watchman service? Υ What is the frequency of rounds?

Are watchman recording rounds?

Υ Are there any fire extinguishers? Υ Are they serviced annually?

Are there any hose stations? Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: blank

Description:

## Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

OFFICES/HOMES Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

How far is the body of water from major buildings?

Is there a body of water nearby?

Previous history of flooding? Ν Description: Any property damage losses in the past 3 years: Description:

					r age 5
			Pro	perty Detail Form	
Agency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT OF A	DMINISTRA	ATION	
Property:	Original Governor's Mansi	on			
Property Address:	304 N Ewing HELENA				
Property ID:	37				
Construction:					
Total number of insure	d buildings:	1		Total square footage of insured buildings: 93	371
Year built:		1888		Number of stories: 3	
Construction of roof:		Wood Joists		Construction of floors:	ood Timber
Construction of exterio	r walls:	Masonry		Construction of interior walls:	asonry w/ Openings
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Museum		
Provide a brief descript	tion of operations:		Historic H	Home	
Storage height of warel	housed products:		N/A		
Are flammable and con	nbustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A		
Protection:					
Are there any automatic	c sprinklers?	N	V	What are the design densities for each area?	
The water supply for au	utomatic sprinklers is?		н	How many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cov	erages provided for your fa	cility:	S	Smoke Detectors	
Are alarms connected t	to a constantly attended loc	ation?	Y	Y	
Is there a watchman se	rvice?	Υ	V	What is the frequency of rounds?	Every 3 hours
Are watchman recording	ng rounds?		Y	Y	
Are there any fire exting	guishers?	Υ	Α	Are they serviced annually?	Υ
Are there any hose stat	tions?	N	ls	Is there a fire private fire brigade?	N
Frequency of training r	eceived by the private fire b	origade:			
Type of public fire depart	artment:	Paid	D	Distance:	blank
Exposure:					
How many buildings(no	ot part of Account) are with	n 100 feet of insured buildings?	2		
Describe the Occupano	cy of those buildings(s) nea	rby (within 100 feet):	Private re	esidences	
Is there a body of water	r nearby?	N	Descripti	tion:	
How far is the body of	water from major buildings'	?			

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

			Pr	roperty D	Detail Form			
Agency:	DEPARTMENT OF ADMIN	NISTRATION / PUBLIC DEFENDERS	OFFICE	<b>=</b>				
Property:	R6 Havre Public Defenders	s Office						
Property Address:	109 2nd Street West HAVF	RE						
Property ID:	61080							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	3349		
Year built:		0			Number of stories:	1		
Construction of roof:		null			Construction of floors:	null		
Construction of exterior	walls:	null			Construction of interior walls:	null		
Do major interior masonr	y walls (fire walls) extend	above the roofline?			null			
Occupancy:								
Occupancy Type:			Office					
Provide a brief description	on of operations:		blank					
Storage height of wareho	oused products:		blank					
Are flammable and comb	ustible liquids stored in a	cut-off room?	null					
Safegaurds taken for the	Safegaurds taken for the storage and dispensing of flammable liquids:							
Protection:								
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?			
The water supply for auto	omatic sprinklers is?		How many hydrants are located within 500 feet of buildings? blank					
Indicate the Alarm Cover	ages provided for your fac	cility:		blank				
Are alarms connected to	a constantly attended loca	ation?	null					
Is there a watchman serv	ice?	null	What is the frequency of rounds?					
Are watchman recording	rounds?							
Are there any fire extingu	uishers?	null		Are they	serviced annually?		null	
Are there any hose station	ons?	null		Is there a	a fire private fire brigade?		null	
Frequency of training red	eived by the private fire b	rigade:						
Type of public fire depart	ment:	null		Distance	x:		blank	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	null	Descri	ption:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	null	Descrip	ption:				
Any property damage los	sses in the past 3 years:	null	Descrip	ption:				

					1 45	
			Pro	perty Detail Form		
Agency:	DEPARTMENT OF ADMIN	NISTRATION / DEPARTMENT OF AL	OMINISTR <i>A</i>	ATION		
Property:	Scott Hart Building					
Property Address:	302 N Roberts HELENA					
Property ID:	20					
Construction:						
Total number of insured	l buildings:	1		Total square footage of insured buildings:	78608	
Year built:		1936		Number of stories:	5	
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Glass and Steel Curtain		Construction of interior walls:	Gypsum Board	
Do major interior masonry walls (fire walls) extend above the roofline?			N			
Occupancy:						
Occupancy Type:			Office			
Provide a brief descripti	on of operations:		OFFICES	S STATE GOVERNMENT		
Storage height of warehoused products:			N/A			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A			
Protection:						
Are there any automatic	sprinklers?	N	1	Nhat are the design densities for each area?		
The water supply for au	tomatic sprinklers is?		H	How many hydrants are located within 500 feet of buildings?	3	
Indicate the Alarm Cove	rages provided for your fac	cility:	5	Smoke Detectors		
Are alarms connected to a constantly attended location?			١	1		
Is there a watchman ser	vice?	Υ	١	What is the frequency of rounds?	EVERY 3 HOURS	
Are watchman recording	g rounds?		١	(		
Are there any fire exting	juishers?	Υ	,	Are they serviced annually?	Υ	
Are there any hose stati	ons?	Υ	I	s there a fire private fire brigade?	N	
Frequency of training received by the private fire brigade:						
Type of public fire depa	rtment:	Paid	[	Distance:	blank	
Exposure:						
How many buildings(not part of Account) are within 100 feet of insured buildings? 0						
Describe the Occupancy of those buildings(s) nearby (within 100 feet):						
Is there a body of water	nearby?	N	Descript	ion:		
How far is the body of w	ater from major buildings?					
Previous history of floor	ding?	N	Descript	ion:		

							i age
			P	Property Detail Form			
Agency:	DEPARTMENT OF ADM	INISTRATION / DEPARTMENT OF A	DMINIST	TRATION			
Property:	Sec. of State Records Mg	gmt Bureau Bldg 1					
Property Address:	1320 Bozeman HELENA						
Property ID:	36						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	19800		
Year built:		1960		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Reinforced C	Concrete	
Construction of exterio	r walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Boa	ard	
Do major interior maso	nry walls (fire walls) extend	d above the roofline?		null			
Occupancy:							
Occupancy Type:			Quons	set Warehouse			
Provide a brief descript	ion of operations:		Wareh	nouse			
Storage height of wareh	noused products:		8 feet				
Are flammable and com	bustible liquids stored in	a cut-off room?	Υ				
Safegaurds taken for th	e storage and dispensing	of flammable liquids:	Υ				
Protection:							
Are there any automation	sprinklers?	Υ		What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings	s?	2	
Indicate the Alarm Cove	erages provided for your fa	acility:		Smoke Detectors, Burglar Alarms (Door Contacts), Sprinkler W (Motion Detection)	aterflow, Sprink	ler Valve Tamper, Burglar Al	arms
Are alarms connected t	o a constantly attended lo	cation?		Υ			
ls there a watchman se	rvice?	Υ		What is the frequency of rounds?		Every 3 hours	
Are watchman recordin	g rounds?			Υ			
Are there any fire exting	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire	brigade:					
Type of public fire depa	rtment:	Paid		Distance:		blank	
Exposure:							
How many buildings(no	ot part of Account) are with	in 100 feet of insured buildings?	blank				
Describe the Occupanc	y of those buildings(s) nea	arby (within 100 feet):					
Is there a body of water	nearby?	N	Descr	iption:			
How far is the body of v	vater from major buildings	?					
Previous history of floo	ding?	N	Descr	iption:			

					Page
			Pro	perty Detail Form	
Agency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT OF A	.DMINISTR	ATION	
Property:	Teachers Retirement				
Property Address:	1500 E 6th HELENA				
Property ID:	15				
Construction:					
Total number of insure	ed buildings:	1		Total square footage of insured buildings: 6	486
Year built:		1968		Number of stories: 2	
Construction of roof:		Steel Deck		Construction of floors:	einforced Concrete
Construction of exterio	or walls:	Masonry		Construction of interior walls:	lasonry w/ Fire Doors
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief descrip	tion of operations:		Offices		
Storage height of ware	housed products:		N/A		
Are flammable and cor	mbustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for t	he storage and dispensing o	of flammable liquids:	N/A		
Protection:					
Are there any automat	ic sprinklers?	N	,	What are the design densities for each area?	
The water supply for a	utomatic sprinklers is?		1	How many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cov	verages provided for your fac	cility:	;	Smoke Detectors	
Are alarms connected	to a constantly attended loc	ation?	,	Y	
Is there a watchman se	ervice?	Υ	,	What is the frequency of rounds?	Every 3 hours
Are watchman recordi	ng rounds?		,	Y	
Are there any fire extir	nguishers?	Υ		Are they serviced annually?	Υ
Are there any hose sta	tions?	N	1	Is there a fire private fire brigade?	N
Frequency of training	received by the private fire b	rigade:			
Type of public fire dep	artment:	Paid	1	Distance:	blank
Exposure:					
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	2		
Describe the Occupan	cy of those buildings(s) near	rby (within 100 feet):			
Is there a body of water	er nearby?	N	Descript	tion:	
How far is the body of	water from major buildings?	?			
Previous history of flo	odina?	N	Descript	tion:	

						Page
			Prop	perty Detail Form		
Agency:	DEPARTMENT OF ADMI	NISTRATION / DEPARTMENT OF A	DMINISTRAT	TION		
Property:	Veterans & Pioneers Mem	orial Bldg.				
Property Address:	225 N Roberts HELENA					
Property ID:	11					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	92318	
Year built:		1952		Number of stories:	4	
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete	
Construction of exterio	or walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Museum			
Provide a brief descrip	tion of operations:		OFFICES	STATE GOVERNMENT		
Storage height of ware	housed products:		N/A			
Are flammable and con	nbustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for th	ne storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automati	c sprinklers?	Υ	w	hat are the design densities for each area?		
The water supply for a	utomatic sprinklers is?	Public	Н	ow many hydrants are located within 500 feet of buildings?	4	
Indicate the Alarm Cov	erages provided for your fa	cility:	Sr	moke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected	to a constantly attended loc	ation?	Υ			
Is there a watchman se	ervice?	Υ	w	/hat is the frequency of rounds?	EVERY 3 HOURS	
Are watchman recordir	ng rounds?		Υ			
Are there any fire extin	guishers?	Υ	Aı	re they serviced annually?	Υ	
Are there any hose star	tions?	Υ	Is	there a fire private fire brigade?	N	
Frequency of training r	eceived by the private fire b	rigade:				
Type of public fire depart	artment:	Paid	Di	istance:	blank	
Exposure:						
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	2			
Describe the Occupand	cy of those buildings(s) near	by (within 100 feet):	OFFICES			
Is there a body of wate	r nearby?	N	Description	on:		
How far is the body of	water from major buildings?	•				
Previous history of floo	oding?	N	Description	on:		
Any property damage I	osses in the past 3 years:	N	Description	on:		

			Pi	roperty [	Detail Form			
Agency:	DEPARTMENT OF AGRIC	CULTURE / DEPARTMENT OF AGR	ICULTUR	RE				
Property:	Leased - Ag Sciences/Boz	zeman Laboratory						
Property Address:	MSU McCall Hall Rm 10 B	BOZEMAN						
Property ID:	LE 6205							
Construction:								
Γotal number of insured	buildings:	1			Total square footage of insured buildings:	10448		
Year built:		1952			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Labora	atory				
Provide a brief description	on of operations:		laborate	tory				
Storage height of wareh	oused products:		n/a					
Are flammable and com	bustible liquids stored in a	cut-off room?	Υ					
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?			
The water supply for aut	omatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?	1	7	
ndicate the Alarm Cove	rages provided for your fac	cility:						
Are alarms connected to	a constantly attended loc	ation?		N				
s there a watchman serv	vice?	Υ		What is	the frequency of rounds?		average 4 per week	
Are watchman recording	ı rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	y serviced annually?		Υ	
Are there any hose station	ons?	N		Is there	a fire private fire brigade?		N	
requency of training re	ceived by the private fire b	origade:						
Гуре of public fire depar	tment:	Paid		Distance	e:		1.09 miles	
Exposure:								
How many buildings(not	part of Account) are withi	in 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):						
s there a body of water	nearby?	N	Descri	ption:				
How far is the body of w	ater from major buildings?	?						
Previous history of flood	ding?	N	Descri	ption:				

			Pr	perty Detail Form		
Agency:	DEPARTMENT OF COMM	IERCE / DEPARTMENT OF COMME	RCE			
Property:	Bozeman Building					
Property Address:	2273 Boothill Court BRAD	Y				
Property ID:						
Construction:						
Γotal number of insured	buildings:	1		Total square footage of insured buildings:	15213	
Year built:		2004		Number of stories:	1	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior masonr	ry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Office			
Provide a brief description	on of operations:		blank			
Storage height of wareho	oused products:		blank			
Are flammable and comb	oustible liquids stored in a	cut-off room?	null			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	<b>?</b>	blank
ndicate the Alarm Cover	ages provided for your fac	cility:		olank		
Are alarms connected to	a constantly attended loca	ation?		null		
s there a watchman serv	rice?	null		What is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire extingu	uishers?	null		Are they serviced annually?		null
Are there any hose statio	ons?	null		s there a fire private fire brigade?		null
requency of training rec	ceived by the private fire b	rigade:				
Type of public fire depart	tment:	null		Distance:		blank
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
	nearhy?	null	Descri	ion:		
s there a body of water r	icarby.					
s there a body of water r low far is the body of wa	ater from major buildings?					
-	ater from major buildings?		Descri	ion:		

			Pr	operty D	Petail Form			
Agency:	DEPARTMENT OF COMM	IERCE / MONTANA HERITAGE COI	MMISSIO	N				
Property:	Buford Center Part (Wells	Fargo Coffee House)						
Property Address:	Block 193 VIRGINIA CITY							
Property ID:								
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	8240		
Year built:		1880			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Other					
Provide a brief description	on of operations:		seasona	al restuara	ant May-Sept			
Storage height of wareh	oused products:		0					
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?	?	blank	
ndicate the Alarm Cover	rages provided for your fac	ility:		Smoke D	etectors			
Are alarms connected to	a constantly attended loca	ation?		N				
s there a watchman serv	vice?	N		What is t	the frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose station	ons?	N		Is there a	a fire private fire brigade?		N	
requency of training re	ceived by the private fire b	rigade:						
Гуре of public fire depar	tment:	Voluntary		Distance	::		1/2 mile	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
s there a body of water	nearby?	N	Descrip	otion:				
How far is the body of w	ater from major buildings?							
Previous history of flood	ling?	N	Descrip	otion:				
Any property damage lo	sses in the nast 3 years.	N	Descrin	ntion.				

			Prope	erty Detail Form	
Agency:	DEPARTMENT OF COMM	ERCE / DEPARTMENT OF COMME	RCE		
Property:	Colonial Drive Building				
Property Address:	2401 Colonial Drive HELEN	NA			
Property ID:	65010				
Construction:					
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	59214
Year built:		1998		Number of stories:	3
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior masonr	y walls (fire walls) extend	above the roofline?		Υ	
Occupancy:					
Occupancy Type:			Office		
Provide a brief descriptio	n of operations:		OFFICES/S	State/private	
Storage height of wareho	used products:		N/A		
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A		
Protection:					
Are there any automatic s	sprinklers?	Υ	Wł	hat are the design densities for each area?	
The water supply for auto	matic sprinklers is?	Public	Но	w many hydrants are located within 500 feet of buildings?	blank
ndicate the Alarm Covera	ages provided for your fac	ility:	Sp	rinkler Waterflow, Smoke Detectors	
Are alarms connected to	a constantly attended loca	ition?	Υ		
s there a watchman servi	ice?	Υ	Wł	hat is the frequency of rounds?	7 days
Are watchman recording	rounds?		Υ		
Are there any fire extingu	ishers?	Υ	Are	e they serviced annually?	Υ
Are there any hose statio	ns?	Υ	Is	there a fire private fire brigade?	N
requency of training rec	eived by the private fire br	rigade:			
Гуре of public fire depart	ment:	Paid	Dis	stance:	1 mile
Exposure:					
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	1		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Hotel		
s there a body of water n	earby?	N	Description	n:	
How far is the body of wa	ter from major buildings?				
Previous history of floodi	ng?	N	Description	n:	
Any property damage los	ses in the past 3 years:	N	Description	n:	Water line froze & broke

			Propert	y Detail Form		
Agency:	DEPARTMENT OF COMM	IERCE / MONTANA HERITAGE CON	MISSION			
Property:	Content's Corner & Root C	Cellar				
Property Address:	Block 193 VIRGINIA CITY					
Property ID:						
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	4096	
Year built:		1864		Number of stories:	2	
Construction of roof:		null		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board	
Do major interior mason	y walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Other			
Provide a brief description	on of operations:		pizza, sandwid	ch shop, sale of pottery; 2nd floor-offices		
Storage height of wareho	oused products:		0			
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	N	What	are the design densities for each area?		
The water supply for auto	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	3	
Indicate the Alarm Cover	ages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ation?	N			
Is there a watchman serv	ice?	N	What	is the frequency of rounds?		
Are watchman recording	rounds?		N			
Are there any fire extingu	iishers?	Υ	Are th	ney serviced annually?	Υ	
Are there any hose station	ons?	N	Is the	re a fire private fire brigade?	N	
Frequency of training red	eived by the private fire b	rigade:				
Type of public fire depart	ment:	Voluntary	Dista	nce:	8 miles	
Exposure:						
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	2			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	retail stores			
Is there a body of water r	nearby?	Υ	Description:		Dredge pond	
How far is the body of wa	ater from major buildings?		1000 ft			
Previous history of flood	ing?	N	Description:			
Any property damage los	sses in the past 3 years:	N	Description:			

			P	roperty Detail Form	
Agency:	DEPARTMENT OF COM	MERCE / DEPARTMENT OF COMMI	ERCE		
Property:	DOC - Main (no BOI)				
Property Address:	301 S. Park HELENA				
Property ID:	65010				
Construction:					
Total number of insured	d buildings:	1		Total square footage of insured buildings:	54078
Year built:		1977		Number of stories:	5
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete
Construction of exterior	r walls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ Openings
Oo major interior masor	nry walls (fire walls) extend	I above the roofline?		Υ	
Occupancy:					
Occupancy Type:			Office		
Provide a brief descript	ion of operations:		OFFIC	ES	
Storage height of wareh	oused products:		BELO\	N SPRINKLER COVERAGE	
Are flammable and com	bustible liquids stored in a	a cut-off room?	Υ		
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	Υ		
Protection:					
Are there any automation	sprinklers?	N		What are the design densities for each area?	
The water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of building	gs? 1
ndicate the Alarm Cove	erages provided for your fa	cility:	Burglar Alarms (Door Contacts), Fire Pump Alarms, Sprinkler Valve Tamper, Smoke Detectors, Sprinkler Waterflow		
Are alarms connected to	o a constantly attended loc	cation?		Υ	
s there a watchman ser	rvice?	N		What is the frequency of rounds?	
Are watchman recording	g rounds?				
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ
Are there any hose stati	ions?	N		Is there a fire private fire brigade?	N
requency of training re	eceived by the private fire b	origade:			
Гуре of public fire depa	rtment:	Paid		Distance:	1 MILE
Exposure:					
How many buildings(no	t part of Account) are with	in 100 feet of insured buildings?	0		
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):			
s there a body of water	nearby?	N	Descri	ption:	
How far is the body of w	vater from major buildings'	?			
Previous history of floo	ding?	N	Descri	ption:	

			Pro	pperty Detail Form	
Agency:	DEPARTMENT OF COMM	MERCE / MONTANA HERITAGE COM	MISSION	N	
Property:	Fairweather Inn				
Property Address:	Block 154 VIRGINIA CITY				
Property ID:					
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings: 70	019
Year built:		1863		Number of stories: 2	
Construction of roof:		Wood Joists		Construction of floors: Po	oured Concrete
Construction of exterior	walls:	Wood Frame		Construction of interior walls: G	ypsum Board
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Other		
Provide a brief description	on of operations:		Hotel		
Storage height of wareh	oused products:		N/A		
Are flammable and com	oustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	3
Indicate the Alarm Cove	ages provided for your fac	cility:		Smoke Detectors	
Are alarms connected to	a constantly attended loca	ation?		N	
Is there a watchman serv	rice?	Υ		What is the frequency of rounds?	24 Hours during open seas
Are watchman recording	rounds?			N	
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose static	ons?	N		Is there a fire private fire brigade?	N
Frequency of training re	ceived by the private fire b	rigade:			
Type of public fire depar	tment:	Voluntary		Distance:	.25 Miles
Exposure:					
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water	nearby?	Υ	Descrip	tion: Ci	reek
How far is the body of w	ater from major buildings?				
Previous history of flood	ling?	N	Descrip	tion:	
Any property damage lo	sses in the past 3 years:	N	Descrip	tion:	

			Р	roperty <b>E</b>	Detail Form			
Agency:	DEPARTMENT OF COMM	MERCE / DEPARTMENT OF COMMI	ERCE					
Property:	IBM Building							
Property Address:	100 N. Park HELENA							
Property ID:	65010							
Construction:								
Total number of insure	d buildings:	1			Total square footage of insured buildings:	72022		
Year built:		1984			Number of stories:	4		
Construction of roof:		Steel Deck			Construction of floors:	Poured Concr	rete	
Construction of exterio	r walls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior maso	nry walls (fire walls) extend	above the roofline?			Υ			
Occupancy:								
Occupancy Type:			Office					
Provide a brief descript	ion of operations:		OFFIC	ES				
Storage height of warel	noused products:		N/A					
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	N/A					
Protection:								
Are there any automation	sprinklers?	Υ		What are	e the design densities for each area?			
The water supply for au	tomatic sprinklers is?	Public		How ma	ny hydrants are located within 500 feet of buildings	?	1	
Indicate the Alarm Cove	erages provided for your fac	cility:		Smoke D	Detectors, Sprinkler Waterflow			
Are alarms connected t	o a constantly attended loc	ation?		Υ				
ls there a watchman se	rvice?	Υ		What is	the frequency of rounds?		7 Days	
Are watchman recordin	g rounds?			Υ				
Are there any fire exting	guishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stat	ions?	Υ		Is there	a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:						
Type of public fire depart	rtment:	Paid		Distance	e:		blank	
Exposure:								
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	5					
Describe the Occupand	y of those buildings(s) near	rby (within 100 feet):	Comm	ercial/Resi	idential			
Is there a body of water	nearby?	N	Descri	ption:				
How far is the body of v	vater from major buildings?	•						
Previous history of floo	ding?	N	Descri	ption:				
Any property damage l	osses in the past 3 years:	N	Descri	ption:				

			Property	Detail Form	
Agency:	DEPARTMENT OF COMM	MERCE / MONTANA HERITAGE COI	MMISSION		
Property:	McFarland Curatorial Cent	er			
Property Address:	Curatorial Addition to Town	nsite VIRGINIA CITY			
Property ID:					
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	6630
Year built:		1999		Number of stories:	1
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Museum		
Provide a brief description	on of operations:		fine arts storage		
Storage height of wareho	oused products:		0		
Are flammable and comb	ustible liquids stored in a	cut-off room?	Υ		
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ		
Protection:					
Are there any automatic	sprinklers?	Υ	What a	re the design densities for each area?	unknown
The water supply for auto	omatic sprinklers is?	Public	How m	any hydrants are located within 500 feet of buildings?	0
Indicate the Alarm Cover	ages provided for your fac	cility:	Burglar Sprinkle	Alarms (Door Contacts), Burglar Alarms (Motion Detection Waterflow	n), Smoke Detectors, Sprinkler Valve Tamper,
Are alarms connected to	a constantly attended loca	ation?	Υ		
Is there a watchman serv	ice?				
	100:	N	What is	the frequency of rounds?	
Are watchman recording		N	<b>What is</b> N	the frequency of rounds?	
Are watchman recording  Are there any fire extingu	rounds?	N Y	N	s the frequency of rounds?  y serviced annually?	Υ
_	rounds? iishers?		N Are the		Y N
Are there any fire extingu	rounds? iishers?	Y N	N Are the	y serviced annually?	
Are there any fire extingu	rounds? iishers? ins? eived by the private fire b	Y N	N Are the	y serviced annually? e a fire private fire brigade?	
Are there any fire extingu Are there any hose station Frequency of training reco	rounds? iishers? ins? eived by the private fire b	Y N rigade:	N Are the	y serviced annually? e a fire private fire brigade?	N
Are there any fire extingu Are there any hose station Frequency of training recommendation Type of public fire depart Exposure:	rounds? iishers? ins? eived by the private fire b ment:	Y N rigade:	N Are the	y serviced annually? e a fire private fire brigade?	N
Are there any fire extinguate there any hose station. Frequency of training recomplete of public fire depart Exposure:  How many buildings(not	rounds? iishers? ins? eived by the private fire b ment:	Y N rigade: Voluntary n 100 feet of insured buildings?	N Are the Is there Distance	y serviced annually? e a fire private fire brigade?	N
Are there any fire extinguate there any hose station. Frequency of training recomplete of public fire depart Exposure:  How many buildings(not	rounds?  iishers?  ins?  eived by the private fire be ment:  part of Account) are within of those buildings(s) near	Y N rigade: Voluntary n 100 feet of insured buildings?	N Are the Is there Distance	y serviced annually? e a fire private fire brigade?	N
Are there any fire extinguate there any hose station. Frequency of training recompany of public fire departed to the exposure:  How many buildings (not Describe the Occupancy Is there a body of water recompany).	rounds?  iishers?  ins?  eived by the private fire be ment:  part of Account) are within of those buildings(s) near	Y N rigade: Voluntary n 100 feet of insured buildings? by (within 100 feet):	N Are the Is there	y serviced annually? e a fire private fire brigade? ee:	N 3/4 mile
Are there any fire extinguate there any hose station. Frequency of training recompany of public fire departed to the exposure:  How many buildings (not Describe the Occupancy Is there a body of water recompany).	rounds? uishers? uishers? eleived by the private fire betweent:  part of Account) are within of those buildings(s) near hearby?  uter from major buildings?	Y N rigade: Voluntary n 100 feet of insured buildings? by (within 100 feet):	N Are the Is there Distance  O Description:	y serviced annually? e a fire private fire brigade? ee:	N 3/4 mile

							0		
			Pro	perty Detail Form					
Agency:	DEPARTMENT OF COMM	MERCE / MONTANA HERITAGE CO	MMISSION						
Property:	Nevada City Depot Restro	ooms							
Property Address:	Wood Street #2 VIRGINIA	CITY							
Property ID:									
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings: 5	12				
Year built:		2008		Number of stories: 1					
Construction of roof:		Wood Joists		Construction of floors:	teinforced Con	ncrete			
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Sypsum Board				
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Roadside	e Rest Area					
Provide a brief description of operations:			Public res	Public restrooms					
Storage height of warehoused products:			8 feet						
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	Υ						
Protection:									
Are there any automatic	sprinklers?	N	\	What are the design densities for each area?	I	na			
The water supply for au	tomatic sprinklers is?		ŀ	How many hydrants are located within 500 feet of buildings?	,	1			
Indicate the Alarm Cove	rages provided for your fac	cility:							
Are alarms connected to	a constantly attended loc	ation?	1	N					
Is there a watchman ser	vice?	N	1	What is the frequency of rounds?					
Are watchman recording	g rounds?		1	N					
Are there any fire exting	uishers?	Υ	,	Are they serviced annually?	`	Υ			
Are there any hose stati	ons?	Υ	I	s there a fire private fire brigade?	`	Υ			
Frequency of training re	ceived by the private fire b	rigade:	á	annually					
Type of public fire depa	rtment:	Voluntary	[	Distance:		1.5 miles			
Exposure:									
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	1						
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):	offices						
Is there a body of water	nearby?	Υ	Descript	ion: d	redge pond				
How far is the body of w	rater from major buildings?	•	100 ft						
Previous history of floo	ding?	N	Descript	ion:					
Any property damage lo	sses in the past 3 years:	N	Descript	ion:					

			P	roperty Detail Form					
Agency:	DEPARTMENT OF COMM	IERCE / MONTANA HERITAGE CO	MMISSIC	N					
Property:	Opera House Inc. Stage								
Property Address:	Block 193 VIRGINIA CITY								
Property ID:									
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	4209				
Year built:		1895		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concr	ete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	d			
Oo major interior masor	ry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Other						
Provide a brief description of operations:			Live the	Live theatre & vaudeville performances May-Labor Day					
Storage height of warehoused products:			0						
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	N		What are the design densities for each area?		no sprinklers			
The water supply for au	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	•	2			
ndicate the Alarm Cove	rages provided for your fac	cility:		Smoke Detectors					
Are alarms connected to	a constantly attended loca	ation?		N					
s there a watchman ser	vice?	N		What is the frequency of rounds?					
Are watchman recording	g rounds?			N					
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ			
Are there any hose stati	ons?	N		Is there a fire private fire brigade?		N			
requency of training re	ceived by the private fire b	rigade:							
Гуре of public fire depa	tment:	Voluntary		Distance:		1/2 mile			
Exposure:									
How many buildings(no	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
s there a body of water	nearby?	Υ	Descri	ption:	pond				
How far is the body of w	ater from major buildings?		500 ya	rds					
Previous history of floor	ding?	N	Descri	ption:					
Any property damage lo	sses in the nast 3 years.	N	Descri	intion.					

			Pr	operty D	etail Form		
Agency:	DEPARTMENT OF COMMI	ERCE / DEPARTMENT OF COMME	RCE				
Property:	PERD Building, Leased to J	lustice Legal Services					
Property Address:	1712 9th Avenue HELENA						
Property ID:	65010						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	7200	
ear built:		1971			Number of stories:	1	
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Cor	ncrete
Construction of exterior v	valls:	Masonry			Construction of interior walls:	Gypsum Board	i
Oo major interior masonr	y walls (fire walls) extend a	above the roofline?			Υ		
Occupancy:							
Occupancy Type:			Office				
Provide a brief descriptio	n of operations:		DOJ off	fices			
Storage height of wareho	used products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	N		What are	the design densities for each area?		
The water supply for auto	omatic sprinklers is?			How man	y hydrants are located within 500 feet of buildings?		1
ndicate the Alarm Covera	ages provided for your faci	lity:		Smoke De	etectors		
Are alarms connected to	a constantly attended loca	tion?		Υ			
s there a watchman servi	ice?	null		What is t	he frequency of rounds?		7 days
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose station	ns?	N		Is there a	fire private fire brigade?		N
requency of training rec	eived by the private fire br	igade:					
Гуре of public fire depart	ment:	Paid		Distance	:		1 mile
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) nearb	y (within 100 feet):					
s there a body of water n	earby?	N	Descrip	ption:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ing?	N	Descrip	ption:			
Any property damage los	ses in the past 3 years:	N	Descrip	ption:			

			Pro	operty Detail Form				
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTION	NS, PINE HILLS YOUTH CORRECTIONAL FACILITY				
Property:	Academic Training Center							
Property Address:	4 North Haynes Avenue Mi	ILES CITY						
Property ID:	57							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings: 2	2584			
Year built:		1966		Number of stories: 2	2			
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concrete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	Sypsum Board			
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Governr	mental Building				
Provide a brief description	on of operations:		OFFICE	DFFICES/CLASSROOMS				
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	N		What are the design densities for each area?				
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	4			
Indicate the Alarm Cover	ages provided for your fac	ility:		Smoke Detectors				
Are alarms connected to	a constantly attended loca	ation?		Υ				
ls there a watchman serv	rice?	Υ		What is the frequency of rounds?	6/	DAY OR 2/SHIFT		
Are watchman recording	rounds?			Υ				
Are there any fire extingu	uishers?	Υ		Are they serviced annually?	Y			
Are there any hose statio	ons?	Υ		Is there a fire private fire brigade?	N			
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depart	tment:	Paid		Distance:	2	CITY BLOCKS		
Exposure:								
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	2					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	GYM &	CLIENT HOUSING				
Is there a body of water r	nearby?	N	Descrip	otion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	otion:				
Any property damage los	sses in the past 3 years:	N	Descrip	otion:				

							Page
			Prope	erty Detail Form			
Agency:	DEPARTMENT OF CORI	RECTIONS / DEPARTMENT OF CO	RRECTIONS,	RIVERSIDE YOUTH CORRECTIONAL FACILITY			
Property:	Administration/Education						
Property Address:	2 Riverside Rd BOULDER	₹					
Property ID:	13						
Construction:							
Γotal number of insure	d buildings:	1		Total square footage of insured buildings:	6971		
Year built:		1960		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Con	ncrete	
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Gypsum Board		
Oo major interior maso	onry walls (fire walls) extend	d above the roofline?		N			
Occupancy:							
Occupancy Type:			Governmer	ntal Building			
Provide a brief descrip	tion of operations:		OFFICES,	SCHOOL CLASSROOMS			
Storage height of ware	housed products:		N/A				
Are flammable and con	nbustible liquids stored in a	a cut-off room?	N/A				
Safegaurds taken for th	ne storage and dispensing	of flammable liquids:	N/A				
Protection:							
Are there any automati	c sprinklers?	N	Wł	nat are the design densities for each area?			
The water supply for a	utomatic sprinklers is?		Но	w many hydrants are located within 500 feet of building	s?	1	
ndicate the Alarm Cov	erages provided for your fa	cility:					
Are alarms connected	to a constantly attended lo	cation?	nul	I			
s there a watchman se	ervice?	Υ	Wł	nat is the frequency of rounds?		24 HOUR FACILITY	
Are watchman recordir	ng rounds?		Υ				
Are there any fire extin	guishers?	Υ	Arc	e they serviced annually?		Υ	
Are there any hose sta	tions?	null	Is	there a fire private fire brigade?	1	null	
requency of training r	eceived by the private fire	origade:					
Гуре of public fire depa	artment:	Part-Paid	Dis	stance:		1/2 MILE & VOLUNTARY	

JUVENILE HALL, SCHOOL, KITCHEN, MAINTENANCE

SMALL RIVER

3

Description:

Description:

Description:

300 FEET

**Exposure:** 

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

					Page
			P	roperty Detail Form	
Agency:	DEPARTMENT OF CORF	RECTIONS / DEPARTMENT O	F CORRECTIO	NS, STATE PRISON	
Property:	Close Unit I				
Property Address:	400 Conley Lake Rd DEE	R LODGE			
Property ID:	9P				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	22613
Year built:		1979		Number of stories:	2
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Masonry
Do major interior mason	ry walls (fire walls) extend	I above the roofline?		N	
Occupancy:					
Occupancy Type:			Jail		
Provide a brief description	on of operations:		INMA	TE HOUSING/MANAGEMENT STAFF	
Storage height of wareho	oused products:		N/A		
Are flammable and comb	oustible liquids stored in a	a cut-off room?	N		
Safegaurds taken for the	storage and dispensing	of flammable liquids:	N		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for aut	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildi	ings? 4
Indicate the Alarm Cover	ages provided for your fa	cility:		Burglar Alarms (Door Contacts), Sprinkler Valve Tamper, Sr	moke Detectors, Sprinkler Waterflow
Are alarms connected to	a constantly attended loo	cation?		Υ	
Is there a watchman serv	rice?	Υ		What is the frequency of rounds?	1 HOUR
Are watchman recording	rounds?			Υ	
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose static	ons?	N		Is there a fire private fire brigade?	Υ
Frequency of training red	ceived by the private fire b	origade:		ANNUAL	
Type of public fire depar	tment:	null		Distance:	1/2 MILE/MSP FIRE BRIGADE
Exposure:					

How many buildings(not part of Account) are within 100 feet of insured buildings? 2

Describe the Occupancy of those buildings(s) nearby (within 100 feet): FOOD SERVICES & INMATE HOUSIBNG

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Description: Ν

Any property damage losses in the past 3 years: N

Description:

						1 age 6
			Proper	ty Detail Form		
Agency:	DEPARTMENT OF CORRI	ECTIONS / DEPARTMENT OF COR	RECTIONS, S	TATE PRISON		
Property:	Close Unit II					
Property Address:	400 Conley Lake Rd DEER	RLODGE				
Property ID:	9P					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	22613	
Year built:		1979		Number of stories:	2	
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concre	te
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Masonry	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Jail			
Provide a brief description	on of operations:		INMATE HOL	JSING/HOUSING UNIT MANAGMENT STAFF		
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?			N			
Safegaurds taken for the storage and dispensing of flammable liquids:		f flammable liquids:	N			
Protection:						
Are there any automatic	sprinklers?	N	Wha	t are the design densities for each area?		
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?		4
Indicate the Alarm Cover	ages provided for your fac	ility:	Smo	ke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	ation?	Υ			
Is there a watchman serv	rice?	Υ	Wha	t is the frequency of rounds?		1 HOUR
Are watchman recording	rounds?		Υ			
Are there any fire extingu	uishers?	Υ	Are	they serviced annually?		Υ
Are there any hose static	ons?	N	ls th	ere a fire private fire brigade?		Υ
Frequency of training red	ceived by the private fire br	rigade:	ANN	UAL		
Type of public fire depart	tment:	null	Dista	ance:		1/2 MILE/MSP FIRE BRIGADE
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	2			
Describe the Occupancy of those buildings(s) nearby (within 100 feet):		INMATE HO	JSING/RECREATION			
Is there a body of water r	nearby?	N	Description:			
How far is the body of wa	ater from major buildings?					
Previous history of flood	ing?	N	Description:			
Any property damage los	sses in the past 3 years:	N	Description:			

					9		
			Property	Detail Form			
Agency:	DEPARTMENT OF CORRI	ECTIONS / DEPARTMENT OF COR	RECTIONS, STA	TE PRISON			
Property:	Close Unit III						
Property Address:	400 Conley Lake Rd DEER	LODGE					
Property ID:	16P						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	34038		
Year built:		1986		Number of stories:	2		
Construction of roof:		null		Construction of floors:	Poured Concrete		
Construction of exterior v	walls:	Tilt-Up Concrete		Construction of interior walls:	Masonry w/ Fire Doors		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Jail				
Provide a brief description of operations:		HOUSES INMA	HOUSES INMATE&HOUSING UNIT'S MANAGEMENT STAFF				
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?			N				
Safegaurds taken for the storage and dispensing of flammable liquids:		flammable liquids:	N				
Protection:							
Are there any automatic s	sprinklers?	Υ	What	are the design densities for each area?			
The water supply for auto	omatic sprinklers is?	Public	How n	nany hydrants are located within 500 feet of buildings	? 4		
Indicate the Alarm Covera	ages provided for your fac	ility:	Burglar Alarms (Door Contacts), Sprinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors				
Are alarms connected to	a constantly attended loca	ition?	Υ				
Is there a watchman servi	ice?	Υ	What i	s the frequency of rounds?	1 HOUR		
Are watchman recording	rounds?		Υ				
Are there any fire extingu	ishers?	Υ	Are th	ey serviced annually?	Υ		
Are there any hose statio	ns?	Υ	Is ther	e a fire private fire brigade?	Υ		
Frequency of training rec	eived by the private fire br	rigade:	ANNU	AL			
Type of public fire depart	ment:	null	Distan	ce:	1/2 MILE/MSP FIRE BRIGADE		
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	2				
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):	LAUNDRY/REG	CREATION			
Is there a body of water n	earby?	N	Description:				
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ing?	N	Description:				
Any property damage los	ses in the past 3 years:	N	Description:				

			Pro	perty Detail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTIONS	S, PRISON INDUSTRIES			
Property:	Cook Chill (Food Factory)						
Property Address:	600 Conley Lake Rd DEEF	RLODGE					
Property ID:							
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	17611		
Year built:		2000		Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board		
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Governme	ental Building			
Provide a brief description of operations:			receive, produce and send out bulk & tray food tomsp & outside customers				
Storage height of warehoused products:		14 feet					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A					
Protection:							
Are there any automatic	sprinklers?	N	V	What are the design densities for each area?			
The water supply for auto	omatic sprinklers is?	Public	Н	low many hydrants are located within 500 feet of buildings?	? 1		
Indicate the Alarm Cover	ages provided for your fac	ility:	S	Sprinkler Waterflow, Smoke Detectors, Fire Pump Alarms			
Are alarms connected to	a constantly attended loca	ation?	Y	,			
Is there a watchman serv	rice?	Υ	v	What is the frequency of rounds?			
Are watchman recording	rounds?		Y	,			
Are there any fire extingu	uishers?	Υ	A	Are they serviced annually?	Υ		
Are there any hose statio	ons?	N	ls	s there a fire private fire brigade?	Υ		
Frequency of training red	ceived by the private fire b	rigade:					
Type of public fire depart	tment:	Paid	D	Distance:	blank		
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	1				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	warehous	se			
Is there a body of water r	nearby?	null	Descripti	ion:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Descripti	ion:			
Any property damage los	sses in the past 3 years:	N	Descripti	ion:			

			Prop	perty Detail Form			
Agency:	DEPARTMENT OF CORRE	ECTIONS / DEPARTMENT OF CORF	RECTIONS				
Property:	Eastmont Cottage 3 - Long	Term Care Facility					
Property Address:	700 E. Little St. GLENDIVE						
Property ID:							
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	17343		
Year built:		1977		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	ncrete	
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Gypsum Board	d	
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N			
Occupancy:							
Occupancy Type:			Jail				
Provide a brief description of operations:		Residentia	Residential treatment facility				
Storage height of wareho	used products:		7 feet				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ					
Protection:							
Are there any automatic s	sprinklers?	Υ	W	Vhat are the design densities for each area?			
The water supply for auto	matic sprinklers is?	Public	н	low many hydrants are located within 500 feet of buildings?	•	2	
Indicate the Alarm Covera	ages provided for your faci	ility:	В	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loca	ition?	Υ				
Is there a watchman servi	ice?	Υ	W	hat is the frequency of rounds?		hourly	
Are watchman recording	rounds?		Υ				
Are there any fire extingu	ishers?	Υ	Α	re they serviced annually?		Υ	
Are there any hose station	ns?	N	Is	there a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	igade:					
Type of public fire depart	ment:	Paid	D	istance:		blank	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	1				
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):	treatment	rooms, offices			
Is there a body of water n	earby?	N	Description	on:	1 mile		
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Description	on:			
Any property damage los	ses in the past 3 years:	Υ	Description	on:	leaky roof		

							Page
			Pr	operty Detail Form			
Agency:	DEPARTMENT OF CORE	RECTIONS / DEPARTMENT OF COP	RRECTION	NS			
Property:	Eastmont Multi-Purpose E	Building & Addition					
Property Address:	700 E. Little St. GLENDIV	Έ					
Property ID:							
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	9778		
Year built:		1969		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board	d	
Do major interior maso	nry walls (fire walls) extend	I above the roofline?		N			
Occupancy:							
Occupancy Type:			Jail				
Provide a brief description of operations:			Treatme	ent classes & offices			
Storage height of ware	housed products:		7 feet				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	Υ				
Protection:							
Are there any automati	c sprinklers?	N		What are the design densities for each area?		no sprinklers	
The water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	<b>?</b>	1	
Indicate the Alarm Cov	erages provided for your fa	cility:					
Are alarms connected	to a constantly attended loc	cation?		Υ			
Is there a watchman se	rvice?	Υ		What is the frequency of rounds?		hourly	
Are watchman recordir	ng rounds?			Υ			
Are there any fire extin	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose star	tions?	N		Is there a fire private fire brigade?		null	
Frequency of training r	eceived by the private fire b	origade:					
Type of public fire depart	artment:	Paid		Distance:		blank	
Exposure:							
How many buildings(no	ot part of Account) are with	in 100 feet of insured buildings?	1				
Describe the Occupand	cy of those buildings(s) nea	rby (within 100 feet):	Reside	ntial treatment			
Is there a body of wate	r nearby?	N	Descri	ption:			
How far is the body of	water from major buildings	?					

Description:

Roof leaks

Previous history of flooding?

Any property damage losses in the past 3 years: Y

Ν

							Page 60
			Pr	operty Detail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTION	NS, PRISON INDUSTRIES			
Property:	Grainary						
Property Address:	600 Conley Lake Rd DEE	R LODGE					
Property ID:	5H						
Construction:							
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	3200		
Year built:		blank		Number of stories:	1		
Construction of roof:		Other		Construction of floors:	Reinforced Co	oncrete	
Construction of exterion	or walls:	Corrugated Metal Panel		Construction of interior walls:	Other		
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Barn				
Provide a brief description of operations:		milling a	and storage of grain				
Storage height of warehoused products:		0					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for t	he storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automat	ic sprinklers?	N		What are the design densities for each area?		no sprinklers	
The water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	?	1	
Indicate the Alarm Cov	verages provided for your fac	cility:					
Are alarms connected	to a constantly attended loc	ation?		null			
ls there a watchman se	ervice?	N		What is the frequency of rounds?			
Are watchman recordi	ng rounds?			N			
Are there any fire extir	nguishers?	Υ		Are they serviced annually?		null	
Are there any hose sta	tions?	N		Is there a fire private fire brigade?		Υ	
Frequency of training	received by the private fire b	rigade:					
Type of public fire dep	artment:	Voluntary		Distance:		7 miles	
Exposure:							
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupan	cy of those buildings(s) near	by (within 100 feet):					
Is there a body of wate	er nearby?	N	Descrip	otion:			
How far is the body of	water from major buildings?	•					
Previous history of flo	oding?	N	Descrip	otion:			
Any property damage	losses in the past 3 years:	N	Descrip	otion:			

			Property I	Detail Form	
Agency:	DEPARTMENT OF CORRE	ECTIONS / DEPARTMENT OF CORE	RECTIONS, PRIS	ON INDUSTRIES	
Property:	H S Laundry/Education				
Property Address:	600 Conley Lake Rd DEER	LODGE			
Property ID:					
Construction:					
Total number of insured I	ouildings:	1		Total square footage of insured buildings:	18800
Year built:		1995		Number of stories:	2
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N	
Occupancy:					
Occupancy Type:			Governmental Bo	uilding	
Provide a brief description	n of operations:		COMMERCIAL L	AUNDRY/CLASSROOMS	
Storage height of warehoused products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N		
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A		
Protection:					
Are there any automatic s	sprinklers?	N	What ar	e the design densities for each area?	
The water supply for auto	omatic sprinklers is?	Public	How ma	ny hydrants are located within 500 feet of buildings?	3
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke [	Detectors	
Are alarms connected to	a constantly attended loca	tion?	Υ		
Is there a watchman serv	ice?	Υ	What is	the frequency of rounds?	1 HOUR
Are watchman recording	rounds?		Υ		
Are there any fire extingu	ishers?	Υ	Are the	y serviced annually?	Υ
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?	Υ
Frequency of training rec	eived by the private fire br	igade:	ANNUA	LTRAINING	
Type of public fire depart	ment:	null	Distanc	e:	1/2 MILE/FIRE BRIGADE
Exposure:					
How many buildings(not	part of Account) are within	100 feet of insured buildings?	1		
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):	INMATE LAUND	RY	
Is there a body of water n	earby?	N	Description:		
How far is the body of wa	ter from major buildings?				
Previous history of floodi	ing?	N	Description:		
Any property damage los	ses in the past 3 years:	N	Description:		

								r age o
			Pr	operty D	Detail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTION	NS, STATI	E PRISON			
Property:	High Security Gym							
Property Address:	400 Conley Lake Rd DEEF	RLODGE						
Property ID:	8P							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	11900		
Year built:		1950			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Reinforced C	oncrete	
Construction of exterior	walls:	Corrugated Metal Panel			Construction of interior walls:	Gypsum Boa	rd	
Do major interior masonr	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Jail					
Provide a brief description	on of operations:		houses	recreation	activities for the high security inmates			
Storage height of wareho	oused products:		0					
Are flammable and comb	oustible liquids stored in a	cut-off room?	N					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?		no automatic sprinklers	
The water supply for auto	omatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings	?	4	
Indicate the Alarm Cover	ages provided for your fac	cility:		Smoke D	Detectors			
Are alarms connected to	a constantly attended loca	ation?		N				
ls there a watchman serv	rice?	Υ		What is t	the frequency of rounds?		1 per hour	
Are watchman recording	rounds?			N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ons?	N		Is there a	a fire private fire brigade?		Υ	
Frequency of training rec	ceived by the private fire b	rigade:		Fire extin	nquisher annualy			
Type of public fire depart	tment:	null		Distance	e:		blank	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	4					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Office					
Is there a body of water r	nearby?	N	Descrip	otion:				
How far is the body of wa	ater from major buildings?		N/A					
Previous history of flood	ing?	N	Descrip	otion:				
Any property damage los	sses in the past 3 years:	N	Descrip	otion:				

								- 3
			P	roperty D	etail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTIO	NS, STATI	E PRISON			
Property:	High Security Support Buil	ding						
Property Address:	400 Conley Lake Rd DEEF	RLODGE						
Property ID:	18P							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	13248		
Year built:		1982			Number of stories:	1		
Construction of roof:		Steel Deck			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Tilt-Up Concrete			Construction of interior walls:	Masonry w/ F	ire Doors	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Jail					
Provide a brief description	on of operations:		houses	administra	ation offices, visiting operation, school function for inmate	es		
Storage height of wareho	oused products:		0					
Are flammable and comb	oustible liquids stored in a	cut-off room?	N					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		1 hr	
The water supply for aut	omatic sprinklers is?	Public		How mai	ny hydrants are located within 500 feet of buildings?		3	
ndicate the Alarm Cover	rages provided for your fac	cility:		Sprinkler	Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loc	ation?		N				
s there a watchman serv	vice?	Υ		What is t	the frequency of rounds?		1 per hour	
Are watchman recording	rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose station	ons?	N		Is there a	a fire private fire brigade?		Υ	
requency of training re	ceived by the private fire b	rigade:		extinguis	her training ann			
Гуре of public fire depar	tment:	null		Distance	::		blank	
Exposure:								
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	3					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	office					
s there a body of water	nearby?	N	Descri	ption:				
How far is the body of w	ater from major buildings?	,						
Previous history of flood	ling?	N	Descri	ption:				
Any property damage lo	sses in the past 3 years:	N	Descri	ption:				

								i ago o
			Pr	operty D	etail Form			
Agency:	DEPARTMENT OF CORF	RECTIONS / DEPARTMENT OF COR	RRECTION	IS, STATE	PRISON			
Property:	High Side Food Service B	uilding						
Property Address:	400 Conley Lake Rd DEE	R LODGE						
Property ID:	3P							
Construction:								
Total number of insure	ed buildings:	1			Total square footage of insured buildings:	12144		
Year built:		1976			Number of stories:	1		
Construction of roof:		Steel Deck			Construction of floors:	Reinforced C	oncrete	
Construction of exterio	or walls:	Reinforced Concrete			Construction of interior walls:	Masonry		
Do major interior mase	onry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Jail					
Provide a brief descrip	otion of operations:		houses	main food	service operation + bakery & warehouse			
Storage height of ware	ehoused products:		7 ft					
Are flammable and co	mbustible liquids stored in a	cut-off room?	N					
Safegaurds taken for t	he storage and dispensing o	of flammable liquids:	N/A					
Protection:								
Are there any automat	ic sprinklers?	N		What are	the design densities for each area?		1 hour	
The water supply for a	utomatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings	?	3	
Indicate the Alarm Cov	verages provided for your fa	cility:		Smoke D	etectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected	to a constantly attended loc	ation?		N				
Is there a watchman se	ervice?	Υ		What is t	he frequency of rounds?		1 hour	
Are watchman recordi	ng rounds?			N				
Are there any fire extir	nguishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose sta	itions?	N		Is there a	a fire private fire brigade?		Υ	
Frequency of training	received by the private fire b	origade:		annual ex	rtinguisher trng			
Type of public fire dep	artment:	null		Distance	:		blank	
Exposure:								
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	3					
Describe the Occupan	cy of those buildings(s) nea	rby (within 100 feet):	office -	inmate hou	using			
Is there a body of water	er nearby?	N	Descrip	otion:				
How far is the body of	water from major buildings?	?	N/A					
Previous history of flo	oding?	N	Descrip	otion:				
Any property damage	losses in the past 3 years:	N	Descrip	tion:				

			Property	Detail Form		
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF CORF	RECTIONS, RIV	ERSIDE YOUTH CORRECTIONAL FACILITY		
Property:	Housing Unit 14					
Property Address:	2 Riverside Rd BOULDER					
Property ID:	14					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	7926	
Year built:		1972		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	ncrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	I
Do major interior mason	y walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Juvenile Hall			
Provide a brief description	on of operations:		JUNVENILE H	ALL LIVING FACILITY		
Storage height of wareho	oused products:		N/A			
Are flammable and comb	ustible liquids stored in a	cut-off room?	N			
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N			
Protection:						
Are there any automatic	sprinklers?	Υ	What	are the design densities for each area?		
The water supply for auto	omatic sprinklers is?	Public	How n	nany hydrants are located within 500 feet of buildings?	•	1
Indicate the Alarm Cover	ages provided for your fac	ility:	Sprink	ler Waterflow, Sprinkler Valve Tamper, Smoke Detectors		
Are alarms connected to	a constantly attended loca	ition?	Υ			
Is there a watchman serv	rice?	Υ	What	is the frequency of rounds?		24 HOUR FACILITY-CONSTANT
Are watchman recording	rounds?		Υ			
Are there any fire extingu	uishers?	Υ	Are th	ey serviced annually?		Υ
Are there any hose station	ons?	N	Is the	re a fire private fire brigade?		null
Frequency of training red	eived by the private fire b	rigade:				
Type of public fire depart	ment:	Part-Paid	Distar	nce:		1/2 MILE & VOLUNTARY
Exposure:						
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	2			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	ADMINISTRAT	TION, SCHOOL, KITCHEN		
Is there a body of water r	nearby?	Υ	Description:		SMALL RIVER	
How far is the body of wa	ater from major buildings?		300 FEET			
Previous history of flood	ing?	N	Description:			
Any property damage los	sses in the past 3 years:	N	Description:			

			Prop	perty Detail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTIONS	s, PRISON INDUSTRIES			
Property:	Industrial Complex Furnitur	e Shop					
Property Address:	600 Conley Lake Rd DEER	RLODGE					
Property ID:	11P						
Construction:							
Total number of insured I	buildings:	1		Total square footage of insured buildings:	20795		
Year built:		1975		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Poured Concre	rete	
Construction of exterior v	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Garage, S	Service Center			
Provide a brief descriptio	n of operations:		manufactu	uring wood furniture			
Storage height of wareho	used products:		0				
Are flammable and comb	ustible liquids stored in a	cut-off room?	Υ				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ				
Protection:							
Are there any automatic s	sprinklers?	N	W	What are the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings?	?	2	
Indicate the Alarm Cover	ages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	ation?	N	I			
ls there a watchman serv	ice?	N	W	What is the frequency of rounds?			
Are watchman recording	rounds?		N	I			
Are there any fire extingu	ishers?	Υ	Α	are they serviced annually?		Υ	
Are there any hose statio	ns?	N	Is	s there a fire private fire brigade?		Υ	
Frequency of training rec	eived by the private fire b	rigade:	m	nonthly			
Type of public fire depart	ment:	Voluntary	D	Distance:		3 miles	
Exposure:							
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water n	earby?	N	Description	on:			
How far is the body of wa	ter from major buildings?						
Previous history of flood	ing?	N	Description	on:			
Any property damage los	ses in the past 3 years:	N	Description	on:			

							. age e
			Prop	perty Detail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTIONS	S, PRISON INDUSTRIES			
Property:	Industrial Complex Wareho	ouse					
Property Address:	600 Conley Lake Rd DEEF	R LODGE					
Property ID:	11P						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	17231		
Year built:		1986		Number of stories:	2		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concre	ete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Masonry w/ Fir	re Doors	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		Υ			
Occupancy:							
Occupancy Type:			Garage, S	Service Center			
Provide a brief description	on of operations:		storage of	f raw materials & finished good for furniture manufacture/purcha	sing and directo	rs offices	
Storage height of wareh	oused products:		16 feet				
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N	v	What are the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings?	•	2	
Indicate the Alarm Cove	rages provided for your fac	cility:					
Are alarms connected to	a constantly attended loc	ation?	N	1			
ls there a watchman serv	vice?	N	v	Vhat is the frequency of rounds?			
Are watchman recording	rounds?		N	1			
Are there any fire exting	uishers?	Υ	А	are they serviced annually?		Υ	
Are there any hose station	ons?	N	Is	s there a fire private fire brigade?		Υ	
Frequency of training re	ceived by the private fire b	rigade:	m	nontly			
Type of public fire depar	tment:	Voluntary	D	Distance:		3 miles	
Exposure:							
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
ls there a body of water	nearby?	N	Descripti	on:			
How far is the body of w	ater from major buildings?						
Previous history of flood	ling?	N	Descripti	on:			
Any property damage lo	sses in the past 3 years:	N	Descripti	on:			

			Pr	operty Detail Form		
Agency:	DEPARTMENT OF CORRI	ECTIONS / DEPARTMENT OF COR	RECTION	NS, MONTANA WOMEN'S PRISON		
Property:	Industries Building					
Property Address:	701 27th St. BILLINGS					
Property ID:						
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	6400	
Year built:		1998		Number of stories:	1	
Construction of roof:		Steel Deck		Construction of floors:	Poured Concr	ete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry	
Do major interior masor	ry walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			Jail			
Provide a brief descripti	on of operations:		daily ca	re of inmates		
Storage height of wareh	oused products:		0			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	e storage and dispensing of	flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		
The water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	•	2
Indicate the Alarm Cove	rages provided for your fac	ility:	Sprinkler Valve Tamper, Smoke Detectors, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loca	ition?		Υ		
Is there a watchman ser	vice?	Υ		What is the frequency of rounds?		
Are watchman recording	g rounds?			Υ		
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ
Are there any hose stati	ons?	Υ		Is there a fire private fire brigade?		null
Frequency of training re	ceived by the private fire br	igade:				
Type of public fire depa	rtment:	Paid		Distance:		blank
Exposure:						
How many buildings(no	t part of Account) are withir	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water	nearby?	Υ	Descrip	otion:	river	
How far is the body of w	rater from major buildings?		3/4 mile			
Previous history of floo	ding?	Υ	Descrip	otion:	100 year flood	l plain
Any property damage lo	sses in the past 3 years:	N	Descrip	otion:		

			Prop	perty Detail Form	
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTIONS,	, PRISON INDUSTRIES	
Property:	Industries Furniture Shop A	Addition			
Property Address:	600 Conley Lake Rd DEEF	RLODGE			
Property ID:					
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings: 16	6670
Year built:		2001		Number of stories: 2	
Construction of roof:		Steel Deck		Construction of floors: Po	oured Concrete
Construction of exterior v	walls:	Corrugated Metal Panel		Construction of interior walls:	asonry w/ Fire Doors
Do major interior masonr	ry walls (fire walls) extend	above the roofline?		Υ	
Occupancy:					
Occupancy Type:			Garage, S	Service Center	
Provide a brief description	on of operations:		manufactu	uring wood furniture	
Storage height of wareho	oused products:		0		
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A		
Protection:					
Are there any automatic s	sprinklers?	N	w	What are the design densities for each area?	no sprinklers
The water supply for auto	omatic sprinklers is?		Н	low many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cover	ages provided for your fac	ility:			
Are alarms connected to	a constantly attended loca	ation?	N	I	
Is there a watchman serv	rice?	N	w	What is the frequency of rounds?	
Are watchman recording	rounds?		N	I	
Are there any fire extingu	uishers?	Υ	Α	re they serviced annually?	Υ
Are there any hose statio	ons?	null	Is	s there a fire private fire brigade?	Υ
Frequency of training rec	ceived by the private fire b	rigade:	m	nonthly	
Type of public fire depart	tment:	Voluntary	D	vistance:	3 miles
Exposure:					
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water n	nearby?	N	Description	on:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ing?	N	Description	on:	
Any property damage los	sses in the past 3 years:	N	Description	on:	

SMALL RIVER

						Page
			Proj	perty Detail Form		
Agency:	DEPARTMENT OF CO	RRECTIONS / DEPARTMENT C	OF CORRECTIONS	, RIVERSIDE YOUTH CORRECTIONAL FACILITY		
Property:	Industries/Maintenance	Building				
Property Address:	2 Riverside Rd BOULDI	≣R				
Property ID:	12					
Construction:						
Total number of insur	ed buildings:	1		Total square footage of insured buildings:	6971	
Year built:		1972		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete	
Construction of exteri	ior walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior mas	onry walls (fire walls) exte	nd above the roofline?		N		
Occupancy:						
Occupancy Type:			Governme	ental Building		
Provide a brief descri	ption of operations:		OFFICE,	CLASSROOMS, MAINTENANCE		
Storage height of war	ehoused products:		N/A			
Are flammable and co	mbustible liquids stored ir	a cut-off room?	N/A			
Safegaurds taken for	the storage and dispensing	g of flammable liquids:	N/A			
Protection:						
Are there any automa	tic sprinklers?	Υ	v	/hat are the design densities for each area?		
The water supply for a	automatic sprinklers is?		н	ow many hydrants are located within 500 feet of buildings	? 1	
Indicate the Alarm Co	verages provided for your	facility:				
Are alarms connected	I to a constantly attended I	ocation?	n	ull		
Is there a watchman s	ervice?	Υ	v	/hat is the frequency of rounds?	24 HOUF	RFACILITY
Are watchman record	ing rounds?		N			
Are there any fire exti	nguishers?	Υ	A	re they serviced annually?	Υ	
Are there any hose sta	ations?	N	ls	there a fire private fire brigade?	null	
Frequency of training	received by the private fire	e brigade:				
Type of public fire dep	partment:	Paid		istance:	1/2 MILE	& VOLUNTARY
Exposure:						

2

Description:

Description:

Description:

300 FEET

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

								i age i
			Pr	operty D	etail Form			
gency:	DEPARTMENT OF CORRECT	TIONS / DEPARTMENT OF COR	RECTION	NS, PRISC	ON INDUSTRIES			
Property:	License Plate Distribution Cent	ter						
roperty Address:	600 Conley Lake Road DEER	LODGE						
Property ID:	64010							
Construction:								
otal number of insured	buildings: 1				Total square footage of insured buildings:	9404		
ear built:	20	16			Number of stories:	1		
Construction of roof:	nu	II			Construction of floors:	null		
Construction of exterior	walls: nu	II			Construction of interior walls:	null		
o major interior masonr	ry walls (fire walls) extend abo	ve the roofline?			null			
Occupancy:								
Occupancy Type:			Governi	mental Bu	ilding			
Provide a brief description	on of operations:		blank					
storage height of wareho	oused products:		blank					
are flammable and comb	oustible liquids stored in a cut-	-off room?	null					
afegaurds taken for the	storage and dispensing of fla	mmable liquids:	null					
Protection:								
are there any automatic	sprinklers?	Υ		What are	the design densities for each area?			
he water supply for auto	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?	<b>?</b>	blank	
ndicate the Alarm Cover	ages provided for your facility	r:		blank				
are alarms connected to	a constantly attended location	n?		null				
s there a watchman serv	rice?	null		What is t	the frequency of rounds?			
are watchman recording	rounds?							
are there any fire extingu	uishers?	null		Are they	serviced annually?		null	
are there any hose statio	ons?	null		Is there a	a fire private fire brigade?		null	
requency of training rec	ceived by the private fire briga	de:						
ype of public fire depart	tment:	null		Distance	:		blank	
xposure:								
low many buildings(not	part of Account) are within 10	0 feet of insured buildings?	blank					
escribe the Occupancy	of those buildings(s) nearby (	within 100 feet):						
s there a body of water r	nearby? nu	II	Descrip	otion:				
low far is the body of wa	ater from major buildings?							

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: null

null

								- 3 -
			Pro	perty D	etail Form			
Agency:	DEPARTMENT OF CORR	RECTIONS / DEPARTMENT OF COR	RECTION	S, STATE	PRISON			
Property:	Low Security Gym							
Property Address:	400 Conley Lake Rd DEE	R LODGE						
Property ID:	14P							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	9816		
Year built:		1984			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Reinforced C	oncrete	
Construction of exterior	walls:	Tilt-Up Concrete			Construction of interior walls:	Gypsum Boa	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Jail					
Provide a brief descripti	on of operations:		houses r	ecreation	activities for the low security inmates			
Storage height of wareh	oused products:		N/A					
Are flammable and com	bustible liquids stored in a	cut-off room?	N					
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ	,	What are	the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?		I	How mar	ny hydrants are located within 500 feet of buildings?	?	3	
Indicate the Alarm Cove	rages provided for your fa	cility:	:	Smoke D	etectors			
Are alarms connected to	a constantly attended loc	ation?	I	N				
ls there a watchman ser	vice?	Υ	,	What is t	he frequency of rounds?		1 hour	
Are watchman recording	g rounds?		I	N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stati	ons?	N	ı	ls there a	a fire private fire brigade?		Υ	
Frequency of training re	ceived by the private fire b	rigade:	6	annual ex	ktinguisher trng			
Type of public fire depar	rtment:	null	I	Distance	:		blank	
Exposure:								
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	3					
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):	housing	units-offic	cers			
Is there a body of water	nearby?	N	Descript	ion:				
How far is the body of w	ater from major buildings?	•						
Previous history of flood	ding?	N	Descript	ion:				
Any property damage lo	sses in the past 3 years:	N	Descript	ion:				

								r age 7
			Pr	operty D	etail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTION	NS, STATE	E PRISON			
Property:	Low Security Housing Unit	D						
Property Address:	400 Conley Lake Rd DEEF	RLODGE						
Property ID:	23P							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	13760		
Year built:		1990			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Tilt-Up Concrete			Construction of interior walls:	Masonry		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Jail					
Provide a brief description	on of operations:		house lo	ow security	y inmates			
Storage height of warehoused products:			N/A	N/A				
Are flammable and combustible liquids stored in a cut-off room?			N					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		1 hr	
The water supply for auto	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?	•	3	
Indicate the Alarm Cover	ages provided for your fac	cility:	Sprinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors					
Are alarms connected to	a constantly attended loc	ation?		N				
Is there a watchman serv	vice?	Υ		What is t	the frequency of rounds?		twice hourly	
Are watchman recording	rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose station	ons?	N		Is there a	a fire private fire brigade?		Υ	
Frequency of training red	ceived by the private fire b	rigade:		annual ex	ktinguisher trng			
Type of public fire depar	tment:	null		Distance	:		blank	
Exposure:								
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	4					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	housing	units				
Is there a body of water i	nearby?	N	Descrip	otion:				
How far is the body of wa	dy of water from major buildings?			N/A				
Previous history of flood	ling?	N	Descrip	otion:				
Any property damage los	sses in the past 3 years:	N	Descrip	otion:				

33877 2

Masonry

Reinforced Concrete

1 hr

1 hr

blank

3

### **Property Detail Form** DEPARTMENT OF CORRECTIONS / DEPARTMENT OF CORRECTIONS, STATE PRISON Agency: Property: Low Security Support (Rothe) **Property Address:** 400 Conley Lake Rd DEER LODGE 6P **Property ID:** Construction: Total number of insured buildings: 1 Total square footage of insured buildings: Year built: 1968 Number of stories: Construction of roof: Reinforced Concrete Construction of floors: Construction of exterior walls: Masonry Construction of interior walls: Do major interior masonry walls (fire walls) extend above the roofline?

Jail

0

Ν

N/A

office, dining hall, support service-low security visiting

What is the frequency of rounds?

Is there a fire private fire brigade?

Are they serviced annually?

annual extinguisher trng

Distance:

office & housing

Description:

Description:

What are the design densities for each area?

How many hydrants are located within 500 feet of buildings?

Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow

Occupancy:
Occupancy Type:

Protection:

Exposure:

Provide a brief description of operations:

Storage height of warehoused products:

Are there any automatic sprinklers?

Is there a watchman service?

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

Are watchman recording rounds?

Are there any fire extinguishers?

The water supply for automatic sprinklers is?

Indicate the Alarm Coverages provided for your facility:

Are alarms connected to a constantly attended location?

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Are flammable and combustible liquids stored in a cut-off room?

Safegaurds taken for the storage and dispensing of flammable liquids:

Υ

Υ

Ν

null

Ν

Ν

**Public** 

			Prop	erty Detail Form			
Agency:	DEPARTMENT OF CORR	RECTIONS / DEPARTMENT OF COR	RECTIONS,	PINE HILLS YOUTH CORRECTIONAL FACILITY			
Property:	Main Building/PHYCF						
Property Address:	4 North Haynes Avenue M	IILES CITY					
Property ID:	61						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	43838		
Year built:		2000		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Poured Cond	crete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Masonry w/ F	Fire Doors	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Jail				
Provide a brief description	on of operations:		OFFICES/	HOUSING/CLASS ROOMS/COOKING/			
Storage height of wareh	oused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?			N				
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ	w	hat are the design densities for each area?			
The water supply for aut	omatic sprinklers is?	Private	He	ow many hydrants are located within 500 feet of building	s?	5	
Indicate the Alarm Cove	rages provided for your fac	cility:	Burglar Alarms (Motion Detection), Sprinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors				
Are alarms connected to	a constantly attended loc	ation?	Υ				
ls there a watchman serv	vice?	Υ	W	hat is the frequency of rounds?			
Are watchman recording	y rounds?		Υ				
Are there any fire exting	uishers?	Υ	Aı	re they serviced annually?		Υ	
Are there any hose station	ons?	N	Is	there a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	Di	stance:		2 CITY BLOCKS	
Exposure:							
How many buildings(not	part of Account) are withi	in 100 feet of insured buildings?	2				
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):	GYM & CL	LIENT HOUSING			
Is there a body of water	nearby?	N	Descriptio	on:			
How far is the body of w	rater from major buildings?	<i>t</i>					
Previous history of flood	ling?	N	Descriptio	on:			
Any property damage lo	sses in the past 3 years:	N	Descriptio	on:			

			Pr	roperty D	Detail Form			
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF CORI	RECTION	NS, STATI	E PRISON			
Property:	Main Prison Warehouse							
Property Address:	400 Conley Lake Rd DEER	RLODGE						
Property ID:	21P							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	23490		
Year built:		1988			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Poured Conci	rete	
Construction of exterior	walls:	Corrugated Metal Panel			Construction of interior walls:	Masonry		
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Garage	e, Parts Sto	orage			
Provide a brief description	on of operations:		wareho	ouse				
Storage height of wareho	oused products:		0					
Are flammable and combustible liquids stored in a cut-off room?			N					
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?	?	2	
Indicate the Alarm Cover	ages provided for your fac	eility:		Smoke D	Detectors			
Are alarms connected to	a constantly attended loca	ation?		N				
ls there a watchman serv	rice?	N		What is	the frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose static	ons?	N		Is there	a fire private fire brigade?		Υ	
Frequency of training red	ceived by the private fire bi	rigade:		annual e	xtinguisher trng			
Type of public fire depart	ment:	null		Distance	e:		blank	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	2					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	office -	warehouse	e			
Is there a body of water r	nearby?	N	Descrip	ption:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	ption:				
Any property damage los	sses in the past 3 years:	N	Descrip	ption:				

						Page 7	
			Pr	operty Detail Form			
gency:	DEPARTMENT OF CORRECT	CTIONS / DEPARTMENT OF COR	RECTIO	NS, STATE PRISON			
Property:	Maintenance Complex						
roperty Address:	400 Conley Lake Rd DEER L	ODGE					
roperty ID:	29H						
Construction:							
otal number of insured b	uildings: 1			Total square footage of insured buildings:	22000		
ear built:	1	965		Number of stories:	2		
Construction of roof:	S	teel Deck w/ Fasterners		Construction of floors:	Poured Concrete		
Construction of exterior w	valls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board		
o major interior masonry	walls (fire walls) extend ab	ove the roofline?		N			
Occupancy:							
Occupancy Type:			Garage	, Service Center			
Provide a brief description	n of operations:		maintenance operation - industrial shops				
storage height of warehou	used products:		7 feet				
are flammable and combu	ıstible liquids stored in a cu	t-off room?	Υ				
afegaurds taken for the s	storage and dispensing of fl	ammable liquids:	Υ				
Protection:							
are there any automatic s	prinklers?	Υ		What are the design densities for each area?	1 hr		
he water supply for auto	matic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	1		
ndicate the Alarm Covera	ges provided for your facili	ty:		Sprinkler Valve Tamper, Sprinkler Waterflow			
are alarms connected to a	a constantly attended location	on?		N			
s there a watchman servi	ce?	N		What is the frequency of rounds?			
are watchman recording r	ounds?			N			
are there any fire extingui	shers?	Υ		Are they serviced annually?	Υ		

Is there a fire private fire brigade? Are there any hose stations? Ν Υ Frequency of training received by the private fire brigade: 4hr per month brigade trn Type of public fire department: Distance: blank null

Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

manufacturing Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding?

Description: Ν Any property damage losses in the past 3 years: N

Description:

		Pro	operty Detail Form		
EPARTMENT OF CORREC	CTIONS / DEPARTMENT OF COR	RECTION	IS, STATE PRISON		
Martz Diagnostic and Intake	Unit (MDIU)				
00 Conley Lake Rd DEER L	ODGE				
ildings: 1			Total square footage of insured buildings:	34861	
2	004		Number of stories:	2	
S	Steel Deck		Construction of floors:	Poured Concrete	
lls: N	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
walls (fire walls) extend ab	ove the roofline?		N		
		Jail			
of operations:		inmate h	nousing unit		
sed products:		0			
tible liquids stored in a cu	it-off room?	N			
orage and dispensing of f	ammable liquids:	N/A			
rinklers?	Υ		What are the design densities for each area?	1 hr	
atic sprinklers is?			How many hydrants are located within 500 feet of buildings?	2	
es provided for your facili	ty:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
constantly attended locati	on?		Υ		
e?	Υ		What is the frequency of rounds?	1 hr	
unds?			N		
hers?	Υ		Are they serviced annually?	Υ	
?	N		Is there a fire private fire brigade?	Υ	
ved by the private fire brig	ade:		annual extinguisher trng		
ent:	null		Distance:	blank	
	lartz Diagnostic and Intake In the Interest of Operations:  sed products: stible liquids stored in a curorage and dispensing of flurinklers? static sprinklers is? es provided for your facility constantly attended locations? sunds? thers?	fartz Diagnostic and Intake Unit (MDIU)  00 Conley Lake Rd DEER LODGE  ildings:  2004 Steel Deck Masonry walls (fire walls) extend above the roofline?  of operations: sed products: stible liquids stored in a cut-off room? orage and dispensing of flammable liquids:  rinklers?  y natic sprinklers is? es provided for your facility: constantly attended location? e? y unds? hers? y y ved by the private fire brigade:	Martz Diagnostic and Intake Unit (MDIU)  OO Conley Lake Rd DEER LODGE  ildings:  1 2004 Steel Deck  Ills: Masonry walls (fire walls) extend above the roofline?  Jail of operations: inmate R sed products: 0 Norage and dispensing of flammable liquids: N/A  rinklers? Y static sprinklers is? es provided for your facility: constantly attended location? e? Y unds? hers? Y y ved by the private fire brigade:	ildings: 1 Total square footage of insured buildings: 2004 Number of stories: Steel Deck Construction of floors:  Ills: Masonry Construction of interior walls: walls (fire walls) extend above the roofline? N  Jail of operations: inmate housing unit sed products: 0 stible liquids stored in a cut-off room? N orage and dispensing of flammable liquids: N/A  winklers? Y What are the design densities for each area? waltic sprinklers is? How many hydrants are located within 500 feet of buildings? es provided for your facility: Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow constantly attended location?  27 What is the frequency of rounds? Nhers? Y What is the frequency of rounds? Nhers? Y What is the frequency of rounds? Nhers? Y Are they serviced annually? Is there a fire private fire brigade? wed by the private fire brigade: annual extinguisher trng	flartz Diagnostic and Intake Unit (MDIU)  00 Conley Lake Rd DEER LODGE    Idings:   1

0

Description:

Description:

Description:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

			Property Detail Form						
Agency:	DEPARTMENT OF	DEPARTMENT OF CORRECTIONS / DEPARTMENT OF CORRECTIONS, STATE PRISON							
Property:	Maximum Security L	Maximum Security Unit							
Property Address:	400 Conley Lake Ro	DEER LODGE							
Property ID:	17P								
Construction:									
Total number of insure	ed buildings:	1	Total square footage of insured buildings:	34017					
Year built:		1986	Number of stories:	2					
Construction of roof:		Steel Deck	Construction of floors:	Poured Concrete					
Construction of exterio	or walls:	Tilt-Up Concrete	Construction of interior walls:	Masonry w/ Fire Doors					
Do major interior mase	onrv walls (fire walls) e	extend above the roofline?	N						

### Occupancy:

Storage height of warehoused products:

**Occupancy Type:** Jail

Do major interior masonry walls (fire walls) extend above the roofline?

Provide a brief description of operations: INMATE HOUSING UNIT/HOUSING UNIT'S MANAGEMENT STAFF

Are flammable and combustible liquids stored in a cut-off room?

Ν

Safegaurds taken for the storage and dispensing of flammable liquids:

### Protection:

Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? Boosted by Fire Pump How many hydrants are located within 500 feet of buildings? 2

N/A

Indicate the Alarm Coverages provided for your facility: Sprinkler Waterflow, Smoke Detectors, Sprinkler Valve Tamper, Burglar Alarms (Door Contacts)

Υ Are alarms connected to a constantly attended location?

Is there a watchman service? Υ What is the frequency of rounds? 1 HOUR

Υ Are watchman recording rounds?

Are there any fire extinguishers? Υ Are they serviced annually? Υ

Are there any hose stations? Is there a fire private fire brigade?

Frequency of training received by the private fire brigade: ANNUAL

3/4 MILE/MSP FIRE BRIGADE Type of public fire department: null Distance:

Exposure:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Description:

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding? Ν Description:

Any property damage losses in the past 3 years: Description:

			Property	Detail Form		
Agency:	DEPARTMENT OF CORRE	ECTIONS / DEPARTMENT OF COF	RECTIONS, MO	NTANA STATE CORRECTIONAL TREATMENT CENT	ER	
Property:	Montana State Correctional	Treatment Center				
Property Address:	1100 Conley Lake Road DE	EER LODGE				
Property ID:						
Construction:						
Total number of insured I	buildings:	1		Total square footage of insured buildings:	22436	
Year built:		1998		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concre	te
Construction of exterior v	walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N		
Occupancy:						
Occupancy Type:			Jail			
Provide a brief descriptio	n of operations:		OFFICES/CLA	SSROOMS/KITCHEN/DINING/HOUSING		
Storage height of wareho	used products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?			Υ			
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ			
Protection:						
i rotootion.						
Are there any automatic s	sprinklers?	N	What	are the design densities for each area?		DETENTION CELLS ONLY
		N Public		are the design densities for each area? nany hydrants are located within 500 feet of building		DETENTION CELLS ONLY
Are there any automatic s The water supply for auto		Public	How n		js?	0
Are there any automatic s The water supply for auto Indicate the Alarm Covera	omatic sprinklers is?	Public	How n	nany hydrants are located within 500 feet of building	js?	0
Are there any automatic s The water supply for auto Indicate the Alarm Covera	omatic sprinklers is? ages provided for your fact a constantly attended loca	Public	<b>How n</b> Burgla Y	nany hydrants are located within 500 feet of building	<b>gs?</b> /alve Tamper, Sprin	0
Are there any automatic s The water supply for auto Indicate the Alarm Covers Are alarms connected to	omatic sprinklers is? ages provided for your fact a constantly attended loca ice?	Public ility: ttion?	<b>How n</b> Burgla Y	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V	<b>gs?</b> /alve Tamper, Sprin	0 skler Waterflow
Are there any automatic some state of the water supply for auton auton and the water the Alarm Covers and alarms connected to the state a watchman serv	omatic sprinklers is?  ages provided for your fact a constantly attended loca ice?  rounds?	Public ility: ttion?	How n Burgla Y What i	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V	<b>gs?</b> /alve Tamper, Sprin	0 skler Waterflow
Are there any automatic some supply for automatic supply for a watchman servording supply for a supply for a watchman recording supply for a watchman recording supply for a watchman recording supply for automatic supply for autom	omatic sprinklers is?  ages provided for your fact a constantly attended locatice?  rounds?  sishers?	Public ility: ation? Y	How n Burgla Y What i Y Are th	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?	<b>gs?</b> /alve Tamper, Sprin	0 akler Waterflow 1 HOUR
Are there any automatic some content of the water supply for automatic some connected to the state of the watchman servolus there a watchman recording the watchman fire extinguished there any fire extinguished there any hose stations.	omatic sprinklers is?  ages provided for your fact a constantly attended locatice?  rounds?  sishers?	Public ility: tion? Y Y N	How n Burgla Y What i Y Are th	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?	<b>gs?</b> /alve Tamper, Sprin	0 okler Waterflow 1 HOUR
Are there any automatic some content of the water supply for automatic some connected to the state of the watchman servolus there a watchman recording the watchman fire extinguished there any fire extinguished there any hose stations.	omatic sprinklers is?  ages provided for your fact a constantly attended local ice?  rounds?  iishers?  ns?  eived by the private fire br	Public ility: tion? Y Y N	How n Burgla Y What i Y Are th	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?  ey serviced annually? e a fire private fire brigade?	<b>ys?</b> /alve Tamper, Sprin	0 okler Waterflow 1 HOUR
Are there any automatic some content of the water supply for automatic some connected to the state of the watchman serve and the watchman recording the there any fire extinguitation of the station of t	omatic sprinklers is?  ages provided for your fact a constantly attended local ice?  rounds?  iishers?  ns?  eived by the private fire br	Public  ility:  tion?  Y  Y  N  rigade:	How n Burgla Y What i Y Are th Is ther	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?  ey serviced annually? e a fire private fire brigade?	<b>ys?</b> /alve Tamper, Sprin	0 okler Waterflow 1 HOUR Y Y
Are there any automatic some content of the water supply for automatic some connected to the alarms connected to the state of the watchman recording are there any fire extingulare there any hose stations. Frequency of training recording the state of the public fire departs.	omatic sprinklers is?  ages provided for your fact a constantly attended local ice?  rounds?  iishers?  ins?  eived by the private fire briment:	Public  ility:  tion?  Y  Y  N  rigade:	How n Burgla Y What i Y Are th Is ther	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?  ey serviced annually? e a fire private fire brigade?	<b>ys?</b> /alve Tamper, Sprin	0 okler Waterflow 1 HOUR Y Y
Are there any automatic some content of the water supply for automatic some case of the water supply for automatic some case of the water and	omatic sprinklers is?  ages provided for your fact a constantly attended local ice?  rounds?  iishers?  ins?  eived by the private fire briment:	Public  ility:  ition?  Y  N  rigade:  null  100 feet of insured buildings?	How n Burgla Y What i Y Are th Is ther N/A Distan	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?  ey serviced annually? e a fire private fire brigade?	<b>ys?</b> /alve Tamper, Sprin	0 okler Waterflow 1 HOUR Y Y
Are there any automatic some content of the water supply for automatic some case of the water supply for automatic some case of the water and	omatic sprinklers is?  ages provided for your fact a constantly attended local ice?  rounds?  iishers?  ns?  eived by the private fire br ment:  part of Account) are within of those buildings(s) nearl	Public  ility:  ition?  Y  N  rigade:  null  100 feet of insured buildings?	How n Burgla Y What i Y Are th Is ther N/A Distan	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?  ey serviced annually? e a fire private fire brigade?	<b>ys?</b> /alve Tamper, Sprin	0 skler Waterflow  1 HOUR  Y  Y  2 MILES - MSP'S FIRE BRIG
Are there any automatic some content of the water supply for automatic some connected to the state of the watchman recording the watchman recording the watchman recording the watchman recording the state of the st	omatic sprinklers is?  ages provided for your fact a constantly attended local ice?  rounds?  iishers?  ns?  eived by the private fire br ment:  part of Account) are within of those buildings(s) nearl	Public  ility:  ition?  Y  N  rigade:  null  a 100 feet of insured buildings?  by (within 100 feet):	How n Burgla Y What i Y Are th Is ther N/A Distant	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?  ey serviced annually? e a fire private fire brigade?	<b>gs?</b> /alve Tamper, Sprin	0 skler Waterflow  1 HOUR  Y  Y  2 MILES - MSP'S FIRE BRIG
Are there any automatic some content of the water supply for automatic some connected to the state of the watchman recording the watchman recording the watchman recording the watchman recording the state of the st	omatic sprinklers is?  ages provided for your fact a constantly attended local ice?  rounds?  dishers?  ns?  deived by the private fire briment:  part of Account) are within of those buildings(s) nearly dearby?  atter from major buildings?	Public  ility:  ition?  Y  N  rigade:  null  a 100 feet of insured buildings?  by (within 100 feet):	How n Burgla Y What i Y Are th Is ther N/A Distant	nany hydrants are located within 500 feet of building r Alarms (Door Contacts), Smoke Detectors, Sprinkler V s the frequency of rounds?  ey serviced annually? e a fire private fire brigade?	<b>gs?</b> /alve Tamper, Sprin	0 skler Waterflow  1 HOUR  Y  Y  2 MILES - MSP'S FIRE BRIG

100 year flood plain

						ı age
			Pro	operty Detail Form		
Agency:	DEPARTMENT OF CORRI	ECTIONS / DEPARTMENT OF COF	RECTION	IS, MONTANA WOMEN'S PRISON		
Property:	Montana Women's Prison I	Main Building				
Property Address:	701 27th St S. BILLINGS					
Property ID:						
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	76543	
Year built:		1985		Number of stories:	3	
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry	
Do major interior mason	nry walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			Jail			
Provide a brief description of operations:			daily car	re of inmates		
Storage height of warehoused products:			0			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	e storage and dispensing of	flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		
The water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	2	
ndicate the Alarm Cove	rages provided for your fac	ility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	tion?		Υ		
s there a watchman ser	vice?	Υ		What is the frequency of rounds?		
Are watchman recording	g rounds?			Υ		
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stati	ons?	Υ		Is there a fire private fire brigade?	Υ	
requency of training re	ceived by the private fire br	igade:				
Type of public fire depar	rtment:	Paid		Distance:	blank	(
Exposure:						
How many buildings(no	t part of Account) are withir	100 feet of insured buildings?	0			
Describe the Occupancy	y of those buildings(s) near	oy (within 100 feet):				
s there a body of water	nearby?	Υ	Descrip	tion:	river	

3/4 mile

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Υ

Previous history of flooding?

						Page 8
			Pı	operty Detail Form		
Agency:	DEPARTMENT OF CORF	RECTIONS / DEPARTMENT O	F CORRECTIO	NS, STATE PRISON		
Property:	MSP Armory					
Property Address:	400 Conley Lake Rd DEE	R LODGE				
Property ID:	5P					
Construction:						
Γotal number of insure	d buildings:	1		Total square footage of insured buildings:	6903	
Year built:		1968		Number of stories:	1	
Construction of roof:		Concrete Panels		Construction of floors:	Poured Concrete	
Construction of exterio	r walls:	Reinforced Concrete		Construction of interior walls:	Masonry	
Oo major interior maso	nry walls (fire walls) extend	I above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descript	tion of operations:		Armory	operation, lockshop,msp phone room, IT operation, offices		
Storage height of warel	housed products:		0			
Are flammable and con	nbustible liquids stored in a	cut-off room?	N			
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A			
Protection:						
Are there any automati	c sprinklers?	N		What are the design densities for each area?	no sprinklers	
The water supply for aι	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	s? 1	
ndicate the Alarm Cov	erages provided for your fa	cility:		Smoke Detectors		
Are alarms connected t	o a constantly attended loc	eation?		N		
s there a watchman se	rvice?	N		What is the frequency of rounds?		
Are watchman recordin	g rounds?			N		
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?	Υ	
requency of training r	eceived by the private fire b	origade:		annual extinguisher trng		
Type of public fire depart	artment:	null		Distance:	blank	

Description:

# **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet): infirmary, adminstration

Ν

How far is the body of water from major buildings?

Is there a body of water nearby?

Previous history of flooding? Description: Ν

Any property damage losses in the past 3 years: N Description:

Property Detail Form								
Agency:	DEPARTMENT OF CORRE	ECTIONS / DEPARTMENT OF CORF	RECTIONS, RIVE	RSIDE YOUTH CORRECTIONAL FACILITY				
Property:	Multi Purpose Building							
Property Address:	2 Riverside Rd BOULDER							
Property ID:	16							
Construction:								
Total number of insured I	ouildings:	1		Total square footage of insured buildings:	9540			
Year built:		1999		Number of stories:	1			
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Cor	ncrete		
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Masonry w/ Op	penings		
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N				
Occupancy:								
Occupancy Type:			Other					
Provide a brief descriptio	n of operations:		GYM, TRAINING	ROOM				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic s	sprinklers?	Υ	What ar	e the design densities for each area?				
The water supply for auto	omatic sprinklers is?	Public	How ma	ny hydrants are located within 500 feet of buildings?	ı	1		
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ition?	Υ					
Is there a watchman serv	ice?	N	What is	the frequency of rounds?				
Are watchman recording	rounds?							
Are there any fire extingu	ishers?	Υ	Are the	y serviced annually?		Υ		
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire depart	ment:	Part-Paid	Distanc	e:		1/2 MILE & VOLUNTARY		
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	1					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):	SCHOOL, MAIN	TENANCE				
Is there a body of water n	re a body of water nearby?		Description:		SMALL RIVER			
How far is the body of wa	ter from major buildings?		300 FEET					
Previous history of floodi	ng?	N	Description:					
Any property damage los	ses in the past 3 years:	N	Description:					

						Page 8
			Pro	perty Detail Form		
gency:	DEPARTMENT OF COF	RRECTIONS / DEPARTMENT O	OF CORRECTIONS	S, PRISON INDUSTRIES		
Property:	Parlor					
roperty Address:	600 Conley Lake Rd DE	ER LODGE				
roperty ID:	2M					
Construction:						
otal number of insured	l buildings:	1		Total square footage of insured buildings:	42324	
ear built:		1949		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete	
Construction of exterior	r walls:	Masonry		Construction of interior walls:	Gypsum Board	
o major interior masonry walls (fire walls) extend above the roofline?				N		
Occupancy:						
Occupancy Type: Go				ental Building		
Provide a brief descript	ion of operations:		dairy milk	ing parlor, dairy products processing		
Storage height of wareh	oused products:		0			
are flammable and com	bustible liquids stored in	a cut-off room?	N/A			
afegaurds taken for th	e storage and dispensing	of flammable liquids:	N/A			
Protection:						
are there any automatic	sprinklers?	N	v	Vhat are the design densities for each area?	no sprinklers	
he water supply for au	tomatic sprinklers is?		F	low many hydrants are located within 500 feet of building	s? 1	
ndicate the Alarm Cove	erages provided for your f	acility:	S	Smoke Detectors		
are alarms connected to	o a constantly attended lo	ocation?	N	I		
s there a watchman ser	vice?	Υ	v	Vhat is the frequency of rounds?	every 4 hours	
are watchman recording	g rounds?		N	I		
are there any fire exting	guishers?	Υ	A	are they serviced annually?	null	
are there any hose stati	ions?	N	ls	s there a fire private fire brigade?	Υ	
requency of training re	eceived by the private fire	brigade:				
ype of public fire depa	rtment:	Voluntary	0	Distance:	4 miles	

# Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Any property damage losses in the past 3 years: N

Ν

Description:

Description:

1

Description:

			Pro	pperty Detail Form			
Agency:	DEPARTMENT OF CORRI	ECTIONS / DEPARTMENT OF CORI	RECTION	S, PINE HILLS YOUTH CORRECTIONAL FACILITY			
Property:	Physical Training Center						
Property Address:	4 North Haynes Avenue MI	LES CITY					
Property ID:	52						
Construction:							
Total number of insured I	buildings:	1		Total square footage of insured buildings:	42863		
Year built:		1968		Number of stories:	2		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concrete		
Construction of exterior v	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Governn	nental Building			
Provide a brief descriptio	on of operations:		PHYSIC	AL ED/RECREATION			
Storage height of wareho	used products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?			N				
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A				
Protection:							
Are there any automatic s	sprinklers?	N		What are the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	3		
Indicate the Alarm Covera	ages provided for your fac	ility:		Smoke Detectors			
Are alarms connected to	a constantly attended loca	tion?		Υ			
Is there a watchman serv	ice?	Υ		What is the frequency of rounds?			
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they serviced annually?	Υ		
Are there any hose statio	ns?	N		Is there a fire private fire brigade?	N		
Frequency of training rec	eived by the private fire br	igade:					
Type of public fire depart	ment:	Paid		Distance:	2 CITY BLOCKS		
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	2				
Describe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):	SCHOO	L BUILDING/CLIENT HOUSING			
ls there a body of water n	nearby?	N	Descrip	tion:			
How far is the body of wa	ater from major buildings?						
Previous history of floodi	flooding?			Description:			
Any property damage los	ses in the past 3 years:	N	Descrip	tion:			

						- 9			
			Prope	rty Detail Form					
Agency:	DEPARTMENT OF CORRECTIONS / DEPARTMENT OF CORRECTIONS, PRISON INDUSTRIES								
Property:	Print & Sign								
Property Address:	600 Conley Lake Rd DEEF	RLODGE							
Property ID:	48H								
Construction:									
Total number of insured l	buildings:	1		Total square footage of insured buildings:	14250				
Year built:		1975		Number of stories:	1				
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concr	rete			
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board				
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Garage, Par	rts Storage					
Provide a brief description of operations:			houses tag p	houses tag plant, sign shop, & paint shop					
Storage height of warehoused products:		10 feet	10 feet						
Are flammable and combustible liquids stored in a cut-off room?			Υ						
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ							
Protection:									
Are there any automatic	sprinklers?	N	Wh	at are the design densities for each area?	nc	sprinklers			
The water supply for auto	omatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?	3				
Indicate the Alarm Cover	ages provided for your fac	ility:							
Are alarms connected to	a constantly attended loca	ation?	N						
ls there a watchman serv	ice?	Υ	Wh	at is the frequency of rounds?	4	per hr			
Are watchman recording	rounds?		N						
Are there any fire extingu	ishers?	N	Are	they serviced annually?	Υ				
Are there any hose statio	ns?	N	ls ti	here a fire private fire brigade?	Υ				
Frequency of training rec	eived by the private fire b	rigade:	onc	e a year					
Type of public fire depart	ment:	Voluntary	Dis	tance:	8 1	miles			
Exposure:									
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water n	nearby?	N	Description	n:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	s history of flooding?		Description:						
Any property damage los	ses in the past 3 years:	N	Description	ı:					

	Property Detail Fo
ey:	DEPARTMENT OF CORRECTIONS / DEPARTMENT OF CORRECTIONS, RIVERSIDE YO
rtv-	Programs Ruilding #15

			Property	Detail Form					
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTIONS, RIVE	RSIDE YOUTH CORRECTIONAL FACILITY					
Property:	Programs Building #15								
Property Address:	2 Riverside Rd BOULDER								
Property ID:	15								
Construction:									
Total number of insured	d buildings:	1		Total square footage of insured buildings:	6980				
ear built:		1972		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete			
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd			
Oo major interior maso	nry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Lodge						
Provide a brief descript	ion of operations:		KITCHEN, STOR	KITCHEN, STORAGE					
Storage height of warehoused products:		N/A							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automation	sprinklers?	Υ	What ar	re the design densities for each area?					
The water supply for au	tomatic sprinklers is?		How ma	any hydrants are located within 500 feet of buildings?	<b>?</b>	blank			
ndicate the Alarm Cove	erages provided for your fac	cility:							
Are alarms connected t	o a constantly attended loc	ation?	null						
s there a watchman se	rvice?	Υ	What is	the frequency of rounds?		24 HOUR FACILITY			
Are watchman recordin	g rounds?		N						
Are there any fire exting	guishers?	Υ	Are the	y serviced annually?		Υ			
Are there any hose stat	ions?	null	Is there	a fire private fire brigade?		null			
requency of training re	eceived by the private fire b	rigade:							
Гуре of public fire depa	rtment:	Part-Paid	Distanc	ee:		1/2 MILE & VOLUNTARY			
Exposure:									
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	2						
Describe the Occupancy of those buildings(s) nearby (within 100 feet):		SCHOOL, JUVE	NILE HALL						
s there a body of water	nearby?	Υ	Description:		SMALL RIVER	R			
How far is the body of v	vater from major buildings?		300 FEET						
Previous history of floo	ding?	N	Description:						
Any property damage lo	osses in the past 3 years:	N	Description:						

								. ago o
			Pro	perty D	etail Form			
Agency:	DEPARTMENT OF CORRECTIONS / DEPARTMENT OF CORRECTIONS, STATE PRISON							
Property:	Reception Building							
Property Address:	400 Conley Lake Rd DEER	LODGE						
Property ID:	7P							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	10160		
Year built:		1968			Number of stories:	1		
Construction of roof:		Reinforced Concrete			Construction of floors:	Reinforced Co	ncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry		
Do major interior mason	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Jail					
Provide a brief description	on of operations:		Inmate h	ousing				
Storage height of warehoused products:		0						
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for the storage and dispensing of flammable liquids:		N						
Protection:								
Are there any automatic	sprinklers?	Υ	,	What are	the design densities for each area?		1 hr	
The water supply for auto	omatic sprinklers is?	Public	1	How man	y hydrants are located within 500 feet of buildings?		3	
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ition?	I	N				
ls there a watchman serv	rice?	N	,	What is tl	he frequency of rounds?			
Are watchman recording	rounds?		I	N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose station	ons?	N	ı	ls there a	fire private fire brigade?		Υ	
Frequency of training rec	eived by the private fire br	igade:	;	annual ex	tinguisher trng			
Type of public fire depart	ment:	null	I	Distance:	:		blank	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	4					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):	Offices					
ls there a body of water r	nearby?	N	Descript	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descript	tion:				
Any property damage los	sses in the past 3 years:	N	Descript	tion:				

						Page			
			Propert	y Detail Form					
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RRECTIONS, PI	NE HILLS YOUTH CORRECTIONAL FACILITY					
Property:	Spirituality Center								
Property Address:	4 North Haynes Avenue M	ILES CITY							
Property ID:	60								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	9404				
Year built:		1983		Number of stories:	1				
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete				
Construction of exterior	walls:	Glass and Steel Curtain		Construction of interior walls:	Masonry w/ Fire Doors	<b>;</b>			
Do major interior masonry walls (fire walls) extend above the roofline?		above the roofline?		Υ					
Occupancy:									
Occupancy Type:			Governmenta	l Building					
Provide a brief description of operations:			WAREHOUS	WAREHOUSE/DISTRIBUTION					
Storage height of warehoused products:			5 FEET	5 FEET					
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ							
Protection:									
Are there any automatic	sprinklers?	Υ	Wha	t are the design densities for each area?					
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	3				
Indicate the Alarm Cover	ages provided for your fac	cility:	Sprin	kler Waterflow, Sprinkler Valve Tamper, Smoke Detectors					
Are alarms connected to	a constantly attended loc	ation?	Υ						
Is there a watchman serv	rice?	Υ	Wha	t is the frequency of rounds?	3 TIME	S DAILY			
Are watchman recording	rounds?		Υ						
Are there any fire extingu	uishers?	Υ	Are t	hey serviced annually?	Υ				
Are there any hose static	ons?	N	Is the	ere a fire private fire brigade?	N				
Frequency of training red	ceived by the private fire b	rigade:							
Type of public fire depart	tment:	Paid	Dista	ince:	3000 F	EET			
Exposure:									
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	5						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	SCHOOL, ST	ORAGE, WARHOUSE, SHOPS					
Is there a body of water r	nearby?	Υ	Description:		YELLOSTONE RIVER				
How far is the body of wa	ater from major buildings?		1.5 MILES						
Previous history of flood	ing?	N	Description:						
Any property damage los	sses in the past 3 years:	N	Description:						

						900
			Prop	erty Detail Form		
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RRECTIONS,	RIVERSIDE YOUTH CORRECTIONAL FACILITY		
Property:	Storage Building					
Property Address:	310 4th Avenue BOULDER	8				
Property ID:	24					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	6480	
Year built:		1960		Number of stories:	1	
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
Do major interior masor	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Storage			
Provide a brief description of operations:		VACANT-S	STORAGE BLDG.			
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A				
Protection:						
Are there any automation	sprinklers?	N	w	hat are the design densities for each area?		
The water supply for au	tomatic sprinklers is?		Н	ow many hydrants are located within 500 feet of buildings?	blank	
Indicate the Alarm Cove	rages provided for your fac	ility:				
Are alarms connected to	a constantly attended loc	ation?	nu	III		
Is there a watchman ser	vice?	null	w	hat is the frequency of rounds?		
Are watchman recording	g rounds?		N			
Are there any fire exting	uishers?	N	Aı	re they serviced annually?	null	
Are there any hose stati	ons?	N	Is	there a fire private fire brigade?	null	
Frequency of training re	ceived by the private fire b	rigade:				
Type of public fire depa	rtment:	Part-Paid	Di	istance:	1/2 MILE & VOLUTARY	
Exposure:						
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	2			
Describe the Occupanc	y of those buildings(s) near	by (within 100 feet):	DRY STOR	RAGE		
Is there a body of water	nearby?	Υ	Description	on:	SMALL RIVER	
How far is the body of w	rater from major buildings?		300 FEET			
Previous history of floo	ding?	N	Description	on:		
Any property damage lo	sses in the past 3 years:	N	Description	on:		

						Page
			Prop	erty Detail Form		
Agency:	DEPARTMENT OF CO	DRRECTIONS / DEPARTMENT O	F CORRECTIONS,	STATE PRISON		
Property:	Unit A Housing					
Property Address:	400 Conley Lake Rd D	EER LODGE				
Property ID:	1P(A)					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	19415	
Year built:		1976		Number of stories:	3	
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete	
Construction of exterio	or walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board	
Do major interior masonry walls (fire walls) extend above the roofline?			N			
Occupancy:						
Occupancy Type:			Jail			
Provide a brief description of operations:		INMATE H	OUSING/MANAGEMENT STAFF HOUSING			
Storage height of ware	housed products:		N/A			
Are flammable and cor	nbustible liquids stored i	in a cut-off room?	N			
Safegaurds taken for the	he storage and dispensir	ng of flammable liquids:	N			
Protection:						
Are there any automati	ic sprinklers?	N	W	nat are the design densities for each area?		
The water supply for a	utomatic sprinklers is?		Но	ow many hydrants are located within 500 feet of building	s? 4	
Indicate the Alarm Cov	erages provided for you	r facility:	Sn	noke Detectors		
Are alarms connected	to a constantly attended	location?	Υ			
Is there a watchman se	ervice?	Υ	W	nat is the frequency of rounds?	1 H	OUR
Are watchman recording	ng rounds?		Υ			
Are there any fire extin	guishers?	Υ	Ar	e they serviced annually?	Υ	
Are there any hose sta	tions?	N	Is	there a fire private fire brigade?	Υ	
Frequency of training i	eceived by the private fi	re brigade:	AN	INUAL		
Type of public fire dep	artment:	null	Di	stance:	1/4	MILE/FIRE BRIGADE

Description:

## Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet): FOOD SERVICE/SUPPORT BUILD/GYM

How far is the body of water from major buildings?

Is there a body of water nearby?

Previous history of flooding? Description: Ν Description:

Ν

Any property damage losses in the past 3 years: N

						- 3 -			
			Pro	perty Detail Form					
Agency:	DEPARTMENT OF CORR	ECTIONS / DEPARTMENT OF COR	RECTION	S, STATE PRISON					
Property:	Unit B Housing								
Property Address:	400 Conley Lake Rd DEEF	R LODGE							
Property ID:	1P(B)								
Construction:									
Total number of insured	l buildings:	1		Total square footage of insured buildings:	19415				
Year built:		1976		Number of stories:	3				
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete	•			
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board				
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Jail						
Provide a brief descripti	on of operations:		INMATE	INMATE HOUSING/MANAGEMENT STAFF HOUSING					
Storage height of warehoused products:		N/A							
Are flammable and combustible liquids stored in a cut-off room?		N							
Safegaurds taken for the storage and dispensing of flammable liquids:		N							
Protection:									
Are there any automatic	sprinklers?	N	,	What are the design densities for each area?					
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	4				
Indicate the Alarm Cove	rages provided for your fac	cility:	;	Smoke Detectors					
Are alarms connected to	o a constantly attended loca	ation?		Y					
Is there a watchman ser	vice?	Υ	,	What is the frequency of rounds?	1	HOUR			
Are watchman recording	g rounds?			Y					
Are there any fire exting	juishers?	Υ		Are they serviced annually?	Υ				
Are there any hose stati	ons?	N		Is there a fire private fire brigade?	Υ				
Frequency of training re	eceived by the private fire b	rigade:		ANNUAL					
Type of public fire depa	rtment:	null		Distance:	1/	/4 MILE/FIRE BRIGADE			
Exposure:									
How many buildings(no	t part of Account) are within	n 100 feet of insured buildings?	6						
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):	FOOD S	ERVICE/INMAGE HOUSING					
Is there a body of water	nearby?	N	Descript	tion:					
How far is the body of w	ater from major buildings?								
Previous history of floo	ding?	N	Descript	tion:					
Any property damage lo	sses in the past 3 years:	N	Descript	tion:					

						i age s			
			Pro	perty Detail Form					
Agency:	DEPARTMENT OF CORF	ECTIONS / DEPARTMENT OF COR	RRECTIONS	S, STATE PRISON					
Property:	Unit C Housing								
Property Address:	400 Conley Lake Rd DEE	RLODGE							
Property ID:	1P(C)								
Construction:									
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	19415				
Year built:		1976		Number of stories:	3				
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete				
Construction of exteri	or walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Board				
Do major interior mas	onry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Jail						
Provide a brief descrip	otion of operations:		INMATE	INMATE & STAFF HOUSING					
Storage height of warehoused products:			N/A						
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the storage and dispensing of flammable liquids:		N							
Protection:									
Are there any automat	tic sprinklers?	N	1	Nhat are the design densities for each area?					
The water supply for a	automatic sprinklers is?		H	How many hydrants are located within 500 feet of buildings?	4				
Indicate the Alarm Co	verages provided for your fa	cility:	S	Smoke Detectors					
Are alarms connected	to a constantly attended loc	ation?	١	1					
Is there a watchman s	ervice?	Υ	1	What is the frequency of rounds?	1 HOUR				
Are watchman recordi	ing rounds?		١	(					
Are there any fire exti	nguishers?	Υ	,	Are they serviced annually?	Υ				
Are there any hose sta	ations?	N	I	s there a fire private fire brigade?	Υ				
Frequency of training	received by the private fire b	rigade:	A	ANNUAL					
Type of public fire dep	partment:	null	Ι	Distance:	1/4 MILE/FIRE BRIGA	DE			
Exposure:									
How many buildings(r	not part of Account) are withi	n 100 feet of insured buildings?	6						
Describe the Occupan	cy of those buildings(s) nea	by (within 100 feet):	FOOD SI	ERVICE/INMATE HOUSING					
Is there a body of water	er nearby?	N	Descript	ion:					
How far is the body of	water from major buildings?	•							
Previous history of flo	oding?	N	Descript	ion:					
Any property damage	losses in the past 3 years:	N	Descript	ion:					

Spring run-off through large shop doors, filled floor drain system. No damage other than clean-up

							Page
				Property Detail Form			
Agency:	DEPARTMENT OF CO	RRECTIONS / DEPARTMENT OF COI	RRECTION	ONS, PRISON INDUSTRIES			
Property:	Vocational Education M	VM Addition					
Property Address:	600 Conley Lake Rd DE	EER LODGE					
Property ID:							
Construction:							
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	5000		
Year built:		blank		Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Cor	ncrete	
Construction of exteri	or walls:	Corrugated Metal Panel		Construction of interior walls:	No Interior Wall	ls	
Do major interior mas	onry walls (fire walls) exte	nd above the roofline?		N			
Occupancy:							
Occupancy Type:		Gara	Sarage, Service Center				
Provide a brief description of operations:		vehic	le & equipment maintenance and training				
Storage height of warehoused products:		0					
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ					
Protection:							
Are there any automat	tic sprinklers?	N		What are the design densities for each area?		no sprinklers	
The water supply for a	nutomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		1	
Indicate the Alarm Co	verages provided for your	facility:		Smoke Detectors			
Are alarms connected	to a constantly attended I	ocation?		Υ			
Is there a watchman s	ervice?	N		What is the frequency of rounds?			
Are watchman recordi	ing rounds?						
Are there any fire exti	nguishers?	Υ		Are they serviced annually?		Υ	
Are there any hose sta	ations?	N		Is there a fire private fire brigade?		Υ	
Frequency of training	received by the private fire	e brigade:		regularly			
Type of public fire dep	partment:	Voluntary		Distance:		3 & 1/2 miles	
Exposure:							
How many buildings(r	not part of Account) are wi	thin 100 feet of insured buildings?	2				
Describe the Occupan	cy of those buildings(s) ne	earby (within 100 feet):	manufacturing & food service				
Is there a body of water	er nearby?	N	Desc	ription:			
How far is the body of	water from major building	js?					

Description:

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

Υ

Property Detail Form							
Agency:	DEPARTMENT OF CORRE	ECTIONS / DEPARTMENT OF CORF	RECTIONS, ST	TATE PRISON			
Property:	Wallace Administration Buil	lding					
Property Address:	400 Conley Lake Rd DEER	RLODGE					
Property ID:	15P						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	23838		
Year built:		1979		Number of stories:	2		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concret	te	
Construction of exterior v	valls:	Tilt-Up Concrete		Construction of interior walls:	Gypsum Board		
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N			
Occupancy:							
Occupancy Type:			Office				
Provide a brief description of operations:			OFFICES				
Storage height of warehoused products:			N/A				
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		N					
Protection:							
Are there any automatic s	sprinklers?	Υ	Wha	t are the design densities for each area?			
The water supply for auto	matic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	<b>!</b>	4	
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow, Burglar Alarms (Door Contacts)				
Are alarms connected to	a constantly attended loca	ation?	Υ				
Is there a watchman servi	ice?	Υ	Wha	t is the frequency of rounds?		1 HOUR	
Are watchman recording	rounds?		Υ				
Are there any fire extingu	ishers?	Υ	Are t	hey serviced annually?	,	Υ	
Are there any hose statio	ns?	N	Is the	ere a fire private fire brigade?	,	Υ	
Frequency of training rec	eived by the private fire br	rigade:	ANN	UAL			
Type of public fire depart	ment:	null	Dista	ince:		1/2 MILE/PAID EMPLOYEES	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	2				
Describe the Occupancy of those buildings(s) nearby (within 100 feet):		by (within 100 feet):	INMATE HOL	JSING/GYM			
Is there a body of water n	earby?	N	Description:				
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Description:				
Any property damage los	ses in the past 3 years:	N	Description:				

			P	roperty D	Detail Form			
Agency:	DEPARTMENT OF CORR	RECTIONS / DEPARTMENT OF COR	RECTIO	NS, STATE	E PRISON			
Property:	Work Dorm/Expansion							
Property Address:	400 Conley Lake Rd DEEI	R LODGE						
Property ID:	24P							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	30932		
Year built:		1995			Number of stories:	2		
Construction of roof:		Wood Joists			Construction of floors:	Poured Conc	rete	
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			Υ			
Occupancy:								
Occupancy Type:			Jail					
Provide a brief description	on of operations:		Inmate	housing				
Storage height of wareho	oused products:		0					
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for the	storage and dispensing o	of flammable liquids:	N					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	e the design densities for each area?		1 hr - 2008 addition	
The water supply for aut	omatic sprinklers is?	Public		How mai	ny hydrants are located within 500 feet of buildings	?	2	
Indicate the Alarm Cover	ages provided for your fac	cility:		Smoke D	Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loc	ation?		Υ				
ls there a watchman serv	rice?	Υ		What is t	the frequency of rounds?		1 hr	
Are watchman recording	rounds?			Υ				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		Υ	
Frequency of training red	ceived by the private fire b	rigade:		annual ex	xtinguisher trng			
Type of public fire depar	tment:	null		Distance	e:		blank	
Exposure:								
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):						
ls there a body of water i	nearby?	N	Descri	ption:				
How far is the body of wa	ater from major buildings?	•						
Previous history of flood	ling?	N	Descri	ption:				
Any property damage los	sses in the past 3 years:	N	Descri	ption:				

Lined pond/Acidic water

N/A

N/A

						i age a
			F	Property Detail Form		
Agency:	DEPARTMENT OF EN	NVIRONMENTAL QUALITY / DEPARTM	MENT OF	ENVIRONMENTAL QUALITY		
Property:	Landusky Upper Ware	ehouse				
Property Address:	Landusky Mine-Landu	sky Route-Landusky City ZORTMAN				
Property ID:						
Construction:						
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	11500	
Year built:		1985		Number of stories:	1	
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete	
Construction of exteri	or walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board	
Do major interior mase	onry walls (fire walls) ext	end above the roofline?		null		
Occupancy:						
Occupancy Type:			Quon	set Warehouse		
Provide a brief description of operations:			Shop/	Office/Warehouse		
Storage height of warehoused products:			some	7' metal bin/shelves		
Are flammable and combustible liquids stored in a cut-off room?		N				
Safegaurds taken for t	he storage and dispensi	ng of flammable liquids:	Υ			
Protection:						
Are there any automat	ic sprinklers?	N		What are the design densities for each area?	n/a	
The water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	0	
Indicate the Alarm Cov	verages provided for you	r facility:		Smoke Detectors		
Are alarms connected	to a constantly attended	location?		N		
ls there a watchman se	ervice?	N		What is the frequency of rounds?	N/A	
Are watchman recordi	ng rounds?			N		
Are there any fire extir	nguishers?	Υ		Are they serviced annually?	Υ	
Are there any hose sta	tions?	N		Is there a fire private fire brigade?	N	
Frequency of training	received by the private fi	re brigade:		N/A		
Type of public fire dep	artment:	Voluntary		Distance:	70 Miles	
Exposure:						
How many buildings(n	ot part of Account) are w	vithin 100 feet of insured buildings?	0			
Describe the Occupan	cy of those buildings(s)	nearby (within 100 feet):	NI/A			

Description:

Description:

Description:

7200 ft

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Υ

Ν

			Prop	perty Detail Form			
Agency:	DEPARTMENT OF FISH, V	WILDLIFE & PARKS / DEPARTMENT	Γ OF FISH,	WILDLIFE & PARKS			
Property:	1) Regional HQ - Building						
Property Address:	490 N Meridian Rd KALISF	PELL					
Property ID:	100500						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	16545		
Year built:		1990		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Poured Concre	rete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Governme	ental Building			
Provide a brief description of operations:			governmental offices				
Storage height of warehoused products:		n/a					
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A				
Protection:							
Are there any automatic	sprinklers?	N	W	What are the design densities for each area?		n/a	
The water supply for auto	omatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings?	?	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	ation?	N	I			
ls there a watchman serv	vice?	N	W	Vhat is the frequency of rounds?			
Are watchman recording	rounds?		N	I			
Are there any fire exting	uishers?	Υ	Α	re they serviced annually?		Υ	
Are there any hose station	ons?	N	Is	s there a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	D	listance:		1 mile	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
ls there a body of water i	nearby?	N	Description	on:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ling?	null	Description	on:			
Any property damage los	sses in the past 3 years:	N	Description	on:			

						Page 9			
			Proj	perty Detail Form					
Agency:	DEPARTMENT OF FISH,	WILDLIFE & PARKS / DEPARTMEN	IT OF FISH,	WILDLIFE & PARKS					
Property:	2) Regional HQ - Building								
Property Address:	3201 Spurgin Rd MISSOU	ILA							
Property ID:	200751								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	10296				
Year built:		1981		Number of stories:	2				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete				
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board				
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null					
Occupancy:									
Occupancy Type:			Governme	ental Building					
Provide a brief descripti	on of operations:		governme	governmental offices					
Storage height of wareh	oused products:		n/a						
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	N	v	What are the design densities for each area?	n/a				
The water supply for aut	omatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings?	blank				
Indicate the Alarm Cove	rages provided for your fac	cility:	S	Smoke Detectors					
Are alarms connected to	a constantly attended loc	ation?	N	I					
ls there a watchman ser	vice?	N	V	What is the frequency of rounds?					
Are watchman recording	g rounds?		N	I					
Are there any fire exting	uishers?	Υ	A	are they serviced annually?	Υ				
Are there any hose stati	ons?	N	ls	s there a fire private fire brigade?	N				
Frequency of training re	ceived by the private fire b	rigade:							
Type of public fire depar	rtment:	Paid	D	Distance:	blank				
Exposure:									
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	blank						
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):							
Is there a body of water	nearby?	N	Descripti	on:					
How far is the body of w	ater from major buildings?	•							
Previous history of flood	ding?	N	Descripti	on:					
Any property damage lo	sses in the past 3 years:	null	Descripti	on:					

CREEK AND POND

					i age			
			Prope	rty Detail Form				
Agency:	DEPARTMENT OF FISH,	WILDLIFE & PARKS / DEPARTMEN	T OF FISH, W	ILDLIFE & PARKS				
Property:	2) Washoe Park Hatchery	- Building						
Property Address:	600 West Pennsylvania St	ANACONDA						
Property ID:	210157							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	7728			
Year built:		1998		Number of stories:	1			
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete			
Construction of exterior	of exterior walls: Corrugated Metal Panel			Construction of interior walls:	Masonry			
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Hatchery					
Provide a brief description of operations:			TROUT HAT	CHERY				
Storage height of warehoused products:			NA					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the	e storage and dispensing of	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N	Wha	at are the design densities for each area?				
The water supply for aut	omatic sprinklers is?		Hov	v many hydrants are located within 500 feet of buildings?	? 36			
Indicate the Alarm Cover	rages provided for your fac	ility:	Smo	oke Detectors				
Are alarms connected to	a constantly attended loca	ation?	N					
Is there a watchman serv	vice?	N	Wha	at is the frequency of rounds?				
Are watchman recording	g rounds?		N					
Are there any fire exting	uishers?	Υ	Are	they serviced annually?	Υ			
Are there any hose static	ons?	N	ls th	nere a fire private fire brigade?	N			
Frequency of training re-	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid	Dist	rance:	2 MILES			
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank					
Describe the Occupancy of those buildings(s) nearby (within 100 feet):								

Description:

Description:

Description:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

						1 490 10
			Pi	roperty Detail Form		
Agency:	DEPARTMENT OF FISH,	WILDLIFE & PARKS / DEPARTM	IENT OF FIS	SH, WILDLIFE & PARKS		
Property:	3) Regional HQ - Building					
Property Address:	1400 South 19th BOZEMA	AN				
Property ID:	300154					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	17292	
Year built:		1987		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterior	r walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Govern	nmental Building		
Provide a brief description of operations:			govern	mental offices		
Storage height of warehoused products:			n/a			
Are flammable and com	bustible liquids stored in a	cut-off room?	N			
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automation	sprinklers?	N		What are the design densities for each area?	n/a	
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	P blank	
Indicate the Alarm Cove	erages provided for your fac	eility:		Smoke Detectors		
Are alarms connected to	o a constantly attended loca	ation?		N		
ls there a watchman ser	rvice?	N		What is the frequency of rounds?		
Are watchman recording	g rounds?			N		
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?	N	
Frequency of training re	eceived by the private fire b	rigade:				
Type of public fire depa	rtment:	Paid		Distance:	blank	
Exposure:						

How many buildings(not part of Account) are within 100 feet of insured buildings?

blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet): Is there a body of water nearby?

How far is the body of water from major buildings?

Description:

Previous history of flooding?

Description:

Any property damage losses in the past 3 years: N

Ν

Ν

Description:

								1 490 102
			Pı	roperty D	Detail Form			
Agency:	DEPARTMENT OF FISH,	WILDLIFE & PARKS / DEPARTMEN	T OF FIS	H, WILDLI	IFE & PARKS			
Property:	3) Regional HQ - Building	- Lab/Shop						
Property Address:	1400 South 19th BOZEMA	N						
Property ID:	300162							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	8087		
Year built:		1988			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Poured Conc	rete	
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			null			
Occupancy:								
Occupancy Type:			Labora	tory				
Provide a brief description of operations:			lab / sh	ор				
Storage height of warehoused products:			n/a					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?		n/a	
The water supply for aut	omatic sprinklers is?	Public		How mai	ny hydrants are located within 500 feet of buildings	?	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:		Smoke D	Detectors			
Are alarms connected to	a constantly attended loca	ation?		N				
ls there a watchman serv	rice?	N		What is t	the frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose station	ons?	N		Is there	a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid		Distance	e:		blank	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Descri	ption:				
How far is the body of w	ater from major buildings?							
Previous history of flood	ling?	N	Descri	ption:				
Any property damage lo	sses in the past 3 years:	N	Descri	ption:				

			Pro	perty Detail Form	
gency:	DEPARTMENT OF FISH, V	VILDLIFE & PARKS / DEPARTMENT	OF FISH	, WILDLIFE & PARKS	
Property:	4) First Peoples Buffalo Jun	np SP - Building - Visitor Center			
Property Address:	10 mi S of GF I-15, Ulm exit	t, 3.5 mi NW Vaughn Rd GREAT FAL	LS		
roperty ID:	454852				
Construction:					
otal number of insured l	buildings:	1		Total square footage of insured buildings: 65	516
ear built:		1999		Number of stories:	
Construction of roof:		Wood Joists		Construction of floors: Po	oured Concrete
Construction of exterior v	walls:	Wood Frame		Construction of interior walls: Gy	ypsum Board
o major interior masonr	y walls (fire walls) extend a	bove the roofline?		null	
Occupancy:					
Occupancy Type:			Museum		
Provide a brief description of operations:			visitor ce	nter-public	
Storage height of warehoused products:			n/a		
are flammable and combustible liquids stored in a cut-off room?			N/A		
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A		
Protection:					
are there any automatic s	sprinklers?	N	,	What are the design densities for each area?	
he water supply for auto	omatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?	blank
ndicate the Alarm Covera	ages provided for your faci	lity:	I	Burglar Alarms (Door Contacts), Smoke Detectors	
are alarms connected to	a constantly attended loca	tion?	ļ	N	
s there a watchman serv	ice?	N	,	What is the frequency of rounds?	
are watchman recording	rounds?		I	N	
are there any fire extingu	ishers?	Υ		Are they serviced annually?	Υ
are there any hose statio	ns?	N	I	Is there a fire private fire brigade?	N
requency of training rec	eived by the private fire bri	igade:			
ype of public fire depart	ment:	Paid	l	Distance:	blank
exposure:					
low many buildings(not	part of Account) are within	100 feet of insured buildings?	blank		

Description:

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

						Page 10
			Pr	operty Detail Form		
agency:	DEPARTMENT OF FISH,	WILDLIFE & PARKS / DEPARTMEN	NT OF FIS	H, WILDLIFE & PARKS		
Property:	4) Regional HQ - Building					
Property Address:	4600 Giant Springs Rd GR	EAT FALLS				
Property ID:	400352					
Construction:						
otal number of insured	buildings:	1		Total square footage of insured buildings:	8858	
ear built:		1987		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
o major interior mason	nry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Govern	mental Building		
rovide a brief descripti	on of operations:		governi	mental offices		
storage height of wareh	oused products:		n/a			
re flammable and comi	bustible liquids stored in a	cut-off room?	N/A			
afegaurds taken for the	e storage and dispensing of	f flammable liquids:	N/A			
Protection:						
re there any automatic	sprinklers?	N		What are the design densities for each area?	n/a	
he water supply for aut	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank	
ndicate the Alarm Cove	rages provided for your fac	sility:		Smoke Detectors		
are alarms connected to	a constantly attended loca	ation?		N		
s there a watchman ser	vice?	N		What is the frequency of rounds?		
are watchman recording	g rounds?			N		
are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
are there any hose stati	ons?	N		Is there a fire private fire brigade?	N	
requency of training re	ceived by the private fire b	rigade:				
vne of nublic fire dena	rtment:	Paid		Distance:	hlank	

blank

Description:

Description:

Description:

**Exposure:** 

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

						Page 10		
			Propert	y Detail Form				
Agency:	DEPARTMENT OF FISH,	WILDLIFE & PARKS / DEPARTMEN	NT OF FISH, WIL	DLIFE & PARKS				
Property:	5) Regional HQ - Building							
Property Address:	2300 Lake Elmo Dr BILLIN	IGS						
Property ID:	501200							
Construction:								
Total number of insure	d buildings:	1		Total square footage of insured buildings:	8023			
Year built:		1989		Number of stories:	1			
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete			
Construction of exterio	kterior walls: Wood Frame			Construction of interior walls:	Gypsum Board			
Do major interior masonry walls (fire walls) extend above the roofline?			null					
Occupancy:								
Occupancy Type:			Governmental	Building				
Provide a brief description of operations:			governmental	governmental offices				
Storage height of warehoused products:			n/a					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for tl	ne storage and dispensing o	f flammable liquids:	Υ					
Protection:								
Are there any automati	c sprinklers?	N	What	are the design densities for each area?	n/a			
The water supply for a	utomatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildin	i <b>gs?</b> blank			
Indicate the Alarm Cov	erages provided for your fac	ility:	Burglar Alarms (Motion Detection), Burglar Alarms (Door Contacts), Smoke Detectors					
Are alarms connected	to a constantly attended loca	ation?	Υ					
Is there a watchman se	rvice?	N	What	is the frequency of rounds?				
Are watchman recording	ng rounds?		N					
Are there any fire extin	guishers?	Υ	Are ti	ney serviced annually?	Υ			
Are there any hose sta	tions?	N	Is the	ere a fire private fire brigade?	N			
Frequency of training r	eceived by the private fire b	rigade:						
Type of public fire dep	artment:	Paid	Dista	nce:	blank			
Exposure:								
How many buildings(n	ot part of Account) are within	n 100 feet of insured buildings?	2					
Describe the Occupand	y of those buildings(s) near	by (within 100 feet):	storage					
Is there a body of wate	r nearby?	Υ	Description:		small urban reservoir			
How far is the body of	water from major buildings?		30 feet					
Previous history of floo	oding?	N	Description:					
Any property damage I	osses in the past 3 years:	N	Description:					

			Prop	erty Detail Form			
Agency:	DEPARTMENT OF FISH, V	WILDLIFE & PARKS / DEPARTMENT	ΓOF FISH, V	WILDLIFE & PARKS			
Property:	6) Regional HQ - Building						
Property Address:	1 Airport Rd GLASGOW						
Property ID:	600251						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	4369		
Year built:		1986		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Boar	rd	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Governmen	ntal Building			
Provide a brief description of operations:			governmental offices				
Storage height of warehoused products:			n/a				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A					
Protection:							
Are there any automatic	sprinklers?	N	W	hat are the design densities for each area?		n/a	
The water supply for auto	omatic sprinklers is?		Но	ow many hydrants are located within 500 feet of buildings	?	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:	Sn	noke Detectors			
Are alarms connected to	a constantly attended loca	ition?	N				
Is there a watchman serv	rice?	N	W	hat is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire extingu	uishers?	Υ	Ar	e they serviced annually?		Υ	
Are there any hose station	ons?	N	Is	there a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:					
Type of public fire depart	tment:	Paid	Di	stance:		blank	
Exposure:							
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water r	nearby?	N	Descriptio	n:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Descriptio	on:			
Any property damage los	sses in the past 3 years:	N	Descriptio	n:			

		_					
		Property	Detail Form				
Agency: DEPARTMENT OF FISH	, WILDLIFE & PARKS / DEPARTME	NT OF FISH, WILD	DLIFE & PARKS				
<b>Property:</b> 7) Regional HQ - Building	l						
Property Address: 352 I-94 Business Loop N	MILES CITY						
<b>Property ID:</b> 700652							
Construction:							
Total number of insured buildings:	1		Total square footage of insured buildings:	12612			
Year built:	1991		Number of stories:	2			
Construction of roof:	Wood Joists		Construction of floors:	Poured Concrete			
Construction of exterior walls:	Wood Frame		Construction of interior walls:	Gypsum Board			
Do major interior masonry walls (fire walls) extend	d above the roofline?		null				
Occupancy:							
Occupancy Type:		Governmental	Building				
Provide a brief description of operations:		governmental o	governmental offices				
Storage height of warehoused products:		n/s					
Are flammable and combustible liquids stored in a	a cut-off room?	N/A					
Safegaurds taken for the storage and dispensing	of flammable liquids:	N/A					
Protection:							
Are there any automatic sprinklers?	N	What a	are the design densities for each area?	none			
The water supply for automatic sprinklers is?	Public	How n	nany hydrants are located within 500 feet of buildings	s? 1			
Indicate the Alarm Coverages provided for your fa	acility:	Burgla	r Alarms (Door Contacts), Smoke Detectors				
Are alarms connected to a constantly attended loo	cation?	N					
Is there a watchman service?	N	What i	s the frequency of rounds?				
Are watchman recording rounds?		N					
Are there any fire extinguishers?	Υ	Are th	ey serviced annually?	Υ			
Are there any hose stations?	N	Is ther	e a fire private fire brigade?	N			
Frequency of training received by the private fire	brigade:						
Type of public fire department:	Paid	Distan	ce:	blank			
Exposure:							
How many buildings(not part of Account) are with	in 100 feet of insured buildings?	2					
Describe the Occupancy of those buildings(s) near	arby (within 100 feet):	storage					
Is there a body of water nearby?	Υ	Description:		tongue river			
How far is the body of water from major buildings	?	half mile					
Previous history of flooding?	N	Description:					
Any property damage losses in the past 3 years:	N	Description:					

			FI	operty Detail Form			
gency:	DEPARTMENT OF JUSTIC	CE / DEPARTMENT OF JUSTICE					
roperty:	Butte Justice Center						
Property Address:	3615 Wynn St BUTTE						
roperty ID:							
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	18808		
ear built:		2014		Number of stories:	2		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
o major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Office				
Provide a brief description of operations:			blank				
Storage height of warehoused products:			blank				
re flammable and combustible liquids stored in a cut-off room?			null				
afegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
are there any automatic	sprinklers?	Υ		What are the design densities for each area?			
he water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		blank	
ndicate the Alarm Cover	ages provided for your fac	ility:		blank			
are alarms connected to	a constantly attended loca	ition?		null			
s there a watchman serv	rice?	null		What is the frequency of rounds?			
are watchman recording	rounds?						
are there any fire extingu	uishers?	null		Are they serviced annually?		null	
are there any hose station	ons?	null		Is there a fire private fire brigade?		null	
requency of training red	ceived by the private fire br	igade:					
ype of public fire depar	tment:	null		Distance:		blank	
xposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
escribe the Occupancy	of those buildings(s) nearl	by (within 100 feet):					
s there a body of water i	nearby?	null	Descri	tion:			
low far is the body of wa	ow far is the body of water from major buildings?						
revious history of flood	ing?	null	Descri	ition:			
any property damage los	sses in the past 3 years:	null	Descri	tion:			

			Pr	roperty Detail Form		
Agency:	DEPARTMENT OF JUSTION	CE / DEPARTMENT OF JUSTICE				
Property:	FSD - Forensics, Missoula	a e				
Property Address:	2679 Palmer Street MISSO	DULA				
Property ID:	LE 4163					
Construction:						
Γotal number of insured	buildings:	1		Total square footage of insured buildings:	31145	
ear built:		2000		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Masonry w/ F	Fire Doors
Oo major interior mason	ry walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			Labora	tory		
Provide a brief description	on of operations:		Forens	ic Science Lab		
Storage height of wareh	oused products:		N/A			
Are flammable and comb	oustible liquids stored in a	cut-off room?	Υ			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		Entire Building
The water supply for aut	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings	?	3
ndicate the Alarm Cover	rages provided for your fac	cility:		Burglar Alarms (Motion Detection), Sprinkler Valve Tamper, Sprinkler	inkler Waterflow	· ·
Are alarms connected to	a constantly attended loca	ation?		Υ		
s there a watchman serv	vice?	N		What is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ
Are there any hose station	ons?	N		Is there a fire private fire brigade?		null
requency of training re	ceived by the private fire b	rigade:				
Type of public fire depar	tment:	Paid		Distance:		3 Blocks
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	2			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	State/F	ed Offices		
s there a body of water	nearby?	Υ	Descri	ption:	Clark Fork Riv	ver
How far is the body of w	ater from major buildings?		.5 Miles	S		
Previous history of flood	ling?	N	Descri	ption:		
Any property damage lo	sses in the past 3 years:	N	Descri	ption:		

			Pr	operty D	etail Form			
gency:	DEPARTMENT OF JUSTIC	E / DEPARTMENT OF JUSTICE						
Property:	GCD/MHP/MVD/DCI Confid	dential, Billings						
roperty Address:	615 South 27th St. Box 310	94 BILLINGS						
roperty ID:	LE 4159							
Construction:								
otal number of insured b	ouildings:	1			Total square footage of insured buildings:	26376		
ear built:		blank			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Poured Concre	ete	
Construction of exterior v	valls:	Wood Frame			Construction of interior walls:	Gypsum Board	d	
o major interior masonr	y walls (fire walls) extend a	above the roofline?			N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief descriptio	n of operations:		OFFICE	MHP				
storage height of wareho	used products:		N/A					
are flammable and comb	ustible liquids stored in a c	cut-off room?	N					
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
are there any automatic s	sprinklers?	N		What are	the design densities for each area?			
he water supply for auto	matic sprinklers is?			How man	ny hydrants are located within 500 feet of buildings?		4	
ndicate the Alarm Covera	ages provided for your faci	lity:		Smoke D	etectors			
are alarms connected to	a constantly attended loca	tion?		N				
s there a watchman servi	ice?	N		What is t	he frequency of rounds?			
are watchman recording	rounds?							
are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ	
are there any hose station	ns?	N		Is there a	a fire private fire brigade?		N	
requency of training rec	eived by the private fire br	igade:						
ype of public fire depart	ment:	Paid		Distance	:		ONE BLOCK	
xposure:								
low many buildings(not p	part of Account) are within	100 feet of insured buildings?	0					
escribe the Occupancy	of those buildings(s) neark	y (within 100 feet):						
s there a body of water n	earby?	N	Descrip	otion:				
low far is the body of wa	ter from major buildings?							
revious history of floodi	ng?	N	Descrip	otion:				
any property damage los	ses in the past 3 years:	N	Descrip	otion:				

			Pr	operty Detail Form			
gency:	DEPARTMENT OF JUSTIC	CE / DEPARTMENT OF JUSTICE					
roperty:	ITSD - HAFRC DOJ FUSIC	ON Center					
Property Address:	1956 Mt. Majo St / Fort Hai	rrison HELENA					
roperty ID:	LE						
Construction:							
otal number of insured l	buildings:	1		Total square footage of insured buildings:	700		
ear built:		blank		Number of stories:	2		
Construction of roof:		Steel Deck		Construction of floors:	Reinforced C	Concrete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Boar	rd	
o major interior masonr	ry walls (fire walls) extend	above the roofline?		Υ			
Occupancy:							
Occupancy Type:			Govern	mental Building			
Provide a brief description	on of operations:		State &	Federal Govt			
storage height of wareho	oused products:		N/A				
are flammable and comb	oustible liquids stored in a	cut-off room?	N/A				
afegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A				
Protection:							
are there any automatic	sprinklers?	Υ		What are the design densities for each area?			
he water supply for auto	omatic sprinklers is?	Private		How many hydrants are located within 500 feet of buildings	?	4	
ndicate the Alarm Cover	ages provided for your fac	ility:		Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Va	ılve Tamper, Spr	rinkler Waterflow	
are alarms connected to	a constantly attended loca	ation?		Υ			
s there a watchman serv	rice?	Υ		What is the frequency of rounds?		24X7 Continually	
are watchman recording	rounds?			Υ			
are there any fire extingu	uishers?	Υ		Are they serviced annually?		Υ	
are there any hose statio	ons?	N		Is there a fire private fire brigade?		Υ	
requency of training rec	ceived by the private fire b	rigade:		Annually			
ype of public fire depart	tment:	Paid		Distance:		On site	
xposure:							
low many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0				
escribe the Occupancy	of those buildings(s) near	by (within 100 feet):					
s there a body of water n	nearby?	N	Descrip	otion:			
low far is the body of wa	ater from major buildings?						
revious history of flood	ing?	N	Descrip	otion:			
any property damage los	sses in the past 3 years:	N	Descrip	otion:			

			Pi	operty Detail Form			
Agency:	DEPARTMENT OF JUSTI	CE / DEPARTMENT OF JUSTICE					
Property:	MHP - Dist #1 Hdqtrs, Miss	soula					
Property Address:	2681 Palmer MISSOULA						
Property ID:	LE 4164						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	18905		
Year built:		blank		Number of stories: 2	2		
Construction of roof:		null		Construction of floors:	null		
Construction of exterio	r walls:	null		Construction of interior walls:	null		
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Office				
Provide a brief descript	ion of operations:		blank				
Storage height of wareh	noused products:		blank				
Are flammable and com	bustible liquids stored in a	cut-off room?	null				
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	null				
Protection:							
Are there any automation	sprinklers?	N		What are the design densities for each area?			
Γhe water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		blank	
ndicate the Alarm Cove	erages provided for your fac	cility:		blank			
Are alarms connected t	o a constantly attended loca	ation?		null			
s there a watchman se	rvice?	null		What is the frequency of rounds?			
Are watchman recordin	g rounds?						
Are there any fire exting	guishers?	null		Are they serviced annually?		null	
Are there any hose stat	ions?	null		Is there a fire private fire brigade?		null	
requency of training re	eceived by the private fire b	rigade:					
Гуре of public fire depa	rtment:	null		Distance:		blank	
Exposure:							
How many buildings(no	ot part of Account) are within	n 100 feet of insured buildings?	blank				
Describe the Occupanc	y of those buildings(s) near	by (within 100 feet):					
s there a body of water	nearby?	null	Descri	otion:			
How far is the body of v	vater from major buildings?						
Previous history of floo	ding?	null	Descri	otion:			
Any property damage lo	osses in the past 3 years:	null	Descri	otion:			

			Pro	operty Detail Form			
gency:	DEPARTMENT OF JUSTIC	CE / DEPARTMENT OF JUSTICE					
Property:	MHP/GCD-, Helena						
Property Address:	2550 Prospect HELENA						
roperty ID:	LE 4157						
construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	22678		
ear built:		blank		Number of stories:	1		
construction of roof:		Other		Construction of floors:	Reinforced Co	oncrete	
onstruction of exterior	walls:	Wood Frame		Construction of interior walls:	Other		
o major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
ccupancy Type:			Office				
rovide a brief description	on of operations:		OFFICE	STORAGE/MAINTENANCE			
torage height of wareho	oused products:		N/A				
re flammable and comb	oustible liquids stored in a	cut-off room?	N/A				
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
re there any automatic	sprinklers?	N		What are the design densities for each area?		UNKNOWN	
he water supply for aut	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	•	0	
ndicate the Alarm Cover	ages provided for your fac	ility:		Smoke Detectors, Sprinkler Waterflow			
re alarms connected to	a constantly attended loca	tion?		N			
s there a watchman serv	vice?	N		What is the frequency of rounds?			
re watchman recording	rounds?						
are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ	
are there any hose station	ons?	N		Is there a fire private fire brigade?		null	
requency of training re	ceived by the private fire br	igade:					
ype of public fire depar	tment:	Paid		Distance:		1 MILE	
xposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?	0				
escribe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):					
there a body of water	nearby?	N	Descrip	tion:			
low far is the body of w	ater from major buildings?						
revious history of flood	ling?	N	Descrip	tion:			
ny property damage los	sses in the past 3 years:	N	Descrip	tion:			

			Pro	perty Detail Form		
Agency:	DEPARTMENT OF JUSTIC	CE / DEPARTMENT OF JUSTICE				
Property:	MLEA - Maple Cottage No.	2				
Property Address:	2260 Sierra Rd. East HELE	ENA				
Property ID:	3					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	15665	
ear built:		1920		Number of stories:	3	
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boa	rd
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State Uni	iversity		
Provide a brief description	on of operations:		OFFICES	S AND DORMATORY		
Storage height of wareh	oused products:		N/A			
Are flammable and com	oustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N	V	What are the design densities for each area?		NO SPRINKLERS
The water supply for aut	omatic sprinklers is?		H	How many hydrants are located within 500 feet of buildings	?	3
ndicate the Alarm Cove	rages provided for your fac	ility:	S	Smoke Detectors		
Are alarms connected to	a constantly attended loca	ation?	Υ	Y		
s there a watchman serv	vice?	N	V	What is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire exting	uishers?	Υ	A	Are they serviced annually?		Υ
Are there any hose station	ons?	N	ls	s there a fire private fire brigade?		N
requency of training re	ceived by the private fire bi	rigade:				
Type of public fire depar	tment:	Voluntary		Distance:		2 MILES
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
s there a body of water	nearby?	Υ	Descripti	ion:	CREEK	
How far is the body of w	ater from major buildings?		300 FEET	Т		
Previous history of flood	ling?	Υ	Descripti	ion:	CAMPUS GR	OUNDS NOT BUILDINGS
Any property damage lo	sses in the past 3 years:	N	Descripti	ion:		

			Pro	operty Detail Form	
Agency:	DEPARTMENT OF JUSTIC	E / DEPARTMENT OF JUSTICE			
Property:	MLEA - School Building & A	Administration			
Property Address:	2260 Sierra Rd. East HELE	NA			
Property ID:	4				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	13321
ear built:		1920		Number of stories:	3
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior mason	ry walls (fire walls) extend a	above the roofline?		N	
Occupancy:					
Occupancy Type:			State Un	niversity	
Provide a brief description	on of operations:		Classroo	oms, offices	
Storage height of wareho	oused products:		N/A		
Are flammable and comb	oustible liquids stored in a d	cut-off room?	N/A		
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	3
ndicate the Alarm Cover	ages provided for your faci	ility:		Smoke Detectors	
Are alarms connected to	a constantly attended loca	tion?		Υ	
s there a watchman serv	vice?	N		What is the frequency of rounds?	
Are watchman recording	rounds?				
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose station	ons?	N		Is there a fire private fire brigade?	N
requency of training re	ceived by the private fire br	igade:			
Type of public fire depar	tment:	Voluntary		Distance:	2 Miles
Exposure:					
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank		
Describe the Occupancy	of those buildings(s) nearly	y (within 100 feet):			
s there a body of water	nearby?	Υ	Descrip	tion:	Creek
low far is the body of w	ater from major buildings?		300 feet		
Previous history of flood	ling?	Υ	Descrip	tion:	Campus grounds, no buildings
Any property damage lo	sses in the past 3 years:	N	Descrip	tion:	

			Prope	erty Detail Form	
Agency:	DEPARTMENT OF LABOR	R & INDUSTRY / DEPARTMENT OF I	_ABOR & INI	DUSTRY	
Property:	Billings UI Phone Claims				
Property Address:	624 N 24th St BILLINGS				
Property ID:					
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	12960
Year built:		1958		Number of stories:	2
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior mason	ry walls (fire walls) extend	above the roofline?		Υ	
Occupancy:					
Occupancy Type:			Office		
Provide a brief description	on of operations:		UI PHONE	CLAIMS CENTER GOVT. OFC.	
Storage height of wareho	oused products:		N/A		
Are flammable and comb	oustible liquids stored in a	cut-off room?	N		
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	N	Wh	nat are the design densities for each area?	
The water supply for auto	omatic sprinklers is?		Ho	w many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cover	ages provided for your fac	ility:	Bur	rglar Alarms (Motion Detection), Sprinkler Valve Tamper	
Are alarms connected to	a constantly attended loca	ation?	Υ		
ls there a watchman serv	rice?	N	Wh	nat is the frequency of rounds?	
Are watchman recording	rounds?				
Are there any fire exting	uishers?	Υ	Are	e they serviced annually?	Υ
Are there any hose static	ons?	Υ	ls t	here a fire private fire brigade?	N
Frequency of training red	ceived by the private fire br	rigade:			
Type of public fire depar	tment:	Paid	Dis	stance:	blank
Exposure:					
How many buildings(not	part of Account) are within	100 feet of insured buildings?	6		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	RESIDENTA	AL, APT. COMPLEX GARAGES	
ls there a body of water i	nearby?	N	Description	1:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ling?	N	Description	1:	
Any property damage los	sses in the past 3 years:	N	Description	1:	

1/2 MILE

	Property Detail Fo
Agency:	DEPARTMENT OF LABOR & INDUSTRY / DEPARTMENT OF LABOR & INDUSTRY
Property:	Bozeman Job Service
Property Address:	121 N Willson BOZEMAN

Property Address: 121 N Willson BOZEMAN
---

**Property ID:** 

Construction						
	•					
	r:n	nst	711	Cti	O	n

Total number of insured buildings:	1	Total square footage of insured buildings:	8181

Year built: 1973 Number of stories: **Poured Concrete** Construction of roof: Other Construction of floors:

Construction of exterior walls: Other Construction of interior walls: Gypsum Board

N/A

Do major interior masonry walls (fire walls) extend above the roofline?

#### Occupancy:

**Occupancy Type:** Office

Provide a brief description of operations: GOVT OFFICES TO ASSIST JOB SEEKERS/EMMPLOYERS

Storage height of warehoused products:

Are flammable and combustible liquids stored in a cut-off room? Ν

Safegaurds taken for the storage and dispensing of flammable liquids: N/A

# Protection:

Exposure:

Υ Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? **Public** How many hydrants are located within 500 feet of buildings? 3

Burglar Alarms (Beams), Burglar Alarms (Ultrasound), Burglar Alarms (Door Contacts), Burglar Alarms (Motion Indicate the Alarm Coverages provided for your facility: Detection), Smoke Detectors, Sprinkler Valve Tamper

Distance:

Are alarms connected to a constantly attended location?

Is there a watchman service? Ν What is the frequency of rounds?

Are watchman recording rounds?

Is there a body of water nearby?

Are there any fire extinguishers? Are they serviced annually?

Are there any hose stations? Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

#### Type of public fire department: Paid

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet): RESIDENTIAL, BUSINESS

Ν

How far is the body of water from major buildings?

Description:

Previous history of flooding?

Description:

Any property damage losses in the past 3 years: Description:

Property Detail Form
R & INDUSTRY

			Proper	ty Detail Form				
Agency:	DEPARTMENT OF LABOR	R & INDUSTRY / DEPARTMENT OF	LABOR & IND	USTRY				
Property:	Great Falls Job Service							
Property Address:	1018 7th St S GREAT FAL	LS						
Property ID:	1							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	18576			
Year built:		1971		Number of stories:	3			
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board			
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Office					
Provide a brief description	on of operations:		JOB SERVIC	E OFFICE/GOVT				
Storage height of wareho	oused products:		N/A	N/A				
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ	Wha	t are the design densities for each area?				
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings	? 2			
Indicate the Alarm Cover	ages provided for your fac	ility:	Sprir	nkler Waterflow				
Are alarms connected to	a constantly attended loca	ation?	Υ					
ls there a watchman serv	vice?	N	Wha	t is the frequency of rounds?				
Are watchman recording	rounds?							
Are there any fire extingu	uishers?	Υ	Are	they serviced annually?	Υ			
Are there any hose static	ons?	Υ	ls th	ere a fire private fire brigade?	N			
Frequency of training red	ceived by the private fire br	rigade:						
Type of public fire depart	tment:	Paid	Dista	ance:	1.5 MILES			
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	Υ	Description:		RIVER			
How far is the body of wa	ater from major buildings?		1 MILE					
Previous history of flood	ling?	N	Description:					
Any property damage los	sses in the past 3 years:	Υ	Description:		SEWER BACKUP 11/08. CAUSED BY PROSPECTOR CASINO			

WATER SEEPAGE FLOODING FROM RAIN,

			Property Detail Form							
Agency:	DEPARTMENT OF LAE	EPARTMENT OF LABOR & INDUSTRY / DEPARTMENT OF LABOR & INDUSTRY								
Property:	Helena Job Service									
Property Address:	715 Front St HELENA	715 Front St HELENA								
Property ID:										
Construction:										
Total number of insured buildings:		1	Total square footage of insured buildings:	9400						
Year built:		1974	Number of stories:	3						
Construction of roof:		Wood Joists	Construction of floors:	Reinfor						

 Construction of roof:
 Wood Joists
 Construction of floors:
 Reinforced Concrete

 Construction of exterior walls:
 Reinforced Concrete
 Construction of interior walls:
 Gypsum Board

Construction of exterior walls. Remorted Construction of Interior walls.

Do major interior masonry walls (fire walls) extend above the roofline?

## Occupancy:

Occupancy Type: Office

Provide a brief description of operations: GOVT AGENCY/OFFICES

Storage height of warehoused products: N/A

Are flammable and combustible liquids stored in a cut-off room?

Safegaurds taken for the storage and dispensing of flammable liquids: N/A

## Protection:

Are there any automatic sprinklers? N What are the design densities for each area?

The water supply for automatic sprinklers is? Public How many hydrants are located within 500 feet of buildings? 1

Indicate the Alarm Coverages provided for your facility:

Smoke Detectors

Are alarms connected to a constantly attended location?

Is there a watchman service? null What is the frequency of rounds?

Are watchman recording rounds?

Are there any fire extinguishers?

Y

Are they serviced annually?

Y

Are there any hose stations?

N Is there a fire private fire brigade?

N

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: 1/4 MILE

Description:

Description:

### Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Υ

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

AUTO BODY SHOP, BANK, WAREHOUSE, BUS DEPO, WAREHOUSE

How far is the body of water from major buildings?

Is there a body of water nearby?

Previous history of flooding?

now far is the body of water from major buildings:

SPRINKLERS, WATER TABLE, BOILER BRÉAK

Any property damage losses in the past 3 years: Y Description: MOLD REMEDIATION, CARPET DRYING

			Pr	operty D	etail Form			
Agency:	DEPARTMENT OF LABOR	R & INDUSTRY / DEPARTMENT OF	LABOR 8	& INDUST	RY			
Property:	Kalispell Job Service							
Property Address:	427 1st Ave E KALISPELL							
Property ID:								
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	7900		
Year built:		1956			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			null			
Occupancy:								
Occupancy Type:			Office					
Provide a brief description	on of operations:		GOVT	OFFICES,	MEETING ROOMS, COMPUTER RESOURCE STAT	IONS		
Storage height of wareho	oused products:		N/A					
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?			
The water supply for aut	omatic sprinklers is?	Public		How mai	ny hydrants are located within 500 feet of buildings	?	1	
Indicate the Alarm Cover	ages provided for your fac	ility:		Smoke D	etectors			
Are alarms connected to	a constantly attended loca	ation?		N				
ls there a watchman serv	vice?	null		What is t	the frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid		Distance	r.		1 BLOCK	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	2					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	BUSIN	ESSES				
ls there a body of water i	nearby?	N	Descri	otion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ling?	N	Descri	otion:				
Any property damage los	sses in the past 3 years:	N	Descri	otion:				

						Page 121
			Property	Detail Form		
Agency:	DEPARTMENT OF LABOR	R & INDUSTRY / DEPARTMENT OF	LABOR & INDUS	STRY		
Property:	Missoula 3rd St Job Service	ee				
Property Address:	539 S 3rd St W MISSOUL	A				
Property ID:	1					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	9700	
Year built:		1972		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descrip	tion of operations:		GOVT OFFICE	-EMPLOYMENT EXCHANGE		
Storage height of ware	housed products:		N/A			
Are flammable and cor	nbustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for tl	ne storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automati	c sprinklers?	Υ	What a	re the design densities for each area?		
The water supply for a	utomatic sprinklers is?	Public	How m	nany hydrants are located within 500 feet of buildings?	? 1	
Indicate the Alarm Cov	erages provided for your fac	cility:	Smoke	Detectors, Sprinkler Waterflow		
Are alarms connected	to a constantly attended loca	ation?	N			
Is there a watchman se	rvice?	N	What i	s the frequency of rounds?		
Are watchman recordir	ng rounds?					
Are there any fire extin	guishers?	Υ	Are the	ey serviced annually?	Υ	
Are there any hose sta	tions?	N	Is ther	e a fire private fire brigade?	N	
Frequency of training r	eceived by the private fire b	rigade:				
Type of public fire dep	artment:	Paid	Distan	ce:	1.25 MILES	
Exposure:						
How many buildings(n	ot part of Account) are within	n 100 feet of insured buildings?	5			
Describe the Occupand	cy of those buildings(s) near	by (within 100 feet):	OFFICE, APAR	TMENTS, HOMES		
Is there a body of wate	r nearby?	Υ	Description:		RIVER	
How far is the body of	water from major buildings?		1/2 MILE			
Previous history of floo	oding?	N	Description:			
Any property damage I	osses in the past 3 years:	N	Description:			

					9				
			Pr	roperty Detail Form					
gency:	DEPARTMENT OF MILIT	ARY AFFAIRS / DEPARTMENT OF	MILITARY	/ AFFAIRS					
Property:	Anaconda Armory								
roperty Address:	101 N Polk ANACONDA								
Property ID:	1								
Construction:									
otal number of insured	l buildings:	1		Total square footage of insured buildings:	8817				
ear built:		1970		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete				
construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Openings				
o major interior masor	nry walls (fire walls) extend	above the roofline?		Υ					
Occupancy:									
Occupancy Type:			Govern	nmental Building					
Provide a brief descript	on of operations:		Military	Military - admin, supply storage - army unit					
storage height of wareh	oused products:		8 feet	8 feet					
are flammable and com	bustible liquids stored in a	cut-off room?	N/A						
afegaurds taken for the	e storage and dispensing o	of flammable liquids:	Υ						
Protection:									
are there any automation	sprinklers?	N		What are the design densities for each area?	no sprinklers				
he water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	<b>s?</b> 0				
ndicate the Alarm Cove	rages provided for your fa	cility:		Burglar Alarms (Door Contacts), Burglar Alarms (Motion Detect	tion), Smoke Detectors, Burglar Alarms (Beams)				
are alarms connected to	a constantly attended loc	eation?		Υ					
s there a watchman ser	vice?	N		What is the frequency of rounds?					
re watchman recording	g rounds?			N					
are there any fire exting	juishers?	Υ		Are they serviced annually?	Υ				
are there any hose stati	ons?	N		Is there a fire private fire brigade?	N				
requency of training re	eceived by the private fire b	origade:							
ype of public fire depa	rtment:	Paid		Distance:	blank				
xposure:						ı			
low many buildings(no	t part of Account) are with	in 100 feet of insured buildings?	0						
escribe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):							
s there a body of water	nearby?	Υ	Descri	ption:					
low far is the body of w	vater from maior buildings	?	1/2 mile	9					

Description:

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

Ν

					Pag	je 12
			Pro	perty Detail Form		
gency:	DEPARTMENT OF MILITAR	RY AFFAIRS / DEPARTMENT OF N	/IILITARY A	FFAIRS		
Property:	Billings AFRC					
Property Address:	2915 Gabel Road BILLINGS	3				
Property ID:						
Construction:						
otal number of insured	buildings:	1		Total square footage of insured buildings:	134434	
ear built:		1999		Number of stories:	2	
construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete	
construction of exterior	walls:	Tilt-Up Concrete		Construction of interior walls:	Masonry w/ Fire Doors	
o major interior mason	ry walls (fire walls) extend a	bove the roofline?		N		
Occupancy:						
Occupancy Type:			Governm	ental Building		
Provide a brief description	on of operations:		Military- a	ndmin, supply, storage, army unit		
storage height of wareh	oused products:		8 feet			
are flammable and comb	oustible liquids stored in a c	ut-off room?	Υ			
afegaurds taken for the	e storage and dispensing of	flammable liquids:	Υ			
Protection:						
are there any automatic	sprinklers?	Υ	V	What are the design densities for each area?	0.24	
he water supply for aut	omatic sprinklers is?		F	low many hydrants are located within 500 feet of buildings?	1	
ndicate the Alarm Cove	rages provided for your faci	lity:	E S	Burglar Alarms (Door Contacts), Burglar Alarms (Motion Detection Sprinkler Waterflow	n), Smoke Detectors, Sprinkler Valve Tamper,	
are alarms connected to	a constantly attended locat	ion?	Υ	′		
s there a watchman serv	vice?	N	V	What is the frequency of rounds?		
are watchman recording	g rounds?		١	N		
are there any fire exting	uishers?	Υ	A	Are they serviced annually?	Υ	
are there any hose station	ons?	N	ls	s there a fire private fire brigade?	N	
requency of training re	ceived by the private fire bri	gade:				
ype of public fire depar	tment:	Paid		Distance:	1 mile	
xposure:						
low many buildings(not	part of Account) are within	100 feet of insured buildings?	0			

 Previous history of flooding?
 N
 Description:

 Any property damage losses in the past 3 years:
 Y
 Description:
 sprinkler pipe frozen, broke water main

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

How far is the body of water from major buildings?

Ν

blank

What is the frequency of rounds?

Is there a fire private fire brigade?

Are they serviced annually?

Distance:

0

Description:

Description: Description:

Is there a watchman service?

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

Exposure:

Are watchman recording rounds? Are there any fire extinguishers?

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Paid

Ν

Ν

<b>Property Detail Form</b>	
ARY AFFAIRS	

			Pr	operty D	etail Form			
Agency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF M	IILITARY	AFFAIRS				
Property:	Butte Armory							
Property Address:	600 Gilman St BUTTE							
Property ID:	1							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	12873		
Year built:		2000			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Poured Conc	rete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ F	ire Doors	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			Υ			
Occupancy:								
Occupancy Type:			Govern	mental Bu	ilding			
Provide a brief description	on of operations:		Military-	admin, su	upply storage, army unit			
Storage height of wareho	oused products:		8 feet					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		0.24	
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?	•	0	
Indicate the Alarm Cover	ages provided for your fac	ility:		Burglar A	larms (Motion Detection), Smoke Detectors			
Are alarms connected to	a constantly attended loca	ition?		Υ				
ls there a watchman serv	ice?	N		What is t	he frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire depart	ment:	Paid		Distance	:		1 mile	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
Is there a body of water r	nearby?	N	Descrip	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	tion:				
Any property damage los	sses in the past 3 years:	N	Descrip	tion:				

					i age i				
			Pr	operty Detail Form					
Agency:	DEPARTMENT OF MILITAR	Y AFFAIRS / DEPARTMENT OF M	MILITARY	AFFAIRS					
Property:	Butte Readiness Center Haza	ardous Material Storage							
Property Address:	600 Gilman BUTTE								
Property ID:									
Construction:									
Total number of insured	buildings: 1			Total square footage of insured buildings: 1	28				
Year built:	2	2008		Number of stories:					
Construction of roof:	C	Other		Construction of floors:	Other				
Construction of exterior	walls:	Other		Construction of interior walls:	lo Interior Walls				
Oo major interior mason	ry walls (fire walls) extend ab	pove the roofline?		N					
Occupancy:									
Occupancy Type:			Storage						
Provide a brief description	on of operations:		Starage	Starage of hazardous materials					
Storage height of wareho	oused products:		0						
Are flammable and comb	oustible liquids stored in a cu	ut-off room?	Υ						
Safegaurds taken for the	storage and dispensing of f	lammable liquids:	Υ						
Protection:									
Are there any automatic	sprinklers?	N		What are the design densities for each area?	Total flooding				
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank				
ndicate the Alarm Cover	ages provided for your facili	ty:							
Are alarms connected to	a constantly attended location	on?		null					
s there a watchman serv	rice?	null		What is the frequency of rounds?					
Are watchman recording	rounds?								
Are there any fire exting	uishers?	null		Are they serviced annually?	null				
Are there any hose station	ons?	null		Is there a fire private fire brigade?	null				
requency of training red	ceived by the private fire brig	jade:							
Гуре of public fire depar	tment:	null		Distance:	blank				
Exposure:									
How many buildings(not	part of Account) are within 1	100 feet of insured buildings?	3						

Shop Storage office space / classroom

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Description: Ν

Any property damage losses in the past 3 years: N Description:

								1 ago 127
			Pro	perty D	etail Form			
Agency:	DEPARTMENT OF MILITA	ARY AFFAIRS / DEPARTMENT OF M	/IILITARY	AFFAIRS				
Property:	Culbertson Armory							
Property Address:	819 6th Avenue East CULI	BERTSON						
Property ID:	4							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	15219		
Year built:		1980			Number of stories:	1		
Construction of roof:		Steel Deck			Construction of floors:	Poured Conc	rete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ F	Fire Doors	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Governn	nental Bui	ilding			
Provide a brief description	on of operations:		Military,	admin, su	upply, storage, army unit			
Storage height of wareho	oused products:		8 feet					
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings	?	0	
Indicate the Alarm Cover	rages provided for your fac	sility:		Burglar A	larms (Door Contacts), Smoke Detectors			
Are alarms connected to	a constantly attended loca	ation?		Υ				
Is there a watchman serv	vice?	N		What is t	he frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Voluntary		Distance	:		blank	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	4					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Descrip	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ling?	N	Descrip	tion:				
Any property damage los	sses in the past 3 years:	N	Descrip	tion:				

			Pr	operty D	etail Form		
Agency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF M	ILITARY	AFFAIRS			
Property:	DES Mobile Command Pos	et Storage					
Property Address:	1956 MT Majo Street FORT	T HARRISON					
Property ID:							
Construction:							
Total number of insured l	ouildings:	1			Total square footage of insured buildings:	1080	
Year built:		2008			Number of stories:	1	
Construction of roof:		Other			Construction of floors:	Poured Concre	ete
Construction of exterior	valls:	Corrugated Metal Panel			Construction of interior walls:	Gypsum Board	d
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			N		
Occupancy:							
Occupancy Type:			Storage				
Provide a brief descriptio	n of operations:		blank				
Storage height of wareho	used products:		12 feet				
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	N		What are	the design densities for each area?		N/A
The water supply for auto	matic sprinklers is?			How man	y hydrants are located within 500 feet of buildings?		1
Indicate the Alarm Covera	ages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	tion?		N			
Is there a watchman serv	ice?	Υ		What is t	he frequency of rounds?		Daily
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose statio	ns?	N		Is there a	fire private fire brigade?		Υ
Frequency of training rec	eived by the private fire br	igade:		Unknown			
Type of public fire depart	ment:	Paid		Distance	:		2 Miles
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	2				
Describe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):	Storage	, office			
Is there a body of water n	earby?	N	Descrip	otion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descrip	otion:			
Any property damage los	ses in the past 3 years:	N	Descrip	otion:			

Property	Detail	Form

			Prop	perty De	etail Form			
Agency:	DEPARTMENT OF MILITA	ARY AFFAIRS / DEPARTMENT OF M	IILITARY A	AFFAIRS				
Property:	Dillon Readiness Center							
Property Address:	1070 Highway 41 DILLON							
Property ID:								
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	28152		
Year built:		2000			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Poured Conc	rete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ F	rire Doors	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Armory					
Provide a brief description	on of operations:		Military, s	supply, a	dmin, storage, army unit			
Storage height of wareho	oused products:		8 feet					
Are flammable and comb	oustible liquids stored in a	cut-off room?	Υ					
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	Υ	v	What are	the design densities for each area?		0.24	
The water supply for auto	omatic sprinklers is?	Public	н	How man	y hydrants are located within 500 feet of buildings	?	0	
Indicate the Alarm Cover	ages provided for your fac	eility:	В	3urglar Al	larms (Door Contacts), Smoke Detectors			
Are alarms connected to	a constantly attended loca	ation?	Y	Y				
ls there a watchman serv	rice?	N	v	What is th	he frequency of rounds?			
Are watchman recording	rounds?		N	N				
Are there any fire extingu	uishers?	Υ	Α	Are they	serviced annually?		Υ	
Are there any hose static	ons?	N	Is	s there a	fire private fire brigade?		N	
Frequency of training red	ceived by the private fire br	rigade:						
Type of public fire depart	iment:	Paid	D	Distance:	:		2 miles	
Exposure:								
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Descripti	ion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descripti	ion:				
Any property damage los	sses in the past 3 years:	N	Descripti	ion:				

					i age i
			Pr	operty Detail Form	
Agency:	DEPARTMENT OF MILIT	ARY AFFAIRS / DEPARTME	NT OF MILITARY	AFFAIRS	
Property:	Gallatin Readiness Cente	r			
Property Address:	350 Airport Road BELGF	RADE			
Property ID:					
Construction:					
Total number of insure	d buildings:	1		Total square footage of insured buildings:	50132
Year built:		2003		Number of stories:	1
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors
Do major interior maso	nry walls (fire walls) extend	d above the roofline?		N	
Occupancy:					
Occupancy Type:			Govern	mental Building	
Provide a brief descript	tion of operations:		Military	admin, supply, storage, army unit	
Storage height of warel	housed products:		8 feet		
Are flammable and con	nbustible liquids stored in a	a cut-off room?	Υ		
Safegaurds taken for th	ne storage and dispensing	of flammable liquids:	Υ		
Protection:					
Are there any automatic	c sprinklers?	Υ		What are the design densities for each area?	0.24
The water supply for au	utomatic sprinklers is?	Public		How many hydrants are located within 500 feet of building	ngs? 0
Indicate the Alarm Cov	erages provided for your fa	cility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflo	ow, Burglar Alarms (Door Contacts)
Are alarms connected t	to a constantly attended lo	cation?		Υ	
Is there a watchman se	rvice?	N		What is the frequency of rounds?	
Are watchman recording	ng rounds?			N	
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ
Are there any hose stat	tions?	N		Is there a fire private fire brigade?	N
Frequency of training r	eceived by the private fire	brigade:			
Type of public fire depart	artment:	Paid		Distance:	2 miles

Description:

## Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How far is the body of water from major buildings?

Is there a body of water nearby?

Previous history of flooding?

Description: Ν Any property damage losses in the past 3 years: N Description:

Ν

						Page 13
			Prop	perty Detail Form		
gency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF N	MILITARY A	FFAIRS		
roperty:	Harlowton Armory					
Property Address:	9895 Highway 12 West HA	RLOWTON				
roperty ID:	1					
Construction:						
otal number of insured	buildings:	1		Total square footage of insured buildings:	12916	
ear built:		1984		Number of stories:	1	
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
o major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Governme	ental Building		
Provide a brief description	on of operations:		Military, a	dmin, supply storage, army unit		
storage height of wareho	oused products:		8 feet			
are flammable and comb	oustible liquids stored in a	cut-off room?	Υ			
afegaurds taken for the	e storage and dispensing of	flammable liquids:	Υ			
Protection:						
are there any automatic	sprinklers?	N	W	hat are the design densities for each area?	no sprinklers	
he water supply for aut	omatic sprinklers is?		н	ow many hydrants are located within 500 feet of buildings?	0	
ndicate the Alarm Cover	rages provided for your fac	ility:	В	urglar Alarms (Door Contacts), Smoke Detectors		
are alarms connected to	a constantly attended loca	ition?	Υ			
s there a watchman serv	vice?	N	W	/hat is the frequency of rounds?		
are watchman recording	rounds?		N			
are there any fire exting	uishers?	Υ	Α	re they serviced annually?	Υ	

Frequency of training received by the private fire brigade:

Are there any hose stations?

Type of public fire department:

Exposure:

Ν

1 mile

Is there a fire private fire brigade?

Distance:

0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How many buildings(not part of Account) are within 100 feet of insured buildings?

Is there a body of water nearby? Description: Ν

How far is the body of water from major buildings?

Previous history of flooding? Description: Ν Any property damage losses in the past 3 years: N Description:

Ν

Voluntary

			Pro	operty D	etail Form			
Agency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF M	IILITARY	AFFAIRS				
Property:	Havre Armory							
Property Address:	1050 2nd St West HAVRE							
Property ID:	1							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	12780		
Year built:		1970			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ Fi	ire Doors	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Governr	mental Bu	ilding			
Provide a brief description	on of operations:		Military,	admin, su	upply storage, army unit			
Storage height of wareho	oused products:		8 feet					
Are flammable and comb	oustible liquids stored in a	cut-off room?	Υ					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		0.24	
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings	?	0	
Indicate the Alarm Cover	ages provided for your fac	ility:		Burglar A	larms (Door Contacts), Smoke Detectors, Sprinkler Val	ve Tamper, Spr	inkler Waterflow	
Are alarms connected to	a constantly attended loca	ition?		Υ				
ls there a watchman serv	rice?	N		What is t	he frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire br	igade:						
Type of public fire depart	tment:	Paid		Distance	:		1 mile	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Descrip	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	tion:				
Any property damage los	sses in the past 3 years:	N	Descrip	tion:				

					- 3 -
			Pro	pperty Detail Form	
gency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF I	MILITARY .	AFFAIRS	
Property:	Havre Readiness Center (a	dd to Havre Armory)			
roperty Address:	1050 2nd St W HAVRE				
roperty ID:					
Construction:					
otal number of insured	buildings:	1		Total square footage of insured buildings:	16148
ear built:		2006		Number of stories:	1
construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concrete
construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors
o major interior masonr	y walls (fire walls) extend a	bove the roofline?		N	
Occupancy:					
Occupancy Type:			Armory		
rovide a brief description	on of operations:		military o	offices	
torage height of wareho	oused products:		8'		
re flammable and comb	ustible liquids stored in a d	cut-off room?	Υ		
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ		
rotection:					
are there any automatic	sprinklers?	Υ		What are the design densities for each area?	0.24
he water supply for auto	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	? 0
ndicate the Alarm Cover	ages provided for your faci	lity:		Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Val	ve Tamper, Sprinkler Waterflow
are alarms connected to	a constantly attended loca	tion?		Υ	
s there a watchman serv	rice?	N		What is the frequency of rounds?	
re watchman recording	rounds?			N	
are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ
are there any hose statio	ons?	N		Is there a fire private fire brigade?	N
requency of training rec	eived by the private fire br	igade:			
ype of public fire depart	ment:	Paid		Distance:	1 mile
xposure:					

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings? 2 miles

Previous history of flooding? Description: Ν

Description: Any property damage losses in the past 3 years: N

							1 490 101		
			Pr	perty Detail Form					
Agency:	DEPARTMENT OF MILIT	ARY AFFAIRS / DEPARTMENT OF I	MILITARY	AFFAIRS					
Property:	Helena OMS								
Property Address:	2177 Williams Street HEL	ENA							
Property ID:	3								
Construction:									
Total number of insure	ed buildings:	1		Total square footage of ins	ured buildings:	19272			
Year built:		1971		Number of stories:		1			
Construction of roof:		Steel Deck		Construction of floors:		Reinforced Concrete			
Construction of exterio	or walls:	Masonry		Construction of interior wal	lls:	Masonry w/ Fire Doors			
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Governi	nental Building					
Provide a brief descrip	tion of operations:		Mainten	flaintenance shop & admin spaces					
Storage height of ware	housed products:		20 feet						
Are flammable and combustible liquids stored in a cut-off room?			Υ						
Safegaurds taken for t	he storage and dispensing o	of flammable liquids:	Υ						
Protection:									
Are there any automati	ic sprinklers?	N		What are the design densities for each	ch area?	no sprinklers			
The water supply for a	utomatic sprinklers is?			How many hydrants are located with	in 500 feet of buildings?	? 1			
Indicate the Alarm Cov	erages provided for your fa	cility:		Burglar Alarms (Door Contacts), Burgla	r Alarms (Motion Detectio	on)			
Are alarms connected	to a constantly attended loc	ation?		null					
Is there a watchman se	ervice?	Υ		What is the frequency of rounds?		hourly			
Are watchman recordi	ng rounds?			Y					
Are there any fire extin	guishers?	Υ		Are they serviced annually?		Υ			
Are there any hose sta	tions?	N		s there a fire private fire brigade?		null			
Frequency of training I	received by the private fire b	origade:							
Type of public fire dep	artment:	Paid		Distance:		2 miles			
Exposure:									
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	2						
Describe the Occupant	cy of those buildings(s) nea	rby (within 100 feet):	storage						
Is there a body of wate	r nearby?	N	Descrip	ion:					
How far is the body of	water from major buildings?	?							
Previous history of floo	oding?	N	Descrip	ion:					
Any property damage	losses in the past 3 years:	N	Descrip	ion:					

Property Detail Form
DV AFFAIRS

			Pro	perty D	etail Form			
Agency:	DEPARTMENT OF MILITA	ARY AFFAIRS / DEPARTMENT OF M	IILITARY A	AFFAIRS				
Property:	Kalispell AFRC							
Property Address:	2989 Hwy 93 North KALIS	PELL						
Property ID:								
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	50362		
Year built:		2005			Number of stories:	1		
Construction of roof:		Steel Deck			Construction of floors:	Poured Conci	rete	
Construction of exterior	walls:	Tilt-Up Concrete			Construction of interior walls:	Masonry w/ F	ire Doors	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Governme	ental Bui	lding			
Provide a brief description	on of operations:		Military, a	admin, su	pply, storage, army unit			
Storage height of wareho	oused products:		8 feet					
Are flammable and comb	oustible liquids stored in a	cut-off room?	Υ					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	Υ	V	What are	the design densities for each area?		0.24	
The water supply for auto	omatic sprinklers is?	Private	н	How man	y hydrants are located within 500 feet of buildings?	?	1	
Indicate the Alarm Cover	ages provided for your fac	eility:	В	Burglar Al	larms (Door Contacts), Fire Pump Alarms, Smoke Dete	ctors, Sprinkler	Valve Tamper, Sprinkler Wa	aterflow
Are alarms connected to	a constantly attended loca	ation?	Y	ſ				
ls there a watchman serv	rice?	N	V	What is t	he frequency of rounds?			
Are watchman recording	rounds?		N	N				
Are there any fire exting	uishers?	Υ	A	Are they	serviced annually?		Υ	
Are there any hose static	ons?	N	ls	s there a	fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid	D	Distance	:		2 miles	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
ls there a body of water i	nearby?	N	Descripti	ion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ling?	null	Descripti	ion:				
Any property damage los	sses in the past 3 years:	N	Descripti	ion:				

2.7 MILES

FIRE WATER SUPPLY RESERVO

						Page
			Proper	ty Detail Form		
Agency:	DEPARTMENT OF MILIT	ARY AFFAIRS / DEPARTMENT OF	MILITARY AFF	AIRS		
Property:	Kalispell AFRC Fire Pum	o Building				
Property Address:	2989 Hwy 93 North KALIS	PELL				
Property ID:						
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	872	
Year built:		2005		Number of stories:	1	
Construction of roof:		Other		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Pump House			
Provide a brief description	on of operations:		FIRE PROTE	CTION PUMP HOUSE		
Storage height of wareho	oused products:		12 FEET			
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing of	of flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	Υ	Wha	t are the design densities for each area?		
The water supply for aut	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	2	
Indicate the Alarm Cover	rages provided for your fa	cility:	Fire	Pump Alarms		
Are alarms connected to	a constantly attended loc	ation?	Υ			
ls there a watchman serv	vice?	N	Wha	t is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire exting	uishers?	Υ	Are	they serviced annually?	Υ	
Are there any hose static	ons?	N	Is th	ere a fire private fire brigade?	Υ	

3 HRS WEEKLY

Distance:

0

Description:

Description: Description:

100 FEET

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Voluntary

Ν

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

**Exposure:** 

FIRE SUPPLY RESERVOIR

						Page '
			Prop	perty Detail Form		
Agency:	DEPARTMENT OF MILIT	ARY AFFAIRS / DEPARTMENT	OF MILITARY A	FFAIRS		
Property:	Kalispell AFRC Storage					
Property Address:	2989 Hwy 93 North KALIS	SPELL				
Property ID:						
Construction:						
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	4637	
Year built:		2005		Number of stories:	1	
Construction of roof:		Other		Construction of floors:	Poured Concrete	
Construction of exterio	or walls:	Corrugated Metal Panel		Construction of interior walls:	Other	
Do major interior maso	onry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Storage			
Provide a brief descrip	tion of operations:		UNHEATE	ED STORAGE		
Storage height of ware	housed products:		12 FEET			
Are flammable and cor	mbustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for t	he storage and dispensing o	of flammable liquids:	Υ			
Protection:						
Are there any automat	ic sprinklers?	N	V	hat are the design densities for each area?		
The water supply for a	utomatic sprinklers is?		н	ow many hydrants are located within 500 feet of building	<b>js?</b> 2	
ndicate the Alarm Cov	verages provided for your fa	cility:	В	urglar Alarms (Ultrasound), Burglar Alarms (Motion Detection	n)	
Are alarms connected	to a constantly attended loc	ation?	Y			
s there a watchman se	ervice?	N	V	/hat is the frequency of rounds?		
Are watchman recordi	ng rounds?					
Are there any fire extin	nguishers?	N	A	re they serviced annually?	null	
Are there any hose sta	tions?	null	ls	there a fire private fire brigade?	Υ	
requency of training	received by the private fire b	origade:	3	HOURS PER WEEK		
Гуре of public fire dep	artment:	Voluntary	D	istance:	2.7 MILES	
Exposure:						

0

Description:

Description:

Description:

100 FEET

How many buildings(not part of Account) are within 100 feet of insured buildings?

null

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

								1 490 10	
			Pr	roperty [	Detail Form				
Agency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF N	/IILITARY	/ AFFAIRS	8				
Property:	Kalispell Organizational Ma	aint Shop No. 2							
Property Address:	2987 Hwy 93 North KALISI	PELL							
Property ID:	6								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	9688			
Year built:		1989			Number of stories:	1			
Construction of roof:		Steel Deck			Construction of floors:	Reinforced C	concrete		
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ F	Fire Doors		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			Garage	e, Parts St	orage				
Provide a brief description	on of operations:		shop m	shop maintenance					
Storage height of warehoused products:			8 feet						
Are flammable and combustible liquids stored in a cut-off room?			Υ						
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ						
Protection:									
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?		no sprinklers		
The water supply for aut	omatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?	?	0		
Indicate the Alarm Coverages provided for your facility:				Smoke [	Detectors				
Are alarms connected to	a constantly attended loca	ation?		Υ					
ls there a watchman serv	vice?	N		What is	the frequency of rounds?				
Are watchman recording	rounds?			N					
Are there any fire exting	uishers?	Υ		Are they	y serviced annually?		Υ		
Are there any hose static	ons?	N		Is there	a fire private fire brigade?		N		
Frequency of training re	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Paid		Distance	e:		3 miles		
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water nearby?		Descri	ption:						
How far is the body of w	ater from major buildings?								
Previous history of flood	ling?	N	Descri	ption:					
Any property damage lo	sses in the past 3 years:	N	Descri	ption:					

								- 3	
			Pr	operty D	Petail Form				
Agency:	DEPARTMENT OF MILITA	ARY AFFAIRS / DEPARTMENT OF N	MILITARY	AFFAIRS	3				
Property:	Libby Armory								
Property Address:	1004 Treasure Ave. LIBBY	,							
Property ID:									
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	20762			
Year built:		1990			Number of stories:	1			
Construction of roof:		Steel Deck			Construction of floors:	Poured Conc	rete		
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ F	ire Doors		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			Govern	mental Bu	ilding				
Provide a brief description	on of operations:		Military	, admin, sı	upply, storage, army unit				
Storage height of warehoused products:			8 feet	8 feet					
Are flammable and comb	oustible liquids stored in a	cut-off room?	Υ						
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ						
Protection:									
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?		no sprinklers		
The water supply for automatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?	<b>&gt;</b>	0			
Indicate the Alarm Cover	rages provided for your fac	cility:		Burglar A	Alarms (Door Contacts), Smoke Detectors				
Are alarms connected to	a constantly attended loc	ation?		null					
Is there a watchman serv	vice?	N		What is	the frequency of rounds?				
Are watchman recording	rounds?			N					
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose static	ons?	N		Is there	a fire private fire brigade?		N		
Frequency of training red	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Paid		Distance	x:		1 mile		
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water i	nearby?	N	Descri	otion:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ling?	N	Descri	otion:					
Any property damage los	sses in the past 3 years:	N	Descri	otion:					

			Property Detail Form							
Agency:	DEPARTMENT OF	DEPARTMENT OF MILITARY AFFAIRS / DEPARTMENT OF MILITARY AFFAIRS								
Property:	Livingston Armory	Livingston Armory								
Property Address:	24 Fleshman Creek	24 Fleshman Creek Road LIVINGSTON								
Property ID:										
Construction:										
Total number of insure	d buildings:	1	Total square footage of insured buildings:	16868						
Year built:		1991	Number of stories:	1						
Construction of roof:		Steel Deck	Construction of floors:	Poured Concrete						
Construction of exterio	or walls:	Masonry	Construction of interior walls:	Masonry w/ Fire Doors						

#### Occupancy:

Occupancy Type: Governmental Building

Provide a brief description of operations: Military, admin, supply, storage, army unit

Storage height of warehoused products: 8 feet

Do major interior masonry walls (fire walls) extend above the roofline?

Are flammable and combustible liquids stored in a cut-off room?

Safegaurds taken for the storage and dispensing of flammable liquids:

## Protection:

Are there any automatic sprinklers? N What are the design densities for each area? no sprinklers

The water supply for automatic sprinklers is? How many hydrants are located within 500 feet of buildings? 1

Indicate the Alarm Coverages provided for your facility:

Burglar Alarms (Door Contacts), Smoke Detectors

Are alarms connected to a constantly attended location?

Is there a watchman service?

N

What is the frequency of rounds?

Are watchman recording rounds?

Are there any fire extinguishers?

Y

Are they serviced annually?

Y

Are there any hose stations?

N Is there a fire private fire brigade?

0

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: 2 miles

### **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? N Description:

How far is the body of water from major buildings?

Previous history of flooding? N Description:

Any property damage losses in the past 3 years: N Description:

			Pro	operty Detail Form						
Agency:	DEPARTMENT OF MILITARY AFFAIRS / DEPARTMENT OF MILITARY AFFAIRS									
Property:	Maint Bldg - Cemetery (A/E93-33-11)									
Property Address:	1892 Williams Street HELE	NA								
Property ID:										
Construction:										
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	2644					
Year built:		1994		Number of stories:	1					
Construction of roof:		Other		Construction of floors:	Poured Concre	te				
Construction of exterior w	/alls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board					
Do major interior masonry	walls (fire walls) extend a	above the roofline?		N						
Occupancy:										
Occupancy Type:			Garage,	Service Center						
Provide a brief description	n of operations:		CEMET	ERY MAINTENANCE SHOP						
Storage height of warehou	used products:		N/A							
Are flammable and combu	ustible liquids stored in a c	cut-off room?	N							
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ							
Protection:										
Are there any automatic s	prinklers?	N		What are the design densities for each area?						
The water supply for automatic sprinklers is?				How many hydrants are located within 500 feet of buildings?		0				
Indicate the Alarm Covera	ges provided for your faci	ility:								
Are alarms connected to a	a constantly attended loca	tion?		null						
ls there a watchman servi	ce?	Υ		What is the frequency of rounds?		2-4 NIGHTLY				
Are watchman recording i	rounds?			Υ						
Are there any fire extingui	ishers?	Υ		Are they serviced annually?		Υ				
Are there any hose station	ns?	N		Is there a fire private fire brigade?		N				
Frequency of training reco	eived by the private fire br	igade:								
Type of public fire departr	ment:	Paid		Distance:		.75 MILES				
Exposure:										
How many buildings(not part of Account) are within 100 feet of insured buildings?										
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):								
Is there a body of water nearby?		Description:								
How far is the body of water from major buildings?										
Previous history of flooding	ng?	N	Descrip	tion:						
Any property damage loss	ses in the past 3 years:	N	Description:							

						Page 14				
			Р	roperty Detail Form						
gency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF I	MILITAR	Y AFFAIRS						
Property:	Maint Bldg - Cemetery Mile	Maint Bldg - Cemetery Miles City								
roperty Address:	Highway 59 & Cemetery Ro	oad MILES CITY								
Property ID:										
Construction:										
otal number of insure	d buildings:	1		Total square footage of insured buildings:	2425					
ear built:		2001		Number of stories:	1					
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete					
Construction of exterio	r walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board					
o major interior maso	nry walls (fire walls) extend	above the roofline?		N						
Occupancy:										
Occupancy Type:			Garage	e, Service Center						
Provide a brief descript	tion of operations:		CEME	TERY MAINTENANCE SHOP						
Storage height of warel	housed products:		N/A							
are flammable and con	nbustible liquids stored in a	cut-off room?	N							
afegaurds taken for th	ne storage and dispensing of	flammable liquids:	Υ							
Protection:										
are there any automati	c sprinklers?	N		What are the design densities for each area?	N/A					
he water supply for au	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	0					
ndicate the Alarm Cov	erages provided for your fac	ility:		Smoke Detectors						
are alarms connected t	to a constantly attended loca	ition?		N						
s there a watchman se	rvice?	N		What is the frequency of rounds?						
are watchman recordin	ng rounds?									
are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ					
are there any hose stat	tions?	N		Is there a fire private fire brigade?	N					

Type of public fire department:

Frequency of training received by the private fire brigade: 1.5 MILES Paid Distance:

## **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Description: Previous history of flooding? Ν Description: Any property damage losses in the past 3 years: N

						Page 1			
			Pr	operty Detail Form					
gency:	DEPARTMENT OF MILITARY AFFAIRS / DEPARTMENT OF MILITARY AFFAIRS								
Property:	Missoula Armed Forces Reserve Center								
roperty Address:	9383 Running West Roa	9383 Running West Road MISSOULA							
roperty ID:	NG#300055								
Construction:									
otal number of insured	l buildings:	1		Total square footage of insured buildings:	65932				
ear built:		2010		Number of stories:	1				
construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete				
construction of exterior	r walls:	Masonry		Construction of interior walls:	Gypsum Board				
o major interior masor	nry walls (fire walls) exten	nd above the roofline?		N					
Occupancy:									
Occupancy Type:			Govern	mental Building		•			
Provide a brief description of operations:			MT Nat	MT National Guard & US Army Reserve Operations					
storage height of warehoused products:			12 Fee	12 Feet					
are flammable and combustible liquids stored in a cut-off room?			Υ						
safegaurds taken for the storage and dispensing of flammable liquids:			Υ						
rotection:									
re there any automatic	sprinklers?	Υ		What are the design densities for each area?					
he water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of building	<b>gs?</b> 1				
ndicate the Alarm Cove	erages provided for your f	acility:		Smoke Detectors, Sprinkler Waterflow					
are alarms connected to	o a constantly attended lo	ocation?		Υ					
s there a watchman ser	vice?	null		What is the frequency of rounds?					
re watchman recording	g rounds?								
are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ				
re there any hose stati	ions?	N		Is there a fire private fire brigade?	N				
requency of training re	eceived by the private fire	brigade:							
ype of public fire depa	rtment:	Part-Paid		Distance:	6 miles				
xposure:									
low many buildings(no	t part of Account) are wit	hin 100 feet of insured buildings	? 0						
escribe the Occupancy	v of those buildings(s) ne	arby (within 100 feet):							

Description:

Description:

Description:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Ν

						Page 14			
			Pı	roperty Detail Form					
gency:	DEPARTMENT OF MILIT	ARY AFFAIRS / DEPARTMENT OF	MILITARY	AFFAIRS					
roperty:	Missoula Armed Forces R	Missoula Armed Forces Reserve Center AMSA/OMS SHOP							
Property Address:	9407 Running West Road	Building 00200 MISSOULA							
roperty ID:	NG#300055								
Construction:									
otal number of insure	ed buildings:	1		Total square footage of insured buildings:	13293				
ear built:		2010		Number of stories:	2				
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete				
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Gypsum Board				
o major interior maso	onry walls (fire walls) extend	I above the roofline?		N					
Occupancy:									
Occupancy Type:			Garage	e, Service Center					
Provide a brief descrip	tion of operations:		MTNG	MTNG & USAR ORG Maitenance Shops					
storage height of ware	housed products:		14 feet						
are flammable and con	nbustible liquids stored in a	cut-off room?	Υ						
afegaurds taken for th	he storage and dispensing o	of flammable liquids:	Υ						
Protection:									
are there any automati	ic sprinklers?	N		What are the design densities for each area?					
he water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	1				
ndicate the Alarm Cov	rerages provided for your fa	cility:		Smoke Detectors					
are alarms connected	to a constantly attended loc	eation?		Υ					
s there a watchman se	ervice?	N		What is the frequency of rounds?					
are watchman recordir	ng rounds?								
are there any fire extin	guishers?	Υ		Are they serviced annually?	Υ				
are there any hose sta	tions?	N		Is there a fire private fire brigade?	N				
requency of training r	received by the private fire b	origade:							
ype of public fire dep	artment:	Part-Paid		Distance:	6 miles				
xposure:									
low many buildings(no	ot part of Account) are with	in 100 feet of insured buildings?	blank						

Description:

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

			Pro	operty D	etail Form			
agency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF M	ILITARY	AFFAIRS				
Property:	Missoula Armed Forces Reserve Center Cold Storage							
roperty Address:	9407 Running W Road Bui	ding 00300 MISSOULA						
Property ID:	NG# 300055							
Construction:								
otal number of insured	buildings:	1			Total square footage of insured buildings:	5530		
ear built:		2010			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry		
o major interior masonr	y walls (fire walls) extend	above the roofline?			Υ			
Occupancy:								
Occupancy Type:			Garage,	, Service (	Center			
Provide a brief description	n of operations:		Unheate	ed storage	)			
storage height of wareho	used products:		14 feet					
are flammable and combustible liquids stored in a cut-off room?			N/A					
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
are there any automatic	sprinklers?	N		What are	the design densities for each area?			
he water supply for auto	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?		0	
ndicate the Alarm Cover	ages provided for your fac	ility:						
are alarms connected to	a constantly attended loca	ition?		null				
s there a watchman serv	ice?	N		What is t	the frequency of rounds?			
are watchman recording	rounds?							
are there any fire extingu	ishers?	N		Are they	serviced annually?		null	
are there any hose statio	ns?	N		Is there a	a fire private fire brigade?		null	
requency of training rec	eived by the private fire b	igade:						
ype of public fire depart	ment:	Part-Paid		Distance	:		6 miles	
xposure:								
low many buildings(not	part of Account) are withir	100 feet of insured buildings?	1					
escribe the Occupancy	of those buildings(s) near	by (within 100 feet):	Vehilce I	Maintenar	nce Shop			
s there a body of water n	earby?	N	Descrip	otion:				
low far is the body of wa	ter from major buildings?							
revious history of flood	ing?	N	Descrip	otion:				
any property damage los	ses in the past 3 years:	N	Descrip	otion:				

null

blank

Irrigation Canal

						Page 1
			Pro	operty Detail Form		
Agency:	DEPARTMENT OF MILIT	ARY AFFAIRS / DEPARTMENT C	F MILITARY	AFFAIRS		
Property:	Western Mt State Veterar	ns Cemetery Admin				
Property Address:	1911 Tower Road MISSC	PULA				
Property ID:						
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	2015	
Year built:		2008		Number of stories:	1	
Construction of roof:		Other		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior mason	ry walls (fire walls) extend	d above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descripti	on of operations:		Admin V	A staff benefits and cemetery		
Storage height of wareh	oused products:		10 feet			
Are flammable and com	bustible liquids stored in a	a cut-off room?	N/A			
Safegaurds taken for the	e storage and dispensing	of flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for aut	tomatic sprinklers is?			How many hydrants are located within 500 feet of building	ngs? blank	
Indicate the Alarm Cove	rages provided for your fa	cility:				
Are alarms connected to	a constantly attended lo	cation?		null		
Is there a watchman ser	vice?	null		What is the frequency of rounds?		
Are watchman recording	g rounds?					
Are there any fire exting	uishers?	null		Are they serviced annually?	null	

Is there a fire private fire brigade?

Distance:

Public Rest Room and Shop

Description:

Description:

Description:

50'

null

null

Ν

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

Exposure:

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Irrigation Canal

						Page 14
			Р	roperty Detail Form		
Agency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF	MILITAR'	Y AFFAIRS		
Property:	Western MT State Veteran	s Cemetery Rest Rooms				
Property Address:	1911 Tower Road MISSOL	JLA				
Property ID:						
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	298	
Year built:		2008		Number of stories:	1	
Construction of roof:		Other		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Oo major interior masonry walls (fire walls) extend above the roofline?				N		
Occupancy:						
Occupancy Type:			Other			
Provide a brief description of operations:			Public	Restrooms and location terminal		
Storage height of warehoused products:			0			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	? blank	
ndicate the Alarm Cove	rages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ation?		null		
s there a watchman ser	vice?	null		What is the frequency of rounds?		
Are watchman recording	g rounds?					
Are there any fire exting	uishers?	null		Are they serviced annually?	null	
Are there any hose stati	ons?	null		Is there a fire private fire brigade?	null	
requency of training re	ceived by the private fire b	rigade:				
Гуре of public fire depar	tment:	null		Distance:	blank	
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	2			
escribe the Occupancy of those buildings(s) nearby (within 100 feet):			Admin	and shop		

Description:

Description:

Description:

50"

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Υ

					1 ago 1		
			Pr	operty Detail Form			
Agency:	DEPARTMENT OF MILITA	ARY AFFAIRS / DEPARTMENT OF I	MILITARY	AFFAIRS			
Property:	Western MT State Veteran	s Cemetery Shop					
Property Address:	1911 Tower Road MISSOL	JLA					
Property ID:							
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	2171		
Year built:		2008		Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete		
Construction of exterior	r walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board		
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Garage	, Vehicle Storage			
Provide a brief descript	ion of operations:		Shop ar	nd vehicle storage			
Storage height of wareh	oused products:		ground	level			
Are flammable and com	bustible liquids stored in a	cut-off room?	N				
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	Υ				
Protection:							
Are there any automation	sprinklers?	N		What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank		
Indicate the Alarm Cove	erages provided for your fac	cility:					
Are alarms connected t	o a constantly attended loc	ation?		null			
ls there a watchman sei	rvice?	null		What is the frequency of rounds?			
Are watchman recordin	g rounds?						
Are there any fire exting	guishers?	null		Are they serviced annually?	null		
Are there any hose stat	ions?	null		Is there a fire private fire brigade?	null		
Frequency of training re	eceived by the private fire b	rigade:					
Type of public fire depa	rtment:	null		Distance:	blank		
Exposure:							
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	2				
Describe the Occupanc	y of those buildings(s) near	by (within 100 feet):	Public F	Rest Room and Admin			
Is there a body of water nearby?			Descrip	otion:	Irrigation Canal		
How far is the body of water from major buildings?			50 feet				
Previous history of flooding?			Description:				
Any property damage lo	osses in the past 3 years:	N	Descrip	otion:			

							i ago i
			Propert	y Detail Form			
Agency:	DEPARTMENT OF MILITA	RY AFFAIRS / DEPARTMENT OF I	MILITARY AFFA	IRS			
Property:	Womack Armory						
Property Address:	Womack Bldg, Ft Harrison	HELENA					
Property ID:	2						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	20982		
Year built:		1971		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Masonry w/ Fi	ire Doors	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		Υ			
Occupancy:							
Occupancy Type:			Armory				
Provide a brief description of operations:			Admin-ng trai	ning/classroom			
Storage height of wareh	noused products:		14 feet				
Are flammable and com	nbustible liquids stored in a	cut-off room?	Υ				
Safegaurds taken for th	e storage and dispensing of	f flammable liquids:	Υ				
Protection:							
Are there any automatic	c sprinklers?	N	What	are the design densities for each area?		no sprinklers	
The water supply for au	tomatic sprinklers is?		How	many hydrants are located within 500 feet of buildir	ngs?	2	
Indicate the Alarm Cove	erages provided for your fac	ility:	Burgl	ar Alarms (Door Contacts), Burglar Alarms (Motion Dete	ection), Smoke Dete	ectors	
Are alarms connected t	o a constantly attended loca	ation?	null				
Is there a watchman se	rvice?	Υ	What	is the frequency of rounds?		hourly	
Are watchman recording	g rounds?		Υ				
Are there any fire exting	guishers?	Υ	Are t	hey serviced annually?		Υ	
Are there any hose stat	ions?	N	Is the	ere a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:					
Type of public fire depa	artment:	Paid	Dista	ince.		1/2 mile	

0

Description:

Description:

Description:

**Exposure:** 

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

						1 490 100			
			Pro	perty Detail Form					
Agency:	DEPARTMENT OF NATU	RAL RESOURCES / DEPARTMENT	OF NATUR	RAL RESOURCES					
Property:	BOGC Field Office-Billings	S							
Property Address:	2535 St John Ave BILLIN	GS							
Property ID:	1								
Construction:									
Total number of insure	d buildings:	1		Total square footage of insured buildings:	14886				
Year built:		1978		Number of stories:	I				
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete				
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board				
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Office						
Provide a brief descript	tion of operations:		Offices, r	ffices, rock sample storage & public hearings room					
Storage height of warel	housed products:		8' shelvir	s' shelving for samples					
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A						
Protection:									
Are there any automatic	c sprinklers?	Υ	,	What are the design densities for each area?					
The water supply for au	utomatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?	1				
Indicate the Alarm Cove	erages provided for your fa	cility:	I	blank					
Are alarms connected t	o a constantly attended loc	ation?	ı	null					
Is there a watchman se	rvice?	N	1	What is the frequency of rounds?	Aroun	nd the Clock			
Are watchman recording	g rounds?								
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ				
Are there any hose stat	ions?	N	I	Is there a fire private fire brigade?	null				
Frequency of training re	eceived by the private fire b	rigade:							
Type of public fire depart	artment:	Paid	I	Distance:	blank				
Exposure:									
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	3						
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):							
Is there a body of water	r nearby?	N	Descript	tion:					
How far is the body of water from major buildings?									
Previous history of floo	oding?	N	Descript	tion:					
Any property damage lo	osses in the past 3 years:	N	Descript	tion:					

							Page 15
			Р	roperty Detail Form			
gency:	DEPARTMENT OF NATUR	RAL RESOURCES / DEPARTMENT	OF NAT	URAL RESOURCES			
Property:	Stillwater Bathhouse						
Property Address:	7425 Hwy 93 South OLNE	Y					
Property ID:	6						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	672		
ear built:		blank		Number of stories:	1		
construction of roof:		null		Construction of floors:	null		
construction of exterior	walls:	null		Construction of interior walls:	null		
o major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Cabins	s/Bunkhouses			
Provide a brief description	on of operations:		blank				
storage height of wareh	oused products:		blank				
are flammable and comb	bustible liquids stored in a	cut-off room?	null				
Safegaurds taken for the	e storage and dispensing of	f flammable liquids:	null				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?			
he water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		blank	
ndicate the Alarm Cove	rages provided for your fac	ility:		blank			
are alarms connected to	a constantly attended loca	ation?		null			
s there a watchman serv	vice?	null		What is the frequency of rounds?			
are watchman recording	y rounds?						
are there any fire exting	uishers?	null		Are they serviced annually?		null	
are there any hose station	ons?	null		Is there a fire private fire brigade?		null	
requency of training re	ceived by the private fire b	rigade:					
ype of public fire depar	tment:	null		Distance:		blank	
xposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
		h., (ithin 400 faat).					

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? null

Description:

How far is the body of water from major buildings?

Previous history of flooding?

Description:

Any property damage losses in the past 3 years: null

null

Description:

			Pr	Property D	Detail Form				
Agency:	DEPARTMENT OF NATUR	RAL RESOURCES / DEPARTMENT	OF NATU	URAL RES	SOURCES, SWAN RIVER FOREST CAMP				
Property:	Swan Youth Center Lodge,	Dormitory & Addition							
Property Address:	34925 MT Hwy 83 BIGFOR	RK							
Property ID:	2								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	21763			
Year built:		1968			Number of stories:	2			
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Reinforced Co	oncrete		
Construction of exterior	walls:	Reinforced Concrete			Construction of interior walls:	Masonry w/ F	ire Doors		
Do major interior mason	ry walls (fire walls) extend a	above the roofline?			N				
Occupancy:									
Occupancy Type:			Govern	nmental Bu	uilding				
Provide a brief description	on of operations:		marked	marked for lease or being considered for sale under the Land Banking Program					
Storage height of wareho	oused products:		0						
Are flammable and combustible liquids stored in a cut-off room?			N						
afegaurds taken for the storage and dispensing of flammable liquids:  N/A									
Protection:									
Are there any automatic	sprinklers?	Υ		What are	e the design densities for each area?				
Γhe water supply for aut	omatic sprinklers is?	Public		How ma	ny hydrants are located within 500 feet of buildings?	?	50		
ndicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors, Fire Pump Alarms, Sprinkler Waterflow						
Are alarms connected to	a constantly attended loca	tion?		N					
s there a watchman serv	vice?	N		What is	the frequency of rounds?				
Are watchman recording	rounds?			N					
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose station	ons?	N		Is there	a fire private fire brigade?		N		
requency of training re	ceived by the private fire br	igade:							
Гуре of public fire depar	tment:	Voluntary		Distance	e:		7 miles		
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):							
s there a body of water	nearby?	N	Descri	iption:					
How far is the body of w	ater from major buildings?								
Previous history of flood	ling?	N	Descri	iption:					
Any property damage lo	sses in the past 3 years:	N	Descri	iption:					

			Pr	operty Detail Form					
Agency:	DEPARTMENT OF NATU	IRAL RESOURCES / DEPARTMENT	OF NATU	JRAL RESOURCES					
Property:	Toston Dam Power House	e							
Property Address:	Toston Dam Road TOSTO	ON							
Property ID:	2								
Construction:									
Total number of insured	l buildings:	1		Total square footage of insured buildings:	10450				
Year built:		1989		Number of stories:	5				
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Co	oncrete			
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Other				
Do major interior masor	nry walls (fire walls) extend	I above the roofline?		N					
Occupancy:									
Occupancy Type:			Power F	Plant					
Provide a brief description of operations:			single u	single unit hydroelectric Pit Kaplan tubine. Generates electricity 24 hours/daily					
Storage height of warehoused products:			0						
Are flammable and combustible liquids stored in a cut-off room?									
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	Υ						
Protection:									
Are there any automatic	sprinklers?	N		What are the design densities for each area?		no sprinklers			
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of building	s?	0			
ndicate the Alarm Cove	erages provided for your fa	cility:		Burglar Alarms (Door Contacts), Burglar Alarms (Motion Detect	ion)				
Are alarms connected to	o a constantly attended loc	cation?		Υ					
s there a watchman ser	vice?	N		What is the frequency of rounds?					
Are watchman recording	g rounds?			N					
Are there any fire exting	juishers?	Υ		Are they serviced annually?		Υ			
Are there any hose stati	ons?	N		Is there a fire private fire brigade?		N			
requency of training re	eceived by the private fire b	origade:							
Гуре of public fire depa	rtment:	Voluntary		Distance:		5 miles			
Exposure:									
How many buildings(no	t part of Account) are with	in 100 feet of insured buildings?	0						
Describe the Occupancy	y of those buildings(s) nea	rby (within 100 feet):							
s there a body of water nearby?			Description: Re:			iver			
How far is the body of w	vater from major buildings	?	Abuts th	ne hydro-electric					
Previous history of floor	poding? N Description:								

							- 3 -		
			Prope	erty Detail Form					
Agency:	DEPARTMENT OF NATU	RAL RESOURCES / DEPARTMENT	OF NATURA	L RESOURCES					
Property:	Toston Dam Storage Build	ling							
Property Address:	Toston Dam Road TOSTO	N .							
Property ID:	4								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	2400				
Year built:		1991		Number of stories:	1				
Construction of roof:		Other		Construction of floors:	Reinforced Co	oncrete			
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Other				
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null					
Occupancy:									
Occupancy Type:			Quonset W	arehouse					
Provide a brief description of operations:			storage of o	storage of consumables, spare parts, construction materials, tools used to maintain hydro plant					
Storage height of warehoused products:				le					
Are flammable and combustible liquids stored in a cut-off room?									
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ						
Protection:									
Are there any automatic	sprinklers?	N	Wh	nat are the design densities for each area?		no sprinklers			
The water supply for aut	omatic sprinklers is?		Но	w many hydrants are located within 500 feet of buildings	.?	0			
ndicate the Alarm Cove	rages provided for your fa	cility:	Burglar Alarms (Door Contacts), Burglar Alarms (Motion Detection)						
Are alarms connected to	a constantly attended loc	ation?	Υ						
s there a watchman ser	vice?	N	Wh	nat is the frequency of rounds?					
Are watchman recording	g rounds?		N						
Are there any fire exting	uishers?	Υ	Are	e they serviced annually?		Υ			
Are there any hose stati	ons?	null	ls t	there a fire private fire brigade?		N			
requency of training re	ceived by the private fire b	rigade:							
Гуре of public fire depar	tment:	Voluntary	Dis	stance:		5 miles			
Exposure:									
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
s there a body of water nearby? Y Description				ption: Reservoir & river					
How far is the body of w	ater from major buildings?	•	abuts hydro	plant					
Previous history of floor	ding?	N	Description	n:					

							i ago
			Property	Detail Form			
Agency:	DEPARTMENT OF NATU	RAL RESOURCES / DEPARTMENT	OF NATURAL RE	ESOURCES			
Property:	Toston Dam Sub-station						
Property Address:	Toston Dam Road TOSTO	N					
Property ID:	1						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	344		
Year built:		blank		Number of stories:	1		
Construction of roof:		Other		Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	No Interior Wa	alls	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Power Plant				
Provide a brief descripti	on of operations:		Electric substat	ion			
Storage height of wareh	oused products:		0				
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N	What a	are the design densities for each area?		no sprinklers	
The water supply for au	tomatic sprinklers is?		How m	nany hydrants are located within 500 feet of buildings	.?	0	
ndicate the Alarm Cove	rages provided for your fac	cility:					
Are alarms connected to	a constantly attended loc	ation?	null				
s there a watchman ser	vice?	N	What is	s the frequency of rounds?			
Are watchman recording	g rounds?		N				
Are there any fire exting	uishers?	Υ	Are the	ey serviced annually?		Υ	
Are there any hose stati	ons?	null	Is there	e a fire private fire brigade?		N	
requency of training re	ceived by the private fire b	rigade:					
Гуре of public fire depa	rtment:	Voluntary	Distan	ce:		2 miles	
Exposure:							
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):					
s there a body of water	nearby?	Υ	Description:		River		
How far is the body of w	rater from major buildings?	,	1/4 mile				
Previous history of floo	ding?	N	Description:				

			Propert	y Detail Form					
Agency:	DEPARTMENT OF REVEN	NUE / DEPARTMENT OF REVENUE							
Property:	New Liquor Warehouse								
Property Address:	2517 Airport Road HELENA	A							
Property ID:	1								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	108258				
Year built:		1977		Number of stories:	2				
Construction of roof:		Other		Construction of floors:	Poured Concr	ete			
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Other				
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null					
Occupancy:									
Occupancy Type:			Quonset Ware	house					
Provide a brief description	on of operations:		Offices, Warel	Offices, Warehouse					
Storage height of warehoused products:			20 feet						
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the storage and dispensing of flammable liquids:									
Protection:									
Are there any automatic	sprinklers?	Υ	What	are the design densities for each area?		Unkown			
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	?	4			
Indicate the Alarm Cover	ages provided for your fac	ility:	Burgla	ar Alarms (Door Contacts), Smoke Detectors, Sprinkler Wa	terflow				
Are alarms connected to	a constantly attended loca	ition?	Υ						
Is there a watchman serv	rice?	Υ	What	is the frequency of rounds?		3 rounds in the off hours			
Are watchman recording	rounds?		Υ						
Are there any fire extingu	uishers?	Υ	Are th	ney serviced annually?		Υ			
Are there any hose static	ons?	Υ	Is the	re a fire private fire brigade?		N			
Frequency of training red	ceived by the private fire br	igade:							
Type of public fire depart	tment:	Paid	Dista	nce:		Less than 5 miles			
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	1						
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):	Warehouse						
Is there a body of water r	nearby?	N	Description:						
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Description:						
Any property damage los	mage losses in the past 3 years: N Description:								

Property Detail Form	
PORTATION	

			Property	Detail Form				
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF TI	RANSPORTATI	ON				
Property:	Aeronautics Helena Operat	tions						
Property Address:	2630 Airport Road HELEN	A						
Property ID:	1							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	6397			
Year built:		1958		Number of stories:	1			
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete		
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Gypsum Board	d		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Office					
Provide a brief descriptio	n of operations:		Office space ar	nd airplane hanger storage				
Storage height of wareho	used products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:								
Protection:								
Are there any automatic s	sprinklers?	N	What	are the design densities for each area?		no sprinklers		
The water supply for auto	matic sprinklers is?		How n	nany hydrants are located within 500 feet of buildings?	•	blank		
Indicate the Alarm Covera	ages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ition?	N					
Is there a watchman servi	ice?	N	What i	s the frequency of rounds?				
Are watchman recording	rounds?		N					
Are there any fire extingu	ishers?	Υ	Are th	ey serviced annually?		Υ		
Are there any hose statio	ns?	N	Is ther	e a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid	Distan	ce:		2 miles	_	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
Is there a body of water n	earby?	N	Description:					
How far is the body of wa	ter from major buildings?							
Previous history of floodi	ng?	N	Description:					
Any property damage los	ses in the past 3 years:	N	Description:					

						Page 158
			Pr	operty Detail Form		
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF 1	TRANSPO	PRTATION		
Property:	Billings Equipment Storage	e 24 Bay				
Property Address:	424 Morey Lane BILLINGS	3				
Property ID:	5601-04					
Construction:						
Total number of insured l	buildings:	1		Total square footage of insured buildings:	23070	
Year built:		1981		Number of stories:	1	
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior masonr	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Garage	, Vehicle Storage		
Provide a brief description	on of operations:		Equipm	ent storage		
Storage height of warehoused products:		13'				
Are flammable and combustible liquids stored in a cut-off room?			N/A			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?	no sprinklers	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ation?		null		
ls there a watchman serv	rice?	N		What is the frequency of rounds?		
Are watchman recording	rounds?			N		
Are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ	
Are there any hose statio	ons?	N		Is there a fire private fire brigade?	N	
Frequency of training rec	ceived by the private fire b	rigade:				
Type of public fire depart	tment:	Paid		Distance:	2 miles	
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water n	nearby?	N	Descrip	otion:		
How far is the body of wa	ater from major buildings?					
Previous history of flood	ing?	N	Descrip	otion:		
Any property damage los	sses in the past 3 years:	N	Descrip	otion:		

Υ

Ν

2 miles

						Page 15		
			Proper	ty Detail Form				
Agency:	DEPARTMENT OF T	RANSPORTATION / DEPARTMEI	NT OF TRANSPORTA	TION				
Property:	Billings Office and Sh	ор						
Property Address:	424 Morey Lane BILL	LINGS						
Property ID:	5601-02							
Construction:								
Total number of insure	d buildings:	1		Total square footage of insured buildings:	21267			
Year built:		1981		Number of stories:	2			
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete			
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board			
Do major interior maso	nry walls (fire walls) ex	tend above the roofline?		N				
Occupancy:								
Occupancy Type:			Office					
Provide a brief descripe	tion of operations:		Offce, & equi	Offce, & equipment repair shop				
Storage height of ware	housed products:		N/A					
Are flammable and con	nbustible liquids stored	I in a cut-off room?	N/A					
Safegaurds taken for th	ne storage and dispens	ing of flammable liquids:	Υ					
Protection:								
Are there any automati	c sprinklers?	N	Wha	t are the design densities for each area?				
The water supply for au	utomatic sprinklers is?		How	many hydrants are located within 500 feet of build	dings? blank			
Indicate the Alarm Cov	erages provided for yo	ur facility:						
Are alarms connected t	to a constantly attende	d location?	null					
Is there a watchman se	rvice?	N	Wha	t is the frequency of rounds?				
Are watchman recording	ng rounds?		N					

Are they serviced annually?

Distance:

blank

Description:

Description:

Is there a fire private fire brigade?

Are there any fire extinguishers?

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

Exposure:

Υ

Ν

Paid

Ν

			Prope	erty Detail Form			
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	RANSPORTA	ATION			
Property:	Bozeman Rest Area						
Property Address:	3204 N. 19th Street BOZE	MAN					
Property ID:							
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	2598		
Year built:		2003		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced C	oncrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Roadside R	est Area			
Provide a brief description	on of operations:		Public restro	ooms			
Storage height of wareho	oused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ				
Protection:							
Are there any automatic	sprinklers?	N	Wh	at are the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings	?	blank	
Indicate the Alarm Cover	ages provided for your fac	cility:					
Are alarms connected to	a constantly attended loca	ation?	null	l'			
ls there a watchman serv	rice?	N	Wh	at is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire exting	uishers?	Υ	Are	they serviced annually?		Υ	
Are there any hose station	ons?	N	ls t	here a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	Dis	stance:		2 miles	
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
ls there a body of water i	nearby?	N	Description	n:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ling?	N	Description	n:			
Any property damage los	sses in the past 3 years:	N	Description	n:			

								- 3
			Pro	operty D	etail Form			
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	RANSPO	RTATION	ı			
Property:	Butte Office and Shop							
Property Address:	3751 Wynne Avenue BUTT	ΓE						
Property ID:	4704-02							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	20791		
Year built:		1970			Number of stories:	1		
Construction of roof:		Steel Deck			Construction of floors:	Reinforced C	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief description of operations:		Office &	Office & vechilce equipment repair shop					
Provide a brief description of operations:  Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:								
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?	?	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ation?		null				
ls there a watchman serv	rice?	N		What is t	he frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid		Distance	:		2 miles	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
ls there a body of water i	nearby?	N	Descrip	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ling?	N	Descrip	tion:				
Any property damage los	sses in the past 3 years:	N	Descrip	tion:				

							<u> </u>
			Propert	y Detail Form			
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	RANSPORTAT	TION			
Property:	Butte Storage 24 Bay						
Property Address:	3751 Wynne Avenue BUT	ТЕ					
Property ID:	4704-03						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	15600		
Year built:		1980		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Garage, Vehi	cle Storage			
Provide a brief description	on of operations:		Truck equipm	ent storage			
Storage height of wareho	oused products:		N/A				
Storage height of warehoused products:  Are flammable and combustible liquids stored in a cut-off room?  Safegaurds taken for the storage and dispensing of flammable liquids:		cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ				
Protection:							
Are there any automatic	sprinklers?	N	Wha	t are the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	?	blank	
Indicate the Alarm Cover	ages provided for your fac	cility:					
Are alarms connected to	a constantly attended loca	ation?	null				
ls there a watchman serv	rice?	N	Wha	t is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire exting	uishers?	Υ	Are t	hey serviced annually?		Υ	
Are there any hose station	ons?	N	Is the	ere a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	Dista	ince:		2 miles	
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
ls there a body of water i	nearby?	N	Description:				
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Description:				
Any property damage los	sses in the past 3 years:	N	Description:				

			Proper	rty Detail Form			
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	RANSPORTA	TION			
Property:	Culbertson Rest Area						
Property Address:	US 2 MP 645.2 CULBERT	SON					
Property ID:							
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	1408		
Year built:		2003		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced C	oncrete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Boa	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Roadside Re	est Area			
Provide a brief description	on of operations:		Roadside Re	estarea			
Storage height of wareho	oused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ				
Protection:							
Are there any automatic	sprinklers?	N	Wha	at are the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	?	blank	
Indicate the Alarm Cover	ages provided for your fac	cility:					
Are alarms connected to	a constantly attended loca	ation?	null				
ls there a watchman serv	rice?	N	Wha	at is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire exting	uishers?	Υ	Are	they serviced annually?		Υ	
Are there any hose static	ons?	N	Is th	nere a fire private fire brigade?		N	
Frequency of training red	Insured buildings:    1						
Type of public fire depar	tment:	Voluntary	Dist	ance:		1 miles	
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
ls there a body of water i	nearby?	N	Description	:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ling?	N	Description	:			
Any property damage los	sses in the past 3 years:	N	Description	:			

St Regis River

							i ago it
			Pı	operty Detail Form			
gency:	DEPARTMENT OF TRANS	PORTATION / DEPARTMENT OF T	TRANSPO	DRTATION			
Property:	Dena Mora Rest Area East						
roperty Address:	I 90 MP 4.6 SALTESE						
roperty ID:							
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	2088		
ear built:		2004		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Con	ncrete	
Construction of exterior	walls:	Tilt-Up Concrete		Construction of interior walls:	Masonry w/ Ope	enings	
o major interior mason	ry walls (fire walls) extend a	above the roofline?		N			
Occupancy:							
Occupancy Type:			Roadsi	de Rest Area			
Provide a brief description	on of operations:		Roadsi	de Restarea			
Storage height of wareho	oused products:		N/A				
are flammable and comb	oustible liquids stored in a	cut-off room?	N/A				
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?	ļ	no sprinklers	
he water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	ļ	blank	
ndicate the Alarm Cover	ages provided for your fac	lity:					
are alarms connected to	a constantly attended loca	tion?		N			
s there a watchman serv	rice?	N		What is the frequency of rounds?			
are watchman recording	rounds?			N			
are there any fire exting	uishers?	Υ		Are they serviced annually?	,	Υ	
are there any hose station	ons?	N		Is there a fire private fire brigade?	ļ	N	
requency of training re	ceived by the private fire br	igade:					
ype of public fire depar	tment:	Voluntary		Distance:		11 miles	
xposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
escribe the Occupancy	of those buildings(s) nearly	ov (within 100 feet):					

Description:

Description:

Description:

300 feet

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Υ

						Page 16
			Pı	operty Detail Form		
gency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT O	F TRANSPO	DRTATION		
Property:	Dena Mora Rest Area Wes	st				
roperty Address:	I 90 MP 4.6 SALTESE					
Property ID:						
Construction:						
otal number of insured	l buildings:	1		Total square footage of insured buildings:	2088	
ear built:		2004		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete	
construction of exterior	walls:	Tilt-Up Concrete		Construction of interior walls:	Masonry w/ Openings	
o major interior masor	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Roadsi	de Rest Area		
Provide a brief descripti	on of operations:		roadsic	le restarea		
Storage height of wareh	oused products:		n/a			
are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
afegaurds taken for the	e storage and dispensing o	f flammable liquids:	Υ			
Protection:						
are there any automatic	sprinklers?	N		What are the design densities for each area?		
he water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	s? blank	
ndicate the Alarm Cove	rages provided for your fac	cility:				
are alarms connected to	o a constantly attended loc	ation?		null		
s there a watchman ser	vice?	N		What is the frequency of rounds?		
are watchman recording	g rounds?			N		
are there any fire exting	juishers?	Υ		Are they serviced annually?	Y	
are there any hose stati	ons?	N		Is there a fire private fire brigade?	N	
requency of training re	eceived by the private fire b	rigade:				
ype of public fire depa	rtment:	Voluntary		Distance:	11 miles	

# Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Description:

How far is the body of water from major buildings?

Previous history of flooding?

Any property damage losses in the past 3 years: N

Description:

Description:

			Prope	rty Detail Form					
Agency:	DEPARTMENT OF TRANS	PORTATION / DEPARTMENT OF TR	RANSPORTA	ATION					
Property:	Glendive Equipment Shop								
Property Address:	123 River Road GLENDIVE	•							
Property ID:									
Construction:									
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	12000				
Year built:		blank		Number of stories:	1				
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete				
Construction of exterior v	valls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board				
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N					
Occupancy:									
Occupancy Type:			Garage, Ser	vice Center					
Provide a brief description	n of operations:		vehicle equi	vehicle equipment repair shop					
Storage height of warehoused products:		n/a							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:									
Protection:									
Are there any automatic s	sprinklers?	N	Wh	at are the design densities for each area?					
The water supply for auto	matic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?	blank				
Indicate the Alarm Covera	ages provided for your faci	ility:							
Are alarms connected to	a constantly attended loca	tion?	null						
Is there a watchman servi	ice?	N	Wha	at is the frequency of rounds?					
Are watchman recording	rounds?		N						
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?	Υ				
Are there any hose station	ns?	N	ls ti	here a fire private fire brigade?	N				
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire departs	ment:	Voluntary	Dis	tance:	2 miles				
Exposure:									
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	blank						
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):							
Is there a body of water n	earby?	N	Description	ı:					
How far is the body of wa	ter from major buildings?								
Previous history of floodi	ng?	N	Description	:					
Any property damage los	ses in the past 3 years:	N	Description	:					

					i age it
			Р	roperty Detail Form	
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF	F TRANSP	ORTATION	
Property:	Glendive Office and Shop				
Property Address:	503 N River Avenue GLEI	NDIVE			
Property ID:	1101-02				
Construction:					
Total number of insured	d buildings:	1		Total square footage of insured buildings:	23691
Year built:		1946		Number of stories:	1
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief descript	ion of operations:		mANU	FACTURING/OFFICES	
Storage height of wareh	noused products:		N/A		
Are flammable and com	nbustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	Υ		
Protection:					
Are there any automatic	c sprinklers?	N		What are the design densities for each area?	
The water supply for au	itomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank
Indicate the Alarm Cove	erages provided for your fac	cility:			
Are alarms connected t	o a constantly attended loca	ation?		N	
Is there a watchman se	rvice?	N		What is the frequency of rounds?	
Are watchman recordin	g rounds?			N	
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ
Are there any hose stat	ions?	N		Is there a fire private fire brigade?	N
Frequency of training re	eceived by the private fire b	rigade:			
Type of public fire depart	artment:	Voluntary		Distance:	1/2 mile
Exposure:					
How many buildings(no	ot part of Account) are within	n 100 feet of insured buildings?	blank		

Description:

Description:

300 yards

River

Last flood 12 years ago

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Υ

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

						Page 1
			Pro	operty Detail Form		
Agency:	DEPARTMENT OF TRAN	SPORTATION / DEPARTMENT OF	TRANSPO	PRTATION		
Property:	Great Falls Office and Sho	рр				
Property Address:	104 18th Avenue NE GRE	AT FALLS				
Property ID:	0701-02					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	18024	
Year built:		1963		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descript	ion of operations:		equipme	ent shop attached to office		
Storage height of wareh	noused products:		n/a			
Are flammable and com	nbustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	Υ			
Protection:						
Are there any automatic	c sprinklers?	N		What are the design densities for each area?		
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	? blank	
Indicate the Alarm Cove	erages provided for your fa	cility:				
Are alarms connected t	o a constantly attended loc	ation?		null		
Is there a watchman ser	rvice?	N		What is the frequency of rounds?		
Are watchman recording	g rounds?			N		
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?	N	
Frequency of training re	eceived by the private fire b	rigade:				
Type of public fire depa	artment:	Paid		Distance:	1 mile	

**Exposure:** 

How many buildings(not part of Account) are within 100 feet of insured buildings? 0 Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Description:

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Description: Ν

Any property damage losses in the past 3 years: N

Description:

						i age it
			Pr	roperty Detail Form		
gency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	TRANSPO	ORTATION		
Property:	Havre Office and Shop					
roperty Address:	1649 US-2 NW HAVRE					
Property ID:	2101-02					
Construction:						
otal number of insured	buildings:	1		Total square footage of insured buildings:	21276	
ear built:		1953		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
o major interior masoni	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief description of operations:		equipm	ent shop attached to office			
storage height of wareho	oused products:		n/a			
are flammable and comb	oustible liquids stored in a	cut-off room?	N/A			
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ			
Protection:						
are there any automatic	sprinklers?	N		What are the design densities for each area?		
he water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank	
ndicate the Alarm Cover	ages provided for your fac	ility:				
are alarms connected to	a constantly attended loca	ition?		null		
s there a watchman serv	rice?	N		What is the frequency of rounds?		
are watchman recording	rounds?			N		
are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ	
are there any hose station	ons?	N		Is there a fire private fire brigade?	N	
requency of training rec	ceived by the private fire br	igade:				
ype of public fire depart	tment:	Paid		Distance:	1 mile	
xposure:						
low many buildings(not	part of Account) are within	100 feet of insured buildings?	0			

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

					1 490 1				
			Pro	perty Detail Form					
Agency:	DEPARTMENT OF TRANS	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION							
Property:	Helena Headquarters Core	Helena Headquarters Core Drill							
Property Address:	2701 Prospect Ave. HELE	NA							
Property ID:									
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	18939				
Year built:		2002		Number of stories:	1				
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete				
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board				
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Garage, S	Service Center					
Provide a brief description of operations:			office and	office and equipment storage					
Storage height of warehoused products:			n/a						
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A						
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	Υ						
Protection:									
Are there any automatic	sprinklers?	N	V	What are the design densities for each area?					
The water supply for aut	tomatic sprinklers is?		H	low many hydrants are located within 500 feet of buildings?	blank				
Indicate the Alarm Cove	rages provided for your fac	cility:							
Are alarms connected to	a constantly attended loca	ation?	r	ull					
Is there a watchman ser	vice?	N	V	What is the frequency of rounds?					
Are watchman recording	g rounds?		١	I					
Are there any fire exting	uishers?	Υ	A	are they serviced annually?	Υ				
Are there any hose static	ons?	N	l:	s there a fire private fire brigade?	N				
Frequency of training re	ceived by the private fire b	rigade:							
Type of public fire depart	rtment:	Paid		Distance:	1 mile				
Exposure:									
How many buildings(not	t part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water	nearby?	N	Descripti	on:					

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Previous history of flooding?

						Page 171
			Р	Property Detail Form		
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF	TRANSP	PORTATION		
Property:	Helena Headquarters Moto	r Pool Office				
Property Address:	2701 Prospect Avenue HE	LENA				
Property ID:	2512-03					
Construction:						
Total number of insured	l buildings:	1		Total square footage of insured buildings:	1000	
Year built:		blank		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descripti	ion of operations:		Motor	pool office		
Storage height of warehoused products:		n/a				
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	e storage and dispensing of	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	s? blank	
ndicate the Alarm Cove	rages provided for your fac	ility:				
Are alarms connected to	o a constantly attended loca	ation?		null		
s there a watchman ser	vice?	N		What is the frequency of rounds?		
Are watchman recording	g rounds?			N		
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stati	ons?	N		Is there a fire private fire brigade?	null	
Frequency of training re	eceived by the private fire bu	rigade:				
Гуре of public fire depa	rtment:	Paid		Distance:	1 mile	
Exposure:						
	t part of Account) are withir	100 feet of insured buildings?	0			
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):				
s there a body of water	nearby?	N	Descri	iption:		

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Previous history of flooding?

					1 ugo 11
			Pr	operty Detail Form	
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	TRANSPO	DRTATION	
Property:	Helena Headquarters Office	e Complex			
Property Address:	2701 Prospect Avenue HEI	_ENA			
Property ID:	2512-02				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	186236
Year built:		1978		Number of stories:	3
Construction of roof:		Reinforced Concrete		Construction of floors:	Poured Concrete
Construction of exterior	walls:	Tilt-Up Concrete		Construction of interior walls:	Gypsum Board
Do major interior mason	ry walls (fire walls) extend	above the roofline?		Υ	
Occupancy:					
Occupancy Type:			Govern	mental Building	
Provide a brief description	on of operations:		OFFICE	ES	
Storage height of wareh	oused products:		N/A		
Are flammable and com	bustible liquids stored in a	cut-off room?	Υ		
Safegaurds taken for the	e storage and dispensing of	flammable liquids:	Υ		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	? blank
Indicate the Alarm Cove	rages provided for your fac	ility:		Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Wa	terflow
Are alarms connected to	a constantly attended loca	ition?		Υ	
Is there a watchman serv	vice?	N		What is the frequency of rounds?	
Are watchman recording	g rounds?			N	
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose static	ons?	Υ		Is there a fire private fire brigade?	N
Frequency of training re	ceived by the private fire br	igade:			
Type of public fire depar	rtment:	Paid		Distance:	blank
Exposure:					
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			

Description:

Description:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

Ν

	Property Detail Fo
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION
Property:	Helena Headquarters Section House

Property Address: 2701 Prospect Avenue HELENA

**Property ID:** 2512-09

<u> </u>	 	
Consi	ınn	

Total number of insured buildings: 1 Total square footage of insured buildings: 16000

Year built: 1995 Number of stories:

Construction of roof: Steel Deck Construction of floors: Reinforced Concrete

Construction of exterior walls: Corrugated Metal Panel Construction of interior walls: Gypsum Board

Do major interior masonry walls (fire walls) extend above the roofline?

### Occupancy:

Occupancy Type: Garage, Vehicle Storage

Provide a brief description of operations: Offices & vehicle storage

Storage height of warehoused products: NA

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids:

## Protection:

Are there any automatic sprinklers? N What are the design densities for each area?

The water supply for automatic sprinklers is? How many hydrants are located within 500 feet of buildings? blank

Indicate the Alarm Coverages provided for your facility:

Are alarms connected to a constantly attended location?

Is there a watchman service? N What is the frequency of rounds?

Are watchman recording rounds?

Are there any fire extinguishers?

Y

Are they serviced annually?

Y

Are there any hose stations?

N Is there a fire private fire brigade?

N

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: 1 Mile

#### **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings? blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? N Description:

How far is the body of water from major buildings?

Previous history of flooding? N Description:

Any property damage losses in the past 3 years: N Description:

Property Detail Form	
PORTATION	

			Pro	perty Detail Form				
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	RANSPOF	TATION				
Property:	Helena Headquarters Shop	Complex						
Property Address:	2701 Prospect Avenue HE	LENA						
Property ID:	2512-04							
Construction:								
Total number of insured	buildings:	1		Total square footage of insure	d buildings:	30607		
Year built:		1981		Number of stories:		2		
Construction of roof:		Poured Concrete		Construction of floors:		Reinforced Concrete	е	
Construction of exterior	walls:	Tilt-Up Concrete		Construction of interior walls:		Gypsum Board		
Do major interior masoni	y walls (fire walls) extend	above the roofline?		null				
Occupancy:								
Occupancy Type:			Garage,	Service Center				
Provide a brief description	on of operations:		OFFICES	/FABRICATION/REPAIR				
Storage height of wareho	oused products:		N/A					
Are flammable and comb	ustible liquids stored in a	cut-off room?	Υ					
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ					
Protection:								I
Are there any automatic	sprinklers?	N	V	What are the design densities for each a	area?			
The water supply for auto	omatic sprinklers is?		H	low many hydrants are located within 5	500 feet of buildings?	blan	k	
Indicate the Alarm Cover	ages provided for your fac	ility:	9	moke Detectors, Sprinkler Waterflow				
Are alarms connected to	a constantly attended loca	ation?	١					
ls there a watchman serv	ice?	N	V	What is the frequency of rounds?				
Are watchman recording	rounds?		١	I				
Are there any fire extingu	uishers?	Υ	A	re they serviced annually?		Υ		
Are there any hose statio	ons?	Υ	l:	s there a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid		distance:		blan	k	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
ls there a body of water r	nearby?	N	Descript	on:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descript	on:				
Any property damage los	sses in the past 3 years:	null	Descript	on:				

							Page 17
			Pro	operty Detail Form			
agency:	DEPARTMENT OF TRANSPO	ORTATION / DEPARTMENT OF T	TRANSPO	RTATION			
Property:	Helena Headquarters Sign an	d Maintenance Shop					
roperty Address:	2701 Prospect HELENA						
Property ID:	2512-08						
Construction:							
otal number of insured	buildings: 1			Total square footage of insured buildings:	3600		
ear built:	19	985		Number of stories:	1		
Construction of roof:	n	ull		Construction of floors:	null		
Construction of exterior	walls: no	ull		Construction of interior walls:	null		
o major interior mason	ry walls (fire walls) extend ab	ove the roofline?		null			
Occupancy:							
Occupancy Type:			Storage				
Provide a brief description	on of operations:		Equipme	ent Maintenance/Sign Shop			
storage height of wareho	oused products:		blank				
are flammable and comb	oustible liquids stored in a cu	t-off room?	null				
afegaurds taken for the	storage and dispensing of fla	ammable liquids:	Υ				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?			
he water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings	?	blank	
ndicate the Alarm Cover	ages provided for your facilit	y:		blank			
are alarms connected to	a constantly attended location	on?		null			
s there a watchman serv	rice?	null		What is the frequency of rounds?			
are watchman recording	rounds?						
are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ	
are there any hose station	ons?	null		Is there a fire private fire brigade?		null	
requency of training red	ceived by the private fire briga	ade:					
ype of public fire depar	tment:	null		Distance:		blank	
xposure:							

blank

Description:

Description:

Description:

## How many buildings(not part of Account) are within 100 feet of insured buildings?

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

null

null

								- 3
			Pr	operty D	etail Form			
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANS				1			
Property:	Kalispell Office and Shop							
Property Address:	85 5th Avenue EN KALISP	ELL						
Property ID:	1501-02							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	17868		
Year built:		1999			Number of stories:	1		
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Corrugated Metal Panel			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief description	on of operations:		OFFICE	E AND EQ	UIPMENT REPAIR, SHOP COMBINATION			
Storage height of wareho	used products:		N/A					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings?	•	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ition?		N				
Is there a watchman serv	ice?	N		What is t	he frequency of rounds?		n/a	
Are watchman recording	rounds?			N				
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N		Is there a	a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid		Distance	:		blank	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
Is there a body of water r	nearby?	null	Descri	otion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descri	otion:				
Any property damage los	ses in the past 3 years:	N	Descri	otion:				

			Pr	operty D	etail Form			
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	RANSPO	ORTATION	ı			
Property:	Lewistown Maintenance Sh	пор						
Property Address:	1620 Airport Road LEWIST	OWN						
Property ID:	1409-02							
Construction:								
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	18000		
Year built:		1963			Number of stories:	2		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior v	valls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief descriptio	n of operations:		Office &	k equipme	nt repair shop			
Storage height of wareho	used products:		N/A					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
Are there any automatic s	sprinklers?	N		What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings?	•	blank	
Indicate the Alarm Covera	ages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ition?		null				
ls there a watchman serv	ice?	N		What is t	he frequency of rounds?			
Are watchman recording	rounds?							
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N		Is there a	a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire depart	ment:	Paid		Distance	:		1 mile	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
ls there a body of water n	earby?	N	Descrip	otion:				
How far is the body of wa	ter from major buildings?							
Previous history of floodi	ng?	N	Descrip	otion:				
Any property damage los	ses in the past 3 years:	N	Descrip	otion:				

			Pro	perty De	etail Form			
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION							
Property:	Lost Trail Rest Area							
Property Address:	US 93 MP 0.0 MISSOULA							
Property ID:								
Construction:								
Total number of insured buildings:		1		Total square footage of insured buildings:		807		
Year built:		2003			Number of stories:	1		
Construction of roof:	etion of roof: Wood Joists				Construction of floors:	Reinforced Concrete		
Construction of exterior walls: Wood Frame		Wood Frame			Construction of interior walls:	Gypsum Board		
Do major interior masonry walls (fire walls) extend above the roofline?					N			
Occupancy:								
Occupancy Type:			Roadside Rest Area					
Provide a brief description of operations:			Public rest area					
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ					
Protection:								
Are there any automatic	sprinklers?	N	V	What are	the design densities for each area?			
The water supply for automatic sprinklers is?		H	low man	y hydrants are located within 500 feet of buildings?		blank		
Indicate the Alarm Coverages provided for your facility:								
Are alarms connected to a constantly attended location?				null				
ls there a watchman serv	there a watchman service? null		What is the frequency of rounds?					
Are watchman recording	rounds?		N	١				
Are there any fire extingu	uishers?	Υ	A	Are they s	serviced annually?		Υ	
Are there any hose static	ons?	N	ls	s there a	fire private fire brigade?		N	
Frequency of training red	ceived by the private fire br	igade:						
Type of public fire depart	tment:	Voluntary		Distance:			13 miles	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water nearby?		Description:						
How far is the body of wa	ater from major buildings?							
Previous history of flood	revious history of flooding?		Description:					
Any property damage los	sses in the past 3 years:	N	Descripti	ion:				

			Pro	perty Detail Form				
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION							
Property:	Miles City Office and Shop							
Property Address:	217 N. 4th Street MILES C	ITY						
Property ID:	0901-10							
Construction:								
Total number of insured buildings: 1		1		Total square footage of insured buildings:	18500			
Year built:		1997		Number of stories:	2			
Construction of roof:	struction of roof: Steel Deck w/ Fasterners			Construction of floors:	Reinforced Concrete			
Construction of exterior	onstruction of exterior walls: Corrugated Metal Panel		Construction of interior walls: G		Gypsum Board			
Do major interior masonry walls (fire walls) extend above the roofline?				N				
Occupancy:								
Occupancy Type:			Office					
Provide a brief description of operations:			Offices & equipment repair shop					
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ						
Protection:								
Are there any automatic	sprinklers?	N	\	What are the design densities for each area?				
The water supply for aut	omatic sprinklers is?		H	How many hydrants are located within 500 feet of buildings?	blank			
Indicate the Alarm Cover	ages provided for your fac	ility:						
Are alarms connected to a constantly attended location?			r	null				
ls there a watchman serv	there a watchman service? null		١	What is the frequency of rounds?				
Are watchman recording	rounds?		1	N				
Are there any fire exting	uishers?	Υ	,	Are they serviced annually?	Υ			
Are there any hose station	ons?	N	ı	s there a fire private fire brigade?	N			
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid		Distance:	1.5 miles			
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
s there a body of water nearby?		Description:						
How far is the body of wa	ater from major buildings?							
Previous history of flooding?		Description:						
Any property damage los	sses in the past 3 years:	N	Descript	ion:				

			Pr	operty D	etail Form			
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION							
Property:	Missoula Headquarters Office and Shop							
Property Address:	2100 West Broadway MISSOULA							
Property ID:	3211-02							
Construction:								
Total number of insured buildings: 1		1			Total square footage of insured buildings:	18177		
Year built:		1968			Number of stories:	2		
Construction of roof:	uction of roof: Wood Joists			Construction of floors: Reinforced Co		oncrete		
Construction of exterior	nstruction of exterior walls: Masonry			Construction of interior walls: Gypsum Board		<sup>-</sup> d		
Do major interior masonry walls (fire walls) extend above the roofline?					N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief description of operations:			Offices & equipment repair shop					
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?			
The water supply for automatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings?	,	blank		
Indicate the Alarm Coverages provided for your facility:								
Are alarms connected to a constantly attended location?				null				
ls there a watchman serv	there a watchman service?		What is the frequency of rounds?					
Are watchman recording	rounds?			N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose station	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depart	tment:	Paid		Distance	r.		1 mile	
Exposure:								
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water nearby?		Description:						
How far is the body of wa	ater from major buildings?							
Previous history of flood	revious history of flooding?		Description:					
Any property damage los	sses in the past 3 years:	N	Descrip	otion:				

					9-	-		
			Pro	perty Detail Form				
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF T	RANSPOR	RTATION				
Property:	Scobey Section House							
Property Address:	Highway 5 SCOBEY							
Property ID:								
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	15600			
Year built:		1978		Number of stories:	1			
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete			
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board			
Do major interior masor	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Garage,	Vehicle Storage				
Provide a brief descripti	on of operations:		Offices, v	Offices, vehicle equipment storage				
Storage height of wareh	oused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the	e storage and dispensing of	flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N	1	What are the design densities for each area?				
The water supply for au	tomatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?	blank			
Indicate the Alarm Cove	rages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ition?	r	null				
Is there a watchman ser	vice?	null	\	What is the frequency of rounds?				
Are watchman recording	g rounds?		1	N				
Are there any fire exting	uishers?	Υ	,	Are they serviced annually?	Υ			
Are there any hose stati	ons?	null	ı	s there a fire private fire brigade?	null			
Frequency of training re	ceived by the private fire br	igade:						
Type of public fire depa	rtment:	Voluntary	I	Distance:	1 Mile			
Exposure:								
How many buildings(no	t part of Account) are withir	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Descript	ion:				
How far is the body of w	rater from major buildings?							
Previous history of floo	ding?	N	Descript	ion:				
Any property damage lo	sses in the past 3 years:	N	Descript	ion:				

			Proper	ty Detail Form	
Agency:	DEPARTMENT OF TRANS	SPORTATION / DEPARTMENT OF TI	RANSPORTA <sup>*</sup>	TION	
Property:	Sweetgrass Rest Area				
Property Address:	I 15 MP 389.2 SWEET GRA	ASS			
Property ID:					
Construction:					
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	2800
Year built:		2002		Number of stories:	1
Construction of roof:		Other		Construction of floors:	Reinforced Concrete
Construction of exterior v	valls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ Fire Doors
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N	
Occupancy:					
Occupancy Type:			Roadside Re	est Area	
Provide a brief descriptio	n of operations:		Roadside res	st area	
Storage height of wareho	used products:		N/A		
Are flammable and combustible liquids stored in a cut-off room?			N/A		
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A		
Protection:					
Are there any automatic s	sprinklers?	N	Wha	at are the design densities for each area?	
The water supply for auto	matic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	blank
Indicate the Alarm Covera	ages provided for your faci	ility:			
Are alarms connected to	a constantly attended loca	tion?	null		
Is there a watchman servi	ice?	null	Wha	at is the frequency of rounds?	
Are watchman recording	rounds?		N		
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?	Υ
Are there any hose station	ns?	N	Is th	ere a fire private fire brigade?	N
Frequency of training rec	eived by the private fire br	igade:			
Type of public fire depart	ment:	Voluntary	Dista	ance:	1 mile
Exposure:					
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	blank		
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):			
Is there a body of water n	earby?	N	Description:	:	
How far is the body of wa	ter from major buildings?				
Previous history of floodi	ng?	N	Description:	:	
Any property damage los	ses in the past 3 years:	N	Description:	:	

	Property Detail Fo
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION
Property:	West Yellowstone Aeronautics Office

	1 Topotty Detail
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION
Property:	West Yellowstone Aeronautics Office
Property Address:	721 Yellowstone Airport Road WEST YELLOWSTONE
Property ID:	1

$\sim$	nstr			
. n		1112	ď	101

Construction of roof:

Year built:

Total number of insured buildings: 1

1965

Total square footage of insured buildings: Number of stories:

10704 2

Wood Joists

Ν

Ν

Construction of floors:

Construction of interior walls:

Reinforced Concrete

Construction of exterior walls: Masonry

Gypsum Board

Do major interior masonry walls (fire walls) extend above the roofline?

# Occupancy:

**Occupancy Type:** 

Provide a brief description of operations:

Office

Storage height of warehoused products:

Airline offices, cafe, gift shop, car rental company

Are flammable and combustible liquids stored in a cut-off room?

N/A N/A

Safegaurds taken for the storage and dispensing of flammable liquids:

N/A

Protection:

## Are there any automatic sprinklers?

The water supply for automatic sprinklers is?

How many hydrants are located within 500 feet of buildings?

What are the design densities for each area?

blank

Indicate the Alarm Coverages provided for your facility:

Are alarms connected to a constantly attended location?

null

Is there a watchman service?

Ν What is the frequency of rounds?

Are watchman recording rounds?

Are there any fire extinguishers?

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Are they serviced annually?

Υ null

Frequency of training received by the private fire brigade:

Voluntary

Ν

Ν

Is there a fire private fire brigade?

2 miles

## Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How far is the body of water from major buildings?

Description:

Distance:

Previous history of flooding?

Description:

Any property damage losses in the past 3 years:

						Page 18	
			P	operty Detail Form			
Agency:	DEPARTMENT OF TRANSPORTATION / DEPARTMENT OF TRANSPORTATION						
Property:	Wolf Point Office and Shop						
Property Address:	200 E. HWY 25 WOLF POI	NT					
Property ID:	4301-02						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	12417		
Year built:		1937		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board		
Do major interior mason	ry walls (fire walls) extend a	above the roofline?		N			
Occupancy:							
Occupancy Type:			Office				
Provide a brief description	on of operations:		Office 8	k vehicle equipment shop			
Storage height of wareho	oused products:		N/A				
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank		
ndicate the Alarm Cover	rages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	tion?		null			
s there a watchman serv	vice?	N		What is the frequency of rounds?			
Are watchman recording	rounds?						
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ		

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Ν

Ν

Voluntary

Distance:

Is there a fire private fire brigade? Ν

1 mile

Frequency of training received by the private fire brigade:

Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0 Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How far is the body of water from major buildings?

Previous history of flooding?

Description: Ν

Any property damage losses in the past 3 years: N

Description:

			Pr	operty Detail Form		
gency:	HISTORICAL SOCIETY / M	ONTANA HISTORICAL SOCIETY				
Property:	Moss Mansion					
Property Address:	914 Division Street BILLING	SS				
roperty ID:						
Construction:						
otal number of insured b	ouildings:	1		Total square footage of insured buildings:	12311	
ear built:		1902		Number of stories:	3	
Construction of roof:		Other		Construction of floors:	Wood Timber	
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Other	
o major interior masonr	y walls (fire walls) extend a	bove the roofline?		N		
Occupancy:						
Occupancy Type:			Museur	m		
Provide a brief descriptio	n of operations:		Historic	house museum-life at the turn of the century		
storage height of wareho	used products:		0			
re flammable and combustible liquids stored in a cut-off room?			N			
afegaurds taken for the	storage and dispensing of	flammable liquids:	N			
Protection:						
are there any automatic s	sprinklers?	N		What are the design densities for each area?		no sprinklers
he water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		3
ndicate the Alarm Covera	ages provided for your faci	lity:		Burglar Alarms (Door Contacts), Burglar Alarms (Motion Detection	n), Smoke Dete	ectors
are alarms connected to	a constantly attended loca	tion?		Υ		
s there a watchman servi	ice?	N		What is the frequency of rounds?		
are watchman recording	rounds?			N		
are there any fire extingu	ishers?	Υ		Are they serviced annually?		Υ
are there any hose statio	ns?	N		Is there a fire private fire brigade?		N
requency of training rec	eived by the private fire br	igade:				
ype of public fire depart	ment:	Paid		Distance:		1 mile
xposure:						
low many buildings(not	part of Account) are within	100 feet of insured buildings?	1			
escribe the Occupancy	of those buildings(s) nearb	y (within 100 feet):	restrooi	ms & storage		
s there a body of water n	earby?	N	Descri	ption:		
low far is the body of wa	ter from major buildings?					
revious history of floodi	ing?	N	Descri	ption:		
any property damage los	ses in the past 3 years:	N	Descri	ption:		

			Pr	operty Detail Form	
Agency:	HISTORICAL SOCIETY / N	MONTANA HISTORICAL SOCIETY			
Property:	Preservation Office				
Property Address:	1301 East Lockey Ave HEL	_ENA			
Property ID:	LE				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	0
Year built:		blank		Number of stories:	1
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief description	on of operations:		office-a	ssistance to property owners and historical archive maintenance	
Storage height of wareho	oused products:		n/a		
Are flammable and comb	oustible liquids stored in a	cut-off room?	N		
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N		
Protection:					
Are there any automatic	sprinklers?	N		What are the design densities for each area?	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	blank
ndicate the Alarm Cover	ages provided for your fac	ility:		Smoke Detectors	
Are alarms connected to	a constantly attended loca	ation?		null	
s there a watchman serv	rice?	null		What is the frequency of rounds?	
Are watchman recording	rounds?				
Are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose statio	ons?	null		Is there a fire private fire brigade?	null
requency of training rec	ceived by the private fire br	rigade:			
Type of public fire depart	tment:	Paid		Distance:	blank
Exposure:					
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
s there a body of water r	nearby?	N	Descrip	otion:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ing?	N	Descrip	otion:	
Any property damage los	sses in the past 3 years:	N	Descrip	otion:	

			Pro	perty Detail Form	
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN SE	ERVICES, MONTANA DEVELOPMENTAL CENTER	
Property:	Administration bldg 7				
Property Address:	310 4th Avenue BOULDER				
Property ID:	7				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	8099
Year built:		1996		Number of stories:	1
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N	
Occupancy:					
Occupancy Type:			Office		
Provide a brief description	on of operations:		OFFICES	S/HEALTH CARE	
Storage height of wareho	used products:		N/A		
Are flammable and comb	ustible liquids stored in a d	cut-off room?	N/A		
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	Υ	V	What are the design densities for each area?	
The water supply for auto	omatic sprinklers is?	Public	ŀ	How many hydrants are located within 500 feet of buildings?	7
Indicate the Alarm Cover	ages provided for your faci	ility:	Smoke Detectors, Sprinkler Valve Tamper		
Are alarms connected to	a constantly attended loca	tion?	١	Y	
Is there a watchman serv	ice?	Υ	V	What is the frequency of rounds?	
Are watchman recording	rounds?		١	Y	
Are there any fire extingu	ishers?	Υ	A	Are they serviced annually?	Υ
Are there any hose statio	ns?	N	l:	s there a fire private fire brigade?	N
Frequency of training red	eived by the private fire br	igade:			
Type of public fire depart	ment:	Voluntary	[	Distance:	7 BLOCKS
Exposure:					
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):			
Is there a body of water r	nearby?	Υ	Descript	ion:	BOULDER RIVER
How far is the body of wa	ater from major buildings?		500 FT.		
Previous history of flood	ing?	Υ	Descript	ion:	RIVER RAN BANKS IN 1981 BLDG DID NOT EXIST
Any property damage los	ses in the past 3 years:	N	Descript	ion:	

			Pr	operty Detail Form		
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN S	SERVICES, STATE HOSPITAL		
Property:	Administrative Annex					
Property Address:	58 Garnet Way WARM SPF	RINGS				
Property ID:	113					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	22141	
Year built:		1919		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior mason	ry walls (fire walls) extend a	above the roofline?		null		
Occupancy:						
Occupancy Type:			Office			
Provide a brief description	on of operations:		Offices			
Storage height of wareho	oused products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?			N/A			
Safegaurds taken for the	e storage and dispensing of	flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	1	
Indicate the Alarm Cover	rages provided for your fac	ility:	Smoke Detectors			
Are alarms connected to	a constantly attended loca	tion?		N		
Is there a watchman serv	vice?	N		What is the frequency of rounds?		
Are watchman recording	ı rounds?					
Are there any fire exting	uishers?	N		Are they serviced annually?	null	
Are there any hose static	ons?	Υ		Is there a fire private fire brigade?	null	
Frequency of training re-	ceived by the private fire br	igade:				
Type of public fire depar	tment:	Part-Paid		Distance:	blanl	k
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):				
Is there a body of water	nearby?	N	Descrip	otion:		
How far is the body of w	ater from major buildings?					
Previous history of flood	ling?	N	Descrip	otion:		
Any property damage los	sses in the past 3 years:	N	Descrip	otion:		

							1 490 100
			Prop	perty Detail Form			
Agency:	PUBLIC HEALTH & HUMA	AN SERVICES / PUBLIC HEALTH & I	HUMAN SEF	RVICES			
Property:	Billings - Lease #8037A/81	104A					
Property Address:	2121 Rosebud Suite C-D-I	E BILLINGS					
Property ID:	6901-8037A						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	16494		
Year built:		1988		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Boar	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Office				
Provide a brief description	on of operations:		State office	es			
Storage height of wareh	oused products:		N/A				
Are flammable and comi	oustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ	w	hat are the design densities for each area?		Unknown	
The water supply for aut	omatic sprinklers is?	Public	H	low many hydrants are located within 500 feet of buildings?	•	blank	
Indicate the Alarm Cove	rages provided for your fac	cility:	Sr	moke Detectors			
Are alarms connected to	a constantly attended loc	ation?	nı	ull			
Is there a watchman serv	vice?	null	w	What is the frequency of rounds?			
Are watchman recording	g rounds?						
Are there any fire exting	uishers?	null	A	re they serviced annually?		null	
Are there any hose static	ons?	null	Is	s there a fire private fire brigade?		null	
Frequency of training re	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	Di	istance:		blank	
Exposure:							
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water	nearby?	N	Description	on:			
How far is the body of w	ater from major buildings?	•					
Previous history of flood	ding?	null	Description	on:			
Any property damage lo	sses in the past 3 years:	null	Description	on:			

			Pro	perty Detail Form	
Agency:	PUBLIC HEALTH & HUMAI	N SERVICES / PUBLIC HEALTH & I	HUMAN SE	ERVICES, MONTANA DEVELOPMENTAL CENTER	
Property:	BLDG 4				
Property Address:	310 4th Avenue BOULDER				
Property ID:	4				
Construction:					
Total number of insured b	uildings:	1		Total square footage of insured buildings:	4041
Year built:		1996		Number of stories:	1
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber
Construction of exterior w	ralls:	Wood Frame		Construction of interior walls:	Gypsum Board
Do major interior masonry	walls (fire walls) extend a	above the roofline?		N	
Occupancy:					
Occupancy Type:			Cottages	Residential	
Provide a brief description	of operations:		10 BED (	COTTAGE	
Storage height of warehou	used products:		N/A		
Are flammable and combustible liquids stored in a cut-off room?			N/A		
Safegaurds taken for the storage and dispensing of flammable liquids:					
Protection:					
Are there any automatic sp	prinklers?	Υ	\	What are the design densities for each area?	
The water supply for autor	matic sprinklers is?	Public	ŀ	How many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Covera	ges provided for your faci	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected to a	constantly attended loca	tion?	`	Y	
Is there a watchman service	ce?	N	1	What is the frequency of rounds?	
Are watchman recording r	ounds?		1	N	
Are there any fire extingui	shers?	Υ	,	Are they serviced annually?	Υ
Are there any hose station	ns?	N	ı	s there a fire private fire brigade?	N
Frequency of training rece	eived by the private fire br	igade:			
Type of public fire departn	nent:	Paid	I	Distance:	blank
Exposure:					
How many buildings(not p	eart of Account) are within	100 feet of insured buildings?	0		
Describe the Occupancy of	of those buildings(s) near	by (within 100 feet):			
Is there a body of water ne	earby?	Υ	Descript	ion:	BOULDER RIVER
How far is the body of wat	er from major buildings?		800 FT.		
Previous history of flooding	ng?	N	Descript	ion:	
Any property damage loss	ses in the past 3 years:	N	Descript	ion:	

			Property	/ Detail Form					
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & H	UMAN SERVIC	ES, MONTANA DEVELOPMENTAL CENTER					
Property:	Bldg 1								
Property Address:	310 4th Avenue BOULDER								
Property ID:	1								
Construction:									
Total number of insured I	ouildings:	1		Total square footage of insured buildings:	3362				
Year built:		1996		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber				
Construction of exterior v	walls:	Wood Frame		Construction of interior walls:	Gypsum Board				
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Cottages/Resi	dential					
Provide a brief descriptio	n of operations:		6 BED COTTA	GE					
Storage height of wareho	used products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		flammable liquids:	N/A						
Protection:									
Are there any automatic s	sprinklers?	Υ	What	are the design densities for each area?					
The water supply for auto	omatic sprinklers is?	Public	How r	nany hydrants are located within 500 feet of buildings?	2				
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to	a constantly attended loca	ition?	Υ						
Is there a watchman serv	ice?	N	What	is the frequency of rounds?					
Are watchman recording	rounds?		N						
Are there any fire extingu	ishers?	Υ	Are th	ey serviced annually?	Υ				
Are there any hose statio	ns?	N	Is the	re a fire private fire brigade?	N				
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid	Dista	nce:	blank				
Exposure:									
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):							
Is there a body of water n	earby?	Υ	Description:		BOULDER RIVER				
How far is the body of wa	ter from major buildings?		1,000 FT.						
Previous history of floodi	ing?	N	Description:						
Any property damage los	ses in the past 3 years:	N	Description:						

			Pr	operty Detail Form				
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH &	HUMAN S	SERVICES, MONTANA DEVELOPMENTAL CENTER				
Property:	BLDG 2							
Property Address:	310 4th Avenue BOULDER	₹						
Property ID:	2							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	3362			
Year built:		1996		Number of stories:	1			
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber			
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board			
Do major interior masonry walls (fire walls) extend above the roofline?		above the roofline?		N				
Occupancy:								
Occupancy Type:			Cottage	es/Residential				
Provide a brief description of operations:			6 BED	6 BED COTTAGE				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?				
The water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	2			
Indicate the Alarm Cove	rages provided for your fac	ility:		Sprinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors				
Are alarms connected to	o a constantly attended loca	ation?		Υ				
Is there a watchman ser	vice?	N		What is the frequency of rounds?				
Are watchman recording	g rounds?			N				
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ			
Are there any hose stati	ons?	N		Is there a fire private fire brigade?	N			
Frequency of training re	ceived by the private fire b	rigade:						
Type of public fire depa	rtment:	Paid		Distance:	blank			
Exposure:								
How many buildings(no	t part of Account) are withir	n 100 feet of insured buildings?	0					
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	Υ	Descri	ption:	BOULDER RIVER			
How far is the body of w	ater from major buildings?		1,000 F	T.				
Previous history of floor	ding?	N	Descri	ption:				
Any property damage lo	sses in the past 3 years:	N	Descri	ption:				

			Pro	operty Detail Form					
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & I	HUMAN S	SERVICES, MONTANA DEVELOPMENTAL CENTER					
Property:	BLDG 3								
Property Address:	310 4th Avenue BOULDER								
Property ID:	3								
Construction:									
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	4041				
Year built:		1996		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber				
Construction of exterior v	valls:	Wood Frame		Construction of interior walls:	Gypsum Board				
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N					
Occupancy:									
Occupancy Type:			Cottage	s/Residential					
Provide a brief descriptio	n of operations:		10 BED	10 BED COTTAGE					
Storage height of warehoused products:		N/A							
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic s	prinklers?	Υ		What are the design densities for each area?					
The water supply for auto	matic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	? 2				
Indicate the Alarm Covera	ages provided for your fac	ility:	Sprinkler Waterflow, Smoke Detectors, Sprinkler Valve Tamper						
Are alarms connected to	a constantly attended loca	tion?		Υ					
Is there a watchman servi	ce?	N		What is the frequency of rounds?					
Are watchman recording	rounds?			N					
Are there any fire extingu	ishers?	Υ		Are they serviced annually?	Υ				
Are there any hose station	ns?	N		Is there a fire private fire brigade?	N				
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid		Distance:	blank				
Exposure:									
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):							
Is there a body of water n	earby?	Υ	Descrip	otion:	BOULDER RIVER				
How far is the body of wa	ter from major buildings?		800 FT.						
Previous history of floodi	ng?	N	Descrip	otion:					
Any property damage los	ses in the past 3 years:	N	Descrip	otion:					

	Property Detail Form									
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN SE	RVICES, MONTANA DEVELOPMENTAL CENTER						
Property:	BLDG 5									
Property Address:	310 4th Avenue BOULDER									
Property ID:	5									
Construction:										
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	4653					
Year built:		1996		Number of stories:	1					
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber					
Construction of exterior v	valls:	Wood Frame		Construction of interior walls:	Gypsum Board					
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		null						
Occupancy:										
Occupancy Type:			Cottages/	/Residential						
Provide a brief descriptio	n of operations:		12 BED 0	12 BED COTTAGE						
Storage height of warehoused products:			N/A							
Are flammable and combustible liquids stored in a cut-off room?		N								
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A								
Protection:										
Are there any automatic s	sprinklers?	Υ	V	What are the design densities for each area?						
The water supply for auto	matic sprinklers is?	Public	H	How many hydrants are located within 500 feet of buildings?	3					
Indicate the Alarm Covera	ages provided for your fac	ility:	S	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to	a constantly attended loca	ition?	Y	′						
Is there a watchman servi	ice?	N	V	What is the frequency of rounds?						
Are watchman recording	rounds?		N	N						
Are there any fire extingu	ishers?	Υ	P	Are they serviced annually?	Υ					
Are there any hose station	ns?	N	ls	s there a fire private fire brigade?	N					
Frequency of training rec	eived by the private fire br	igade:								
Type of public fire depart	ment:	Paid		Distance:	blank					
Exposure:										
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0							
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):								
Is there a body of water n	earby?	Υ	Descripti	ion:	BOULDER RIVER					
How far is the body of wa	ter from major buildings?		600 FT.							
Previous history of floodi	ng?	null	Descripti	ion:						
Any property damage los	ses in the past 3 years:	N	Descripti	ion:						

			Pr	operty Detail Form				
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH &	HUMAN S	SERVICES, MONTANA DEVELOPMENTAL CENTER				
Property:	BLDG 6							
Property Address:	310 4th Avenue BOULDER							
Property ID:	6							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	4653			
Year built:		1996		Number of stories:	1			
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber			
Construction of exterior w	alls:	Wood Frame		Construction of interior walls:	Gypsum Board			
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N				
Occupancy:								
Occupancy Type:			Cottage	es/Residential				
Provide a brief description	n of operations:		12 BED	12 BED COTTAGE				
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?			N					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic s	prinklers?	Υ		What are the design densities for each area?				
The water supply for auto	matic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?				
Indicate the Alarm Covera	ges provided for your fac	ility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
Are alarms connected to a	a constantly attended loca	tion?		Υ				
Is there a watchman servi	ce?	N		What is the frequency of rounds?				
Are watchman recording	rounds?			N				
Are there any fire extingu	ishers?	Υ		Are they serviced annually?	Υ			
Are there any hose station	ns?	N		Is there a fire private fire brigade?	N			
Frequency of training reco	eived by the private fire br	igade:						
Type of public fire departi	ment:	Paid		Distance:	blank			
Exposure:								
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
Is there a body of water no	earby?	Υ	Descrip	ption:	BOULDER RIVER			
How far is the body of war	ter from major buildings?		600 FT.					
Previous history of floodi	ng?	N	Descrip	ption:				
Any property damage los	ses in the past 3 years:	N	Descri	ption:				

			Fſ	operty Detail Form					
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH &	HUMAN S	SERVICES, VETERANS' HOME - GLENDIVE					
Property:	Eastern Montana Veteran's	Home							
Property Address:	2000 Montana Avenue GLE	ENDIVE							
Property ID:									
Construction:									
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	49340				
Year built:		1995		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete			
Construction of exterior v	/alls:	Masonry		Construction of interior walls: Gypsum Board		rd			
Do major interior masonr	walls (fire walls) extend	above the roofline?		Υ					
Occupancy:									
Occupancy Type:			Hospita	Hospital, Nursing Home					
Provide a brief descriptio	n of operations:		Veteran	Veterans Nursing Home					
Storage height of wareho	used products:		N/A	N/A					
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ							
Protection:									
Are there any automatic s	prinklers?	Υ		What are the design densities for each area?					
The water supply for auto	matic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings	?	2			
Indicate the Alarm Covera	ges provided for your fac	ility:	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to	a constantly attended loca	ntion?		Υ					
Is there a watchman servi	ce?	N		What is the frequency of rounds?					
Are watchman recording	rounds?			N					
Are there any fire extingu	ishers?	Υ		Are they serviced annually?		Υ			
Are there any hose station	ns?	N		Is there a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid		Distance:		3 MILES			
Exposure:									
How many buildings(not p	part of Account) are withir	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	0						
Is there a body of water n	earby?	null	Descrip	otion:	RIVER				
How far is the body of wa	ter from major buildings?		1 MILE						
Previous history of floodi	ng?	N	Descrip	otion:					
Any property damage los	ses in the past 3 years:	N	Descrip	otion:					

Property Detail Form									
Agency: PU	BLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN S	SERVICES, VETERANS' HOME - GLENDIVE					
Property: Ga	rage								
Property Address: 200	00 Montana Ave GLEND	IVE							
Property ID:									
Construction:									
Total number of insured build	lings:	1		Total square footage of insured buildings:	2530				
Year built:		1995		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	ncrete			
Construction of exterior walls	s:	Masonry		Construction of interior walls:	Gypsum Board	d			
Do major interior masonry wa	alls (fire walls) extend	above the roofline?		Υ					
Occupancy:									
Occupancy Type:			Garage,	, Vehicle Storage					
Provide a brief description of	operations:		GARAG	SE & STORAGE					
Storage height of warehouse	d products:		N/A	N/A					
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the storage and dispensing of flammable liquids:		flammable liquids:	Υ						
Protection:									
Are there any automatic sprir	nklers?	N		What are the design densities for each area?					
The water supply for automat	ic sprinklers is?			How many hydrants are located within 500 feet of buildings?		2			
Indicate the Alarm Coverages	s provided for your fac	ility:							
Are alarms connected to a co	nstantly attended loca	tion?		null					
Is there a watchman service?		N		What is the frequency of rounds?					
Are watchman recording roun	nds?								
Are there any fire extinguished	ers?	Υ		Are they serviced annually?		Υ			
Are there any hose stations?		N		Is there a fire private fire brigade?		N			
Frequency of training receive	ed by the private fire br	igade:							
Type of public fire departmen	nt:	Paid		Distance:		3 MILES			
Exposure:									
How many buildings(not part	of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy of the	nose buildings(s) nearl	by (within 100 feet):							
Is there a body of water nearly	by?	Υ	Descrip	otion:	RIVER				
How far is the body of water t	rom major buildings?		1 MILE						
Previous history of flooding?		N	Descrip	otion:					
Any property damage losses	in the past 3 years:	N	Descrip	otion:					

							i age is
			Prope	erty Detail Form			
Agency:	PUBLIC HEALTH & HUMAN	SERVICES / PUBLIC HEALTH & F	HUMAN SER	VICES			
Property:	Great Falls - Lease #8023A	& 8043A					
Property Address:	201 1st St. S GREAT FALLS						
Property ID:	6901-8023						
Construction:							
Total number of insured	buildings: 1			Total square footage of insured buildings:	32964		
Year built:	b	olank		Number of stories:	1		
Construction of roof:	r	null		Construction of floors:	null		
Construction of exterior	walls: r	null		Construction of interior walls:	null		
Do major interior masoni	ry walls (fire walls) extend at	pove the roofline?		null			
Occupancy:							
Occupancy Type:			Office				
Provide a brief description	on of operations:		State offices	s			
Storage height of wareho	oused products:		N/A				
Are flammable and comb	oustible liquids stored in a cu	ut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of f	lammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ	Wh	at are the design densities for each area?		Unknown	
The water supply for auto	omatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings	?	blank	
ndicate the Alarm Cover	ages provided for your facili	ity:	Sm	oke Detectors			
Are alarms connected to	a constantly attended locati	on?	null	I			
s there a watchman serv	rice?	null	Wh	at is the frequency of rounds?			
Are watchman recording	rounds?						
Are there any fire extingu	uishers?	null	Are	they serviced annually?		null	
Are there any hose static	ons?	null	ls t	here a fire private fire brigade?		null	
Frequency of training red	ceived by the private fire brig	gade:					
Гуре of public fire depart	tment:	Paid	Dis	stance:		blank	
Exposure:							

How many buildings(not part of Account) are within 100 feet of insured buildings?

blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? null

Description:

How far is the body of water from major buildings?

Previous history of flooding?

Description: null

Any property damage losses in the past 3 years:

								Page 19		
			Pro	perty De	etail Form					
Agency:	PUBLIC HEALTH & HUM/	AN SERVICES / PUBLIC HEALTH &	HUMAN SE	ERVICES						
Property:	Helena - Commodity Ware	ehouse								
Property Address:	1400 Carter Drive HELEN	A								
Property ID:	Owned									
Construction:										
Total number of insured	buildings:	1			Total square footage of insured buildings:	44301				
Year built:		1996			Number of stories:	2				
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Poured Conc	rete			
Construction of exterior	erior walls: Corrugated Metal Panel				Construction of interior walls:	Gypsum Boa	rd			
Do major interior masonry walls (fire walls) extend above the roofline?				null						
Occupancy:										
Occupancy Type:			Quonset	Quonset Warehouse						
Provide a brief description of operations:			WAREHO	OUSE						
Storage height of warehoused products:			20 FEET							
Are flammable and combustible liquids stored in a cut-off room?			N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A								
Protection:										
Are there any automatic	sprinklers?	Υ	,	What are	the design densities for each area?		UNKNOWN			
The water supply for au	tomatic sprinklers is?	Public	ŀ	How man	y hydrants are located within 500 feet of buildings	?	2			
Indicate the Alarm Cove	rages provided for your fa	cility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow							
Are alarms connected to	a constantly attended loc	ation?	`	Υ						
ls there a watchman ser	vice?	N	1	What is th	he frequency of rounds?					
Are watchman recording	g rounds?									
Are there any fire exting	uishers?	Υ	,	Are they	serviced annually?		Υ			
Are there any hose stati	ons?	null	ı	ls there a	fire private fire brigade?		null			
Frequency of training re	ceived by the private fire b	rigade:								
Type of public fire depa	rtment:	Paid	I	Distance:	:		blank			
Exposure:										
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	0							
Describe the Occupancy	y of those buildings(s) near	rby (within 100 feet):								
Is there a body of water	nearby?	N	Descript	tion:						
How far is the body of w	rater from major buildings?	•								
Previous history of floo	ding?	N	Descript	tion:						
Any property damage lo	sses in the past 3 years:	null	Descript	tion:						

			Pro	perty D	etail Form			
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & H	IUMAN S	ERVICES	3			
Property:	Helena - Lease #8015A &	#8143 for QAD/BFSD/CSED/FH/PRC						
Property Address:	2401 Colonial Dr HELENA							
Property ID:	6901-8015							
Construction:								
Total number of insured I	buildings:	1			Total square footage of insured buildings:	48301		
Year built:		2000			Number of stories:	3		
Construction of roof:		Steel Deck			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior v	walls:	Glass and Steel Curtain			Construction of interior walls:	Gypsum Board	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief descriptio	on of operations:		OFFICE	S				
Storage height of wareho	oused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	Υ		What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How man	ny hydrants are located within 500 feet of buildings?		3	
Indicate the Alarm Cover	ages provided for your fac	ility:	Fire Pump Alarms					
Are alarms connected to	a constantly attended loca	ation?		Y				
ls there a watchman serv	ice?	Υ		What is t	he frequency of rounds?			
Are watchman recording	rounds?			Y				
Are there any fire extingu	iishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ons?	Υ		ls there a	i fire private fire brigade?		N	
Frequency of training rec	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid		Distance	:		1 MILE	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	nearby?	N	Descrip	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	tion:				
Any property damage los	sses in the past 3 years:	N	Descrip	tion:				

			Property	Detail Form	
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN SERVIC	ES, MONTANA DEVELOPMENTAL CENTER	
Property:	Industries/Heating bldg 9				
Property Address:	310 4th Avenue BOULDER	R			
Property ID:	9				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	8437
Year built:		1996		Number of stories:	1
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Power Plant		
Provide a brief description	on of operations:		BOILER PLANT	T/CAN-PAPER PROCESSING	
Storage height of wareho	oused products:		6 FT MAX		
Are flammable and combustible liquids stored in a cut-off room?		N/A			
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A			
Protection:					
Are there any automatic	sprinklers?	N	What a	re the design densities for each area?	
The water supply for auto	omatic sprinklers is?	Public	How m	nany hydrants are located within 500 feet of buildings?	7
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	ation?	Υ		
Is there a watchman serv	rice?	Υ	What i	s the frequency of rounds?	
Are watchman recording	rounds?		Υ		
Are there any fire extingu	uishers?	Υ	Are the	ey serviced annually?	Υ
Are there any hose static	ons?	N	Is there	e a fire private fire brigade?	N
Frequency of training red	ceived by the private fire b	rigade:			
Type of public fire depart	tment:	Voluntary	Distan	ce:	7 BLOCKS
Exposure:					
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water i	nearby?	Υ	Description:		BOULDER RIVER
How far is the body of wa	ater from major buildings?		500 FT.		
Previous history of flood	ing?	Υ	Description:		RIVER RAN ITS BANKS IN 1981 BLDG DID NOT EXIST
Any property damage los	sses in the past 3 years:	N	Description:		

								- 3
			Pr	operty D	etail Form			
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN S	SERVICES				
Property:	Kalispell - Lease #8075							
Property Address:	121 Financial Dr KALISPEI	.L						
Property ID:	6901-8075							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	25009		
Year built:		2007			Number of stories:	2		
Construction of roof:		Wood Joists			Construction of floors:	Other		
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	d	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			null			
Occupancy:								
Occupancy Type:			Office					
Provide a brief description of operations:		OFFICE	S					
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		UNKNOWN	
The water supply for auto	omatic sprinklers is?	Public	How many hydrants are located within 500 feet of buildings?				1	
Indicate the Alarm Cover	ages provided for your fac	ility:	Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ition?		null				
Is there a watchman serv	rice?	N		What is t	he frequency of rounds?			
Are watchman recording	rounds?							
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose static	ons?	Υ		Is there a	fire private fire brigade?		null	
Frequency of training red	ceived by the private fire b	igade:						
Type of public fire depart	tment:	Paid		Distance	:		blank	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	null	Descrip	otion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	otion:				
Any property damage los	sses in the past 3 years:	N	Descrip	otion:				

					- 3	
			Prop	perty Detail Form		
Agency:	PUBLIC HEALTH & HUM	AN SERVICES / PUBLIC HEALTH &	HUMAN SEF	RVICES, MENTAL HEALTH NURSING CARE CENTER		
Property:	Main Building & Addition					
Property Address:	800 Casino Creek Drive L	EWISTOWN				
Property ID:	1					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	76707	
Year built:		1952		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterio	r walls:	Other		Construction of interior walls:	Masonry	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			Hospital, N	Nursing Home		
Provide a brief description of operations:		Offices, R	fices, Res. long term care fac.			
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A				
Protection:						
Are there any automatic	sprinklers?	Υ	w	hat are the design densities for each area?		
The water supply for au	tomatic sprinklers is?	Public	Н	ow many hydrants are located within 500 feet of buildin	ngs? 6	
Indicate the Alarm Cove	erages provided for your fa	cility:	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected t	o a constantly attended loc	ation?	Υ			
Is there a watchman se	rvice?	null	w	/hat is the frequency of rounds?		
Are watchman recording	g rounds?		N			
Are there any fire exting	guishers?	Υ	A	re they serviced annually?	Υ	
Are there any hose stat	ions?	N	Is	there a fire private fire brigade?	null	
Frequency of training re	eceived by the private fire b	rigade:				
Type of public fire depart	rtment:	Paid	Di	istance:	1 Mile	
Exposure:						
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	3			
Describe the Occupano	y of those buildings(s) nea	rby (within 100 feet):	Church &	Two houses		
Is there a body of water	nearby?	Υ	Description	on:	Creek w/2 ponds	
How far is the body of v	vater from major buildings?	?	500 Yards			
Previous history of floo	ding?	N	Description	on:		
Any property damage le	osses in the past 3 years:	N	Description	on:		

			Pr	operty D	Detail Form			
Agency:	PUBLIC HEALTH & HUMA	AN SERVICES / PUBLIC HEALTH & F	HUMAN S	SERVICES	S			
Property:	Missoula - Lease #8019 O	PA/CFS (Reg & Co)/QAD/IHSB/ECSE	B/PAB					
Property Address:	2677 Palmer St MISSOUL	A						
Property ID:	6901-8019							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	35000		
Year built:		2000			Number of stories:	2		
Construction of roof:		Wood Joists			Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masoni	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Office					
Provide a brief description	on of operations:		Offices					
Storage height of wareho	oused products:		N/A					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	e the design densities for each area?		Unknown	
The water supply for auto	omatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?	?	1	
Indicate the Alarm Cover	ages provided for your fac	cility:		Smoke D	Detectors, Sprinkler Waterflow, Sprinkler Valve Tamper			
Are alarms connected to	a constantly attended loca	ation?		N				
ls there a watchman serv	ice?	N		What is	the frequency of rounds?			
Are watchman recording	rounds?							
Are there any fire extingu	iishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ons?	N		Is there	a fire private fire brigade?		N	
Frequency of training red	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid		Distance	e:		blank	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Descrip	otion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	null	Descrip	otion:				
Any property damage los	sses in the past 3 years:	N	Descrip	otion:				

			Pro	operty Detail Form	
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & H	IUMAN S	SERVICES, STATE HOSPITAL	
Property:	New Hospital				
Property Address:	100 Garnet Way WARM SI	PRINGS			
Property ID:	220				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	85863
Year built:		2000		Number of stories:	1
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Hospital	, Nursing Home	
Provide a brief description of operations:			PSYCH	IATRIC HOSPITAL	
Storage height of warehoused products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?		N/A			
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A		
Protection:					
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?	
The water supply for auto	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	blank
Indicate the Alarm Cover	ages provided for your fac	ility:		Sprinkler Waterflow, Smoke Detectors, Sprinkler Valve Tamper	
Are alarms connected to	a constantly attended loca	ation?		Υ	
ls there a watchman serv	rice?	N		What is the frequency of rounds?	
Are watchman recording	rounds?			N	
Are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ
Are there any hose statio	ons?	N		Is there a fire private fire brigade?	Υ
Frequency of training rec	eived by the private fire b	rigade:			
Type of public fire depart	ment:	Part-Paid		Distance:	blank
Exposure:					
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	blank		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water r	nearby?	N	Descrip	tion:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ing?	N	Descrip	tion:	
Any property damage los	sses in the past 3 years:	N	Descrip	tion:	

			Pro	operty Detail Form		
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN S	SERVICES, VETERANS' HOME - COLUMBIA FALLS		
Property:	Nursing Home & Dom &Sp	ecial Care Unit 69-73-84-02				
Property Address:	400 Veterans Dr. COLUME	SIA FALLS				
Property ID:	31					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	70065	
Year built:		1970		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd
Do major interior mason	ry walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			Hospital	I, Nursing Home		
Provide a brief description	on of operations:		Nursing	Home/Personal Care		
Storage height of warehoused products:		18				
Are flammable and combustible liquids stored in a cut-off room?		Υ				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		
The water supply for aut	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of built	ildings?	6
Indicate the Alarm Cover	ages provided for your fac	ility:	Burglar Alarms (Motion Detection), Smoke Detectors, Sprinkler Waterflow, Sprinkler Valve Tamper			
Are alarms connected to	a constantly attended loca	ation?		Υ		
ls there a watchman serv	rice?	N		What is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ
Are there any hose static	ons?	Υ		Is there a fire private fire brigade?		N
Frequency of training re	ceived by the private fire b	rigade:				
Type of public fire depar	tment:	Voluntary		Distance:		3 Miles
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	2			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Service	Bldg/Old Main		
Is there a body of water	nearby?	Υ	Descrip	otion:	River	
How far is the body of w	ater from major buildings?		1000 fee	et		
Previous history of flood	ling?	N	Descrip	otion:		
Any property damage lo	sses in the past 3 years:	N	Descrip	otion:		

			Property	Detail Form		
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	IUMAN SERVIC	ES, MONTANA DEVELOPMENTAL CENTER		
Property:	Nutrition/Distribution BLDG	3 10A-10B				
Property Address:	310 4th Avenue BOULDER					
Property ID:	10					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	8689	
Year built:		1990		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Other			
Provide a brief description	on of operations:		FOOD SERVIC	E/DINING/WAREHOUSE		
Storage height of wareho	oused products:		17FT.			
Are flammable and combustible liquids stored in a cut-off room?		Υ				
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ			
Protection:						
Are there any automatic	sprinklers?	Υ	What a	are the design densities for each area?		
The water supply for auto	omatic sprinklers is?	Public	How m	nany hydrants are located within 500 feet of buildings?	7	
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loca	tion?	Υ			
Is there a watchman serv	rice?	Υ	What i	s the frequency of rounds?		
Are watchman recording	rounds?		Υ			
Are there any fire extingu	uishers?	Υ	Are the	ey serviced annually?	Υ	
Are there any hose static	ons?	N	Is there	e a fire private fire brigade?	N	
Frequency of training red	ceived by the private fire br	igade:				
Type of public fire depart	tment:	Voluntary	Distan	ce:	7 BLOCKS	
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank			
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):				
Is there a body of water r	nearby?	Υ	Description:		BOULDER RIVER	
How far is the body of wa	ater from major buildings?		500 FT.			
Previous history of flood	ling?	Υ	Description:		RIVER RAN BANKS IN 1981 BLDG DID NOT EXIST	
Any property damage los	sses in the past 3 years:	N	Description:		LAG	

			Property	Detail Form		
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & H	UMAN SERVICE	S, VETERANS' HOME - COLUMBIA FALLS		
Property:	Original Old Main Building	(NOT USED)				
Property Address:	400 Veterans Dr. COLUMB	IA FALLS				
Property ID:	1					
Construction:						
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	14329	
Year built:		1896		Number of stories:	3	
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber	
Construction of exterior v	valls:	Wood Frame		Construction of interior walls:	Other	
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N		
Occupancy:						
Occupancy Type:			Other			
Provide a brief descriptio	n of operations:		Historical list bld	g./not used		
Storage height of wareho	used products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N			
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A			
Protection:						
Are there any automatic s	sprinklers?	N	What ar	re the design densities for each area?		N/A
The water supply for auto	matic sprinklers is?		How ma	any hydrants are located within 500 feet of buildings?		4
Indicate the Alarm Covera	ages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	tion?	N			
Is there a watchman servi	ice?	N	What is	the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire extingu	ishers?	N	Are the	y serviced annually?		N
Are there any hose station	ns?	N	Is there	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	igade:				
Type of public fire depart	ment:	Voluntary	Distanc	e:		3 Miles
Exposure:						
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	1			
Describe the Occupancy	of those buildings(s) near	oy (within 100 feet):	House Temp. No	ursing/Storage		
Is there a body of water n	earby?	Υ	Description:		River	
How far is the body of wa	ter from major buildings?		1000 Feet			
Previous history of floodi	ng?	N	Description:			
Any property damage los	ses in the past 3 years:	N	Description:			

			Pr	roperty Detail Form					
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	IUMAN S	SERVICES, STATE HOSPITAL					
Property:	Recovery Center								
Property Address:	32 Trapper Way WARM SF	RINGS							
Property ID:	217								
Construction:									
Total number of insured l	buildings:	1		Total square footage of insured buildings:	16953				
Year built:		1971		Number of stories:	1				
Construction of roof:		Steel Deck		Construction of floors:	Poured Concre	rete			
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Gypsum Board	rd			
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N					
Occupancy:									
Occupancy Type:			Office						
Provide a brief description of operations:			Record	Records, business, classrooms					
Storage height of warehoused products:			N/A	/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A						
Protection:									
Are there any automatic s	sprinklers?	N		What are the design densities for each area?					
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		2			
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke Detectors						
Are alarms connected to	a constantly attended loca	tion?		Υ					
ls there a watchman serv	ice?	N		What is the frequency of rounds?					
Are watchman recording	rounds?								
Are there any fire extingu	ishers?	Υ		Are they serviced annually?		Υ			
Are there any hose statio	ns?	N		Is there a fire private fire brigade?		Υ			
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Part-Paid		Distance:		blank			
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):							
ls there a body of water n	earby?	N	Descrip	ption:					
How far is the body of water from major buildings?									
Previous history of flooding?			Description:						
Any property damage los	ses in the past 3 years:	N	Descrip	ption:					

Property Detail Form									
Agency: PUBLIC	HEALTH & HUMAN	I SERVICES / PUBLIC HEALTH & F	IUMAN SERVICE	S, MONTANA DEVELOPMENTAL CENTER					
Property: Recreat	tion 102								
Property Address: 310 4th	Avenue BOULDER								
Property ID: 102									
Construction:									
Total number of insured buildings	s:	1		Total square footage of insured buildings:	21357				
Year built:		1950		Number of stories:	1				
Construction of roof:	;	Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete				
Construction of exterior walls:	1	Masonry		Construction of interior walls:	Masonry w/ Fire Doors				
Do major interior masonry walls (	fire walls) extend a	bove the roofline?		N					
Occupancy:									
Occupancy Type:			Governmental Bu	uilding					
Provide a brief description of ope	erations:		RECREATION/E	DUCATION/HEALTH CARE					
Storage height of warehoused pro	oducts:		6 FT MAX						
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A						
Protection:									
Are there any automatic sprinkler	rs?	Υ	What ar	e the design densities for each area?					
The water supply for automatic sp	prinklers is?	Public	How ma	ny hydrants are located within 500 feet of buildings?	5				
Indicate the Alarm Coverages pro	vided for your facil	ity:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to a consta	antly attended locat	ion?	Υ						
Is there a watchman service?		N	What is	the frequency of rounds?					
Are watchman recording rounds?	?		N						
Are there any fire extinguishers?		Υ	Are they	serviced annually?	Υ				
Are there any hose stations?		N	Is there	a fire private fire brigade?	N				
Frequency of training received by	the private fire bri	gade:							
Type of public fire department:		Voluntary	Distance	e:	7 BLOCKS				
Exposure:									
How many buildings(not part of A	account) are within	100 feet of insured buildings?	0						
Describe the Occupancy of those	buildings(s) nearb	y (within 100 feet):							
Is there a body of water nearby?	,	Υ	Description:		BOULDER RIVER				
How far is the body of water from	major buildings?		500 FT.						
Previous history of flooding?	•	Υ	Description:		RIVER RAN BANKS IN 1981 NO DAMAGE				
Any property damage losses in th	ne past 3 years:	N	Description:						

								1 490 211	
			Pro	perty De	etail Form				
Agency:	PUBLIC HEALTH & HUMA	AN SERVICES / PUBLIC HEALTH & I	HUMAN SE	RVICES	, VETERANS' HOME - COLUMBIA FALLS				
Property:	Service Building								
Property Address:	400 Veterans Dr. COLUME	BIA FALLS							
Property ID:	2								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	5806			
Year built:		1917			Number of stories:	2			
Construction of roof:		Wood Joists			Construction of floors:	Wood Timber	r		
Construction of exterior	walls:	Masonry			Construction of interior walls:	Gypsum Boa	rd		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			Chapel						
Provide a brief description of operations:			Used for	sed for Training and Temp Services Personnel					
Storage height of warehoused products:			Do Not K	o Not Know					
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	Υ	\	What are	the design densities for each area?		Meets Code		
The water supply for aut	omatic sprinklers is?	Public	H	How man	y hydrants are located within 500 feet of buildings	?	4		
Indicate the Alarm Cove	rages provided for your fac	cility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to	a constantly attended loca	ation?	١	Y					
ls there a watchman ser	vice?	N	١	What is tl	he frequency of rounds?		N/A		
Are watchman recording	g rounds?		1	N					
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose stati	ons?	Υ	I	s there a	fire private fire brigade?		N		
Frequency of training re	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Voluntary	[	Distance:	:		3 miles		
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	1						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	Nursing H	Home					
ls there a body of water	nearby?	N	Descript	ion:					
How far is the body of w	ater from major buildings?	,							
Previous history of flood	ling?	N	Descript	ion:					
Any property damage lo	sses in the past 3 years:	N	Descript	ion:					

			Pr	roperty [	Detail Form			
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & F	HUMAN S	SERVICE	S, STATE HOSPITAL			
Property:	Spratt Building 219							
Property Address:	351 Fleecer Way WARM S	PRINGS						
Property ID:	219							
Construction:								
Total number of insured I	buildings:	1			Total square footage of insured buildings:	19061		
Year built:		1976			Number of stories:	1		
Construction of roof:		Concrete Panels			Construction of floors:	Other		
Construction of exterior v	walls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Hospita	al, Nursing	Home			
Provide a brief description of operations:			PSYCH	HIATRIC H	OSPITAL			
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	Υ		What are	e the design densities for each area?			
The water supply for auto	omatic sprinklers is?	Public		How ma	ny hydrants are located within 500 feet of buildings	•	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ation?		Υ				
ls there a watchman serv	ice?	N		What is	the frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N		Is there	a fire private fire brigade?		Υ	
Frequency of training rec	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Part-Paid		Distance	e:		blank	
Exposure:								
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	earby?	N	Descri	ption:				
How far is the body of wa	ter from major buildings?							
Previous history of floodi	ing?	N	Descri	ption:				
Any property damage los	ses in the past 3 years:	N	Descri	ption:				

							Page 21
			Prop	perty Detail Form			
Agency:	PUBLIC HEALTH 8	HUMAN SERVICES / PUBLIC HE	ALTH & HUMAN SE	RVICES, STATE HOSPITAL			
Property:	Storage Shed						
Property Address:	100 Garnet Way W	ARM SPRINGS					
Property ID:	422						
Construction:							
Total number of insur	ed buildings:	1		Total square footage of insured buildings:	120		
Year built:		1952		Number of stories:	1		
Construction of roof:		null		Construction of floors:	null		
Construction of exteri	ior walls:	null		Construction of interior walls:	null		
Do major interior mas	onry walls (fire walls)	extend above the roofline?		null			
Occupancy:							
Occupancy Type:			Garage, F	Parts Storage			
Provide a brief descri	ption of operations:		blank				
Storage height of war	ehoused products:		7 ft				
Are flammable and co	ombustible liquids store	ed in a cut-off room?	N/A				
Safegaurds taken for	the storage and dispen	sing of flammable liquids:	N/A				
Protection:							
Are there any automa	tic sprinklers?	N	v	hat are the design densities for each area?			
The water supply for a	automatic sprinklers is	?	н	ow many hydrants are located within 500 feet of building	gs?	blank	
Indicate the Alarm Co	verages provided for y	our facility:					
Are alarms connected	I to a constantly attend	ed location?	n	ull			
Is there a watchman s	service?	null	v	/hat is the frequency of rounds?			
Are watchman record	ing rounds?						
Are there any fire exti	nguishers?	null	A	re they serviced annually?		null	
Are there any hose sta	ations?	null	ls	there a fire private fire brigade?		null	
Frequency of training	received by the private	e fire brigade:					
Type of public fire dep	partment:	null	D	istance:		blank	
Exposure:							

How many buildings(not part of Account) are within 100 feet of insured buildings?

blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? null How far is the body of water from major buildings?

Description:

Previous history of flooding?

Description: null

Any property damage losses in the past 3 years:

								- 3 -
			Pro	operty Detail	Form			
Agency:	PUBLIC HEALTH & HUMA	N SERVICES / PUBLIC HEALTH & I	HUMAN SE	SERVICES, STA	ATE HOSPITAL			
Property:	Theraputic Learning Center	r						
Property Address:	156 Garnet Way WARM SE	PRINGS						
Property ID:	102							
Construction:								
Total number of insured b	ouildings:	1		Tota	al square footage of insured buildings:	20638		
Year built:		1951		Nun	nber of stories:	1		
Construction of roof:		Other		Con	struction of floors:	Poured Conci	rete	
Construction of exterior v	valls:	Masonry		Con	struction of interior walls:	Masonry w/ F	ire Doors	
Do major interior masonry walls (fire walls) extend above the roofline?			N					
Occupancy:								
Occupancy Type:			Governm	mental Building				
Provide a brief description of operations:			PHYSICA	CAL, SOCIAL, 8	EDUCATIONAL ACTIVITIES			
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	N	'	What are the	design densities for each area?			
The water supply for auto	omatic sprinklers is?		ŀ	How many hy	drants are located within 500 feet of buildings	s?	blank	
Indicate the Alarm Covera	ages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ition?	r	null				
ls there a watchman servi	ice?	N	•	What is the fr	equency of rounds?			
Are watchman recording	rounds?		1	N				
Are there any fire extingu	ishers?	Υ	,	Are they serv	iced annually?		null	
Are there any hose statio	ns?	N	ı	Is there a fire	private fire brigade?		Υ	
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire depart	ment:	Part-Paid	I	Distance:			blank	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	earby?	N	Descript	otion:				
How far is the body of wa	ter from major buildings?							
Previous history of flooding?		N	Description:					
Any property damage los	ses in the past 3 years:	N	Descript	otion:				

Property Detail Form										
Agency:	PUBLIC HEALTH & HUMAN SERVICES / PUBLIC HEALTH & HUMAN SERVICES, MONTANA DEVELOPMENTAL CENTER									
Property:	Treatment BLDG 8									
Property Address:	310 4th Avenue BOULDER									
Property ID:	8									
Construction:										
Total number of insured buildings:		1		Total square footage of insured buildings:	16000					
Year built:		1996		Number of stories:	1					
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete					
Construction of exterior walls:		Masonry		Construction of interior walls:	Gypsum Board					
Do major interior masonry walls (fire walls) extend above the roofline?			N							
Occupancy:										
Occupancy Type:			Governmental Building							
Provide a brief description of operations:			HEALTH CAF	RE TREATMENT SER/CLASSROOMS						
Storage height of warehoused products:			6 FT MAX							
Are flammable and combustible liquids stored in a cut-off room?			N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A							
Protection:										
Are there any automatic	sprinklers?	Υ	Wha	are the design densities for each area?						
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	7					
Indicate the Alarm Coverages provided for your facility:			Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow							
Are alarms connected to a constantly attended location?			Υ							
Is there a watchman serv	e a watchman service?		Wha	What is the frequency of rounds?						
Are watchman recording	atchman recording rounds?		Υ							
Are there any fire extingu	iishers?	Υ	Are t	hey serviced annually?	Υ					
Are there any hose statio	ons?	N	Is the	ere a fire private fire brigade?	N					
Frequency of training received by the private fire brigade:										
Type of public fire depart	ment:	Voluntary	Dista	nce:	7 BLOCKS					
Exposure:										
How many buildings(not part of Account) are within 100 feet of insured buildings?			0							
Describe the Occupancy of those buildings(s) nearby (within 100 feet):										
Is there a body of water r	nearby?	Υ	Description:		BOULDER RIVER					
How far is the body of water from major buildings?		500 FT.								
Previous history of flood	ing?	Υ	Description:		RIVER RAN BANKS IN 1981 BLDG DID NOT EXIST					
Any property damage los	sses in the past 3 years:	N	Description:							

			Pro	operty D	etaii Form			
gency:	STATE FUND / STATE FU	ND						
roperty:	Montana State Fund Building							
Property Address:	855 Front Street HELENA							
Property ID:	61030							
Construction:								
otal number of insured buildings:		1			Total square footage of insured buildings:	117203		
ear built:		2010			Number of stories:	4		
Construction of roof: Steel Deck		Steel Deck			Construction of floors:	Poured Concre	te	
Construction of exterior walls:		Masonry			Construction of interior walls:	Gypsum Board		
o major interior masonry walls (fire walls) extend above the roofline?					null			
Occupancy:								
Оссирансу Туре:			Office					
Provide a brief description of operations:			Insurance					
storage height of warehoused products:			8'-0					
are flammable and combustible liquids stored in a cut-off room?			N/A					
afegaurds taken for the storage and dispensing of flammable liquids:			Υ					
Protection:								
are there any automatic	sprinklers?	Υ		What are	the design densities for each area?			
The water supply for automatic sprinklers is? Public		How many hydrants are located within 500 feet of buildings?						
ndicate the Alarm Coverages provided for your facility:			Sprinkler Valve Tamper, Smoke Detectors, Sprinkler Waterflow					
are alarms connected to a constantly attended location?				Υ				
s there a watchman service?		What is the frequency of rounds?						
are watchman recording rounds?			N					
are there any fire extinguishers?			Are they	serviced annually?		Υ		
are there any hose station	ons?	N		Is there a	ifire private fire brigade?		N	
requency of training rec	ceived by the private fire br	igade:						
ype of public fire depart	tment:	Paid		Distance	:		1/2 mile	
xposure:								
low many buildings(not part of Account) are within 100 feet of insured buildings?								
Describe the Occupancy of those buildings(s) nearby (within 100 feet):			Parking Structure					
s there a body of water nearby?		Description:						
low far is the body of wa	ater from major buildings?							
Previous history of flooding?		Description:						
any property damage los	sses in the past 3 years:	N	Descrip	otion:				

			Pro	operty De	etail Form				
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, MONTANA S	TATE UNI	IVERSITY	- BOZEMAN				
Property:	1 GLACIER COURT HOUS	Ε							
Property Address:	1 GLACIER COURT BOZE	MAN							
Property ID:	563001								
Construction:									
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	676			
Year built:		1957			Number of stories:	1			
Construction of roof:		Wood Joists			Construction of floors:	Wood Timber			
Construction of exterior v	valls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd		
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			N				
Occupancy:									
Occupancy Type:			Res Apt	Complex					
Provide a brief description of operations:			single fa	single family dwelling					
Storage height of warehoused products:			0						
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A						
Protection:									
Are there any automatic s	sprinklers?	N		What are	the design densities for each area?		no sprinklers		
The water supply for auto	matic sprinklers is?			How man	y hydrants are located within 500 feet of buildings?	•	3		
Indicate the Alarm Covera	ages provided for your faci	ility:							
Are alarms connected to	a constantly attended loca	tion?		N					
Is there a watchman servi	ice?	N		What is the	he frequency of rounds?				
Are watchman recording	rounds?			N					
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose statio	ns?	N		Is there a	fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid		Distance:	:		1.15 miles		
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):							
Is there a body of water n	earby?	N	Descrip	tion:					
How far is the body of wa	ter from major buildings?								
Previous history of floodi	ng?	N	Descrip	otion:					
Any property damage los	ses in the past 3 years:	N	Descrip	tion:					

							- 3		
			Propert	y Detail Form					
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVERS	SITY - BOZEMAN					
Property:	101 BRANEGAN COURT	TOWNHOUSES							
Property Address:	101 BRANEGAN COURT I	BOZEMAN							
Property ID:	529101								
Construction:									
Total number of insured I	buildings:	1		Total square footage of insured buildings:	5303				
Year built:		1976		Number of stories:	2				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concr	rete			
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Masonry				
Do major interior masonry walls (fire walls) extend above the roofline?		above the roofline?		N					
Occupancy:									
Occupancy Type:			Res Apt Comp	olex					
Provide a brief description of operations:			Multi-family re	Multi-family residential					
Storage height of warehoused products:			0						
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A						
Protection:									
Are there any automatic s	sprinklers?	N	What	are the design densities for each area?		no sprinklers			
The water supply for auto	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	?	3			
Indicate the Alarm Cover	ages provided for your fac	ility:	Smok	e Detectors					
Are alarms connected to	a constantly attended loca	ation?	N						
ls there a watchman serv	ice?	N	What	is the frequency of rounds?					
Are watchman recording	rounds?		N						
Are there any fire extingu	iishers?	Υ	Are th	ney serviced annually?		Υ			
Are there any hose statio	ns?	N	Is the	re a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire b	rigade:							
Type of public fire depart	ment:	Paid	Dista	nce:		1.25 miles			
Exposure:									
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water n	nearby?	N	Description:						
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	null	Description:						
Any property damage los	ses in the past 3 years:	N	Description:						

Property	Detail Form	

			Property	y Detail Form			
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVERS	SITY - BOZEMAN			
Property:	101 EAST JULIA MARTIN I	DRIVE APARTMENTS					
Property Address:	101 EAST JULIA MARTIN I	DRIVE BOZEMAN					
Property ID:	523101						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	6012		
Year built:		1968		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber		
Construction of exterior w	valls:	Masonry		Construction of interior walls:	Gypsum Board	d	
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N			
Occupancy:							
Occupancy Type:			Res Apt Comp	olex			
Provide a brief description	n of operations:		Multi family dw	velling			
Storage height of wareho	used products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	prinklers?	N	What	are the design densities for each area?		no sprinklers	
The water supply for auto	matic sprinklers is?		How r	many hydrants are located within 500 feet of buildings?	•	3	
ndicate the Alarm Covera	ages provided for your faci	ility:	Smok	e Detectors			
Are alarms connected to a	a constantly attended loca	tion?	N				
s there a watchman servi	ce?	N	What	is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire extingu	ishers?	Υ	Are th	ney serviced annually?		Υ	
Are there any hose station	ns?	N	Is the	re a fire private fire brigade?		N	
requency of training reco	eived by the private fire br	igade:					
Гуре of public fire departı	ment:	Paid	Dista	nce:		.65 miles	
Exposure:							
How many buildings(not រុ	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):					
s there a body of water no	earby?	N	Description:				
How far is the body of war	ter from major buildings?						
Previous history of floodi	ng?	N	Description:				
Any property damage los	ses in the past 3 years:	N	Description:				

			Pro	perty De	etail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNIV	VERSITY	- BOZEMAN			
Property:	101 GRANT CHAMBERLA	IN DRIVE APARTMENTS						
Property Address:	101 GRANT CHAMBERLA	IN DRIVE BOZEMAN						
Property ID:	528101							
Construction:								
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	20475		
ear built:		1975			Number of stories:	3		
Construction of roof:		Reinforced Concrete			Construction of floors:	Poured Concre	ete	
Construction of exterior v	valls:	Masonry			Construction of interior walls:	Gypsum Board	d	
Oo major interior masonr	y walls (fire walls) extend a	above the roofline?			N			
Occupancy:								
Occupancy Type:			Res Apt 0	Complex				
Provide a brief description of operations:		STUDEN	STUDENT FAMILY HOUSING					
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	N	V	What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?		H	How man	y hydrants are located within 500 feet of buildings?		6	
ndicate the Alarm Covera	ages provided for your fac	ility:	S	Smoke De	etectors			
Are alarms connected to	a constantly attended loca	tion?	N	N				
s there a watchman serv	ice?	N	v	What is tl	he frequency of rounds?			
Are watchman recording	rounds?		N	N				
Are there any fire extingu	ishers?	Υ	A	Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N	ls	ls there a	fire private fire brigade?		N	
requency of training rec	eived by the private fire br	igade:						
Гуре of public fire depart	ment:	Paid		Distance:	:		.45 MILES	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	oy (within 100 feet):						
s there a body of water n	earby?	null	Descripti	tion:				
low far is the body of wa	ter from major buildings?							
Previous history of floodi	ng?	N	Descripti	tion:				
Any property damage los	ses in the past 3 years:	N	Descripti	tion:				

							Page 2
			Prope	erty Detail Form			
Agency:	UNIVERSITY SYSTE	EM / UNIVERSITY SYSTEM, MONT	ANA STATE UNIVE	RSITY - BOZEMAN			
Property:	101 MCINTOSH CO	URT TOWNHOUSES					
Property Address:	101 MCINTOSH CO	URT BOZEMAN					
Property ID:	550101						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	5568		
Year built:		1996		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber		
Construction of exterior walls: Wood Frame		Wood Frame		Construction of interior walls: Gypsum Board			
Do major interior masor	nry walls (fire walls) ex	ktend above the roofline?		N			
Occupancy:							
Occupancy: Occupancy Type:		Res Apt Co	mplex				
		STUDENT	STUDENT FAMILY HOUSING				
Storage height of wareh	noused products:		N/A				
Are flammable and com	bustible liquids store	d in a cut-off room?	N/A				
Safegaurds taken for th	e storage and dispens	sing of flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ	Wh	at are the design densities for each area?		PER NFPA 13	
The water supply for au	tomatic sprinklers is?	Public	Но	w many hydrants are located within 500 feet of buildin	gs?	10	
Indicate the Alarm Cove	erages provided for yo	ur facility:	Sm	oke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflo	ow		
Are alarms connected t	o a constantly attende	d location?	Υ				
Is there a watchman se	rvice?	N	Wh	at is the frequency of rounds?			
Are watchman recordin	g rounds?		N				
Are there any fire exting	guishers?	Υ	Are	e they serviced annually?		Υ	

ls Are there any hose stations? Ν Is there a fire private fire brigade? Ν Frequency of training received by the private fire brigade: Type of public fire department: Paid Distance: .28 MILES

Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Description: Ν Any property damage losses in the past 3 years: N Description:

Description:

Property	Detail	Form

			Prop	erty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVE	ERSITY - BOZEMAN			
Property:	101 PAISLEY COURT FLA	TS					
Property Address:	101 PAISLEY COURT BOZ	ZEMAN					
Property ID:	531101						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	8933		
ear built:		1985		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber		
Construction of exterior v	valls:	Wood Frame		Construction of interior walls:	Gypsum Board	d	
Oo major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Res Apt Co	omplex			
Provide a brief descriptio	n of operations:		STUDENT	FAMILY HOUSING			
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	N	WI	hat are the design densities for each area?			
The water supply for auto	omatic sprinklers is?		Но	ow many hydrants are located within 500 feet of buildings?		11	
ndicate the Alarm Covera	ages provided for your fac	ility:	Sn	noke Detectors			
Are alarms connected to	a constantly attended loca	ntion?	N				
s there a watchman servi	ice?	N	WI	hat is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire extingu	ishers?	Υ	Ar	e they serviced annually?		Υ	
Are there any hose station	ns?	N	Is	there a fire private fire brigade?		N	
requency of training rec	eived by the private fire br	rigade:					
Гуре of public fire depart	ment:	Paid	Di	stance:		.61 MILES	
Exposure:							
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):					
s there a body of water n	earby?	N	Descriptio	n:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descriptio	n:			
Any property damage los	ses in the past 3 years:	N	Descriptio	n:			

							i aye 22
			Pı	roperty Detail Form			
gency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, UNIVERSITY	Y OF MOI	NTANA - MISSOULA			
Property:	1101-1110 Coloma Drive						
Property Address:	1101-1110 Coloma Drive M	ISSOULA					
Property ID:	272						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	9404		
ear built:		1996		Number of stories:	2		
construction of roof:		null		Construction of floors:	null		
construction of exterior	walls:	null		Construction of interior walls:	null		
o major interior mason	ry walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			Res Ap	ot Complex			
Provide a brief description	on of operations:		null				
storage height of warehoused products:			null				
are flammable and com	bustible liquids stored in a c	cut-off room?	null				
afegaurds taken for the	e storage and dispensing of	flammable liquids:	null				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?	nı	ull	
he water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	nı	ull	
ndicate the Alarm Cove	rages provided for your faci	lity:					
are alarms connected to	a constantly attended loca	tion?		null			
s there a watchman serv	vice?	null		What is the frequency of rounds?	nı	ull	
are watchman recording	g rounds?						
are there any fire exting	uishers?	null		Are they serviced annually?	nı	ull	
are there any hose station	ons?	null		Is there a fire private fire brigade?	nı	ull	
requency of training re	ceived by the private fire bri	igade:		null			
ype of public fire depar	rtment:	null		Distance:	nı	ull	
xposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?					

Previous history of flooding?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Description:

null

How far is the body of water from major buildings?

null

Any property damage losses in the past 3 years:

Description: Description:

null

null

null

null

null

						- 3 -		
			Property	Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	ATE UNIVERS	ITY - BOZEMAN				
Property:	112 WEST JULIA MARTIN	DRIVE APARTMENTS						
Property Address:	112 WEST JULIA MARTIN	DRIVE BOZEMAN						
Property ID:	525112							
Construction:								
Total number of insured I	buildings:	1		Total square footage of insured buildings:	6860			
Year built:		1971		Number of stories:	2			
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber			
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Gypsum Board			
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Res Apt Comp	lex				
Provide a brief description of operations:			STUDENT FAMILY HOUSING					
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	N	What	are the design densities for each area?				
The water supply for auto	omatic sprinklers is?		How n	nany hydrants are located within 500 feet of buildings?	13	}		
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke	e Detectors				
Are alarms connected to	a constantly attended loca	ition?	N					
ls there a watchman serv	ice?	N	What	is the frequency of rounds?				
Are watchman recording	rounds?		N					
Are there any fire extingu	ishers?	Υ	Are th	ey serviced annually?	Υ			
Are there any hose statio	ns?	N	Is the	e a fire private fire brigade?	N			
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid	Distar	nce:	.65	5 MILES		
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	nearby?	N	Description:					
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Description:					
Any property damage los	ses in the past 3 years:	N	Description:					

			Pr	operty D	etail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - M	ISSOULA		
Property:	Aber Hall						
Property Address:	844 Connell Avenue MISSO	OULA					
Property ID:	110						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	87178	
Year built:		1968			Number of stories:	11	
Construction of roof:		null			Construction of floors:	Reinforced Co	ncrete
Construction of exterior v	valls:	Reinforced Concrete			Construction of interior walls:	Masonry w/ Fir	re Doors
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			N		
Occupancy:							
Occupancy Type:			State U	niversity			
Provide a brief description of operations:		Student	tudent dorm				
Storage height of warehoused products:		0					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A					
Protection:							
Are there any automatic s	sprinklers?	Υ		What are	the design densities for each area?		0.1
The water supply for auto	matic sprinklers is?	Public		How man	ny hydrants are located within 500 feet of buildings?		2
Indicate the Alarm Covera	ages provided for your fac	ility:	Sprinkler Valve Tamper, Smoke Detectors, Fire Pump Alarms, Sprinkler Waterflow				
Are alarms connected to	a constantly attended loca	ation?		Υ			
Is there a watchman servi	ice?	Υ		What is t	he frequency of rounds?		Campus police 24/7
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose station	ns?	N		Is there a	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	rigade:					
Type of public fire depart	ment:	Paid		Distance	:		under 1 mile
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):					
Is there a body of water n	earby?	N	Descrip	otion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descrip	otion:			
Any property damage los	ses in the past 3 years:	N	Descrip	otion:			

								i aye z
			Pi	operty Detail Form				
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA S	TATE UN	IVERSITY - BILLINGS				
Property:	Academic Support Center							
Property Address:	1500 University Drive BILL	INGS						
Property ID:	600000890/600008112							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured be	uildings:	12968		
Year built:		1955		Number of stories:		1		
Construction of roof:		Wood Joists		Construction of floors:		Wood Timber		
Construction of exterior	walls:	Masonry		Construction of interior walls:		Masonry		
Do major interior masonry walls (fire walls) extend above the roofline?			N					
Occupancy:								
Occupancy Type:			State U	niversity				
Provide a brief descripti	on of operations:		educati	on				
Storage height of warehoused products:			0					
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are the design densities for each area	ı?		no sprinklers	
The water supply for aut	tomatic sprinklers is?			How many hydrants are located within 500	feet of buildings?	1	2	
Indicate the Alarm Cove	rages provided for your fac	cility:		Smoke Detectors				
Are alarms connected to	a constantly attended loca	ation?		N				
Is there a watchman ser	vice?	Υ		What is the frequency of rounds?			daily	
Are watchman recording	g rounds?			N				
Are there any fire exting	uishers?	Υ		Are they serviced annually?			Υ	
Are there any hose stati	ons?	N		Is there a fire private fire brigade?			N	
Frequency of training re	ceived by the private fire b	rigade:						
Type of public fire depart	rtment:	Paid		Distance:			1 to 2 miles	
Exposure:								
How many buildings(no	t part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy of those buildings(s) nearby (within 100 feet):								
Is there a body of water	nearby?			Description:				

300 feet

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Previous history of flooding?

							Page		
			Prop	erty Detail Form					
Agency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, UNIVERSITY	Y OF MONTA	NA - MISSOULA					
Property:	Adams Center								
Property Address:	800 Van Buren St. MISS	OULA							
Property ID:	19								
Construction:									
Total number of insure	d buildings:	1		Total square footage of insured buildings:	180124				
Year built:		1953		Number of stories:	3				
Construction of roof:		Other		Construction of floors:	Reinforced Co	oncrete			
Construction of exterio	r walls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ Fi	ire Doors			
Do major interior maso	nry walls (fire walls) exten	d above the roofline?		Υ					
Occupancy:									
Occupancy Type:			State Unive	ersity					
Provide a brief description of operations:			Offices/athl	Offices/athletic arena/concessions					
Storage height of warehoused products:			0						
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic	c sprinklers?	Υ	WI	hat are the design densities for each area?		no sprinklers			
The water supply for au	tomatic sprinklers is?		Но	ow many hydrants are located within 500 feet of buildings	;?	3			
Indicate the Alarm Cov	erages provided for your fa	acility:	Sn	noke Detectors					
Are alarms connected t	o a constantly attended lo	cation?	Υ						
Is there a watchman se	rvice?	Υ	WI	hat is the frequency of rounds?		Campus police 24/7			
Are watchman recording	g rounds?		Υ						
Are there any fire exting	guishers?	Υ	Ar	e they serviced annually?		Υ			
Are there any hose stat	ions?	N	Is	there a fire private fire brigade?		N			
Frequency of training r	eceived by the private fire	brigade:							
Type of public fire depart	artment:	Paid	Di	stance:		blank			
Exposure:									
How many buildings(no	ot part of Account) are with	nin 100 feet of insured buildings?	0						
Describe the Occupano	y of those buildings(s) nea	arby (within 100 feet):							
Is there a body of water	nearby?	Υ	Descriptio	n:	Clarkfork Rive	er			
How far is the body of water from major buildings?			735 feet						

Description:

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

Ν

			Prop	erty Detail Form				
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVE	ERSITY - NORTHERN				
Property:	Advanced Fuels Lab							
Property Address:	MSU-Northern - 140 College	e Road East HAVRE						
Property ID:	9							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	3946			
Year built:		1952		Number of stories:	1			
Construction of roof:		Other		Construction of floors:	Poured Concre	ete		
Construction of exterior walls: Masonry			Construction of interior walls:	Gypsum Board	3			
Do major interior masonry walls (fire walls) extend above the roofline?			N					
Occupancy:								
Occupancy Type:			Laboratory					
Provide a brief description	n of operations:		storage					
Storage height of wareho	used products:		n/a					
Are flammable and combi	ustible liquids stored in a c	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	N	W	hat are the design densities for each area?		n/a		
The water supply for auto	omatic sprinklers is?		Но	ow many hydrants are located within 500 feet of buildings?	1	2		
Indicate the Alarm Covera	ages provided for your faci	ility:						
Are alarms connected to	a constantly attended loca	tion?	nu	ıll				
Is there a watchman servi	ice?	Υ	W	hat is the frequency of rounds?		every 24 hours		
Are watchman recording	rounds?		Υ					
Are there any fire extingu	ishers?	Υ	Ar	re they serviced annually?		Υ		
Are there any hose station	ns?	N	Is	there a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire bri	igade:						
Type of public fire departs	ment:	Paid	Di	stance:		1 mile		
Exposure:								
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearb	oy (within 100 feet):						
Is there a body of water n	earby?	N	Descriptio	on:				
How far is the body of water from major buildings?								
Previous history of flooding?			Description:					
Any property damage los	ses in the past 3 years:	N	Descriptio	on:				

								. age 220
			Pro	operty D	etail Form			
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA S	TATE UNI	IVERSITY	′ - BOZEMAN			
Property:	AJM JOHNSON HALL							
Property Address:	Grant Street (no official add	dress) BOZEMAN						
Property ID:	113							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	43135		
Year built:		1954			Number of stories:	2		
Construction of roof:		Reinforced Concrete			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ F	ire Doors	
Do major interior masonry walls (fire walls) extend above the roofline?				N				
Occupancy:								
Occupancy Type:			State Un	niversity				
Provide a brief description	on of operations:		Classroo	oms & lab	s			
Storage height of wareho	oused products:		0					
Are flammable and combustible liquids stored in a cut-off room?			N					
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings	?	4	
Indicate the Alarm Cover	ages provided for your fac	eility:		Smoke D	etectors			
Are alarms connected to	a constantly attended loca	ation?		Υ				
ls there a watchman serv	rice?	N		What is t	he frequency of rounds?			
Are watchman recording	rounds?			N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depart	tment:	Paid		Distance	:		1.36 miles	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Descrip	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	tion:				
Any property damage los	sses in the past 3 years:	N	Descrip	tion:				

			Propert	ty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, UNIVERSITY	OF MONTANA	A - MISSOULA			
Property:	Alexander Blewett III Law S	School					
Property Address:	715 S 6th St E MISSOULA	1					
Property ID:	28						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	107815		
Year built:		1962		Number of stories:	3		
Construction of roof:		Poured Concrete		Construction of floors:	Poured Conc	rete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonry walls (fire walls) extend above the roofline?			N				
Occupancy:							
Occupancy Type:			State Univers	ity			
Provide a brief description	on of operations:		Offices/classr	rooms			
Storage height of wareho	oused products:		0				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ	What	t are the design densities for each area?		0.1	
The water supply for aut	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	?	3	
Indicate the Alarm Cover	ages provided for your fac	cility:	Smol	ke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loca	ation?	Υ				
ls there a watchman serv	rice?	Υ	What	t is the frequency of rounds?		campus police 24/7	
Are watchman recording	rounds?		Υ				
Are there any fire exting	uishers?	Υ	Are t	hey serviced annually?		Υ	
Are there any hose station	ons?	N	Is the	ere a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	Dista	ance:		under 1 mile	
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
ls there a body of water i	nearby?	N	Description:				
How far is the body of wa	ater from major buildings?						
Previous history of flood	ling?	N	Description:				
Any property damage los	sses in the past 3 years:	N	Description:				

			Pro	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA TE	ECH OF TH	HE UM			
Property:	Alumni Coliseum Pressbox	& Bleachers					
Property Address:	1300 W. Park Street BUTT	E					
Property ID:	124						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	17587		
Year built:		1965		Number of stories:	2		
Construction of roof:		Steel Deck		Construction of floors:	Other		
Construction of exterior	walls:	Other		Construction of interior walls:	Gypsum Board	d	
Do major interior masonry walls (fire walls) extend above the roofline?				null			
Occupancy:							
Occupancy Type:			State Univ	versity			
Provide a brief description of operations:			Enclosed	pressbox, open bleachers			
Storage height of warehoused products:			N/a				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N	V	What are the design densities for each area?			
The water supply for auto	omatic sprinklers is?		H	low many hydrants are located within 500 feet of buildings?		7	
Indicate the Alarm Cover	ages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	ition?	n	null			
Is there a watchman serv	rice?	Υ	V	What is the frequency of rounds?		2 per shift	
Are watchman recording	rounds?		Y	′			
Are there any fire extingu	uishers?	Υ	A	Are they serviced annually?		Υ	
Are there any hose station	ons?	N	ls	s there a fire private fire brigade?		N	
Frequency of training rec	ceived by the private fire br	igade:					
Type of public fire depart	tment:	Paid		Distance:		0.86 miles	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):					
Is there a body of water r	nearby?	N	Descripti	ion:			

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Previous history of flooding?

**AVERAGE 4 PER NIGHT** 

	Property Detail Form	
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN	
Property:	ANNA PEARL SHERRICK HALL	
Property Address:	West Garfield Street (no official address) BOZEMAN	
Property ID:	122	
Construction:		
Total number of insured	buildings: 1 Total square	footage of insured buildings:

18376 Year built:

1973 Number of stories:

Construction of roof: Steel Deck Construction of floors: Reinforced Concrete

Construction of exterior walls: Masonry Construction of interior walls: Masonry w/ Fire Doors

Do major interior masonry walls (fire walls) extend above the roofline?

### Occupancy:

**Occupancy Type:** State University

Provide a brief description of operations: OFFICES/CLASSROOMS

Storage height of warehoused products: N/A

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids: N/A

# Protection:

Ν Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? How many hydrants are located within 500 feet of buildings? 6

Indicate the Alarm Coverages provided for your facility: **Smoke Detectors** 

Is there a watchman service? Υ

What is the frequency of rounds?

Are watchman recording rounds?

Υ Are there any fire extinguishers? Are they serviced annually?

Are there any hose stations? Ν Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Are alarms connected to a constantly attended location?

1.08 MILES Type of public fire department: Paid Distance:

# Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Ν Description:

Any property damage losses in the past 3 years: Description:

dyno engine

						1 490 2
			P	roperty Detail Form		
gency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	IU STAT	NIVERSITY - NORTHERN		
Property:	Applied Technology Center	•				
roperty Address:	180 College Road West HA	AVRE				
roperty ID:	36					
Construction:						
otal number of insured b	ouildings:	1		Total square footage of insured buildings:	6100	
ear built:		2005		Number of stories: 1		
Construction of roof:		Steel Deck		Construction of floors:	oured Concrete	
Construction of exterior v	valls:	Masonry		Construction of interior walls:	lasonry	
o major interior masonr	y walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			Labora	tory		
Provide a brief descriptio	n of operations:		techno	logy labs/classrooms		
storage height of warehoused products:			n/a			
are flammable and combustible liquids stored in a cut-off room?			N/A			
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A			
Protection:						
are there any automatic s	sprinklers?	Υ		What are the design densities for each area?		
he water supply for auto	matic sprinklers is?	Private		How many hydrants are located within 500 feet of buildings?	2	
ndicate the Alarm Covera	ages provided for your fac	ility:		Smoke Detectors, Sprinkler Waterflow		
are alarms connected to	a constantly attended loca	ition?		Υ		
s there a watchman servi	ice?	Υ		What is the frequency of rounds?	every	24 hours
are watchman recording	rounds?			Υ		
are there any fire extingu	ishers?	Υ		Are they serviced annually?	Υ	
are there any hose statio	ns?	N		Is there a fire private fire brigade?	N	
requency of training rec	eived by the private fire br	igade:				
ype of public fire depart	ment:	Paid		Distance:	1 mile	)
xposure:						
low many buildings(not	part of Account) are withir	100 feet of insured buildings?	0			
escribe the Occupancy	of those buildings(s) nearl	by (within 100 feet):				
s there a body of water n	earby?	N	Descri	ption:		

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: Y

Ν

Previous history of flooding?

								1 age 234
			Pr	operty D	Petail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UN	NIVERSITY	7 - BILLINGS			
Property:	Apsaruke Hall							
Property Address:	1500 University Drive BILL	INGS						
Property ID:	600000889							
Construction:								
Total number of insure	d buildings:	1			Total square footage of insured buildings:	20254		
Year built:		1957			Number of stories:	3		
Construction of roof:	: Poured Concrete				Construction of floors:	Poured Concr	rete	
Construction of exterio	r walls:	Masonry			Construction of interior walls:	Masonry		
Do major interior masonry walls (fire walls) extend above the roofline?				N				
Occupancy:								
Occupancy Type:			State U	Iniversity				
Provide a brief description of operations:		educati	ion					
Storage height of warehoused products:		0						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ						
Protection:								
Are there any automati	c sprinklers?	N		What are	the design densities for each area?		no sprinklers	
The water supply for au	utomatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings	?	1	
Indicate the Alarm Cov	erages provided for your fac	cility:	Smoke Detectors					
Are alarms connected t	o a constantly attended loc	ation?		N				
Is there a watchman se	rvice?	Υ		What is t	the frequency of rounds?		daily	
Are watchman recording	g rounds?			N				
Are there any fire extin	guishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stat	ions?	N		Is there a	a fire private fire brigade?		N	
Frequency of training r	eceived by the private fire b	rigade:						
Type of public fire depart	artment:	Paid		Distance	e:		1 to 2 miles	
Exposure:								
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	blank					
Describe the Occupano	y of those buildings(s) near	by (within 100 feet):	0					
Is there a body of water	r nearby?	Υ	Descri	ption:				
How far is the body of	water from major buildings?	,	100 fee	et				
Previous history of floo	oding?	N	Descri	ption:				
Any property damage l	osses in the past 3 years:	N	Descri	ption:				

irrigation ditch

								Page 2
			Pro	perty Detail Form				
agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, MONTANA S	STATE UNI	/ERSITY - BILLINGS				
Property:	Art Annex							
roperty Address:	1500 University Drive BILLII	NGS						
Property ID:	600000779/10743							
Construction:								
otal number of insured	buildings:	1		Total square footage of insur	ed buildings:	6152		
ear built:		1980		Number of stories:		1		
onstruction of roof:		Wood Joists		Construction of floors:		Poured Concrete		
onstruction of exterior	walls:	Masonry		Construction of interior walls	:	Masonry		
o major interior mason	ry walls (fire walls) extend a	bove the roofline?		N				
Occupancy:								
ccupancy Type:			State Un	versity				
Provide a brief description of operations:			educatio					
storage height of warehoused products:			0					
are flammable and comb	oustible liquids stored in a c	ut-off room?	N/A					
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
are there any automatic	sprinklers?	N		What are the design densities for each	area?	no	o sprinklers	
he water supply for aut	omatic sprinklers is?			low many hydrants are located within	500 feet of buildings?	? 1		
ndicate the Alarm Cover	rages provided for your faci	lity:		Smoke Detectors				
re alarms connected to	a constantly attended locat	ion?		I				
s there a watchman serv	vice?	Υ		Vhat is the frequency of rounds?		da	aily	
re watchman recording	rounds?			I				
are there any fire exting	uishers?	Υ		are they serviced annually?		Υ		
are there any hose static	ons?	N		s there a fire private fire brigade?		N		
requency of training red	ceived by the private fire bri	gade:						
ype of public fire depar	tment:	Paid		Distance:		1 t	to 2 miles	
xposure:								
low many buildings(not	part of Account) are within	100 feet of insured buildings?	0					

Previous history of flooding?

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

How far is the body of water from major buildings? 200 feet

Ν

Description:

Description:

Any property damage losses in the past 3 years: N

Description:

						i age z			
			Property	Detail Form					
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, UNIVERSITY	OF MONTANA -	WESTERN					
Property:	Art Annex								
Property Address:	1001 S. Atlantic DILLON								
Property ID:	26								
Construction:									
Total number of insured	d buildings:	1		Total square footage of insured buildings:	7055				
Year built:		1951		Number of stories:	1				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete				
Construction of exterior walls: Masonry			Construction of interior walls:	Gypsum Board					
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Garage, Parts S	Storage					
Provide a brief description of operations:			Educational bui	ducational building					
Storage height of warehoused products:		N/A							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	N/A						
Protection:									
Are there any automation	sprinklers?	N	What a	are the design densities for each area?					
The water supply for au	tomatic sprinklers is?		How m	nany hydrants are located within 500 feet of buildings?	? 1				
Indicate the Alarm Cove	erages provided for your fac	sility:	Smoke Detectors						
Are alarms connected t	o a constantly attended loca	ation?	Υ						
ls there a watchman se	rvice?	Υ	What i	s the frequency of rounds?					
Are watchman recordin	g rounds?		Υ						
Are there any fire exting	guishers?	Υ	Are the	ey serviced annually?	Υ				
Are there any hose stat	ions?	N	Is ther	e a fire private fire brigade?	N				
Frequency of training re	eceived by the private fire b	rigade:							
Type of public fire depa	rtment:	Voluntary	Distan	ce:	blank				
Exposure:									
How many buildings(no	ot part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupanc	y of those buildings(s) near	by (within 100 feet):							
Is there a body of water	nearby?	Υ	Description:		Beaverhead River				
How far is the body of v	vater from major buildings?		1 Mile						
Previous history of floo	ding?	N	Description:						
Any property damage lo	osses in the past 3 years:	N	Description:						

						Page 23
			P	roperty Detail Form		
gency:	UNIVERSITY SYSTEM / L	UNIVERSITY SYSTEM, UNIVERS	SITY OF MO	NTANA - MISSOULA		
Property:	Art Annex - Pool					
Property Address:	880 Van Buren Street MIS	SSOULA				
Property ID:	26					
Construction:						
otal number of insured	l buildings:	1		Total square footage of insured buildings: 40	0803	
ear built:		1958		Number of stories: 2		
construction of roof:		null		Construction of floors:	ıll	
construction of exterior	walls:	null		Construction of interior walls:	ull	
o major interior mason	nry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			State I	Jniversity		
Provide a brief descripti	on of operations:		null			
storage height of wareh	oused products:		null			
are flammable and com	bustible liquids stored in a	cut-off room?	null			
afegaurds taken for the	e storage and dispensing o	of flammable liquids:	null			
Protection:						
are there any automatic	sprinklers?	N		What are the design densities for each area?	null	
he water supply for aut	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	null	
ndicate the Alarm Cove	rages provided for your fa	cility:				
are alarms connected to	o a constantly attended loc	ation?		null		
s there a watchman ser	vice?	null		What is the frequency of rounds?	null	
are watchman recording	g rounds?					
are there any fire exting	juishers?	null		Are they serviced annually?	null	
are there any hose stati	ons?	null		Is there a fire private fire brigade?	null	
requency of training re	eceived by the private fire b	origade:		null		
ype of public fire depar	rtment:	null		Distance:	null	
xposure:						
low many buildings(no	t part of Account) are withi	in 100 feet of insured buildings	?			
Ascribe the Occupancy	v of those buildings(s) near	rhy (within 100 feet):	null			

null

null

null

Description:

Is there a body of water nearby? null

null

How far is the body of water from major buildings?

Previous history of flooding? null Description:

Any property damage losses in the past 3 years: null Description:

								1 ago 200
			Pro	perty D	etail Form			
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, MONTANA S	TATE UNI	IVERSITY	′ - BOZEMAN			
Property:	ATKINSON QUADRANGL	E RESIDENCE HALL A						
Property Address:	West Cleveland (no official	address) BOZEMAN						
Property ID:	370							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	6807		
Year built:		1935			Number of stories:	3		
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ O	penings	
Do major interior masonry walls (fire walls) extend above the roofline?				null				
Occupancy:								
Occupancy Type:			Res Apt	Complex				
Provide a brief descripti	on of operations:		Dormato	ory				
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		140' sq/ sprinkler	
The water supply for au	tomatic sprinklers is?	Public		How man	ny hydrants are located within 500 feet of buildings	?	3	
Indicate the Alarm Cove	rages provided for your fac	eility:		Smoke D	etectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loca	ation?		Υ				
ls there a watchman ser	vice?	N		What is t	he frequency of rounds?			
Are watchman recording	g rounds?			N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:						
Type of public fire depar	rtment:	Paid		Distance	:		.9 miles	
Exposure:								
How many buildings(no	t part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Descrip	tion:				
How far is the body of w	rater from major buildings?							
Previous history of floor	ding?	N	Descrip	tion:				
Any property damage lo	sses in the past 3 years:	N	Descrip	tion:				

			Pro	perty De	etail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNI\	VERSITY	- BOZEMAN				
Property:	ATKINSON QUADRANGL	E RESIDENCE HALL B							
Property Address:	West Cleveland (no official	address) BOZEMAN							
Property ID:	371								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	6807			
Year built:		1935			Number of stories:	3			
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete		
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ O	penings		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			Res Apt (	Complex					
Provide a brief description of operations:			Dormator	vormatory					
Storage height of warehoused products:			N/A						
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic	sprinklers?	Υ	V	What are	the design densities for each area?		140' sq/ sprinkler		
The water supply for auto	omatic sprinklers is?	Public	H	How man	y hydrants are located within 500 feet of buildings?		3		
ndicate the Alarm Cover	ages provided for your fac	ility:	5	Smoke De	etectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
Are alarms connected to	a constantly attended loca	ation?	١	Y					
s there a watchman serv	rice?	N	V	What is th	he frequency of rounds?				
Are watchman recording	rounds?		1	N					
Are there any fire extingu	uishers?	Υ	A	Are they	serviced annually?		Υ		
Are there any hose statio	ons?	N	I:	s there a	fire private fire brigade?		N		
requency of training rec	ceived by the private fire b	rigade:							
Type of public fire depart	tment:	Paid		Distance:	:		.9 miles		
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
s there a body of water r	nearby?	N	Descript	ion:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Descript	ion:					
Any property damage los	sses in the past 3 years:	N	Descript	ion:					

			Prop	perty De	etail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNIV	VERSITY	- BOZEMAN			
Property:	ATKINSON QUADRANGLI	E RESIDENCE HALL C						
Property Address:	West Cleveland (no official	address) BOZEMAN						
Property ID:	372							
Construction:								
Total number of insured I	buildings:	1			Total square footage of insured buildings:	7473		
Year built:		1935			Number of stories:	3		
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior v	walls:	Masonry			Construction of interior walls:	Masonry w/ O	penings	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Res Apt C	Complex				
Provide a brief description of operations:			Dormatory	ry				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	Υ	W	What are	the design densities for each area?		140' sq/ sprinkler	
The water supply for auto	omatic sprinklers is?	Public	н	How man	y hydrants are located within 500 feet of buildings?	•	3	
Indicate the Alarm Cover	ages provided for your fac	ility:	S	Smoke De	etectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loca	ation?	Y	Y				
ls there a watchman serv	rice?	N	W	What is th	he frequency of rounds?			
Are watchman recording	rounds?		N	N				
Are there any fire extingu	uishers?	Υ	Α	Are they	serviced annually?		Υ	
Are there any hose statio	ons?	N	Is	s there a	fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid	D	Distance:	:		.9 miles	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	nearby?	N	Description	ion:				
How far is the body of wa	ater from major buildings?							
Previous history of floodi	ing?	N	Description	ion:				
Any property damage los	sses in the past 3 years:	N	Description	ion:				

	Property Detail Form
UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE	UNIVERSITY - BOZEMAN
47//W00W00W00W00W00W00W00W00W00	

Property:	ATKINSON QUADRANGLE RESIDENCE HALL D	

**Property Address:** West Cleveland (no official address) BOZEMAN

373 **Property ID:** 

Construction:	
Construction.	

Agency:

Total number of insured buildings: 1 Total square footage of insured buildings: 7473

1935 3 Year built: Number of stories:

Construction of roof: Wood Joists Construction of floors: Reinforced Concrete

Construction of exterior walls: Masonry Construction of interior walls: Masonry w/ Openings

Do major interior masonry walls (fire walls) extend above the roofline?

### Occupancy:

**Occupancy Type:** Res Apt Complex

Provide a brief description of operations: Dormatory

Storage height of warehoused products: N/A

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids: N/A

### Protection:

Υ Are there any automatic sprinklers? What are the design densities for each area? 140' sq/ sprinkler

Υ

The water supply for automatic sprinklers is? **Public** How many hydrants are located within 500 feet of buildings?

Indicate the Alarm Coverages provided for your facility: Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow

Are alarms connected to a constantly attended location?

Are watchman recording rounds? Are there any fire extinguishers?

Are there any hose stations?

Type of public fire department:

Is there a watchman service?

Ν

Ν

Frequency of training received by the private fire brigade:

Paid

Distance:

What is the frequency of rounds?

Is there a fire private fire brigade?

Are they serviced annually?

.9 miles

Ν

# Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Any property damage losses in the past 3 years:

Ν

Description:

Description:

Description:

0

			Pro	perty De	etail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIV	/ERSITY	- BOZEMAN			
Property:	ATKINSON QUADRANGL	E RESIDENCE HALL E						
Property Address:	West Cleveland (no official	address) BOZEMAN						
Property ID:	374							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	6840		
Year built:		1935			Number of stories:	3		
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ O	penings	
Do major interior masonry walls (fire walls) extend above the roofline?				N				
Occupancy:								
Occupancy Type:			Res Apt C	Complex				
Provide a brief description of operations:			Dormator	у				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic	sprinklers?	Υ	V	Vhat are	the design densities for each area?		140' sq/ sprinkler	
The water supply for auto	omatic sprinklers is?	Public	F	low man	y hydrants are located within 500 feet of buildings?		3	
Indicate the Alarm Cover	ages provided for your fac	ility:	Sprinkler Valve Tamper, Smoke Detectors, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ation?	Υ					
ls there a watchman serv	rice?	N	V	Vhat is th	he frequency of rounds?			
Are watchman recording	rounds?		N	1				
Are there any fire exting	uishers?	Υ	A	Are they s	serviced annually?		Υ	
Are there any hose static	ons?	N	ls	s there a	fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid		Distance:	:		.9 miles	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
ls there a body of water i	nearby?	N	Descripti	ion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ling?	N	Descripti	ion:				
Any property damage los	sses in the past 3 years:	N	Descripti	ion:				

						- 3 -			
			Prop	erty Detail Form					
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN								
Property:	ATKINSON QUADRANGL	E RESIDENCE HALL F							
Property Address:	West Cleveland (no official	address) BOZEMAN							
Property ID:	375								
Construction:									
Total number of insured	l buildings:	1		Total square footage of insured buildings:	6840				
Year built:		1935		Number of stories:	3				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete				
Construction of exterior walls: Masonry			Construction of interior walls:	Masonry w/ Openings					
Do major interior masonry walls (fire walls) extend above the roofline?			N						
Occupancy:									
Occupancy Type:			Res Apt Co	omplex					
Provide a brief description of operations:			Restauran	Restaurant					
Storage height of warehoused products:			N/A						
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic	sprinklers?	Υ	W	hat are the design densities for each area?	140' sq/ sprinkler				
The water supply for au	tomatic sprinklers is?	Public	Н	ow many hydrants are located within 500 feet of buildings?	? 3				
Indicate the Alarm Cove	rages provided for your fac	cility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to	o a constantly attended loca	ation?	Υ						
Is there a watchman ser	vice?	N	W	hat is the frequency of rounds?					
Are watchman recording	g rounds?		N						
Are there any fire exting	juishers?	Υ	Ar	re they serviced annually?	Υ				
Are there any hose stati	ons?	N	Is	there a fire private fire brigade?	N				
Frequency of training re	eceived by the private fire b	rigade:							
Type of public fire depa	rtment:	Paid	Di	stance:	.9 miles				
Exposure:									
How many buildings(no	t part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):							
Is there a body of water	nearby?	N	Description	on:					
How far is the body of w	ater from major buildings?								
Previous history of floo	ding?	N	Description	on:					
Any property damage lo	sses in the past 3 years:	N	Description	on:					

						Page
			Pro	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / I	UNIVERSITY SYSTEM, UNIVERSITY				
Property:	Auditorium & Shop					
Property Address:	710 S. Atlantic DILLON					
Property ID:	7					
Construction:						
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	13265	
Year built:	-	1952		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete	
Construction of exteri	or walls:	Masonry		Construction of interior walls:	Other	
Do major interior mas	onry walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			State Ur	niversity		
Provide a brief description of operations:			Drama,	musicals		
Storage height of warehoused products:			N/A			
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for t	the storage and dispensing o	of flammable liquids:	N/A			
Protection:						
Are there any automat	ic sprinklers?	N		What are the design densities for each area?		
The water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	? 3	
Indicate the Alarm Co	verages provided for your fa	cility:		Smoke Detectors		
Are alarms connected	to a constantly attended loc	eation?		Y		
Is there a watchman s	ervice?	Υ		What is the frequency of rounds?	Hourly	
Are watchman recordi	ng rounds?			Y		
Are there any fire extin	nguishers?	Υ		Are they serviced annually?	Υ	
Are there any hose sta	ations?	N		Is there a fire private fire brigade?	N	
Frequency of training	received by the private fire b	origade:				
Type of public fire dep	partment:	Voluntary		Distance:	blank	
Exposure:						
How many buildings(r	not part of Account) are with	in 100 feet of insured buildings?	0			
Describe the Occupan	cy of those buildings(s) nea	rby (within 100 feet):				
Is there a body of water	er nearby?	Υ	Descrip	ition:	Beaverhead River	
How far is the body of	water from major buildings	?	1 Mile			
Previous history of flo	oding?	N	Descrip	ition:		
Any property damage	losses in the past 3 years:	N	Descrip	ition:		

1 mile

								Page 24
			P	roperty I	Detail Form			
Agency:	UNIVERSITY SYSTEM / UN	IVERSITY SYSTEM, MONTANA S	TATE UI	NIVERSIT	Y - NORTHERN			
Property:	Automotive Technology Build	ling						
Property Address:	MSU-Northern 121 College F	Road East HAVRE						
Property ID:	8							
Construction:								
Total number of insured b	ouildings: 1				Total square footage of insured buildings:	22239		
Year built:	1	952			Number of stories:	1		
Construction of roof:	(	Other			Construction of floors:	Poured Concre	ete	
Construction of exterior v	walls:	Other			Construction of interior walls:	Masonry		
Do major interior masonr	y walls (fire walls) extend at	pove the roofline?			N			
Occupancy:								
Occupancy Type:			Labora	tory				
Provide a brief descriptio	n of operations:		auto cl	asses				
Storage height of wareho	used products:		n/a					
Are flammable and comb	ustible liquids stored in a cu	ut-off room?	N					
Safegaurds taken for the	storage and dispensing of f	lammable liquids:	N					
Protection:								
Are there any automatic s	sprinklers?	N		What ar	e the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How ma	any hydrants are located within 500 feet of buildings?		2	
ndicate the Alarm Cover	ages provided for your facili	ty:		Smoke [	Detectors			
Are alarms connected to	a constantly attended locati	on?		null				
s there a watchman serv	ice?	Υ		What is	the frequency of rounds?		every 24 hours	
Are watchman recording	rounds?			Υ				

Are there any fire extinguishers? Are they serviced annually? Υ Is there a fire private fire brigade? Are there any hose stations? Ν Ν Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance:

Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Description: Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding? Ν Description: Description: Any property damage losses in the past 3 years: N

							- 3 -			
			Prope	rty Detail Form						
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MONTANA S	TATE UNIVER	RSITY - BOZEMAN						
Property:	BARNARD HALL									
Property Address:	Grant Street (no official ad	dress) BOZEMAN								
Property ID:	139									
Construction:										
Total number of insured	buildings:	1		Total square footage of insured buildings:	149388					
Year built:		1996		Number of stories:	3					
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Co	oncrete				
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fi	ire Doors				
Oo major interior masonry walls (fire walls) extend above the roofline?			N							
Occupancy:										
Occupancy Type:			Laboratory							
Provide a brief description of operations:			Offices, clas	Offices, classrooms, labs						
Storage height of warehoused products:			0							
Are flammable and combustible liquids stored in a cut-off room?			N							
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ								
Protection:										
Are there any automatic	sprinklers?	Υ	Wha	at are the design densities for each area?		140' sq /sprinkler				
The water supply for aut	omatic sprinklers is?	Public	Hov	w many hydrants are located within 500 feet of buildings	?	4				
ndicate the Alarm Cover	ages provided for your fac	cility:	Smo	oke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to	a constantly attended loca	ation?	Υ							
s there a watchman serv	rice?	N	Wha	at is the frequency of rounds?						
Are watchman recording	rounds?		N							
Are there any fire exting	uishers?	Υ	Are	they serviced annually?		Υ				
Are there any hose station	ons?	N	ls th	here a fire private fire brigade?		N				
requency of training red	ceived by the private fire b	rigade:								
Гуре of public fire depar	tment:	Paid	Dist	tance:		1.39 miles				
Exposure:										
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0							
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):								
s there a body of water i	nearby?	N	Description	:						
low far is the body of wa	ater from major buildings?									
Previous history of flood	ling?	N	Description	:						
Any property damage los	sses in the past 3 years:	N	Description	:						

			Pr	operty D	etail Form						
Agency:	UNIVERSITY SYSTEM / U	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA									
Property:	Bio Research Building										
Property Address:	1310 Maurice Ave. MISSO	ULA									
Property ID:	039										
Construction:											
Total number of insured	buildings:	1			Total square footage of insured buildings:	10260					
Year built:		2004			Number of stories:	2					
Construction of roof:		Steel Deck			Construction of floors:	Poured Concr	rete				
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd				
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N						
Occupancy:											
Occupancy Type:			Laborat	tory							
Provide a brief description of operations:			Biologic	Biological Research lab activities for higher ed							
Storage height of warehoused products:			0	0							
Are flammable and combustible liquids stored in a cut-off room?			N/A								
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ									
Protection:											
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		comply with standard NFPA				
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?	<b>)</b>	2				
Indicate the Alarm Cover	ages provided for your fac	cility:		Smoke D	etectors						
Are alarms connected to	a constantly attended loca	ation?		N							
ls there a watchman serv	ice?	Υ		What is t	he frequency of rounds?		Campus police 24/7				
Are watchman recording	rounds?			N							
Are there any fire extingu	iishers?	Υ		Are they	serviced annually?		Υ				
Are there any hose statio	ons?	N		Is there a	a fire private fire brigade?		N				
Frequency of training red	eived by the private fire b	rigade:									
Type of public fire depart	ment:	Paid		Distance	:		under 1 mile				
Exposure:											
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0								
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):									
Is there a body of water r	nearby?	N	Descrip	otion:							
How far is the body of wa	ater from major buildings?										
Previous history of flood	ing?	N	Descrip	otion:							
Any property damage los	sses in the past 3 years:	N	Descrip	otion:							

BEAVERHEAD RIVER

							Page 2
			Pi	roperty Detail Form			
gency:	UNIVERSITY SYSTEM / I	JNIVERSITY SYSTEM, UNIVERS	ITY OF MOI	NTANA - WESTERN			
roperty:	Block Hall						
roperty Address:	710 S. Atlantic DILLON						
roperty ID:	25						
onstruction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	41560		
ear built:		1970		Number of stories:	3		
onstruction of roof:		Steel Deck		Construction of floors:	Poured Conc	crete	
onstruction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ F	Fire Doors	
o major interior mason	ry walls (fire walls) extend	above the roofline?		Υ			
ccupancy:							
ccupancy Type:			State L	Jniversity			
rovide a brief description of operations:			OFFIC	ES/CLASSROOMS			
torage height of wareh	oused products:		N/A				
re flammable and comi	bustible liquids stored in a	cut-off room?	N/A				
afegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A				
rotection:							
re there any automatic	sprinklers?	Υ		What are the design densities for each area?		BASEMENT ONLY	
he water supply for aut	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of building	js?	4	
dicate the Alarm Cove	rages provided for your fa	cility:		Sprinkler Valve Tamper			
re alarms connected to	a constantly attended loo	ation?		Υ			
there a watchman ser	vice?	Υ		What is the frequency of rounds?		HOUR	
re watchman recording	g rounds?			Υ			
re there any fire exting	uishers?	Υ		Are they serviced annually?		Υ	
re there any hose stati	ons?	N		Is there a fire private fire brigade?		N	
requency of training re	ceived by the private fire b	origade:					
ype of public fire depar	rtment:	Voluntary		Distance:		12 BLOCKS	
xposure:							

0

Description:

Description:

Description:

1 MILE

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

			Prope	rty Detail Form			
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN						
Property:	BOBCAT ANDERSON TEN	NNIS CENTER					
Property Address:	South 11th Avenue (no office	cial address) BOZEMAN					
Property ID:	140						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	29183		
Year built:		2003		Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Co	ncrete	
Construction of exterior v	valls:	Corrugated Metal Panel		Construction of interior walls: Gypsum Board		d	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State Univer	rsity			
Provide a brief descriptio	n of operations:		INDOOR TENNIS COURTS				
Storage height of wareho	used products:		N/A				
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	N	Wh	at are the design densities for each area?			
The water supply for auto	matic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?	?	6	
Indicate the Alarm Covera	ages provided for your fac	ility:					
Are alarms connected to a constantly attended location?			N				
Is there a watchman servi	ice?	Υ	Wha	at is the frequency of rounds?		AVERAGE 4 PER NIGHT	
Are watchman recording	rounds?		N				
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?		Υ	
Are there any hose statio	ns?	N	ls ti	here a fire private fire brigade?		N	
Frequency of training received by the private fire brigade:							
Type of public fire depart	ment:	Paid	Dis	tance:		1.45 MILES	
Exposure:							
How many buildings(not part of Account) are within 100 feet of insured buildings? 0							
Describe the Occupancy of those buildings(s) nearby (within 100 feet):							
Is there a body of water nearby?		Description:					
How far is the body of water from major buildings?							
Previous history of flooding?		Description:					
Any property damage los	ses in the past 3 years:	N	Description	:			

			Prop	erty Detail Form			
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN						
Property:	BOBCAT STADIUM BOOS	STERS - WEST					
Property Address:	1000 Kagy Boulevard BOZ	EMAN					
Property ID:	156101						
Construction:							
Total number of insured I	buildings:	1		Total square footage of insured buildings:	66429		
Year built:		1998		Number of stories:	8		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls: Gypsum Board		d	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State Univ	ersity			
Provide a brief description	n of operations:		FOOTBALL STADIUM/CONFRENCE ROOMS				
Storage height of warehoused products:			N/A				
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	Υ	w	hat are the design densities for each area?		0.10/1950, 575 gpm, 75 psi, 165 temp	
The water supply for auto	omatic sprinklers is?	Public	H	ow many hydrants are located within 500 feet of buildings?	•	4	
Indicate the Alarm Coverages provided for your facility:		ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
Are alarms connected to a constantly attended location?		Υ					
Is there a watchman serv	ice?	Υ	What is the frequency of rounds?			AVERAGE 4 PER NIGHT	
Are watchman recording	rounds?		N				
Are there any fire extingu	ishers?	Υ	A	re they serviced annually?		Υ	
Are there any hose statio	ns?	N	Is	there a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire b	rigade:					
Type of public fire depart	ment:	Paid	Di	istance:		.75 MILES	
Exposure:							
How many buildings(not part of Account) are within 100 feet of insured buildings?		0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water nearby?		Description:					
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ing?	N	Description	on:			
Any property damage los	ses in the past 3 years:	Υ	Description	on:	11/04/02 WA	TER DAMAGE DUE TO PIPE BREAK	

			Property	Detail Form					
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MONTANA S	TATE UNIVERSIT	operty Detail Form  IVERSITY - BOZEMAN					
Property:	BOBCAT STADIUM EAST BLEACHERS								
Property Address:	1000 Kagy Boulevard BOZ	ZEMAN							
Property ID:	155								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	24790				
Year built:		1973		Number of stories:	1				
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Co	ncrete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	d			
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			State University						
		FOOTBALL STADIUM/CONCESSIONS, RESTROOMS/TICKET BOOTH/BLEACHERS							
Storage height of warehoused products:		N/A							
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A						
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	N	What a	re the design densities for each area?					
The water supply for aut	omatic sprinklers is?		How ma	any hydrants are located within 500 feet of buildings?	?	4			
Indicate the Alarm Cover	rages provided for your fac	cility:							
Are alarms connected to a constantly attended location?			null						
ls there a watchman serv	vice?	Υ	What is	the frequency of rounds?		AVERAGE 4 PER NIGHT			
Are watchman recording	rounds?		N						
Are there any fire exting	uishers?	Υ	Are the	y serviced annually?		Υ			
Are there any hose station	ons?	N	Is there	a fire private fire brigade?		N			
Frequency of training red	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Paid	Distanc	ce:		1.64 MILES			
Exposure:									
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
ls there a body of water i	nearby?	N	Description:						
How far is the body of wa	ater from major buildings?								
Previous history of flood	ling?	N	Description:						
Any property damage los	sses in the past 3 years:	N	Description:						

							Page 25
			Property	Detail Form			
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN						
Property:	BOBCAT STADIUM SOUTH ENDZONE						
Property Address:	1000 Kagy Boulevard BOZ	EMAN					
Property ID:	157101						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	38031		
Year built:		2011		Number of stories:	1		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State University	у			
Provide a brief description	on of operations:		Bleachers				
Storage height of warehoused products:			N/A				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A				
Protection:							
Are there any automatic	sprinklers?	N	What a	are the design densities for each area?		no sprinklers	
The water supply for aut	tomatic sprinklers is?		How n	nany hydrants are located within 500 feet of buildings	?	2	
Indicate the Alarm Coverages provided for your facility:							
Are alarms connected to a constantly attended location?			null				
Is there a watchman serv	vice?	N	What i	is the frequency of rounds?			
Are watchman recording	g rounds?		N				
Are there any fire exting	uishers?	Υ	Are th	ey serviced annually?		Υ	
Are there any hose static	ons?	N	Is ther	re a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire br	igade:					
Type of public fire depar	rtment:	Paid	Distan	nce:		1.64 miles	
Exposure:							
How many buildings(not	t part of Account) are within	100 feet of insured buildings?	0				

Describe the Occupancy of those buildings(s) nearby (within 100 feet): Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding?

Ν Any property damage losses in the past 3 years: N Description:

Description:

								Page 2
			Pro	operty D	etail Form			
Agency:	UNIVERSITY SYSTEM / UNIV	VERSITY SYSTEM, UNIVERSITY	OF MON	TANA - N	IISSOULA			
Property:	Brantly Hall							
Property Address:	635 Connell Avenue MISSOU	LA						
Property ID:	100							
Construction:								
Total number of insured	buildings: 1				Total square footage of insured buildings:	33362		
Year built:	19	921			Number of stories:	3		
Construction of roof:	nu	ıll			Construction of floors:	null		
Construction of exterior	walls: nu	ıll			Construction of interior walls:	null		
Do major interior masonr	ry walls (fire walls) extend abo	ove the roofline?			null			
Occupancy:								
Occupancy Type:			State Un	niversity				
Provide a brief description	on of operations:		null					
Storage height of wareho	oused products:		null					
Are flammable and comb	oustible liquids stored in a cut	e-off room?	null					
Safegaurds taken for the	storage and dispensing of fla	ammable liquids:	null					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		null	
The water supply for auto	omatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings?		null	
ndicate the Alarm Cover	ages provided for your facility	y:						
Are alarms connected to	a constantly attended location	n?		null				
s there a watchman serv	rice?	null		What is t	the frequency of rounds?		null	
Are watchman recording	rounds?							
Are there any fire extingu	uishers?	null		Are they	serviced annually?		null	
Are there any hose statio	ons?	null		Is there a	a fire private fire brigade?		null	
requency of training rec	ceived by the private fire briga	ade:		null				
Type of public fire depart	tment:	null		Distance	:		null	
Exposure:								
How many buildings(not	part of Account) are within 10	00 feet of insured buildings?						

Previous history of flooding?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Description:

Is there a body of water nearby? null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

null

Description:

null

Description:

null

null

null

			Prop	perty Detail Form				
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, MONTANA S	TATE UNIV	/ERSITY - BOZEMAN				
Property:	BRICK BREEDEN FIELDH	IOUSE						
Property Address:	South11th Avenue ( no offi	cial address) BOZEMAN						
Property ID:	114							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	184453			
Year built:		1958		Number of stories:	3			
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Co	oncrete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd		
Do major interior masonry walls (fire walls) extend above the roofline?			N					
Occupancy:								
Occupancy Type:			State Univ	versity				
Provide a brief description of operations:		Athletic ev	Athletic event center					
Storage height of warehoused products:		0						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ	W	What are the design densities for each area?		140' sq / sprinkler		
The water supply for aut	omatic sprinklers is?	Public	н	low many hydrants are located within 500 feet of buildings	<b>;</b> ?	4		
Indicate the Alarm Cover	ages provided for your fac	cility:	Fire Pump Alarms, Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ation?	Υ					
ls there a watchman serv	rice?	N	W	What is the frequency of rounds?				
Are watchman recording	rounds?		N	I				
Are there any fire exting	uishers?	Υ	Α	re they serviced annually?		Υ		
Are there any hose static	ons?	Υ	Is	s there a fire private fire brigade?		N		
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid	D	listance:		1.25 ,miles		
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
ls there a body of water i	nearby?	N	Description	on:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ling?	N	Description	on:				
Any property damage los	sses in the past 3 years:	N	Description	on:				

every 24 hours

						Page 2		
			Proper	ty Detail Form				
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MOI	NTANA STATE UNIVER	SITY - NORTHERN				
Property:	Brockmann Center							
Property Address:	MSU-Northern 201 Colleg	e Road West HAVRE						
Property ID:	32							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	53072			
Year built:		1971		Number of stories:	2			
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete			
Construction of exterior v	walls:	Other		Construction of interior walls:	Other			
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Laboratory					
Provide a brief descriptio	n of operations:		plumb/elect/la	plumb/elect/labs/classes				
Storage height of wareho	used products:		n/a					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N					
Safegaurds taken for the	storage and dispensing o	of flammable liquids:	Υ					
Protection:								
Are there any automatic s	sprinklers?	Υ	Wha	t are the design densities for each area?				
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings	3			
ndicate the Alarm Covera	ages provided for your fa	cility:	Smo	ke Detectors, Sprinkler Waterflow				

Is there a watchman service?

Are alarms connected to a constantly attended location?

Are watchman recording rounds?

What is the frequency of rounds?

Are they serviced annually? Are there any fire extinguishers?

Are there any hose stations? Ν Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Paid Distance: Type of public fire department: 1 mile

#### Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Ν Any property damage losses in the past 3 years: N Description:

			Pr	operty D	etail Form				
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - M	IISSOULA				
Property:	Building T-157 (East cellble	ock Drama Storage)							
Property Address:	Post Siding Rd. Ft. Missou	la MISSOULA							
Property ID:	401								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	12687			
Year built:		1943			Number of stories:	1			
Construction of roof:		Reinforced Concrete			Construction of floors:	Poured Conc	rete		
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry w/ F	ire Doors		
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			State U	niversity					
Provide a brief description of operations:			Property	Property storage for Montana Rep Theatre & Dept of Drama Dance for University					
Storage height of warehoused products:			0						
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ						
Protection:									
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		no sprinklers		
The water supply for auto	omatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings?	?	0		
ndicate the Alarm Cover	ages provided for your fac	cility:		Smoke D	etectors				
Are alarms connected to	a constantly attended loca	ation?		N					
s there a watchman serv	rice?	Υ		What is t	the frequency of rounds?		Intermitant 24/7		
Are watchman recording	rounds?								
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N		
requency of training red	ceived by the private fire b	rigade:							
Гуре of public fire depart	tment:	Paid		Distance	:		under 1 mile		
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
s there a body of water r	nearby?	N	Descrip	otion:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Descrip	otion:					
Any property damage los	sses in the past 3 years:	null	Descrip	otion:					

BEAVERHEAD RIVER

				Page 2
			Property Detail Form	
Agency:	UNIVERSITY SYSTE	EM / UNIVERSITY SYSTEM, UNIV	ERSITY OF MONTANA - WESTERN	
Property:	Business & Technolo	gy Building (BTB)		
Property Address:	710 S. Atlantic DILLC	DN		
Property ID:	3			
Construction:				
Total number of insure	ed buildings:	1	Total square footage of insured buildings:	33500
Year built:		1924	Number of stories:	2
Construction of roof:		Wood Joists	Construction of floors:	Wood Timber
Construction of exterio	or walls:	Masonry	Construction of interior walls:	Masonry w/ Fire Doors
Do major interior maso	onry walls (fire walls) ex	tend above the roofline?	Υ	
Occupancy:				
Occupancy Type:			State University	
Provide a brief descrip	tion of operations:		CLASSROOMS/OFFICES/POOL	
Storage height of ware	housed products:		N/A	
Are flammable and cor	mbustible liquids stored	I in a cut-off room?	N/A	
Safegaurds taken for t	he storage and dispens	ing of flammable liquids:	N/A	
Protection:				
Are there any automati	ic sprinklers?	N	What are the design densities for each area?	
The water supply for a	utomatic sprinklers is?		How many hydrants are located within 500 feet of building	s? 3
Indicate the Alarm Cov	rerages provided for yo	ur facility:		
Are alarms connected	to a constantly attende	d location?	Υ	
Is there a watchman se	ervice?	Υ	What is the frequency of rounds?	HOUR
Are watchman recordii	ng rounds?		Υ	
Are there any fire extin	guishers?	Υ	Are they serviced annually?	Υ
Are there any hose sta	tions?	N	Is there a fire private fire brigade?	N
Frequency of training I	received by the private	fire brigade:		
Type of public fire dep	artment:	Voluntary	Distance:	12 BLOCKS
Exposure:				

0

Description:

Description:

Description:

1 MILE

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

			Pro	perty D	etail Form			
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, UNIVERSITY	OF MONT	TANA - M	ISSOULA			
Property:	Castle Forestry Center							
Property Address:	38689 Hwy 200 E. BONNE	ER .						
Property ID:	638							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	5369		
Year built:		1981			Number of stories:	2		
Construction of roof:		Wood Joists			Construction of floors:	Poured Conci	rete	
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonry walls (fire walls) extend above the roofline?				N				
Occupancy:								
Occupancy Type:			State Un	iversity				
Provide a brief description of operations:			School o	f Consy.8	Forestry, main offices, classrooms			
Storage height of warehoused products:		0						
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic	sprinklers?	N	1	What are	the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?		I	How man	y hydrants are located within 500 feet of buildings?	<b>,</b>	0	
Indicate the Alarm Cover	ages provided for your fac	cility:	:	Smoke De	etectors			
Are alarms connected to	a constantly attended loca	ation?	I	N				
ls there a watchman serv	rice?	Υ	•	What is t	he frequency of rounds?		full time caretaker	
Are watchman recording	rounds?		I	N				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose station	ons?	N	I	ls there a	fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Voluntary	I	Distance	:		20 miles	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
ls there a body of water i	nearby?	N	Descript	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ling?	N	Descript	tion:				
Any property damage los	sses in the past 3 years:	N	Descript	tion:				

			Property I	Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTANA - V	WESTERN				
Property:	Centennial Hall							
Property Address:	750 E. Cornell DILLON							
Property ID:	18							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	23252			
Year built:		1964		Number of stories:	3			
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete			
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors			
Do major interior masonry walls (fire walls) extend above the roofline?		above the roofline?		N				
Occupancy:								
Occupancy Type:		Res Apt Comple	x					
Provide a brief descriptio	n of operations:		Dorms/Carpentry	/ Shop				
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:	otection:							
Are there any automatic s	sprinklers?	Υ	What ar	e the design densities for each area?				
The water supply for auto	omatic sprinklers is?	Public	How ma	any hydrants are located within 500 feet of buildings?	3			
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	tion?	Υ					
Is there a watchman serv	ice?	Υ	What is	the frequency of rounds?	Hourly			
Are watchman recording	rounds?		Υ					
Are there any fire extingu	ishers?	Υ	Are the	y serviced annually?	Υ			
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?	N			
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire depart	ment:	Voluntary	Distanc	e:	> 1 mile			
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
Is there a body of water n	earby?	Υ	Description:		Beaverhead River			
How far is the body of wa	ar is the body of water from major buildings? < 1 mile							
Previous history of floodi	ing?	N	Description:					
Any property damage los	ses in the past 3 years:	N	Description:					

							i age zi
			Propert	y Detail Form			
gency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, MONTANA T	TECH OF THE U	М			
Property:	Centennial Hall (Student Re	esidence-East)					
Property Address:	1225 Broadway BUTTE						
Property ID:	119						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	33879		
ear built:		1999		Number of stories:	3		
Construction of roof:		Other		Construction of floors:	Other		
construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	d	
o major interior masonry walls (fire walls) extend above the roofline?				null			
Occupancy:							
Оссирансу Туре:			Res Apt Comp	olex			
rovide a brief description of operations:			Student housi	ng, telephone switch room			
torage height of warehoused products:			N/A				
are flammable and comb	oustible liquids stored in a c	cut-off room?	N/A				
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
are there any automatic	sprinklers?	Υ	What	are the design densities for each area?		118 psi static 87 residul	
he water supply for auto	omatic sprinklers is?	Private	How	many hydrants are located within 500 feet of buildings?	<b>?</b>	4	
ndicate the Alarm Cover	ages provided for your faci	lity:	Smok	e Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
are alarms connected to	a constantly attended loca	tion?	Υ				
s there a watchman serv	rice?	Υ	What	is the frequency of rounds?		2 per shift	
are watchman recording	rounds?		Υ				
are there any fire extingu	uishers?	Υ	Are th	ney serviced annually?		Υ	
are there any hose static	ons?	N	Is the	re a fire private fire brigade?		N	
requency of training red	ceived by the private fire br	igade:					
ype of public fire depart	tment:	Paid	Dista	nce:		0.86 miles	
xposure:							
low many huildings/not	nart of Account) are within	100 feet of incured buildings?	0				-

How many buildings(not part of Account) are within 100 feet of insured buildings? Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding? Ν Any property damage losses in the past 3 years: N

Description:

Description:

		Property [	Detail Form					
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA STATE UNIVERSIT	Y - NORTHERN					
Property:	Chancellor's New Residence	ce						
Property Address:	1325 11th Avenue HAVRE	<u> </u>						
Property ID:	7							
Construction:								
Total number of insured	buildings:	1	Total square footage of insured buildings:	4450				
Year built:		1982	Number of stories:	3				
Construction of roof:		Other	Construction of floors:	Wood Timber				
Construction of exterior walls: Wood Frame		Wood Frame	Construction of interior walls:	Gypsum Board				
Do major interior mason	ry walls (fire walls) extend	above the roofline?	Υ					

#### Occupancy:

Occupancy Type: State University

Provide a brief description of operations: Chancellor's Residence

Storage height of warehoused products: n/a

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids:

N/A

#### Protection:

Are there any automatic sprinklers? N What are the design densities for each area?

The water supply for automatic sprinklers is?

How many hydrants are located within 500 feet of buildings?

Indicate the Alarm Coverages provided for your facility:

Smoke Detectors

Are alarms connected to a constantly attended location?

Ν

Is there a watchman service? N What is the frequency of rounds?

Are watchman recording rounds?

Are there any fire extinguishers?

Y

Are they serviced annually?

Y

Are there any hose stations?

N Is there a fire private fire brigade?

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: 2 miles

# Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

blank

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Description:

How far is the body of water from major buildings?

Previous history of flooding?

Description:

Any property damage losses in the past 3 years:

						i age 20
			Pro	perty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA TI	ECH OF T	HE UM		
Property:	Chemistry - Biology Building	g (CBB) - H				
Property Address:	1300 W. Park Street BUTT	E				
Property ID:	105					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	42974	
Year built:		1921		Number of stories:	3	
Construction of roof:		Other		Construction of floors:	null	
Construction of exterior	walls:	Other		Construction of interior walls:	null	
Do major interior masonry walls (fire walls) extend above the roofline?			null			
Occupancy:						
Occupancy Type:			State Un	iversity		
Provide a brief description of operations:			Classroo	ms and labs		
Storage height of warehoused products:			N/A			
Are flammable and comb	oustible liquids stored in a	cut-off room?	N			
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	N	,	What are the design densities for each area?		
The water supply for aut	omatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?		6
Indicate the Alarm Cover	rages provided for your fac	ility:	;	Smoke Detectors		
Are alarms connected to	a constantly attended loca	ition?	•	Υ		
Is there a watchman serv	vice?	Υ	,	What is the frequency of rounds?		2 per shift
Are watchman recording	rounds?		•	Υ		
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ
Are there any hose static	ons?	N	ı	Is there a fire private fire brigade?		N
Frequency of training red	ceived by the private fire br	igade:				
Type of public fire depar	tment:	Paid	I	Distance:		0.86 miles
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0			

Description:

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

			Prop	erty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVE	ERSITY - BOZEMAN			
Property:	CHEMISTRY BIOCHEMIST	TRY BLDG					
Property Address:	South 11th Avenue (no office	cial address) BOZEMAN					
Property ID:	144						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	90368		
fear built:		2007		Number of stories:	5		
Construction of roof:		Steel Deck		Construction of floors:	Poured Conci	rete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Laboratory				
Provide a brief description of operations:		Chemistry i	research laboratory				
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ					
Protection:							
Are there any automatic	sprinklers?	Υ	Wi	hat are the design densities for each area?		140' sq/sprinkler	
The water supply for auto	omatic sprinklers is?	Public	Но	ow many hydrants are located within 500 feet of buildings	?	4	
ndicate the Alarm Cover	ages provided for your fac	ility:	Sp	rinkler Waterflow, Smoke Detectors, Sprinkler Valve Tamper			
Are alarms connected to	a constantly attended loca	ition?	Υ				
s there a watchman serv	ice?	N	WI	hat is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire extingu	iishers?	Υ	Ar	e they serviced annually?		Υ	
Are there any hose statio	ons?	N	Is	there a fire private fire brigade?		N	
requency of training rec	eived by the private fire br	igade:					
Type of public fire depart	ment:	Paid	Dis	stance:		.75 miles	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):					
s there a body of water r	nearby?	N	Descriptio	n:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Descriptio	n:			
Any property damage los	sses in the past 3 years:	N	Descriptio	n:			

							1 ago 20	
			Property	Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTANA -	MISSOULA				
Property:	Chemistry/Pharmacy							
Property Address:	1350 Mansfield Avenue MI	SSOULA						
Property ID:	014							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	55212			
Year built:		1938		Number of stories:	4			
Construction of roof:		Wood Joists		Construction of floors:	Poured Concr	rete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd		
Do major interior mason	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			State University					
Provide a brief description of operations:		Classrooms/lab	s					
Storage height of warehoused products:		0						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	Υ	What a	re the design densities for each area?		0.15		
The water supply for auto	omatic sprinklers is?	Public	How m	nany hydrants are located within 500 feet of buildings?	•	2		
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke	Detectors				
Are alarms connected to	a constantly attended loca	ation?	Υ					
Is there a watchman serv	ice?	Υ	What is	s the frequency of rounds?		Campus police 24/7		
Are watchman recording	rounds?		Υ					
Are there any fire extingu	iishers?	Υ	Are the	ey serviced annually?		null		
Are there any hose station	ons?	N	Is there	e a fire private fire brigade?		null		
Frequency of training red	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid	Distan	ce:		under 1 mile		
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Description:					
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Description:					
Any property damage los	sses in the past 3 years:	N	Description:					

					1 490	
			Propert	y Detail Form		
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIVERS	SITY - BILLINGS		
Property:	Cisel Hall					
Property Address:	1500 University Drive BILL	LINGS				
Property ID:	600000893/11729					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	38962	
Year built:		1951		Number of stories:	4	
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State Universi	ty		
Provide a brief descript	ion of operations:		education			
Storage height of warel	noused products:		0			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	N	What	are the design densities for each area?		
The water supply for au	tomatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	? 2	
Indicate the Alarm Cove	erages provided for your fa	cility:				
Are alarms connected t	o a constantly attended loc	ation?	Υ			
Is there a watchman se	rvice?	Υ	What	is the frequency of rounds?	daily	
Are watchman recording	g rounds?		N			
Are there any fire exting	guishers?	Υ	Are t	hey serviced annually?	Υ	
Are there any hose stat	ions?	N	Is the	ere a fire private fire brigade?	N	
Frequency of training re	eceived by the private fire b	rigade:				
Type of public fire depart	rtment:	Paid	Dista	nce:	1 to 2 miles	
Exposure:						
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0			
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):				
Is there a body of water	nearby?	Υ	Description:		irrigation ditch	
How far is the body of v	vater from major buildings?	?	300 feet			
Previous history of floo	ding?	N	Description:			
Any property damage lo	osses in the past 3 years:	N	Description:			

			Prope	rty Detail Form	
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVE	RSITY - BILLINGS	
Property:	City College - New Health	Sciences Bldg			
Property Address:	3803 Central Ave. BILLING	SS			
Property ID:	600014914				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	47115
ear built:		2007		Number of stories:	2
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			State Univer	rsity	
Provide a brief description	on of operations:		education		
Storage height of wareh	oused products:		0		
Are flammable and com	oustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ		
Protection:					
Are there any automatic	sprinklers?	Υ	Wh	at are the design densities for each area?	
The water supply for aut	omatic sprinklers is?	Public	Hov	w many hydrants are located within 500 feet of buildings?	2
ndicate the Alarm Cove	rages provided for your fac	ility:	Sm	oke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow	
Are alarms connected to	a constantly attended loca	ation?	Υ		
s there a watchman serv	vice?	Υ	Wh	at is the frequency of rounds?	daily
Are watchman recording	rounds?		N		
Are there any fire exting	uishers?	Υ	Are	they serviced annually?	Υ
Are there any hose station	ons?	Υ	ls t	here a fire private fire brigade?	N
requency of training re	ceived by the private fire b	rigade:			
Type of public fire depar	tment:	Paid	Dis	tance:	1 to 2 miles
Exposure:					
low many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
s there a body of water	nearby?	N	Description	:	
low far is the body of w	ater from major buildings?				
Previous history of flood	ling?	N	Description	ı:	
Any property damage lo	sses in the past 3 years:	null	Description	ı:	

			Prope	rty Detail Form	
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA S	TATE UNIVER	RSITY - BILLINGS	
Property:	City College - Technology I	Building			
Property Address:	3803 Central Avenue BILLI	INGS			
Property ID:	600901051/9182/11721				
Construction:					
Total number of insured	buildings:	1		Total square footage of insured buildings:	139057
Year built:		1987		Number of stories:	2
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			State Univers	sity	
Provide a brief description	on of operations:		education		
Storage height of wareho	oused products:		0		
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ		
Protection:					
Are there any automatic	sprinklers?	Υ	Wha	at are the design densities for each area?	
The water supply for auto	omatic sprinklers is?	Public	How	v many hydrants are located within 500 feet of buildings?	? 3
Indicate the Alarm Cover	ages provided for your fac	ility:	Spri	nkler Valve Tamper, Smoke Detectors, Burglar Alarms (Door	Contacts), Sprinkler Waterflow
Are alarms connected to	a constantly attended loca	ation?	Υ		
Is there a watchman serv	ice?	Υ	Wha	at is the frequency of rounds?	daily
Are watchman recording	rounds?		N		
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?	Υ
Are there any hose station	ns?	Υ	Is th	nere a fire private fire brigade?	N
Frequency of training red	eived by the private fire b	rigade:			
Type of public fire depart	ment:	Paid	Dist	tance:	1 to 2 miles
Exposure:					
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	blank		
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):			
Is there a body of water r	nearby?	N	Description	:	
How far is the body of wa	ater from major buildings?				
Previous history of flood	ing?	N	Description	:	
Any property damage los	ses in the past 3 years:	N	Description	:	

			Proper	ty Detail Form	
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSIT	Y OF MONTAN	A - WESTERN	
Property:	Clark Hall				
Property Address:	750 E. Cornell DILLON				
Property ID:	22				
Construction:					
Total number of insure	d buildings:	1		Total square footage of insured buildings:	30517
Year built:		1967		Number of stories:	3
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Res Apt Com	nplex	
Provide a brief descrip	tion of operations:		Dormitory		
Storage height of ware	housed products:		N/A		
Are flammable and cor	nbustible liquids stored in a	cut-off room?	N/A		
Safegaurds taken for t	ne storage and dispensing o	of flammable liquids:	N/A		
Protection:					
Are there any automati	c sprinklers?	Υ	Wha	t are the design densities for each area?	
The water supply for a	utomatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings	<b>5?</b> 3
Indicate the Alarm Cov	erages provided for your fa	cility:	Smo	ke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow	
Are alarms connected	to a constantly attended loc	ation?	Υ		
Is there a watchman se	rvice?	Υ	Wha	t is the frequency of rounds?	Hourly
Are watchman recordii	ng rounds?		Υ		
Are there any fire extin	guishers?	Υ	Are	they serviced annually?	Υ
Are there any hose sta	tions?	N	ls th	ere a fire private fire brigade?	N
Frequency of training I	eceived by the private fire b	rigade:			
Type of public fire dep	artment:	Voluntary	Dist	ance:	>1 mile
Exposure:					
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	0		
Describe the Occupand	cy of those buildings(s) nea	rby (within 100 feet):			
Is there a body of wate	r nearby?	Υ	Description:		Beaverhead River
How far is the body of	water from major buildings?	?	< 1 mile		
Previous history of floo	oding?	N	Description:		
Any property damage	osses in the past 3 years:	N	Description:		

							- 3
			Property	/ Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSITY	OF MONTANA	- MISSOULA			
Property:	Clinical Psychology Buildin	ng					
Property Address:	1420 Mansfield Avenue M	ISSOULA					
Property ID:	95						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	5280		
Year built:		1983		Number of stories:	2		
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced C	concrete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Boa	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State Universit	у			
Provide a brief description	on of operations:		Clinical psycho	ology office, used for visiting & treating patients on an ourp	atient basis		
Storage height of wareh	oused products:		0				
Are flammable and comi	oustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N	What	are the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?		How r	nany hydrants are located within 500 feet of buildings	?	0	
Indicate the Alarm Cove	rages provided for your fa	cility:	Smok	e Detectors			
Are alarms connected to	a constantly attended loc	ation?	N				
ls there a watchman serv	vice?	Υ	What	is the frequency of rounds?		Campus police 24/7	
Are watchman recording	ı rounds?		Υ				
Are there any fire exting	uishers?	Υ	Are th	ey serviced annually?		Υ	
Are there any hose station	ons?	N	Is the	re a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	Dista	nce:		under 1 mile	
Exposure:							
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):					
ls there a body of water	nearby?	N	Description:				
How far is the body of w	ater from major buildings?	?					
Previous history of flood	ling?	N	Description:				
Any property damage lo	sses in the past 3 years:	N	Description:				

								Page 270
			Pı	operty D	Petail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UN	NIVERSITY	/ - BOZEMAN			
Property:	COBLEIGH HALL							
Property Address:	South 7th Avenue (no office	cial address) BOZEMAN						
Property ID:	119							
Construction:								
Total number of insure	ed buildings:	1			Total square footage of insured buildings:	96634		
Year built:		1970			Number of stories:	6		
Construction of roof:		Reinforced Concrete			Construction of floors:	Reinforced C	oncrete	
Construction of exterio	or walls:	Masonry			Construction of interior walls:	Masonry w/ F	Fire Doors	
Do major interior maso	onry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Labora	tory				
Provide a brief descrip	tion of operations:		Offices	, classsroo	oms, labs			
Storage height of ware	housed products:		0					
Are flammable and co	mbustible liquids stored in a	cut-off room?	N					
Safegaurds taken for t	he storage and dispensing o	f flammable liquids:	Υ					
Protection:								
Are there any automat	ic sprinklers?	N		What are	the design densities for each area?		no sprinklers	
The water supply for a	utomatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings	?	4	
Indicate the Alarm Cov	verages provided for your fac	cility:		Smoke D	etectors			
Are alarms connected	to a constantly attended loc	ation?		Υ				
Is there a watchman se	ervice?	N		What is t	the frequency of rounds?			
Are watchman recordi	ng rounds?			N				
Are there any fire extir	nguishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose sta	tions?	N		Is there a	a fire private fire brigade?		N	
Frequency of training	received by the private fire b	rigade:						
Type of public fire dep	artment:	Paid		Distance	e:		1.37 miles	
Exposure:								
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupan-	cy of those buildings(s) near	by (within 100 feet):						
Is there a body of water	er nearby?	N	Descri	ption:				
How far is the body of	water from major buildings?	•						
Previous history of flo	oding?	N	Descri	ption:				
Any property damage	losses in the past 3 years:	N	Descri	ption:				

						Pag	ge 271
			Pr	roperty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	STATE UN	NIVERSITY - BILLINGS			
Property:	College of Business - McD	onald Hall					
Property Address:	100 Poly Drive BILLINGS						
Property ID:	600010714/10715						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings: 4	10946		
Year built:		1970		Number of stories: 3	<b>;</b>		
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concret	te	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry		
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Office				
Provide a brief description	on of operations:		educati	tion			
Storage height of wareho	oused products:		0				
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		2	
Indicate the Alarm Cover	rages provided for your fac	ility:		Smoke Detectors			
Are alarms connected to	a constantly attended loca	ation?		Υ			
Is there a watchman serv	vice?	Υ		What is the frequency of rounds?	,	daily	
Are watchman recording	rounds?			N			
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ	
Are there any hose static	ons?	N		Is there a fire private fire brigade?	i	N	
Frequency of training red	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid		Distance:		1 to 2 miles	
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	1				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	medica	al			
Is there a body of water	nearby?	Υ	Descri	iption:	rrigation ditch		

500 feet

Description:

Description:

Ν

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Previous history of flooding?

irrigation ditch

Storm

water

					Page 2
				Property Detail Form	
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, M	IONTANA STAT	E UNIVERSITY - BILLINGS	
Property:	College of Education Build	ling			
Property Address:	1500 University Drive BILL	INGS			
Property ID:	600000780/10962				
Construction:					
Total number of insured	d buildings:	1		Total square footage of insured buildings:	96502
Year built:		1972		Number of stories:	4
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete
Construction of exterior	r walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			Sta	ate University	
Provide a brief descript	ion of operations:		ede	ucation	
Storage height of wareh	noused products:		0		
Are flammable and com	bustible liquids stored in a	cut-off room?	N		
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	Υ		
Protection:					
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?	
The water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cove	erages provided for your fac	cility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow	
Are alarms connected to	o a constantly attended loc	ation?		Υ	
Is there a watchman ser	rvice?	Υ		What is the frequency of rounds?	daily
Are watchman recordin	g rounds?			N	
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ
Are there any hose stat	ions?	Υ		Is there a fire private fire brigade?	N
Frequency of training re	eceived by the private fire b	rigade:			
Type of public fire depa	rtment:	Paid		Distance:	1 to 2 miles
Exposure:					
How many buildings(no	ot part of Account) are withi	n 100 feet of insured bu	ildings? 0		
Describe the Occupanc	y of those buildings(s) near	rby (within 100 feet):			

Description:

Description:

Description:

80 feet

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: Y

Υ

Υ

							i age z
			Pr	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / UN	IIVERSITY SYSTEM, MONTANA 1	TECH OF	THE UM			
Property:	College of Technology						
Property Address:	25 Basin Creek Rd. BUTTE						
Property ID:	201						
Construction:							
Total number of insured	l buildings:	1		Total square footage of insured buildings:	94009		
ear built:		1983		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Other		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Other		
Do major interior masor	nry walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			State U	Iniversity			
Provide a brief descript	ion of operations:		Classro	ooms, shops & labs			
Storage height of wareh	oused products:		N/A				
Are flammable and com	bustible liquids stored in a c	ut-off room?	N				
Safegaurds taken for th	e storage and dispensing of	flammable liquids:	Υ				
Protection:							
Are there any automation	sprinklers?	Υ		What are the design densities for each area?		149 psi static 95 residl	
The water supply for au	tomatic sprinklers is?	Private		How many hydrants are located within 500 feet of building	gs?	4	
ndicate the Alarm Cove	erages provided for your facil	ity:		Burglar Alarms (Door Contacts), Burglar Alarms (Motion Dete Valve Tamper, Sprinkler Waterflow	ction), Fire Pump	Alarms, Smoke Detectors, S	3prinkler
Are alarms connected t	o a constantly attended locat	ion?		Υ			
s there a watchman sei	vice?	N		What is the frequency of rounds?			
Are watchman recordin	g rounds?						
Are there any fire exting	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?		N	
requency of training re	eceived by the private fire bri	gade:					
Гуре of public fire depa	rtment:	Paid		Distance:		5.07	
Exposure:							
How many buildings(no	t part of Account) are within	100 feet of insured buildings?	2				
Describe the Occupanc	y of those buildings(s) nearb	y (within 100 feet):	garage	, open shelter			
s there a body of water	nearby?	N	Descri	ption:			
How far is the body of v	vater from major buildings?						

Description:

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

Ν

BEAVERHEAD RIVER

						Page 274
			Pro	pperty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	Y OF MON	TANA - WESTERN		
Property:	Concession Stand at Vigila	inte Field				
Property Address:	745 East Center Street/Vig	ilante Field DILLON				
Property ID:	51080					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	4610	
Year built:		2006		Number of stories:	1	
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Reinforced Concrete	
Construction of exterio	r walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State Un	iversity		
Provide a brief descript	ion of operations:		Concess	sions		
Storage height of wareh	noused products:		N/A			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for th	e storage and dispensing of	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?	None	
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	2	
ndicate the Alarm Cove	erages provided for your fac	ility:				
Are alarms connected t	o a constantly attended loca	ation?		N		
s there a watchman se	rvice?	N		What is the frequency of rounds?		
Are watchman recordin	g rounds?			N		
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?	N	
requency of training re	eceived by the private fire b	rigade:				
Гуре of public fire depa	rtment:	Voluntary		Distance:	12 BLOCKS	
Exposure:						
low many buildings(no	ot part of Account) are within	n 100 feet of insured buildings?	3			
Describe the Occupanc	y of those buildings(s) near	by (within 100 feet):	Resident	t, Resident Garage, Shed		

Description:

Description:

Description:

1 MILE

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Υ

Ν

	Property Detail Form
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN
Property:	COOLEY LABORATORY

**Property Address:** South 11th Avenue (no official address) BOZEMAN

Property ID: 118

- 1 2	
<b>^</b>	
Construction:	

Total number of insured buildings:	1	Total square footage of insured buildings:
------------------------------------	---	--

Year built: 1960 Number of stories:

Construction of roof: Reinforced Concrete Construction of floors: Reinforced Concrete Reinforced Concrete Construction of interior walls:

Construction of exterior walls: Masonry w/ Fire Doors

Laboratory

Do major interior masonry walls (fire walls) extend above the roofline?

### Occupancy:

**Occupancy Type:** 

Provide a brief description of operations: Offices, labs

Storage height of warehoused products: 0

Are flammable and combustible liquids stored in a cut-off room? Ν

Safegaurds taken for the storage and dispensing of flammable liquids:

## Protection: Are there any automatic sprinklers?

Is there a watchman service?

Are there any hose stations?

Is there a body of water nearby?

Previous history of flooding?

The water supply for automatic sprinklers is?

Indicate the Alarm Coverages provided for your facility:

Are alarms connected to a constantly attended location?

Υ

Ν

How many hydrants are located within 500 feet of buildings?

**Smoke Detectors** 

Υ

What is the frequency of rounds?

Are watchman recording rounds?

Are there any fire extinguishers?

Ν

Frequency of training received by the private fire brigade:

Distance:

Are they serviced annually?

Is there a fire private fire brigade?

What are the design densities for each area?

Ν

0.20/1500 407 gpm flow, 66 psi, 165 temp rating 1-4 floors; 0.20/1950, 420 gpm, 64 psi, 165 temp 5th fl

39458

Type of public fire department:

Paid

.75 miles

## Exposure: How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν How far is the body of water from major buildings?

Description:

Ν Description: Any property damage losses in the past 3 years:

			Propert	y Detail Form					
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTANA	- MISSOULA					
Property:	Corbin Hall								
Property Address:	1025 Maurice Avenue MIS	SOULA							
Property ID:	102								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	23190				
Year built:		1927		Number of stories:	4				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concr	ete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	null				
Do major interior masonry walls (fire walls) extend above the roofline?			null						
Occupancy:									
Occupancy Type:		State Universi	ty						
Provide a brief description of operations:			Offices/classro	Offices/classrooms/faculty					
Storage height of warehoused products:		0							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic	sprinklers?	N	What	are the design densities for each area?		no sprinklers			
The water supply for aut	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?		1			
Indicate the Alarm Cover	ages provided for your fac	ility:	Smok	te Detectors					
Are alarms connected to	a constantly attended loca	tion?	Υ						
Is there a watchman serv	rice?	Υ	What	is the frequency of rounds?		Campus police 24/7			
Are watchman recording	rounds?		Υ						
Are there any fire exting	uishers?	Υ	Are ti	hey serviced annually?		Υ			
Are there any hose static	ons?	N	Is the	ere a fire private fire brigade?		N			
Frequency of training red	ceived by the private fire b	igade:							
Type of public fire depar	tment:	Paid	Dista	nce:		under 1 mile			
Exposure:									
		100 feet of insured buildings?	blank						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water i	nearby?	N	Description:						
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	null	Description:						
Any property damage los	sses in the past 3 years:	N	Description:						

						Page 27		
			Pı	roperty Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UN	NIVERSITY - NORTHERN				
Property:	Cowan Hall							
Property Address:	MSU-Northern 200 Cowan	Drive HAVRE						
Property ID:	10							
Construction:								
Total number of insured I	buildings:	1		Total square footage of insured buildings:	66463			
Year built:		1953		Number of stories:	4			
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete			
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Masonry			
o major interior masonry walls (fire walls) extend above the roofline?				N				
Occupancy:								
Occupancy Type:			State L	Iniversity				
Provide a brief descriptio	n of operations:		classes/offices/it/theatre					
Storage height of wareho	used products:		n/a					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	N		What are the design densities for each area?				
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	2			
ndicate the Alarm Cover	ages provided for your fac	ility:		Smoke Detectors				
Are alarms connected to	a constantly attended loca	ition?		N				
s there a watchman serv	ice?	Υ		What is the frequency of rounds?	every 24 hours			
Are watchman recording	rounds?			Υ				

Are there any fire extinguishers? Are they serviced annually? Υ Υ Is there a fire private fire brigade? Are there any hose stations? Ν Frequency of training received by the private fire brigade: Type of public fire department: Paid Distance: 1 mile

Description:

Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0 Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Ν Description: Description: Any property damage losses in the past 3 years: N

							Page 2
			Prope	erty Detail Form			
Agency:	UNIVERSITY SYST	EM / UNIVERSITY SYSTEM, UNIV	ERSITY OF MONTA	NA - MISSOULA			
Property:	Craig Hall						
Property Address:	1301 Maurice Avenu	ue MISSOULA					
Property ID:	104						
Construction:							
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	78116		
Year built:		1953		Number of stories:	4		
Construction of roof:		null		Construction of floors:	null		
Construction of exterio	or walls:	null		Construction of interior walls:	null		
Do major interior maso	onry walls (fire walls) e	xtend above the roofline?		null			
Occupancy:							
Occupancy Type:			State Unive	ersity			
Provide a brief descrip	otion of operations:		null				
Storage height of ware	ehoused products:		null				
Are flammable and co	mbustible liquids store	ed in a cut-off room?	null				
Safegaurds taken for t	he storage and dispen	sing of flammable liquids:	null				
Protection:							
Are there any automat	ic sprinklers?	Υ	WI	nat are the design densities for each area?		null	
The water supply for a	utomatic sprinklers is?	?	Но	ow many hydrants are located within 500 feet of buildir	ngs?	null	
Indicate the Alarm Cov	verages provided for yo	our facility:					
Are alarms connected	to a constantly attende	ed location?	nu	II			
Is there a watchman se	ervice?	null	WI	nat is the frequency of rounds?		null	
Are watchman recordi	ng rounds?						
Are there any fire extir	nguishers?	null	Ar	e they serviced annually?		null	
Are there any hose sta	itions?	null	Is	there a fire private fire brigade?		null	
Frequency of training	received by the private	fire brigade:	nu	II			
Type of public fire dep	artment:	null	Dis	stance:		null	

### Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet): null

Is there a body of water nearby? null

How far is the body of water from major buildings?

Description:

Previous history of flooding? null

Any property damage losses in the past 3 years:

Description:

null

Description:

null

null

null

							Page 2
			Pr	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / UNI	VERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MISSOULA			
Property:	Craighead Apartments						
Property Address:	1900 Maurice Avenue MISSC	OULA					
Property ID:	200						
Construction:							
Γotal number of insured	buildings: 1			Total square footage of insured buildings:	77292		
Year built:	1!	957		Number of stories:	3		
Construction of roof:	n	ull		Construction of floors:	null		
Construction of exterior	walls:	ull		Construction of interior walls:	null		
Do major interior mason	ry walls (fire walls) extend ab	ove the roofline?		null			
Occupancy:							
Occupancy Type:			Res Apt	Complex			
Provide a brief description	on of operations:		null				
Storage height of wareh	oused products:		null				
Are flammable and com	oustible liquids stored in a cu	t-off room?	null				
Safegaurds taken for the	storage and dispensing of fl	ammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?		null	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null	
ndicate the Alarm Cove	rages provided for your facilit	y:					
Are alarms connected to	a constantly attended location	on?		null			
s there a watchman serv	vice?	null		What is the frequency of rounds?		null	
Are watchman recording	rounds?						
Are there any fire exting	uishers?	null		Are they serviced annually?		null	
Are there any hose station	ons?	null		Is there a fire private fire brigade?		null	
requency of training re	ceived by the private fire brig	ade:		null			
Гуре of public fire depar	tment:	null		Distance:		null	
Exposure:							

# How many buildings(not part of Account) are within 100 feet of insured buildings?

Previous history of flooding?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? null

Description: null

How far is the body of water from major buildings?

null

Any property damage losses in the past 3 years:

Description:

null

Description:

null

null

null

							1 age 200
			Propert	ty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MONTANA S	TATE UNIVERS	SITY - BOZEMAN			
Property:	CREATIVE ARTS COMPL	EX - CHEEVER HALL					
Property Address:	South 11th Avenue (no off	icial address) BOZEMAN					
Property ID:	127						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	61314		
Year built:		1974		Number of stories:	2		
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced C	oncrete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Boa	rd	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State Univers	ity			
Provide a brief descripti	on of operations:		classrooms, c	offices			
Storage height of wareh	oused products:		0				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N	What	t are the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	?	3	
Indicate the Alarm Cove	rages provided for your fac	cility:	Smol	ke Detectors			
Are alarms connected to	a constantly attended loc	ation?	Υ				
ls there a watchman ser	vice?	N	What	t is the frequency of rounds?			
Are watchman recording	g rounds?		N				
Are there any fire exting	uishers?	Υ	Are t	hey serviced annually?		Υ	
Are there any hose stati	ons?	N	Is the	ere a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:					
Type of public fire depar	tment:	Paid	Dista	ance:		1-01 miles	
Exposure:							
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water	nearby?	N	Description:				
How far is the body of w	ater from major buildings?	•					
Previous history of flood	ding?	N	Description:				
Any property damage lo	sses in the past 3 years:	N	Description:				

			Property	/ Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	ΓΑΤΕ UNIVERS	ITY - BOZEMAN				
Property:	CREATIVE ARTS COMPL	EX - HAYNES HALL						
Property Address:	South 11th Avenue (no offi	cial address) BOZEMAN						
Property ID:	128							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	44600			
Year built:		1974		Number of stories:	2			
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Cor	ncrete		
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ Fir	re Doors		
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			State Universit	у				
Provide a brief description of operations:			OFFICES/CLASSROOMS					
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the	e storage and dispensing of	f flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N	What	are the design densities for each area?				
The water supply for aut	omatic sprinklers is?		How r	nany hydrants are located within 500 feet of buildings?	<b>?</b>	8		
Indicate the Alarm Cove	rages provided for your fac	ility:	Smoke	e Detectors				
Are alarms connected to	a constantly attended loca	ation?	Υ					
Is there a watchman ser	vice?	Υ	What	is the frequency of rounds?		AVERAGE 4 PER NIGHT		
Are watchman recording	g rounds?		N					
Are there any fire exting	uishers?	Υ	Are th	ey serviced annually?		Υ		
Are there any hose static	ons?	N	Is the	re a fire private fire brigade?		N		
Frequency of training re	ceived by the private fire be	rigade:						
Type of public fire depar	rtment:	Paid	Distar	nce:		1.01 MILES		
Exposure:								
How many buildings(not	t part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Description:					
How far is the body of w	ater from major buildings?							
Previous history of floor	ding?	N	Description:					
Any property damage lo	sses in the past 3 years:	N	Description:					

			Property	Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	ATE UNIVERSIT	Y - BOZEMAN		
Property:	CREATIVE ARTS COMPLI	EX-HOWARD HALL				
Property Address:	South 11th Avenue (no office	cial address) BOZEMAN				
Property ID:	126					
Construction:						
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	30575	
Year built:		1974		Number of stories:	2	
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Co	ncrete
Construction of exterior v	valls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ Fir	re Doors
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State University			
Provide a brief descriptio	n of operations:		OFFICES/CLAS	SROOMS/LABS		
Storage height of warehoused products:			N/A			
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A				
Protection:						
Are there any automatic s	sprinklers?	N	What a	re the design densities for each area?		
The water supply for auto	matic sprinklers is?		How ma	any hydrants are located within 500 feet of buildings?		9
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke	Detectors		
Are alarms connected to	a constantly attended loca	ation?	Υ			
Is there a watchman servi	ice?	Υ	What is	the frequency of rounds?		AVERAGE 4 PER NIGHT
Are watchman recording	rounds?		N			
Are there any fire extingu	ishers?	Υ	Are the	y serviced annually?		Υ
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	rigade:				
Type of public fire depart	ment:	Paid	Distanc	e:		1.05 MILES
Exposure:						
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):				
Is there a body of water n	earby?	N	Description:			
How far is the body of wa	ter from major buildings?					
Previous history of floodi	ng?	N	Description:			
Any property damage los	ses in the past 3 years:	N	Description:			

							Page 28		
			Prop	perty Detail Form					
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	STATE UNIV	/ERSITY - BOZEMAN					
Property:	CULBERTSON HALL								
Property Address:	Harrison Street (no official	address) BOZEMAN							
Property ID:	136								
Construction:									
Total number of insured l	buildings:	1		Total square footage of insured buildings:	50480				
Year built:		1955		Number of stories:	4				
Construction of roof:		Poured Concrete		Construction of floors:	Poured Conc	rete			
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ F	Fire Doors			
Do major interior masonr	ry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			State Univ	versity					
Provide a brief description of operations:		Administra	Administration & post office						
Storage height of warehoused products:		0							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	N	W	What are the design densities for each area?		no sprinklers			
The water supply for auto	omatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings	s?	blank			
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors						
Are alarms connected to	a constantly attended loca	ation?	Y	,					
ls there a watchman serv	rice?	N	W	What is the frequency of rounds?					
Are watchman recording	rounds?		N	I					
Are there any fire extingu	uishers?	Υ	Α	are they serviced annually?		Υ			
Are there any hose statio	ons?	N	Is	s there a fire private fire brigade?		N			
Frequency of training rec	ceived by the private fire b	rigade:							
Type of public fire depart	tment:	Paid	D	Distance:		.84 mile			
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water n	nearby?	N	Description	on:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Description	on:					
Any property damage los	sses in the past 3 years:	N	Description	on:					

			Property	Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTANA -	MISSOULA			
Property:	Curry Health Center						
Property Address:	634 Eddy Avenue MISSOU	JLA					
Property ID:	22						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	56061		
Year built:		1956		Number of stories:	3		
Construction of roof:		Reinforced Concrete		Construction of floors:	Poured Concre	ete	
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Gypsum Board	i	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State University				
Provide a brief description of operations:		Medical offices/	Medical offices/lab				
Storage height of warehoused products:		0					
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		N					
Protection:							
Are there any automatic s	sprinklers?	Υ	What a	re the design densities for each area?		0.15	
The water supply for auto	matic sprinklers is?	Public	How m	any hydrants are located within 500 feet of buildings?	1	3	
Indicate the Alarm Covera	ages provided for your fac	ility:	Burglar Alarms (Door Contacts), Sprinkler Valve Tamper, Smoke Detectors, Sprinkler Waterflow				
Are alarms connected to	a constantly attended loca	ation?	Υ				
Is there a watchman servi	ice?	Υ	What is	s the frequency of rounds?		Campus police 24/7	
Are watchman recording	rounds?		Υ				
Are there any fire extingu	ishers?	Υ	Are the	ey serviced annually?		Υ	
Are there any hose statio	ns?	N	Is there	e a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	rigade:					
Type of public fire depart	ment:	Paid	Distan	ce:		under 1 mile	
Exposure:							
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):					
Is there a body of water n	earby?	null	Description:				
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Description:				
Any property damage los	ses in the past 3 years:	N	Description:				

3 miles

						Page 28
			Proper	ty Detail Form		
gency:	UNIVERSITY SYSTEM	/ UNIVERSITY SYSTEM, UNIV	ERSITY OF MONTANA	A - MISSOULA		
Property:	Daly Mansion					
Property Address:	251 Eastside Highway H	HAMILTON				
Property ID:	910					
Construction:						
otal number of insure	d buildings:	1		Total square footage of insured buildings:	28523	
ear built:		1910		Number of stories:	3	
construction of roof:		Wood Joists		Construction of floors:	Wood Timber	
construction of exterio	or walls:	Wood Frame		Construction of interior walls:	Other	
o major interior maso	onry walls (fire walls) exter	nd above the roofline?		N		
Occupancy:						
Occupancy Type:			Museum			
Provide a brief descrip	tion of operations:		Daly Mansion	a - museum, ground sometimes used for weddings, & reun	ions	
storage height of ware	housed products:		0			
are flammable and con	nbustible liquids stored in	a cut-off room?	N/A			
afegaurds taken for th	ne storage and dispensing	g of flammable liquids:	N/A			
Protection:						
re there any automati	c sprinklers?	N	Wha	t are the design densities for each area?	no sprinklers	
he water supply for a	utomatic sprinklers is?		How	many hydrants are located within 500 feet of building	s? 1	
ndicate the Alarm Cov	erages provided for your	facility:	Burg	lar Alarms (Door Contacts), Smoke Detectors		
are alarms connected	to a constantly attended le	ocation?	Υ			
s there a watchman se	ervice?	N	Wha	t is the frequency of rounds?		
are watchman recordir	ng rounds?		N			
are there any fire extin	guishers?	Υ	Are t	they serviced annually?	Υ	
are there any hose sta	tions?	N	Is the	ere a fire private fire brigade?	N	
requency of training r	eceived by the private fire	e brigade:				

# Exposure:

Type of public fire department:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Ν Any property damage losses in the past 3 years: N

Voluntary

Description:

Description:

Distance:

							. ago 200		
			Prop	perty Detail Form					
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, UNIVERSITY	OF MONTA	ANA - MISSOULA					
Property:	Davidson Honors College								
Property Address:	1235 Madeline Avenue MIS	SSOULA							
Property ID:	88								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	21674				
Year built:		1996		Number of stories:	2				
Construction of roof:		Wood Joists		Construction of floors:	Poured Concre	ete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	d			
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			State Univ	versity					
Provide a brief description	on of operations:		Offices/cla	Offices/classrooms					
Storage height of warehoused products:		0							
Are flammable and combustible liquids stored in a cut-off room?		N							
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	Υ	w	hat are the design densities for each area?		0.1			
The water supply for aut	omatic sprinklers is?	Public	H	ow many hydrants are located within 500 feet of buildings?		1			
Indicate the Alarm Cover	ages provided for your fac	sility:	Sı	moke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ation?	Υ						
Is there a watchman serv	rice?	Υ	w	/hat is the frequency of rounds?		Campus police 24/7			
Are watchman recording	rounds?		Υ						
Are there any fire exting	uishers?	Υ	A	re they serviced annually?		Υ			
Are there any hose static	ons?	N	Is	there a fire private fire brigade?		N			
Frequency of training red	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Paid	Di	istance:		under 1 mile			
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water i	nearby?	N	Description	on:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ling?	N	Description	on:					
Any property damage los	sses in the past 3 years:	N	Description	on:					

					-3				
			Prop	perty Detail Form					
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - WESTERN								
Property:	Davis Hall								
Property Address:	710 S. Atlantic DILLON								
Property ID:	15								
Construction:									
Total number of insured buildings: 1		1		Total square footage of insured buildings:	14388				
Year built:		1959		Number of stories:	2				
Construction of roof:		Reinforced Concrete		Construction of floors:	Poured Concrete				
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry				
Do major interior masonry walls (fire walls) extend above the roofline?				N					
Occupancy:									
Occupancy Type:			Res Apt C	Complex					
Provide a brief description of operations:			Dormitory	Dormitory/Offices					
Storage height of warehoused products:			N/A						
Are flammable and combustible liquids stored in a cut-off room?			N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A						
Protection:						ı			
Are there any automatic	sprinklers?	N	W	Vhat are the design densities for each area?					
The water supply for aut	omatic sprinklers is?	Public	н	low many hydrants are located within 500 feet of buildings?	? 3				
Indicate the Alarm Coverages provided for your facility:			S	moke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to a constantly attended location?			Υ						
Is there a watchman serv	vice?	Υ	W	Vhat is the frequency of rounds?	Hourly				
Are watchman recording	rounds?		Υ						
Are there any fire exting	uishers?	Υ	Α	re they serviced annually?	Υ				
Are there any hose static	ons?	N	Is	s there a fire private fire brigade?	N				
Frequency of training received by the private fire brigade:									
Type of public fire depar	tment:	Voluntary	D	istance:	>1 mile				
Exposure:						ı			
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water	nearby?	Υ	Description	on:	Beaverhead River				
How far is the body of water from major buildings?		<1 mile							
Previous history of flood	ling?	N	Description	on:					
Any property damage los	sses in the past 3 years:	N	Description	on:					

			Property	Detail Form						
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA									
Property:	Don Anderson Hall									
Property Address:	800 Daly Ave MISSOULA									
Property ID:	40									
Construction:										
Total number of insured buildings:		1		Total square footage of insured buildings:	56005					
Year built:		2007		Number of stories:	4					
Construction of roof:		Wood Joists		Construction of floors: Reinford		forced Concrete				
Construction of exterior walls:		Masonry		Construction of interior walls:	Gypsum Boar	d				
Do major interior masonry walls (fire walls) extend above the roofline?				N						
Occupancy:										
Occupancy Type:			State University							
Provide a brief description of operations:			Journalism operation/classroom & offices for higher education							
Storage height of warehoused products:			0							
Are flammable and combustible liquids stored in a cut-off room?			N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A							
Protection:										
Are there any automatic	sprinklers?	Υ	What a	re the design densities for each area?		comply w/standard NPPA 13				
The water supply for auto	omatic sprinklers is?	Public	How m	any hydrants are located within 500 feet of buildings?	•	2				
Indicate the Alarm Coverages provided for your facility:			Smoke	Detectors						
Are alarms connected to a constantly attended location?			Υ							
Is there a watchman serv	ice?	Υ	What is	s the frequency of rounds?		Campus police 24/7				
Are watchman recording	rounds?		N							
Are there any fire extingu	iishers?	Υ	Are the	ey serviced annually?		Υ				
Are there any hose station	ns?	N	Is there	e a fire private fire brigade?		N				
Frequency of training red	eived by the private fire br	igade:								
Type of public fire depart	ment:	Paid	Distan	ce:		under 1 mile				
Exposure:										
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0							
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):								
Is there a body of water nearby?		Description:								
How far is the body of wa	ater from major buildings?									
Previous history of flooding?		Description:								
Any property damage los	ses in the past 3 years:	N	Description:							

								1 age 20
			Pro	perty D	etail Form			
Agency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, HELENA CO	LLEGE UN	IIVERSIT'	Y OF MONTANA			
Property:	Donaldson Building							
Property Address:	1115 North Roberts HELE	ENA						
Property ID:	811							
Construction:								
Total number of insured	d buildings:	1			Total square footage of insured buildings:	90163		
Year built:		1967			Number of stories:	2		
Construction of roof:		null			Construction of floors:	Reinforced C	oncrete	
Construction of exterio	r walls:	Masonry			Construction of interior walls:	Masonry w/ F	Fire Doors	
Do major interior maso	nry walls (fire walls) extend	I above the roofline?			Υ			
Occupancy:								
Occupancy Type:			State Uni	iversity				
Provide a brief descript	ion of operations:		College b	building w	vith both classrooms & administrative offices			
Storage height of warel	noused products:		7 feet					
Are flammable and com	nbustible liquids stored in a	a cut-off room?	Υ					
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	Υ					
Protection:								
Are there any automatic	c sprinklers?	Υ	,	What are	the design densities for each area?			
The water supply for au	tomatic sprinklers is?	Public	ŀ	How man	ny hydrants are located within 500 feet of buildings	?	3	
Indicate the Alarm Cove	erages provided for your fa	cility:	Burglar Alarms (Motion Detection), Smoke Detectors, Sprinkler Waterflow					
Are alarms connected t	o a constantly attended loc	cation?	`	Υ				
ls there a watchman se	rvice?	N	1	What is t	he frequency of rounds?			
Are watchman recordin	g rounds?							
Are there any fire exting	guishers?	Υ	,	Are they	serviced annually?		Υ	
Are there any hose stat	ions?	N	ı	ls there a	a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	origade:						
Type of public fire depa	artment:	Paid	I	Distance	:		blank	
Exposure:								
How many buildings(no	ot part of Account) are with	in 100 feet of insured buildings?	3					
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):	home & 2	2 garages	S			
Is there a body of water	nearby?	N	Descript	tion:				
How far is the body of v	water from major buildings	?						
Previous history of floo	oding?	N	Descript	tion:				
Any property damage lo	osses in the past 3 years:	N	Descript	tion:				

						1 ago 2
			Pro	pperty Detail Form		
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTAN	A STATE UNI	VERSITY - NORTHERN		
Property:	Donaldson Hall					
Property Address:	MSU-Northern 100 Cowar	Drive HAVRE				
Property ID:	3					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	32745	
Year built:		1936		Number of stories:	4	
Construction of roof:		Other		Construction of floors:	Other	
Construction of exterior	r walls:	Masonry		Construction of interior walls:	Other	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State Un	niversity		
Provide a brief descript	ion of operations:		vacant -	storage		
Storage height of wareh	noused products:		n/a			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	? 1	
Indicate the Alarm Cove	erages provided for your fa	cility:		Smoke Detectors		
Are alarms connected to	o a constantly attended loc	ation?		N		
Is there a watchman ser	rvice?	Υ		What is the frequency of rounds?	eve	ry 24 hours
Are watchman recording	g rounds?			Υ		
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
Are there any hose state	ions?	N		Is there a fire private fire brigade?	N	
Frequency of training re	eceived by the private fire b	rigade:				
Type of public fire depa	rtment:	Paid		Distance:	1 M	ile

## **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet): Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Description:

Previous history of flooding?

Description:

Any property damage losses in the past 3 years: N Description: 2005 floor water damage

					Page 29
			Pro	perty Detail Form	
Agency:	UNIVERSITY SYSTEM / I	JNIVERSITY SYSTEM, UNIV	ERSITY OF MONT	TANA - MISSOULA	
Property:	Duniway Hall				
Property Address:	635 McLeod Avenue MIS	SOULA			
Property ID:	105				
Construction:					
Total number of insure	d buildings:	1		Total square footage of insured buildings:	35964
Year built:		1956		Number of stories:	3
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Other
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N	
Occupancy:					
Occupancy Type:			State Un	iversity	
Provide a brief descrip	tion of operations:		Student	dorm	
Storage height of ware	housed products:		0		
Are flammable and con	nbustible liquids stored in a	cut-off room?	N		
Safegaurds taken for the	ne storage and dispensing o	of flammable liquids:	N/A		
Protection:					
Are there any automati	c sprinklers?	Υ	,	What are the design densities for each area?	0.1
The water supply for a	utomatic sprinklers is?	Public	ı	How many hydrants are located within 500 feet of buildin	ı <b>gs?</b> 1
Indicate the Alarm Cov	erages provided for your fa	cility:	ı	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler	Valve Tamper, Sprinkler Waterflow
Are alarms connected	to a constantly attended loc	ation?	,	Y	
Is there a watchman se	ervice?	Υ	,	What is the frequency of rounds?	Campus police 24/7
Are watchman recording	ng rounds?		,	Y	
Are there any fire extin	guishers?	Υ		Are they serviced annually?	Υ
Are there any hose sta	tions?	Υ	1	s there a fire private fire brigade?	N
Frequency of training r	eceived by the private fire b	origade:			
Type of public fire depart	artment:	Paid	I	Distance:	under 1 mile

**Exposure:** 

How many buildings(not part of Account) are within 100 feet of insured buildings? 0 Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding? Any property damage losses in the past 3 years: N

Ν

Description:

Description:

								- 3
			Pro	perty D	etail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	TATE UNI	IVERSITY	- NORTHERN			
Property:	Electronics Building							
Property Address:	MSU-Northern 171 College	e Road East HAVRE						
Property ID:	30							
Construction:								
Total number of insured	l buildings:	1			Total square footage of insured buildings:	14577		
Year built:		1968			Number of stories:	2		
Construction of roof:		Reinforced Concrete			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry		
Do major interior masor	nry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Laborato	ory				
Provide a brief descripti	on of operations:		labs/clas	srooms				
Storage height of wareh	oused products:		n/a					
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?			
The water supply for au	tomatic sprinklers is?			How man	ny hydrants are located within 500 feet of buildings?	•	2	
Indicate the Alarm Cove	rages provided for your fac	cility:		Smoke De	etectors			
Are alarms connected to	a constantly attended loc	ation?		N				
Is there a watchman ser	vice?	Υ		What is tl	he frequency of rounds?		every 24 hours	
Are watchman recording	g rounds?			Υ				
Are there any fire exting	juishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:						
Type of public fire depa	rtment:	Paid		Distance	:		1 mile	
Exposure:								
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Descrip	tion:				
How far is the body of w	ater from major buildings?							
Previous history of floor	ding?	N	Descrip	tion:				
Any property damage lo	esses in the past 3 years:	N	Descrip	tion:				

						. 3
			Propert	y Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTANA	- MISSOULA		
Property:	Elkhorn Ct. (Warehouse &	Shop)				
Property Address:	Elkhorn Court 248 MISSOL	JLA				
Property ID:	248					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	5280	
ear built:		1967		Number of stories:	1	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			State Universi	ty		
Provide a brief description	on of operations:		null			
Storage height of wareh	oused products:		null			
Are flammable and com	oustible liquids stored in a	cut-off room?	null			
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N	What	are the design densities for each area?	1	null
The water supply for aut	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	1	null
ndicate the Alarm Cove	rages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ition?	null			
s there a watchman serv	vice?	null	What	is the frequency of rounds?	1	null
Are watchman recording	rounds?					
Are there any fire exting	uishers?	null	Are th	hey serviced annually?	1	null
Are there any hose station	ons?	null	Is the	ere a fire private fire brigade?	1	null
requency of training re	ceived by the private fire b	igade:	null			
Гуре of public fire depar	tment:	null	Dista	nce:	ı	null
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	null			
s there a body of water	nearby?	null	Description:		null	
How far is the body of w	ater from major buildings?		null			
Previous history of flood	ling?	null	Description:		null	

null

Any property damage losses in the past 3 years: null

			Pro	operty D	etail Form		
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - M	ISSOULA		
Property:	Elrod Hall						
Property Address:	640 Keith Avenue MISSOU	LA					
Property ID:	101						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	33362	
Year built:		1921			Number of stories:	3	
Construction of roof:		Wood Joists			Construction of floors:	Poured Concre	ete
Construction of exterior v	walls:	Masonry			Construction of interior walls:	Other	
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			null		
Occupancy:							
Occupancy Type:			State Ur	niversity			
Provide a brief descriptio	n of operations:		Student	Dorm			
Storage height of wareho	used products:		0				
Are flammable and comb	ustible liquids stored in a d	cut-off room?	N				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	Υ		What are	the design densities for each area?		0.1
The water supply for auto	omatic sprinklers is?	Public		How man	y hydrants are located within 500 feet of buildings?		1
Indicate the Alarm Covera	ages provided for your faci	ility:		Smoke De	etectors, Burglar Alarms (Door Contacts), Sprinkler Water	erflow	
Are alarms connected to	a constantly attended loca	tion?		Υ			
Is there a watchman servi	ice?	Υ		What is the	he frequency of rounds?		
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose statio	ns?	Υ		Is there a	fire private fire brigade?		N
Frequency of training rec	eived by the private fire bri	igade:					
Type of public fire depart	ment:	Paid		Distance	:		under 1 mile
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):					
Is there a body of water n	earby?	N	Descrip	tion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ing?	N	Descrip	tion:			
Any property damage los	ses in the past 3 years:	N	Descrip	tion:			

Flathead lake

					Pa	ige 2
			Proper	ty Detail Form		
Agency:	UNIVERSITY SYSTE	M / UNIVERSITY SYSTEM, UNIV	ERSITY OF MONTAN	A - MISSOULA		
Property:	Elrod Laboratory, Ye	lowbay				
Property Address:	32125 Bio Station La	ne POLSON				
Property ID:	512					
Construction:						
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	8467	
Year built:		1968		Number of stories:	2	
Construction of roof:		Other		Construction of floors:	Poured Concrete	
Construction of exteri	or walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior mas	onry walls (fire walls) ex	tend above the roofline?		N		
Occupancy:						
Occupancy Type:			Laboratory			
Provide a brief descrip	otion of operations:		Research fac	cility that contains offices & classrooms/conference rooms		
Storage height of ware	ehoused products:		0			
Are flammable and co	mbustible liquids stored	I in a cut-off room?	N/A			
Safegaurds taken for t	he storage and dispens	ing of flammable liquids:	Υ			
Protection:						
Are there any automat	ic sprinklers?	N	Wha	at are the design densities for each area?	no spsrinklers	
The water supply for a	utomatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	? 1	
Indicate the Alarm Co	verages provided for yo	ur facility:	Smo	ske Detectors		
Are alarms connected	to a constantly attende	d location?	Υ			
ls there a watchman s	ervice?	Υ	Wha	at is the frequency of rounds?		
Are watchman recordi	ng rounds?		N			
Are there any fire exti	nguishers?	Υ	Are	they serviced annually?	Υ	
Are there any hose sta	ations?	N	Is th	ere a fire private fire brigade?	N	
Frequency of training	received by the private	fire brigade:				
Type of public fire dep	partment:	Voluntary	Dist	ance:	on-site	
Exposure:						

0

Description:

Description:

Description:

### How many buildings(not part of Account) are within 100 feet of insured buildings?

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

			Proper	ty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTAN	A - MISSOULA			
Property:	Emma B. Lommasson Cen	ter					
Property Address:	625 University Avenue MIS	SSOULA					
Property ID:	90						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	104533		
Year built:		1955		Number of stories:	2		
Construction of roof:		Poured Concrete		Construction of floors:	Poured Conc	crete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Boar	ırd	
Do major interior masoni	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State Univers	sity			
Provide a brief description	on of operations:		Staff/Medical	offices			
Storage height of wareho	oused products:		0				
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ	Wha	at are the design densities for each area?		0.1	
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings	.?	0	
Indicate the Alarm Cover	ages provided for your fac	ility:	Burg	glar Alarms (Door Contacts), Smoke Detectors, Sprinkler Va	lve Tamper, Spi	rinkler Waterflow	
Are alarms connected to	a constantly attended loca	ation?	Υ				
ls there a watchman serv	ice?	Υ	Wha	at is the frequency of rounds?		Campus police 24/7	
Are watchman recording	rounds?		Υ				
Are there any fire extingu	uishers?	Υ	Are	they serviced annually?		Υ	
Are there any hose static	ons?	N	Is th	ere a fire private fire brigade?		N	
Frequency of training red	eived by the private fire b	rigade:					
Type of public fire depart	ment:	Paid	Dist	ance:		under 1 mile	
Exposure:							
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water r	nearby?	null	Description:	:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Description:	:			
Any property damage los	sses in the past 3 years:	N	Description:	:			

							Page 29
			Pı	roperty Detail Form			
gency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA	TECH OF	THE UM			
Property:	Engineering Hall-H						
roperty Address:	1300 W. Park Street BUTT	ΓE					
roperty ID:	102						
Construction:							
otal number of insured	l buildings:	1		Total square footage of insured buildings:	13727		
ear built:		1923		Number of stories:	2		
Construction of roof:		Other		Construction of floors:	null		
Construction of exterior	walls:	Other		Construction of interior walls:	null		
o major interior mason	nry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State L	Jniversity			
Provide a brief descripti	on of operations:		Classro	ooms and labs			
Storage height of wareh	oused products:		N/A				
are flammable and com	bustible liquids stored in a	cut-off room?	N				
afegaurds taken for the	e storage and dispensing o	f flammable liquids:	Υ				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?			
he water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of building	s?	7	
ndicate the Alarm Cove	rages provided for your fac	cility:		Smoke Detectors			
are alarms connected to	o a constantly attended loc	ation?		Υ			
s there a watchman ser	vice?	Υ		What is the frequency of rounds?		2 per shift	
are watchman recording	g rounds?			Υ			
are there any fire exting	juishers?	Υ		Are they serviced annually?		null	
are there any hose stati	ons?	N		Is there a fire private fire brigade?		N	
requency of training re	eceived by the private fire b	rigade:					
ype of public fire depar	rtment:	Paid		Distance:		0.86	
vnosura:							

How many buildings(not part of Account) are within 100 feet of insured buildings? 0 Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Description:

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

						1 age 2
			Prop	erty Detail Form		
agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MONT	ANA TECH OF TH	E UM		
Property:	Engineering Laboratory-Cl	assroom Building				
roperty Address:	1300 W. Park Street BUT7	E				
Property ID:	116					
Construction:						
otal number of insured	buildings:	1		Total square footage of insured buildings:	57895	
ear built:		1984		Number of stories:	3	
Construction of roof:		Steel Deck		Construction of floors:	Other	
construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
o major interior masoni	ry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			State Univ	rersity		
Provide a brief description	on of operations:		Offices, cla	assrooms, labs		
Storage height of wareho	oused products:		N/A			
are flammable and comb	oustible liquids stored in a	cut-off room?	N			
afegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ			
Protection:						
are there any automatic	sprinklers?	Υ	W	hat are the design densities for each area?	114 psi	static 106 residl
he water supply for auto	omatic sprinklers is?	Private	н	ow many hydrants are located within 500 feet of building	<b>gs?</b> 5	
ndicate the Alarm Cover	ages provided for your fac	cility:	S	moke Detectors, Fire Pump Alarms, Sprinkler Valve Tamper	, Sprinkler Waterflow	
are alarms connected to	a constantly attended loc	ation?	Υ			
s there a watchman serv	rice?	Υ	W	hat is the frequency of rounds?	2 per sl	hift
are watchman recording	rounds?		Υ			
are there any fire extingu	uishers?	Υ	Α	re they serviced annually?	Υ	
are there any hose static	ons?	N	Is	there a fire private fire brigade?	N	
requency of training rec	ceived by the private fire b	rigade:				
ype of public fire depart	tment:	Paid	D	istance:	0.86 mi	iles
ynosure.						

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Description: Ν

How far is the body of water from major buildings?

Previous history of flooding? Description: Ν Any property damage losses in the past 3 years: N

							Page 29
			Pr	operty Detail Form			
gency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MISSOULA			
Property:	Equipment Storage						
Property Address:	2381 Woodworth Rd. OVA	NDO					
Property ID:	662						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings: 2	413		
ear built:		blank		Number of stories:			
Construction of roof:		null		Construction of floors:	ull		
Construction of exterior	walls:	null		Construction of interior walls:	ull		
o major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Storage				
Provide a brief descripti	on of operations:		blank				
Storage height of wareh	oused products:		0				
are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
afegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?			
he water supply for aut	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		blank	
ndicate the Alarm Cove	rages provided for your fac	ility:					
are alarms connected to	a constantly attended loca	ation?		null			
s there a watchman ser	vice?	null		What is the frequency of rounds?			
are watchman recording	g rounds?						
are there any fire exting	uishers?	null		Are they serviced annually?		null	
are there any hose stati	ons?	null		Is there a fire private fire brigade?		null	
requency of training re	ceived by the private fire b	rigade:					
ype of public fire depar	rtment:	null		Distance:		blank	
xposure:							
low many buildings(not	t part of Account) are within	n 100 feet of insured buildings?	blank				

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

null

null

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

			Property	/ Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVERS	ITY - BOZEMAN			
Property:	FACILITIES MECHANIC/M	IETAL SHOP					
Property Address:	West Grant Street (no offic	ial address) BOZEMAN					
Property ID:	314						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	6715		
Year built:		1952		Number of stories:	1		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Boar	rd	
Do major interior masoni	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Garage, Service	ce Center			
Provide a brief description	on of operations:		Garage, auto r	epair			
Storage height of wareho	oused products:		N/A				
Are flammable and comb	ustible liquids stored in a	cut-off room?	N				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ				
Protection:							
Are there any automatic	sprinklers?	N	What	are the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?		How r	nany hydrants are located within 500 feet of buildings	?	2	
Indicate the Alarm Cover	ages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	ation?	null				
ls there a watchman serv	ice?	N	What	is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire extingu	iishers?	Υ	Are th	ey serviced annually?		Υ	
Are there any hose statio	ons?	N	Is the	re a fire private fire brigade?		N	
Frequency of training red	eived by the private fire b	rigade:					
Type of public fire depart	ment:	Paid	Distar	nce:		1.5 miles	
Exposure:							
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water r	nearby?	N	Description:				
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Description:				
Any property damage los	sses in the past 3 years:	N	Description:				

						Page		
			Property D	Detail Form				
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STA			Y - NORTHERN				
Property:	Faculty Housing							
Property Address:	MSU-Northern 1129 Bonin	e Drive HAVRE						
Property ID:	25	25						
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	2437			
Year built:		1957		Number of stories:	2			
Construction of roof:		Other		Construction of floors:	Wood Timber			
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board			
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Other					
Provide a brief description	on of operations:		residential					
Storage height of wareho	oused products:		n/a					
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N	What are	e the design densities for each area?				
The water supply for aut	omatic sprinklers is?		How ma	ny hydrants are located within 500 feet of buildings?	2			

Indicate the Alarm Coverages provided for your facility:		Smoke Detectors		
Are alarms connected to a constantly attended location	?	N		
Is there a watchman service?	Υ	What is the frequency of rounds?	every 24 hours	
Are watchman recording rounds?		Υ		
Are there any fire extinguishers?	Υ	Are they serviced annually?	Υ	
Are there any hose stations?	N	Is there a fire private fire brigade?	N	
Frequency of training received by the private fire brigad	le:			
Type of public fire department:	Paid	Distance:	1 mile	

### **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings?	blank
Describe the Occupancy of those buildings(s) nearby (within 100 feet):	

Is there a body of water nearby? Ν

Description:

How far is the body of water from major buildings?

Previous history of flooding? Ν Any property damage losses in the past 3 years: N Description:

					i age	, 50
			Prope	erty Detail Form		
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSITY	OF MONTAN	NA - WESTERN		
Property:	Family Housing					
Property Address:	710 S. Atlantic DILLON					
Property ID:	14					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	19960	
Year built:		1958		Number of stories:	3	
Construction of roof:		Concrete Panels		Construction of floors:	Reinforced Concrete	
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Masonry w/ Openings	
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Res Apt Co	mplex		
Provide a brief descrip	tion of operations:		Family Resi	idence		
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?			N/A			
Safegaurds taken for the storage and dispensing of flammable liquids:  N/A						
Protection:						
Are there any automat	ic sprinklers?	N	Wh	nat are the design densities for each area?		
The water supply for a	utomatic sprinklers is?		Ho	w many hydrants are located within 500 feet of buildings?	? 4	
Indicate the Alarm Cov	erages provided for your fac	cility:	Sm	noke Detectors		
Are alarms connected	to a constantly attended loc	ation?	Υ			
Is there a watchman se	ervice?	Υ	Wh	nat is the frequency of rounds?	Hourly	
Are watchman recording	ng rounds?		Υ			
Are there any fire extin	guishers?	Υ	Are	e they serviced annually?	Υ	
Are there any hose sta	tions?	N	ls t	there a fire private fire brigade?	N	
Frequency of training	received by the private fire b	rigade:				
Type of public fire dep	artment:	Voluntary	Dis	stance:	>1 mile	
Exposure:						
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	blank			
Describe the Occupan	cy of those buildings(s) near	rby (within 100 feet):				
Is there a body of water	r nearby?	Υ	Description	n:	Beaverhead River	
How far is the body of	water from major buildings?	•	<1 mile			
Previous history of flo	oding?	N	Description	n:		
Any property damage	osses in the past 3 years:	N	Description	n:		

					1.3-			
			Proper	y Detail Form				
Agency:	UNIVERSITY SYSTEM / UN	IVERSITY SYSTEM, MONTANA T	ECH OF THE U	JM				
Property:	Family Student Housing - Le	amily Student Housing - Lexington Apartments						
Property Address:	1001 - 1039 Lexington Ave E	BUTTE						
Property ID:	401							
Construction:								
Total number of insured	buildings:	I		Total square footage of insured buildings:	20309			
Year built:	1	1950		Number of stories:	2			
Construction of roof:	(	Other		Construction of floors:	Other			
Construction of exterior	walls:	Other		Construction of interior walls:	Gypsum Board			
Do major interior masonr	y walls (fire walls) extend al	pove the roofline?		null				
Occupancy:								
Occupancy Type:			Res Apt Com	plex				
Provide a brief description of operations:			Family studer	nt housing				
Storage height of warehoused products:			N/A	N/A				
Are flammable and combustible liquids stored in a cut-off room? N/A			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic s	sprinklers?	Υ	Wha	are the design densities for each area?	61 psi static 45 psi resd			
The water supply for auto	omatic sprinklers is?	Private	How	many hydrants are located within 500 feet of buildings	? 2			
Indicate the Alarm Covers	ages provided for your facili	ity:	Sprin	kler Valve Tamper, Smoke Detectors, Fire Pump Alarms, S	prinkler Waterflow			
Are alarms connected to	a constantly attended locati	on?	Υ					
Is there a watchman serv	ice?	N	Wha	is the frequency of rounds?				
Are watchman recording	rounds?							
Are there any fire extingu	iishers?	Υ	Are t	hey serviced annually?	Υ			
Are there any hose statio	ons?	N	Is the	ere a fire private fire brigade?	N			
Frequency of training red	eived by the private fire brig	gade:						
Type of public fire depart	ment:	Paid	Dista	nce:	1.28 miles			
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearby	y (within 100 feet):						

Description:

Description:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Ν

							Page 30
			Pro	perty Detail Form			
gency:	UNIVERSITY SYSTEM / UN	IIVERSITY SYSTEM, MONTANA	TECH OF T	HE UM			
Property:	Family Student Housing - Mi	ssoula Apartments North					
Property Address:	1001 - 1039 Missoula Ave B	UTTE					
Property ID:	403						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	20309		
ear built:		1950		Number of stories:	2		
Construction of roof:		Other		Construction of floors:	Other		
construction of exterior	walls:	Other		Construction of interior walls:	Gypsum Board		
o major interior mason	ry walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			Res Apt	Complex			
Provide a brief description	on of operations:		Family st	tudent housing			
Storage height of wareho	oused products:		N/A				
are flammable and comb	oustible liquids stored in a c	ut-off room?	N/A				
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
are there any automatic	sprinklers?	Υ	,	What are the design densities for each area?	6	0 psi static 59 psi resd	
he water supply for aut	omatic sprinklers is?	Private	ı	How many hydrants are located within 500 feet of buildings	? 2	!	
ndicate the Alarm Cover	rages provided for your facil	ity:	ı	Fire Pump Alarms, Smoke Detectors, Sprinkler Valve Tamper, S	Sprinkler Waterflow		
are alarms connected to	a constantly attended locat	ion?	•	Y			
s there a watchman serv	vice?	N	,	What is the frequency of rounds?			
are watchman recording	rounds?						
are there any fire exting	uishers?	Υ		Are they serviced annually?	Y	,	
are there any hose station	ons?	N	ı	Is there a fire private fire brigade?	Ν	I	
requency of training re	ceived by the private fire bri	gade:					
ype of public fire depar	tment:	Paid	ı	Distance:	1	.28 miles	
xposure:							

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding? Any property damage losses in the past 3 years: N

Description: Ν

Description:

					i age s
			Pr	operty Detail Form	
gency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, MONTANA	TECH OF	THE UM	
Property:	Family Student Housing - M	lissoula Apartments South			
Property Address:	1000 - 1038 Missoula Ave E	BUTTE			
Property ID:	402				
Construction:					
otal number of insured	buildings:	1		Total square footage of insured buildings:	20309
ear built:		1950		Number of stories:	2
Construction of roof:		Other		Construction of floors:	Other
Construction of exterior	walls:	Other		Construction of interior walls:	Gypsum Board
o major interior masonr	ry walls (fire walls) extend a	above the roofline?		null	
Occupancy:					
Occupancy Type:			Res Ap	t Complex	
Provide a brief description of operations:			Family	student housing	
storage height of wareho	oused products:		N/A		
are flammable and comb	oustible liquids stored in a c	cut-off room?	N/A		
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A		
Protection:					
are there any automatic	sprinklers?	Υ		What are the design densities for each area?	60 psi static 59 psi resd
he water supply for auto	omatic sprinklers is?	Private		How many hydrants are located within 500 feet of buildings?	? 2
ndicate the Alarm Cover	ages provided for your faci	lity:		Fire Pump Alarms, Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Valve Tam	prinkler Waterflow
are alarms connected to	a constantly attended loca	tion?		null	
s there a watchman serv	rice?	N		What is the frequency of rounds?	
are watchman recording	rounds?				
are there any fire extingu	uishers?	Υ		Are they serviced annually?	Υ
are there any hose statio	ons?	N		Is there a fire private fire brigade?	N
requency of training rec	ceived by the private fire br	igade:			
ype of public fire depart	tment:	Paid		Distance:	1.28 miles
exposure:					
low many buildings(not	part of Account) are within	100 feet of insured buildings?	0		

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

			Pro	perty D	etail Form			
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - NORTHERN							
Property:	Farm Mechanics							
Property Address:	MSU-Northern -200 College Road West HAVRE							
Property ID:	4							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	12290		
Year built:		1984			Number of stories:	1		
Construction of roof:		Other			Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Other			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Laborato	ory				
Provide a brief description	on of operations:		labs no d	classroom	ns/office			
Storage height of warehoused products:			n/a					
Are flammable and combustible liquids stored in a cut-off room?			N					
afegaurds taken for the storage and dispensing of flammable liquids:								
Protection:								
Are there any automatic	sprinklers?	N	,	What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?		How many hydrants are located within 500 feet of buildings?					
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors					
Are alarms connected to	a constantly attended loca	ation?		N				
ls there a watchman serv	rice?	Υ	,	What is t	the frequency of rounds?		every 24 hours	
Are watchman recording	rounds?			Υ				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N		Is there a	a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid		Distance	e:		1 mile	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Descript	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descript	tion:				
Any property damage los	sses in the past 3 years:	N	Descript	tion:				

							Page 30	
			Pr	operty Detail Form				
Agency:	UNIVERSITY SYSTEM / L	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA						
Property:	Field Research Station T-	Field Research Station T-142						
Property Address:	Fort Missoula Road MISSOULA							
Property ID:	402							
Construction:								
Total number of insured	d buildings:	1		Total square footage of insured buildings:	13497			
Year built:		1920		Number of stories:	2			
Construction of roof:		Other		Construction of floors:	Poured Concrete	е		
Construction of exterio	r walls:	Other		Construction of interior walls:	Gypsum Board			
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			State U	niversity				
Provide a brief description of operations:			Higher	education field research lab-main studies are on birds & flight				
Storage height of warel	noused products:		0					
Are flammable and com	bustible liquids stored in a	cut-off room?	N					
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N		What are the design densities for each area?	r	no sprinklers		
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	s? 0	)		
Indicate the Alarm Cove	erages provided for your fa	cility:		Smoke Detectors				
Are alarms connected t	o a constantly attended loc	ation?		N				
Is there a watchman se	rvice?	Υ		What is the frequency of rounds?	С	campus police 24/7		
Are watchman recording	g rounds?			Υ				
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	Y		
Are there any hose stat	ions?	N		Is there a fire private fire brigade?	1	N		
Frequency of training re	eceived by the private fire b	rigade:						
Type of public fire depart	rtment:	Paid		Distance:	ι	under 1 mile		

**Exposure:** 

How many buildings(not part of Account) are within 100 feet of insured buildings? Describe the Occupancy of those buildings(s) nearby (within 100 feet):

0

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Description: Ν

Any property damage losses in the past 3 years: N

Description:

			Pr	operty D	etail Form		
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA						
Property:	Fine Arts (includes 10/97 remodel)						
Property Address:	715 Connell Avenue MISSOULA						
Property ID:	011						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	72069	
Year built:		1935			Number of stories:	4	
Construction of roof:		Poured Concrete			Construction of floors:	Poured Concr	ete
Construction of exterior v	valls:	Masonry			Construction of interior walls:	Other	
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			Υ		
Occupancy:							
Occupancy Type:			State U	niversity			
Provide a brief descriptio	n of operations:		OFFICE	S/CLASS	ROOMS		
Storage height of warehoused products:			N/A				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the storage and dispensing of flammable liquids: N/A							
Protection:							
Are there any automatic s	sprinklers?	Υ		What are	the design densities for each area?		0.15
The water supply for auto	matic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?		blank
Indicate the Alarm Covera	ages provided for your faci	ility:		Smoke D	etectors, Sprinkler Waterflow, Sprinkler Valve Tamper		
Are alarms connected to	a constantly attended loca	tion?		Υ			
Is there a watchman servi	ice?	Υ		What is t	he frequency of rounds?		CAMPUS POLICE/24-7
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose station	ns?	N		Is there a	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	igade:					
Type of public fire depart	ment:	Paid		Distance	:		blank
Exposure:							
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):					
Is there a body of water n	earby?	null	Descrip	tion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descrip	tion:			
Any property damage los	ses in the past 3 years:	N	Descrip	tion:			

								- 9
			Prop	perty De	etail Form			
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA S	STATE UNIV	/ERSITY	- NORTHERN			
Property:	Food Service							
Property Address:	MSU-Northern- 1150-B SUB Drive HAVRE							
Property ID:	33							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	21515		
Year built:		1971			Number of stories:	1		
Construction of roof:		Other			Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Gypsum Boar	d	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			State Univ	versity				
Provide a brief description	on of operations:		meals for	students				
Storage height of wareho	oused products:		n/a					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic	sprinklers?	N	W	Vhat are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?		How many hydrants are located within 500 feet of buildings?					
Indicate the Alarm Cover	ages provided for your fac	ility:	S	Smoke De	etectors			
Are alarms connected to	a constantly attended loca	ation?	N	1				
Is there a watchman serv	rice?	Υ	W	Vhat is th	ne frequency of rounds?		every 24 hours	
Are watchman recording	rounds?		Υ	′				
Are there any fire extingu	uishers?	Υ	Α	re they s	serviced annually?		Υ	
Are there any hose static	ons?	N	Is	s there a	fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depart	tment:	Paid	D	Distance:			1 mile	
Exposure:								
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Description	on:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Description	on:				
Any property damage los	sses in the past 3 years:	N	Description	on:				

	Property Detail Fo
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOUL
Property:	Forestry

**Property Address:** 1310 Madeline Avenue MISSOULA

Property ID: 007

Construction:

Total number of insured buildings: 1 Total square footage of insured buildings: 22912

Year built: 1921 Number of stories:

**Poured Concrete** Construction of roof: Wood Joists Construction of floors:

Construction of exterior walls: Masonry Construction of interior walls: Other

Occupancy:

Protection:

**Occupancy Type:** State University

Provide a brief description of operations: Offices, classrooms

Storage height of warehoused products:

Do major interior masonry walls (fire walls) extend above the roofline?

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids:

Are there any automatic sprinklers?

Ν What are the design densities for each area? no sprinklers

The water supply for automatic sprinklers is? How many hydrants are located within 500 feet of buildings?

0

Indicate the Alarm Coverages provided for your facility: **Smoke Detectors** 

Are alarms connected to a constantly attended location?

Is there a watchman service? Υ What is the frequency of rounds? Campus police 24/7

Are watchman recording rounds?

Are there any fire extinguishers? Are they serviced annually?

Are there any hose stations? Ν Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: uncer 1 mile

Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Ν Description: Any property damage losses in the past 3 years: Description:

							Page 3
			F	Property Detail Form			
gency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSIT	TY OF MO	NTANA - MISSOULA			
roperty:	Fresh Water Research Lab						
roperty Address:	32125 Bio Station Lane PO	LSON					
roperty ID:	570						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	5074		
ear built:		1981		Number of stories:	1		
construction of roof:		null		Construction of floors:	null		
construction of exterior	walls:	null		Construction of interior walls:	null		
o major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
ccupancy Type:			Labora	atory			
rovide a brief descripti	on of operations:		null				
torage height of wareh	oused products:		null				
re flammable and com	bustible liquids stored in a	cut-off room?	null				
afegaurds taken for the	e storage and dispensing of	flammable liquids:	null				
Protection:							
re there any automatic	sprinklers?	N		What are the design densities for each area?		null	
he water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	!	null	
ndicate the Alarm Cove	rages provided for your fac	ility:					
re alarms connected to	a constantly attended loca	ition?		null			
s there a watchman serv	vice?	null		What is the frequency of rounds?	!	null	
re watchman recording	g rounds?						
are there any fire exting	uishers?	null		Are they serviced annually?	1	null	
are there any hose station	ons?	null		Is there a fire private fire brigade?	1	null	
requency of training re	ceived by the private fire br	igade:		null			
ype of public fire depar	rtment:	null		Distance:	J	null	
xposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?					
escribe the Occupancy	of those buildings(s) near	hy (within 100 feet):	null				

null

Description: null

Is there a body of water nearby?

How far is the body of water from major buildings?

Previous history of flooding? null Description: null

Any property damage losses in the past 3 years: null Description: null

null

					Page	3
			Pr	operty Detail Form		
gency:	UNIVERSITY SYSTEM	/ UNIVERSITY SYSTEM, MONT	ANA STATE UN	NIVERSITY - BOZEMAN		
Property:	GAINES HALL					
Property Address:	Grant Street (no official	address) BOZEMAN				
Property ID:	117					
Construction:						
otal number of insure	d buildings:	1		Total square footage of insured buildings:	98960	
ear built:		1961		Number of stories:	5	
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Concrete	
construction of exterio	or walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
o major interior maso	onry walls (fire walls) exter	nd above the roofline?		N		
Occupancy:						
Occupancy Type:			State U	Iniversity		
Provide a brief descrip	tion of operations:		Classro	ooms, labs		
storage height of ware	housed products:		0			
are flammable and cor	nbustible liquids stored in	a cut-off room?	N			
afegaurds taken for tl	ne storage and dispensing	of flammable liquids:	Υ			
Protection:						
re there any automati	c sprinklers?	Υ		What are the design densities for each area?	140' sq /sprinkler	
he water supply for a	utomatic sprinklers is?	Public		How many hydrants are located within 500 feet of building	ngs? 4	
ndicate the Alarm Cov	erages provided for your	acility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterfle	ow	
are alarms connected	to a constantly attended lo	ocation?		Υ		
s there a watchman se	ervice?	N		What is the frequency of rounds?		
re watchman recordir	ng rounds?					
are there any fire extin	guishers?	Υ		Are they serviced annually?	Υ	
are there any hose sta	tions?	N		Is there a fire private fire brigade?	N	
requency of training r	eceived by the private fire	brigade:				
ype of public fire dep	artment:	Paid		Distance:	1.21 miles	

# **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Ν Any property damage losses in the past 3 years: N Description:

Description:

			Propert	y Detail Form					
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, UNIVERSITY	OF MONTANA	- MISSOULA					
Property:	Gallagher Building								
Property Address:	925 Maurice Avenue MISSO	OULA							
Property ID:	89								
Construction:									
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	125645				
Year built:		1996		Number of stories:	3				
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concre	ete			
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Gypsum Board	d			
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N					
Occupancy:									
Occupancy Type:			State Universi	ty					
Provide a brief descriptio	n of operations:		Offices/classrooms						
Storage height of wareho	used products:		0	)					
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic s	sprinklers?	Υ	What	are the design densities for each area?		0.1			
The water supply for auto	matic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?		2			
Indicate the Alarm Covera	ages provided for your faci	ility:	Smoke Detectors, Sprinkler Waterflow, Sprinkler Valve Tamper						
Are alarms connected to	a constantly attended loca	tion?	Υ						
Is there a watchman servi	ice?	Υ	What	is the frequency of rounds?		Campus police 24/7			
Are watchman recording	rounds?		Υ						
Are there any fire extingu	ishers?	Υ	Are ti	hey serviced annually?		Υ			
Are there any hose station	ns?	N	Is the	ere a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid	Dista	nce:		under 1 mile			
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) neark	by (within 100 feet):							
Is there a body of water n	earby?	N	Description:						
How far is the body of wa	ter from major buildings?								
Previous history of floodi	ng?	N	Description:						
Any property damage los	ses in the past 3 years:	N	Description:						

					Page 3
			P	roperty Detail Form	
gency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, UNIV	ERSITY OF MOI	NTANA - MISSOULA	
roperty:	Geology Lab T-156 (cellb	lock West)			
roperty Address:	Fort Missoula Rd. MISSO	ULA			
roperty ID:	400				
construction:					
otal number of insure	d buildings:	1		Total square footage of insured buildings:	12731
ear built:		1943		Number of stories:	1
onstruction of roof:		null		Construction of floors:	null
Construction of exterio	r walls:	null		Construction of interior walls:	null
o major interior maso	nry walls (fire walls) extend	l above the roofline?		null	
Occupancy:					
Occupancy Type:			Labora	tory	
Provide a brief descript	tion of operations:		null		
torage height of warel	noused products:		null		
are flammable and con	nbustible liquids stored in a	a cut-off room?	null		
afegaurds taken for th	ne storage and dispensing	of flammable liquids:	null		
Protection:					
re there any automati	c sprinklers?	N		What are the design densities for each area?	null
he water supply for au	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	null
ndicate the Alarm Cov	erages provided for your fa	cility:			
re alarms connected t	o a constantly attended loo	cation?		null	
s there a watchman se	rvice?	null		What is the frequency of rounds?	null
re watchman recordin	g rounds?				
re there any fire extin	guishers?	null		Are they serviced annually?	null
are there any hose stat	ions?	null		Is there a fire private fire brigade?	null
requency of training r	eceived by the private fire l	origade:		null	
ype of public fire depart	artment:	null		Distance:	null
xposure:					
low many buildings(no	ot part of Account) are with	in 100 feet of insured buildir	ngs?		

Describe the Occupancy of those buildings(s) nearby (within 100 feet): null

Description:

Is there a body of water nearby? null

How far is the body of water from major buildings?

null

Previous history of flooding?

Any property damage losses in the past 3 years:

null

Description:

Description:

null null

null

under 1 mile

						Page 3
			Р	Property Detail Form		
Agency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, UNIVERSIT	TY OF MOI	NTANA - MISSOULA		
Property:	Geology Rock Storage Bl	dg. (T-312)				
Property Address:	Fort Missoula, off of Post	Siding Road MISSOULA				
Property ID:	410					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	29032	
Year built:		blank		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterio	r walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior maso	onstruction of roof:  Wood Joists  Wood Frame  major interior masonry walls (fire walls) extend above the roofline?  Coupancy:  Coupancy Type:			N		
Occupancy:						
Occupancy Type:			Storage	ge		
		Higher	r ed storage location for geological rock & other samples			
Storage height of warel	housed products:		0			
Are flammable and con	nbustible liquids stored in a	a cut-off room?	N/A			
Safegaurds taken for th	ne storage and dispensing	of flammable liquids:	N/A			
Protection:						
Are there any automatic	c sprinklers?	N		What are the design densities for each area?	no sprinklers	
The water supply for au	utomatic sprinklers is?			How many hydrants are located within 500 feet of building	<b>gs?</b> 0	
Indicate the Alarm Cov	erages provided for your fa	cility:		Smoke Detectors		
Are alarms connected t	to a constantly attended lo	cation?		N		
Is there a watchman se	rvice?	Υ		What is the frequency of rounds?		
Are watchman recording	ng rounds?			Υ		
Are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stat	tions?	N		Is there a fire private fire brigade?	N	

Distance:

0

Description:

Description:

Description:

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Paid

Ν

Ν

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

**Exposure:** 

A	LINIVERGITY OVOTEM (LI	NIIVEDOITY OVOTEM LINIVEDOITY			etail Form			
Agency:		NIVERSITY SYSTEM, UNIVERSITY	OF MON	IANA - M	ISSOULA			
Property:	Gilkey Business Center							
Property Address:	950 Arthur Ave., Missoula,	MT MISSOULA						
Property ID:	041							
Construction:								
Total number of insured l	buildings:	1			Total square footage of insured buildings:	30836		
Year built:		2015			Number of stories:	2		
Construction of roof:		Steel Deck			Construction of floors:	Poured Concr	rete	
Construction of exterior v	walls:	Masonry w/ Openings			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			State Ur	niversity				
Provide a brief description	on of operations:		blank					
Storage height of warehoused products:		blank						
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?	Public		How man	ny hydrants are located within 500 feet of buildings?	•	blank	
Indicate the Alarm Cover	ages provided for your fac	ility:	Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ition?		Υ				
ls there a watchman serv	ice?	null		What is t	he frequency of rounds?			
Are watchman recording	rounds?							
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	null		Is there a	a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid		Distance	:		blank	
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	nearby?	N	Descrip	tion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	tion:				
Any property damage los	ses in the past 3 years:	N	Descrip	tion:				

06 mech malf

							Page .
			Pro	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNI	IVERSITY - NORTHERN			•
Property:	Gymnasium						
Property Address:	MSU-Northern 100 Colleg	e Road West HAVRE					
Property ID:	11						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	57373		
fear built:		1957		Number of stories:	2		
Construction of roof:		Other		Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Other		Construction of interior walls:	Masonry		
Oo major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State Ur	niversity			
Provide a brief description of operations:			gym/clas	sses/pool/weight rm			
Storage height of warehoused products:			n/a				
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	?	2	
ndicate the Alarm Cove	rages provided for your fa	cility:		Smoke Detectors			
Are alarms connected to	a constantly attended loc	ation?		N			
s there a watchman ser	vice?	Υ		What is the frequency of rounds?		every 24 hours	
Are watchman recording	g rounds?			Υ			
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:					
Type of public fire depart	rtment:	Paid		Distance:		1 mile	
Exposure:							
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):					
s there a body of water	nearby?	Υ	Descrip	otion:	swim pool		
low far is the body of w	ater from major buildings?	•	in buildir	nα			

Description:

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: Y

Ν

								- 3	
			Pr	operty D	etail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UN	NIVERSITY	′ - NORTHERN				
Property:	Hagener Science Center-M	lath Science Building							
Property Address:	MSU-Northern - 300 Cowa	n Drive HAVRE							
Property ID:	29								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	41453			
Year built:		1968			Number of stories:	2			
Construction of roof:		Poured Concrete			Construction of floors:	Poured Conci	rete		
Construction of exterior	walls:	Reinforced Concrete			Construction of interior walls:	Masonry			
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			Laborat	tory					
Provide a brief description of operations:			classes	classes/dist learn					
Storage height of warehoused products:			n/a	ı/a					
Are flammable and combustible liquids stored in a cut-off room?			N						
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N						
Protection:									
Are there any automatic	sprinklers?	N		What are	the design densities for each area?		n/a		
The water supply for auto	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?	,	1		
ndicate the Alarm Cover	ages provided for your fac	ility:	Smoke Detectors						
Are alarms connected to	a constantly attended loca	ition?		N					
s there a watchman serv	rice?	Υ		What is t	the frequency of rounds?		every 24 hours		
Are watchman recording	rounds?			Υ					
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N		
requency of training rec	ceived by the private fire b	igade:							
Гуре of public fire depart	tment:	Paid		Distance	:		1 mile		
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
s there a body of water r	nearby?	N	Descri	ption:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Descri	ption:					
Any property damage los	sses in the past 3 years:	N	Descri	ption:					

Dranart	/ Detail Form
riopeil	, Detail Follii

			Property i	Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVERSIT	Y - BOZEMAN				
Property:	HAMILTON HALL							
Property Address:	South 7th Avenue (no offic	ial address) BOZEMAN						
Property ID:	301							
Construction:								
Total number of insure	d buildings:	1		Total square footage of insured buildings:	28680			
Year built:		1910		Number of stories:	4			
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber			
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board			
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Office					
Provide a brief descrip	tion of operations:		OFFICES/CLAS	SROOMS				
Storage height of ware	housed products:		N/A	N/A				
Are flammable and con	nbustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for th	ne storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automati	c sprinklers?	Υ	What ar	e the design densities for each area?				
The water supply for au	utomatic sprinklers is?		How ma	nny hydrants are located within 500 feet of buildings?		4		
Indicate the Alarm Cov	erages provided for your fac	ility:						
Are alarms connected t	to a constantly attended loca	ation?	N					
Is there a watchman se	rvice?	Υ	What is	the frequency of rounds?		AVERAGE 4 PER NIGHT		
Are watchman recordir	ng rounds?		N					
Are there any fire extin	guishers?	Υ	Are the	y serviced annually?		Υ		
Are there any hose stat	tions?	N	Is there	a fire private fire brigade?		N		
Frequency of training r	eceived by the private fire b	rigade:						
Type of public fire depart	artment:	Paid	Distanc	e:		1.06 MILES		
Exposure:								
How many buildings(no	ot part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupano	cy of those buildings(s) near	by (within 100 feet):						
Is there a body of water	r nearby?	N	Description:					
How far is the body of	water from major buildings?							
Previous history of floo	oding?	N	Description:					
Any property damage l	osses in the past 3 years:	Υ	Description:		4/20/01 WATEI SPRINKLER LI	R DAMAGE FROM FROZEN NE		

							- 3			
			Property	y Detail Form						
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, MONTANA S	TATE UNIVERS	SITY - BOZEMAN						
Property:	HANNON RESIDENCE HA	ALL								
Property Address:	South 7th Avenue (no office	ial address) BOZEMAN								
Property ID:	331									
Construction:										
Total number of insured	buildings:	1		Total square footage of insured buildings:	90240					
Year built:		1955		Number of stories:	3					
Construction of roof:		Poured Concrete		Construction of floors:	Poured Conc	rete				
Construction of exterior	walls:	Tilt-Up Concrete		Construction of interior walls:	Masonry					
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N						
Occupancy:										
Occupancy Type:			Res Apt Comp	olex						
Provide a brief description of operations:			STUDENT DO	STUDENT DORMS						
Storage height of warehoused products:			N/A							
Are flammable and combustible liquids stored in a cut-off room?		N/A								
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A							
Protection:										
Are there any automatic	sprinklers?	Υ	What	are the design densities for each area?		PER NFPA 13				
The water supply for aut	omatic sprinklers is?	Public	How i	many hydrants are located within 500 feet of buildings	?	5				
Indicate the Alarm Cove	rages provided for your fac	cility:	Smok	e Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow						
Are alarms connected to	a constantly attended loc	ation?	Υ							
ls there a watchman serv	vice?	Υ	What	is the frequency of rounds?		3-4 TIMES PER NIGHT				
Are watchman recording	rounds?		Υ							
Are there any fire exting	uishers?	Υ	Are th	ney serviced annually?		Υ				
Are there any hose station	ons?	N	Is the	re a fire private fire brigade?		N				
Frequency of training re	ceived by the private fire b	rigade:								
Type of public fire depar	tment:	Paid	Dista	nce:		1.15 MILES				
Exposure:										
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0							
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):								
Is there a body of water	nearby?	N	Description:							
How far is the body of w	ater from major buildings?									
Previous history of flood	ling?	N	Description:							
Any property damage lo	sses in the past 3 years:	N	Description:							

							Page 32		
			Proper	ty Detail Form					
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIVER	SITY - BOZEMAN					
Property:	HAPNER RESIDENCE HA	ALL							
Property Address:	West Cleveland (no officia	l address) BOZEMAN							
Property ID:	336								
Construction:									
Total number of insure	d buildings:	1		Total square footage of insured buildings:	94985				
Year built:		1959		Number of stories:	4				
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concre	rete			
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Masonry				
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N					
Occupancy:									
Occupancy Type:			Res Apt Com	Res Apt Complex					
Provide a brief description of operations:			STUDENT D	STUDENT DORMS/BAKERY					
Storage height of warehoused products:		N/A							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for th	ne storage and dispensing o	f flammable liquids:	N/A						
Protection:									
Are there any automati	c sprinklers?	Υ	Wha	t are the design densities for each area?					
The water supply for a	utomatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	?	5			
Indicate the Alarm Cov	erages provided for your fac	cility:	Smo	ke Detectors					
Are alarms connected	to a constantly attended loc	ation?	Υ						
Is there a watchman se	ervice?	Υ	Wha	t is the frequency of rounds?		3-4 TIMES PER MIGHT			
Are watchman recordir	ng rounds?		Υ						
Are there any fire extin	guishers?	Υ	Are	they serviced annually?		Υ			
Are there any hose star	tions?	N	Is th	ere a fire private fire brigade?		N			
Frequency of training r	eceived by the private fire b	rigade:							
Type of public fire depart	artment:	Paid	Dista	ance:		.99 MILES			
Exposure:									
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0						
Describe the Occupand	cy of those buildings(s) near	by (within 100 feet):							
Is there a body of water	r nearby?	N	Description:						
How far is the body of	water from major buildings?	•							
Previous history of floo	oding?	N	Description:						
Any property damage I	osses in the past 3 years:	N	Description:						

			Prope	erty Detail Form			
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA						
Property:	Health Sciences						
Property Address:	720 Keith Avenue MISSOL	JLA					
Property ID:	27						
Construction:							
Total number of insured l	buildings:	1		Total square footage of insured buildings:	63590		
Year built:		1962		Number of stories:	5		
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete		
Construction of exterior walls:		Reinforced Concrete		Construction of interior walls:	Gypsum Board		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:		State Univer	rsity				
Provide a brief description of operations:		Offices/classrooms					
Storage height of warehoused products:		0					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N				
Protection:							
Are there any automatic s	sprinklers?	N	Wh	at are the design densities for each area?			
The water supply for auto	omatic sprinklers is?	Public	Hov	w many hydrants are located within 500 feet of buildings?	<b>&gt;</b>	2	
ndicate the Alarm Coverages provided for your facility:		Sm	oke Detectors				
Are alarms connected to a constantly attended location?			Υ				
s there a watchman service?		Υ	Wh	at is the frequency of rounds?		Campus police 24/7	
Are watchman recording	rounds?		Υ				
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?		Υ	
Are there any hose statio	ns?	N	ls ti	here a fire private fire brigade?		null	
requency of training rec	eived by the private fire b	rigade:					
Гуре of public fire depart	ment:	Paid	Dis	stance:		under 1 mile	
Exposure:							
low many buildings(not	part of Account) are withir	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
s there a body of water nearby?		N	Description:				
low far is the body of wa	ter from major buildings?						
Previous history of flooding?		Description:					
Any property damage losses in the past 3 years: N		Description:					

							. ago 02
			Prope	erty Detail Form			
gency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA TECH OF THE UM						
roperty:	Health Sciences Building (Former Petroleum Bldg)						
roperty Address:	1300 W. Park Street BUTTE	<b></b>					
roperty ID:	110						
onstruction:							
otal number of insured l	buildings:	1		Total square footage of insured buildings:	23694		
ear built:		1953		Number of stories:	3		
onstruction of roof:		Other		Construction of floors:	Other		
onstruction of exterior v	walls:	Masonry		Construction of interior walls:	Gypsum Board	d	
o major interior masonr	y walls (fire walls) extend a	bove the roofline?		null			
ccupancy:							
ccupancy Type:			State Unive	rsity			
rovide a brief descriptio	on of operations:		Offices, classrooms, labs				
torage height of wareho	oused products:		N/a				
re flammable and combustible liquids stored in a cut-off room?			N				
afegaurds taken for the storage and dispensing of flammable liquids:			Υ				
rotection:							
re there any automatic	sprinklers?	N	Wh	at are the design densities for each area?			
he water supply for automatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?	1	10		
dicate the Alarm Coverages provided for your facility:			Sm	oke Detectors			
re alarms connected to a constantly attended location?			Υ				
there a watchman serv	ice?	Υ	Wh	at is the frequency of rounds?		2 per shift	
re watchman recording	rounds?		Υ				
re there any fire extingu	iishers?	Υ	Are	e they serviced annually?		Υ	
re there any hose statio	ns?	N	ls t	here a fire private fire brigade?		N	
requency of training rec	eived by the private fire br	igade:					
ype of public fire depart	ment:	Paid	Dis	stance:		0.86 miles	
xposure:							
						<u> </u>	

How many buildings(not part of Account) are within 100 feet of insured buildings? Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Description:

Previous history of flooding?

Ν Any property damage losses in the past 3 years: N Description: Description:

						Page 32	
			Propert	y Detail Form			
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA TECH OF THE UM						
Property:	Health, Physical Educatio	n, & Recreation Bldg					
Property Address:	1300 W. Park Street BUT	TE					
Property ID:	112						
Construction:							
Total number of insured buildings:			Total square footage of insured buildings:	98236			
Year built:		1980		Number of stories:	1		
Construction of roof:		Other		Construction of floors:	Other		
Construction of exterior walls: Masonry		Masonry		Construction of interior walls:	Gypsum Board		
Do major interior masonry walls (fire walls) extend above the roofline?				null			
Occupancy:							
Occupancy Type:		State Universi	ty				
Provide a brief descrip	otion of operations:		Offices				
Storage height of warehoused products:			N/A				
Are flammable and combustible liquids stored in a cut-off room?			N				
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ				
Protection:							
Are there any automat	ic sprinklers?	N	What	are the design densities for each area?			
The water supply for automatic sprinklers is?		How	many hydrants are located within 500 feet of building	gs? 6			
Indicate the Alarm Coverages provided for your facility:			Smok	te Detectors			
Are alarms connected to a constantly attended location?			Υ				
Is there a watchman se	ervice?	Υ	What	is the frequency of rounds?	2 per shift		
Are watchman recordi	ng rounds?		Υ				
Are there any fire extir	nguishers?	Υ	Are t	hey serviced annually?	Υ		
Are there any hose sta	itions?	N	Is the	ere a fire private fire brigade?	N		
Frequency of training	received by the private fire I	origade:					
Type of public fire dep	artment:	Paid	Dista	nce:	0.86 miles		

Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0 Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Description:

Description:

Previous history of flooding?

Ν

Any property damage losses in the past 3 years: N

			Proper	ty Detail Form				
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, MONTANA ST	ATE UNIVER	SITY - BOZEMAN				
Property:	HEATING PLANT							
Property Address:	West Grant Street (no officia	al address) BOZEMAN						
Property ID:	303							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	11616			
Year built:		1923		Number of stories:	1			
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Co	ncrete		
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Masonry w/ Fir	re Doors		
Do major interior masonry	y walls (fire walls) extend a	bove the roofline?		N				
Occupancy:								
Occupancy Type:			Power Plant					
Provide a brief description of operations:		GENERATES	SENERATES STEAM, ELECTRICITY & AIR TO CAMPUS					
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic s	prinklers?	N	Wha	t are the design densities for each area?				
The water supply for auto	matic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	•	2		
Indicate the Alarm Covera	nges provided for your faci	lity:						
Are alarms connected to	a constantly attended loca	tion?	N					
Is there a watchman servi	ce?	Υ	Wha	t is the frequency of rounds?		MONITORED 24 HOURS		
Are watchman recording	rounds?		Υ					
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?		Υ		
Are there any hose station	ns?	N	Is th	ere a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire departs	ment:	Paid	Dista	ance:		1.42 MILES		
Exposure:								
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearb	y (within 100 feet):						
Is there a body of water n	earby?	N	Description:					
How far is the body of wa	ter from major buildings?							
Previous history of floodi	ng?	N	Description:					
Any property damage los	ses in the past 3 years:	N	Description:					

under 1 mile

							Page 3
			Prop	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTA	ANA - MISSOULA			
Property:	Heating Plant						
Property Address:	840 Connell Avenue MISS	OULA					
Property ID:	009						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	10160		
Year built:		1923		Number of stories:	2		
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Other		
Do major interior masonry walls (fire walls) extend above the roofline?				N			
Occupancy:							
Occupancy Type:			Power Pla	ant			
Provide a brief description of operations:			Boiler ope	eration for steam distribution to heat campus buildings			
Storage height of wareh	oused products:		0				
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	e storage and dispensing of	f flammable liquids:	Υ				
Protection:							
Are there any automatic	sprinklers?	N	W	What are the design densities for each area?		no sprinklers	
The water supply for aut	omatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings?	•	3	
Indicate the Alarm Cove	rages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	ation?	Υ	,			
Is there a watchman serv	vice?	Υ	W	What is the frequency of rounds?		Campus police 24/7	
Are watchman recording	j rounds?		Υ	,			
Are there any fire exting	uishers?	Υ	Α	re they serviced annually?		Υ	
Are there any hose static	ons?	N	Is	s there a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:					

Distance:

0

Description:

Description:

Description:

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Exposure:

Paid

Ν

Ν

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

						Page 32
			Pr	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - WESTERN		
Property:	Heating Plant & Garage					
Property Address:	710 S. Atlantic DILLON					
Property ID:	5					
Construction:						
Γotal number of insured	buildings:	1		Total square footage of insured buildings:	8516	
Year built:		1926		Number of stories:	2	
Construction of roof:		Concrete Panels		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry	
Oo major interior masonry walls (fire walls) extend above the roofline?				N		
Occupancy:						
Occupancy Type:			Power	Plant		
Provide a brief description	on of operations:		Boiler p	lant - steam production		
Storage height of wareho	oused products:		N/A			
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	3	
ndicate the Alarm Cover	rages provided for your fac	cility:		Smoke Detectors		
Are alarms connected to	a constantly attended loca	ation?		Υ		
s there a watchman serv	vice?	Υ		What is the frequency of rounds?	Hourly	
Are watchman recording	rounds?			Υ		
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
Are there any hose station	ons?	N		Is there a fire private fire brigade?	N	
Frequency of training red	ceived by the private fire b	rigade:				

Type of public fire department: Voluntary Distance:

>1 mile

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How many buildings(not part of Account) are within 100 feet of insured buildings?

Exposure:

Description: Beaverhead River

Is there a body of water nearby? Υ

How far is the body of water from major buildings?

Previous history of flooding?

< 1 mile

Description: Ν

Description:

blank

Any property damage losses in the past 3 years: N

							- 3
			Prope	rty Detail Form			
gency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, MONTANA T	ECH OF THE	ИМ			
Property:	Heating Plant Building						
roperty Address:	1300 W. Park Street BUTTI	≣					
Property ID:	107						
Construction:							
otal number of insured l	buildings:	1		Total square footage of insured buildings:	11037		
ear built:		1969		Number of stories:	2		
construction of roof:		Other		Construction of floors:	Other		
construction of exterior v	walls:	Masonry		Construction of interior walls:	Other		
o major interior masonr	y walls (fire walls) extend a	above the roofline?		null			
Occupancy:							
Occupancy Type:			Power Plant				
Provide a brief description of operations:			Warehouse,	steam generation			
storage height of wareho	used products:		9 to 7 feet				
re flammable and comb	ustible liquids stored in a	cut-off room?	N				
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ				
rotection:							
are there any automatic s	sprinklers?	N	Wha	at are the design densities for each area?			
he water supply for auto	omatic sprinklers is?		Hov	v many hydrants are located within 500 feet of buildings	?	7	
ndicate the Alarm Cover	ages provided for your fac	ility:	Smo	oke Detectors			
re alarms connected to	a constantly attended loca	tion?	Υ				
s there a watchman serv	ice?	Υ	Wha	at is the frequency of rounds?		2 per shift	
re watchman recording	rounds?		Υ				
are there any fire extingu	iishers?	Υ	Are	they serviced annually?		Υ	
re there any hose statio	ns?	N	ls th	nere a fire private fire brigade?		N	
requency of training rec	eived by the private fire br	igade:					
ype of public fire depart	ment:	Paid	Dist	tance:		0.86 miles	
xposure:							

How many buildings(not part of Account) are within 100 feet of insured buildings? Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Ν Any property damage losses in the past 3 years: N Description:

Description:

Description:

			Pr	operty D	etail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, HELENA COL	LEGE U	NIVERSIT	Y OF MONTANA				
Property:	Helena College of Technolo	ogy Airport Campus							
Property Address:	2300 Airport Rd. HELENA								
Property ID:	817								
Construction:									
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	86694			
Year built:		1975			Number of stories:	2			
Construction of roof:		null			Construction of floors:	Reinforced Co	oncrete		
Construction of exterior v	valls:	Corrugated Metal Panel			Construction of interior walls:	Masonry			
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			Υ				
Occupancy:									
Occupancy Type:			Garage	, Service C	Center				
Provide a brief description of operations:			College	college building with both classrooms and administrative offices					
Storage height of warehoused products:		7 feet							
Are flammable and combustible liquids stored in a cut-off room?			Υ						
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ						
Protection:									
Are there any automatic s	sprinklers?	Υ		What are	the design densities for each area?				
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?	•	2		
Indicate the Alarm Covera	ages provided for your fac	ility:		Smoke D	etectors, Sprinkler Waterflow				
Are alarms connected to	a constantly attended loca	tion?		Υ					
ls there a watchman servi	ice?	N		What is t	he frequency of rounds?				
Are watchman recording	rounds?								
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose station	ns?	N		Is there a	a fire private fire brigade?		null		
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid		Distance	:		blank		
Exposure:									
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	1						
Describe the Occupancy of those buildings(s) nearby (within 100 feet):		airplane	e hangar						
Is there a body of water n	earby?	N	Descrip	otion:					
How far is the body of wa	ter from major buildings?								
Previous history of floodi	ng?	N	Descrip	otion:					
Any property damage los	ses in the past 3 years:	N	Descrip	otion:					

Pro	pertv	Detail	Form

			Propert	y Detail Form					
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVERS	ITY - BOZEMAN					
Property:	HERRICK HALL								
Property Address:	West Cleveland (no official	address) BOZEMAN							
Property ID:	109								
Construction:									
Total number of insure	d buildings:	1		Total square footage of insured buildings:	42015				
Year built:		1926		Number of stories:	5				
Construction of roof:		Wood Joists		Construction of floors:	Poured Conci	rete			
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Boar	d			
Do major interior masonry walls (fire walls) extend above the roofline?			N						
Occupancy:									
Occupancy Type:			State Universi	y					
Provide a brief descript	ion of operations:		OFFICES/CLA	OFFICES/CLASSROOMS/LABS					
Storage height of warehoused products:		N/A							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		f flammable liquids:	Υ						
Protection:									
Are there any automati	c sprinklers?	N	What	are the design densities for each area?					
The water supply for au	itomatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	?	5			
Indicate the Alarm Cov	erages provided for your fac	ility:							
Are alarms connected t	o a constantly attended loca	ation?	N						
Is there a watchman se	rvice?	Υ	What	is the frequency of rounds?		AVERAGE 4 PER NIGHT			
Are watchman recording	g rounds?		N						
Are there any fire extin	guishers?	Υ	Are th	ney serviced annually?		Υ			
Are there any hose stat	ions?	N	Is the	re a fire private fire brigade?		N			
Frequency of training r	eceived by the private fire b	rigade:							
Type of public fire depart	artment:	Paid	Dista	nce:		1.08 MILES			
Exposure:									
How many buildings(no	ot part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupano	y of those buildings(s) near	by (within 100 feet):							
Is there a body of water	nearby?	N	Description:						
How far is the body of	water from major buildings?								
Previous history of floo	oding?	N	Description:						
Any property damage l	osses in the past 3 years:	Y	Description:		3/11/02 WATI SPRINKLER	ER DAMAGE DUE TO FROZEN LINE			

						Page 331
			Pr	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / UN	IIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - MISSOULA		
Property:	International Center (formerly	y Linguistics)				
Property Address:	700 McLeod Ave. MISSOUL	A				
Property ID:	013					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings: 688	53	
Year built:		1937		Number of stories: 1		
Construction of roof:	r	null		Construction of floors: nul	I	
Construction of exterior	walls:	null		Construction of interior walls: nul	I	
Do major interior mason	ry walls (fire walls) extend al	bove the roofline?		null		
Occupancy:						
Occupancy Type:			State U	niversity		
Provide a brief description	on of operations:		null			
Storage height of wareho	oused products:		null			
Are flammable and comb	oustible liquids stored in a cu	ut-off room?	null			
Safegaurds taken for the	storage and dispensing of f	flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?	null	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	null	
Indicate the Alarm Cover	rages provided for your facil	ity:				
Are alarms connected to	a constantly attended locati	ion?		null		
Is there a watchman serv	vice?	null		What is the frequency of rounds?	null	
Are watchman recording	rounds?					
Are there any fire exting	uishers?	null		Are they serviced annually?	null	
Are there any hose static	ons?	null		Is there a fire private fire brigade?	null	
Frequency of training red	ceived by the private fire brig	gade:		null		
Type of public fire depar	tment:	null		Distance:	null	
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?				
Describe the Occupancy of those buildings(s) nearby (within 100 feet):			null			

Is there a body of water nearby? Description: null

null How far is the body of water from major buildings? null

Previous history of flooding? Description: null null

Any property damage losses in the past 3 years: null Description: null

			Pro	operty De	etail Form				
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MI	SSOULA				
Property:	James E. Todd Building								
Property Address:	25 Campus Drive MISSOUL	LA							
Property ID:	84								
Construction:									
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	32407			
Year built:		1998			Number of stories:	3			
Construction of roof:		Poured Concrete			Construction of floors:	Reinforced Co	ncrete		
Construction of exterior w	valls:	Masonry			Construction of interior walls:	Gypsum Board	d		
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			Υ				
Occupancy:									
Occupancy Type:			State Un	niversity					
Provide a brief description	n of operations:		Offices/c	Offices/classrooms					
Storage height of warehoused products:		0							
Are flammable and combustible liquids stored in a cut-off room?		N							
Safegaurds taken for the storage and dispensing of flammable liquids:		flammable liquids:	N						
Protection:									
Are there any automatic s	prinklers?	Υ		What are	the design densities for each area?		0.1		
The water supply for auto	matic sprinklers is?	Public		How man	y hydrants are located within 500 feet of buildings?		3		
Indicate the Alarm Covera	iges provided for your faci	ility:		Smoke De	etectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
Are alarms connected to a	a constantly attended loca	tion?		Υ					
ls there a watchman servi	ce?	Υ		What is th	ne frequency of rounds?		Campus police 24/7		
Are watchman recording i	rounds?			Υ					
Are there any fire extingui	ishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose station	ns?	N		Is there a	fire private fire brigade?		N		
Frequency of training rece	eived by the private fire bri	igade:							
Type of public fire departr	ment:	Paid		Distance:			under 1 mile		
Exposure:									
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearb	oy (within 100 feet):							
Is there a body of water no	earby?	N	Descrip	tion:					
How far is the body of wat	ter from major buildings?								
Previous history of flooding	ng?	N	Descrip	tion:					
Any property damage loss	ses in the past 3 years:	N	Descrip	tion:					

						Page 3
			Pro	pperty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONT	TANA - MISSOULA		
Property:	Jeanette Rankin Hall					
Property Address:	815 Daly Avenue MISSOU	LA				
Property ID:	004					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	14586	
Year built:		1909		Number of stories:	2	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior masonry walls (fire walls) extend above the roofline?				null		
Occupancy:						
Occupancy Type:			State Un	iversity		
Provide a brief description of operations:		null				
Storage height of wareho	oused products:		null			
Are flammable and comb	oustible liquids stored in a	cut-off room?	null			
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N	,	What are the design densities for each area?		null
The water supply for aut	omatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?		null
Indicate the Alarm Cover	ages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ition?	ı	null		
Is there a watchman serv	rice?	null	,	What is the frequency of rounds?		null
Are watchman recording	rounds?					
Are there any fire exting	uishers?	null		Are they serviced annually?		null
Are there any hose static	ons?	null	ı	Is there a fire private fire brigade?		null
Frequency of training red	ceived by the private fire b	rigade:	ı	null		
Type of public fire depar	tment:	null	I	Distance:		null
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	null			
Is there a body of water i	nearby?	null	Descript	tion:	null	

Description:

Description:

null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

			Property D	Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVERSIT	Y - BOZEMAN				
Property:	JEFFERSON HALL							
Property Address:	West Garfield (no official ad	ddress) BOZEMAN						
Property ID:	335							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	30145			
Year built:		1998		Number of stories:	3			
Construction of roof:		Other		Construction of floors:	Poured Concre	ete		
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Gypsum Board	d		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Res Apt Complex	•				
Provide a brief description of operations:		STUDENT DORN	STUDENT DORM					
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic s	sprinklers?	Υ	What are	e the design densities for each area?		PER NFPA 13		
The water supply for auto	matic sprinklers is?	Public	How ma	ny hydrants are located within 500 feet of buildings?		6		
Indicate the Alarm Covera	ages provided for your fac	ility:	Sprinkler	r Valve Tamper, Sprinkler Waterflow, Smoke Detectors				
Are alarms connected to	a constantly attended loca	ation?	Υ					
Is there a watchman servi	ice?	Υ	What is	the frequency of rounds?		3-4 TIMES PER NIGHT		
Are watchman recording	rounds?		Υ					
Are there any fire extingu	ishers?	Υ	Are they	serviced annually?		Υ		
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid	Distance	e:		1.26 MILES		
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	earby?	N	Description:					
How far is the body of wa	ter from major buildings?							
Previous history of floodi	ng?	N	Description:					
Any property damage los	ses in the past 3 years:	N	Description:					

							Page 3
			Pr	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / UNI	VERSITY SYSTEM, UNIVERSITY	OF MON	NTANA - MISSOULA			
Property:	Jesse Hall						
Property Address:	610 Daly Avenue MISSOULA						
Property ID:	109						
Construction:							
Total number of insured	buildings: 1			Total square footage of insured buildings:	87178		
Year built:	19	968		Number of stories:	11		
Construction of roof:	ni	ull		Construction of floors:	null		
Construction of exterior	walls: no	ull		Construction of interior walls:	null		
Do major interior mason	ry walls (fire walls) extend ab	ove the roofline?		null			
Occupancy:							
Occupancy Type:			State U	niversity			
Provide a brief description	on of operations:		null				
Storage height of wareho	oused products:		null				
Are flammable and comb	oustible liquids stored in a cu	t-off room?	null				
Safegaurds taken for the	storage and dispensing of fla	ammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		null	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null	
ndicate the Alarm Cover	ages provided for your facilit	y:					
Are alarms connected to	a constantly attended location	on?		null			
s there a watchman serv	rice?	null		What is the frequency of rounds?		null	
Are watchman recording	rounds?						
Are there any fire exting	uishers?	null		Are they serviced annually?		null	
Are there any hose station	ons?	null		Is there a fire private fire brigade?		null	
requency of training red	ceived by the private fire briga	ade:		null			
Гуре of public fire depar	tment:	null		Distance:		null	
Exposure:							
How many buildings(not	part of Account) are within 1	00 feet of insured buildings?					
Describe the Occupancy	of those buildings(s) nearby	(within 100 feet):	null				

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

null

How far is the body of water from major buildings?

null

Previous history of flooding?

null

Description:

null

Any property damage losses in the past 3 years:

null

Description:

null

null

			Property	/ Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	ATE UNIVERS	ITY - BOZEMAN		
Property:	JOHNSTONE CENTER RE	SIDENCE HALL - PRYOR				
Property Address:	West Harrison Street (no of	ficial address) BOZEMAN				
Property ID:	330101					
Construction:						
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	54654	
Year built:		1955		Number of stories:	4	
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concre	ete
Construction of exterior v	valls:	Reinforced Concrete		Construction of interior walls:	Other	
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N		
Occupancy:						
Occupancy Type:			Res Apt Comp	lex		
Provide a brief description	n of operations:		STUDENT DO	RM		
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A				
Protection:						
Are there any automatic s	sprinklers?	Υ	What	are the design densities for each area?		
The water supply for auto	matic sprinklers is?		How r	nany hydrants are located within 500 feet of buildings?	1	5
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke	e Detectors		
Are alarms connected to	a constantly attended loca	tion?	Υ			
Is there a watchman servi	ice?	Υ	What	is the frequency of rounds?		3-4 TIME PER NIGHT
Are watchman recording	rounds?		Υ			
Are there any fire extingu	ishers?	Υ	Are th	ey serviced annually?		Υ
Are there any hose station	ns?	N	Is the	re a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	igade:				
Type of public fire departs	ment:	Paid	Distar	nce:		.86 MILES
Exposure:						
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):				
Is there a body of water n	earby?	N	Description:			
How far is the body of wa	ter from major buildings?					
Previous history of floodi	ng?	N	Description:			
Any property damage los	ses in the past 3 years:	N	Description:			

							Page 33
			Pr	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / I	JNIVERSITY SYSTEM, UNIVERSIT	Y OF MON	NTANA - MISSOULA			
Property:	Knowles Hall						
Property Address:	630 University Avenue MI	SSOULA					
Property ID:	107						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	63330		
Year built:		1963		Number of stories:	4		
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concr	rete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Other		
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State U	Iniversity			
Provide a brief descript	tion of operations:		Student	t dorm			
Storage height of warel	housed products:		0				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automatic	c sprinklers?	Υ		What are the design densities for each area?		0.1	
The water supply for au	utomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings	s?	3	
Indicate the Alarm Cov	erages provided for your fa	cility:		Smoke Detectors, Sprinkler Waterflow, Burglar Alarms (Motion (Door Contacts)	Detection), Sprin	ıkler Valve Tamper, Burglar A	larms
Are alarms connected t	o a constantly attended loc	ation?		Υ			
Is there a watchman se	rvice?	Υ		What is the frequency of rounds?		Campus police 24/7	
Are watchman recording	g rounds?			Υ			
Are there any fire exting	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?		N	
Frequency of training r	eceived by the private fire b	origade:					
Type of public fire depart	artment:	Paid		Distance:		under 1 mile	
Exposure:							
How many buildings(no	ot part of Account) are with	n 100 feet of insured buildings?	0				
Describe the Occupano	y of those buildings(s) nea	rby (within 100 feet):					
Is there a body of water	r nearby?	N	Descri	ption:			

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

						1 490 00
			Pı	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	NTANA - MISSOULA		
Property:	Lakeside Laboratory					
Property Address:	32125 Bio Station Lane PC	DLSON				
Property ID:	516					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	4860	
Year built:		1968		Number of stories:	1	
Construction of roof:		Other		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Gypsum Board	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State U	Iniversity		
Provide a brief description	on of operations:		Higher	education Lakeside lab for freshwater biological research		
Storage height of wareho	oused products:		0			
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?	no sprinklers	;
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	1	
ndicate the Alarm Cove	ages provided for your fac	ility:		Smoke Detectors		
Are alarms connected to	a constantly attended loca	ntion?		N		
s there a watchman serv	rice?	N		What is the frequency of rounds?		
Are watchman recording	rounds?			N		
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
Are there any hose station	ons?	Υ		Is there a fire private fire brigade?	N	
requency of training re	ceived by the private fire br	rigade:				
Type of public fire depar	tment:	Voluntary		Distance:	on-site	
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
s there a body of water	nearby?	Υ	Descri	ption:	Flathead Lake	
How far is the body of w	ater from major buildings?		500 fee	ıt .		
Previous history of flood	ling?	N	Descri	ption:		
Any property damage lo	sses in the past 3 years:	N	Descri	ption:		

			Proper	ty Detail Form					
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN								
Property:	LANGFORD RESIDENCE	LANGFORD RESIDENCE HALL							
Property Address:	West Harrison Street (no of	ficial address) BOZEMAN							
Property ID:	338								
Construction:									
Total number of insured I	ouildings:	1		Total square footage of insured buildings:	107960				
Year built:		1960		Number of stories:	4				
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concre	ete			
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Masonry w/ Op	penings			
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N					
Occupancy:									
Occupancy Type:			Res Apt Com	nplex					
Provide a brief descriptio	n of operations:		STUDENT D	STUDENT DORM					
Storage height of wareho	used products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A						
Protection:									
Are there any automatic s	sprinklers?	Υ	Wha	nt are the design densities for each area?		PER NFPA 13 BASEMENT ONLY			
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	1	5			
Indicate the Alarm Covera	ages provided for your faci	ility:	Smo	ke Detectors					
Are alarms connected to	a constantly attended loca	tion?	Υ						
Is there a watchman serv	ice?	Υ	Wha	at is the frequency of rounds?		3-4 TIMES PER NIGHT			
Are watchman recording	rounds?		Υ						
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?		null			
Are there any hose statio	ns?	null	ls th	ere a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid	Dist	ance:		.81 MILES			
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) neark	oy (within 100 feet):							
Is there a body of water n	earby?	null	Description:	:					
How far is the body of wa	ter from major buildings?								
Previous history of floodi	ng?	N	Description:	:					
Any property damage los	ses in the past 3 years:	Υ	Description:	:		ER DAMAGE DUE TO FROZEN			
					SPRINKLER L	LINE			

<b>Property</b>	, Datail	E o woo
	/ Detail	

Vaeuch:	LINIIVEDSITY SYSTEM / LI	NIVERSITY SYSTEM, MONTANA S'		Detail Form				
Agency: Property:	LEON JOHNSON HALL	WIVERSITT STOTEM, MONTAINA S	TATE UNIVERSI	TT - BOZEWAN				
Property Address:		of Montana Hall) BOZEMAN						
Property ID:	120	or Mortana Hally BOZEWAN						
Construction:	120							
Total number of insured	auildings:	1		Total square footage of insured buildings:	125480			
Year built:	Juliuliigs.	1973		Number of stories:	8			
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Co	oncrete		
Construction of exterior	walle:	Masonry		Construction of interior walls:	Masonry w/ Fi			
	y walls (fire walls) extend	•		N	Wasoniy W/ I	IIC D0013		
Occupancy:	y wans (me wans) extend	above the roomine:		14				
Occupancy Type:			Laboratory					
Provide a brief description	n of operations:		•	SSROOMS/LARS				
-	•		N/A	OFFICES/CLASSROOMS/LABS				
Storage height of warehoused products:  Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		Y						
Protection:	otologo ana aloponomig o		•					
Are there any automatic s	sprinklers?	Υ	What a	are the design densities for each area?		PER NFPA 13 IN 3 FLOORS		
The water supply for auto		Public		nany hydrants are located within 500 feet of buildings:	<b>?</b>	7		
	ages provided for your fac			Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
	a constantly attended loca	-	Y					
Is there a watchman serv	-	Υ	What i	s the frequency of rounds?		AVERAGE 4 PER NIGHT		
Are watchman recording	rounds?		N	, ,				
Are there any fire extingu		Υ	Are the	ey serviced annually?		Υ		
Are there any hose statio	ns?	N	Is ther	e a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid	Distan	ce:		1.02 MILES		
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	earby?	N	Description:					
How far is the body of wa	ter from major buildings?							
Previous history of flood	ing?	N	Description:					
Any property damage los	ses in the past 3 years:	Υ	Description:			ER DAMAGE DUE TO FROZEN LINE/8/02/02WATER DAMAGE		

							Page 341
			Р	roperty Detail Form			
Agency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, UNIVERS	SITY OF MO	NTANA - MISSOULA			
Property:	Lewis and Clark Villages I	Unit A					
Property Address:	3000 S. Higgins MISSOU	LA					
Property ID:	325						
Construction:							
Total number of insured	l buildings:	1		Total square footage of insured buildings:	18215		
Year built:		2004		Number of stories:	3		
Construction of roof:		Other		Construction of floors:	Poured Cond	crete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Boa	ard	
Oo major interior masor	nry walls (fire walls) extend	I above the roofline?		N			
Occupancy:							
Occupancy Type:			Res A <sub>l</sub>	pt Complex			
Provide a brief descripti	on of operations:		Apartn	nent housing complex for students			
Storage height of wareh	oused products:		0				
Are flammable and com	bustible liquids stored in a	a cut-off room?	N/A				
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings	i?	2	
ndicate the Alarm Cove	rages provided for your fa	cility:		Fire Pump Alarms, Sprinkler Waterflow, Smoke Detectors			
Are alarms connected to	o a constantly attended loc	cation?		Υ			
s there a watchman ser	vice?	Υ		What is the frequency of rounds?		Campus Police 24/7	
Are watchman recording	g rounds?			N			
Are there any fire exting	juishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a fire private fire brigade?		N	
requency of training re	eceived by the private fire b	origade:					
Гуре of public fire depa	rtment:	Paid		Distance:		under 1 mile	

0

Description:

Description:

Description:

**Exposure:** 

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

						Page 3
			Pro	perty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONT	TANA - MISSOULA		
Property:	Lewis and Clark Villages U	nit B				
Property Address:	3000 S. Higgins MISSOUL	A				
Property ID:	326					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	18215	
Year built:		2004		Number of stories:	3	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Res Apt	Complex		
Provide a brief description	on of operations:		null			
Storage height of warehoused products:		null				
Are flammable and combustible liquids stored in a cut-off room?		null				
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	Υ	,	What are the design densities for each area?	1	null
The water supply for aut	omatic sprinklers is?		1	How many hydrants are located within 500 feet of buildings?	ı	null
Indicate the Alarm Cover	rages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ation?	ı	null		
Is there a watchman serv	vice?	null	,	What is the frequency of rounds?	ı	null
Are watchman recording	rounds?					
Are there any fire exting	uishers?	null		Are they serviced annually?	1	null
Are there any hose static	ons?	null	ı	Is there a fire private fire brigade?	1	null
Frequency of training red	ceived by the private fire b	rigade:	ı	null		
Type of public fire depar	tment:	null	1	Distance:	1	null
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	null			
Is there a body of water	nearby?	null	Descript	tion:	null	

Description:

Description:

null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

null

						P	age 3
			F	Property Detail Form			
Agency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, UNIVERS	ITY OF MO	NTANA - MISSOULA			
Property:	Lewis and Clark Villages	Unit C					
Property Address:	3000 S. Higgins MISSOL	ILA					
Property ID:	327						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	18215		
Year built:		2004		Number of stories:	3		
Construction of roof:		null		Construction of floors:	null		
Construction of exterio	r walls:	null		Construction of interior walls:	null		
Do major interior maso	nry walls (fire walls) exten	d above the roofline?		null			
Occupancy:							
Occupancy Type:			Res A	pt Complex			
Provide a brief descript	ion of operations:		null				
Storage height of wareh	noused products:		null				
Are flammable and com	nbustible liquids stored in	a cut-off room?	null				
Safegaurds taken for th	e storage and dispensing	of flammable liquids:	null				
Protection:							
Are there any automatic	c sprinklers?	Υ		What are the design densities for each area?	1	null	
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	1	null	
Indicate the Alarm Cove	erages provided for your fa	acility:					
Are alarms connected t	o a constantly attended lo	cation?		null			
Is there a watchman se	rvice?	null		What is the frequency of rounds?	1	null	
Are watchman recording	g rounds?						
Are there any fire exting	guishers?	null		Are they serviced annually?	1	null	
Are there any hose stat	ions?	null		Is there a fire private fire brigade?	1	null	
Frequency of training re	eceived by the private fire	brigade:		null			
Type of public fire depart	artment:	null		Distance:	1	null	
Exposure:							
How many buildings(no	ot part of Account) are with	in 100 feet of insured buildings?					
Describe the Occupano	y of those buildings(s) nea	arby (within 100 feet):	null				

Description:

Description:

Description:

null

null

null

null

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

null

							Page 34
			Pı	operty Detail Form			
gency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	NTANA - MISSOULA			
roperty:	Lewis and Clark Villages U	nit D					
Property Address:	3000 S Higgins MISSOULA	1					
roperty ID:	328						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	18215		
ear built:		2004		Number of stories:	3		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
o major interior mason	ry walls (fire walls) extend a	above the roofline?		null			
Occupancy:							
Occupancy Type:			Res Ap	t Complex			
Provide a brief description	on of operations:		null				
Storage height of wareho	oused products:		null				
re flammable and combustible liquids stored in a cut-off room?			null				
afegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
are there any automatic	sprinklers?	Υ		What are the design densities for each area?		null	
he water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null	
ndicate the Alarm Cover	ages provided for your fac	ility:					
are alarms connected to	a constantly attended loca	tion?		null			
s there a watchman serv	rice?	null		What is the frequency of rounds?		null	
are watchman recording	rounds?						
are there any fire exting	uishers?	null		Are they serviced annually?		null	
are there any hose static	ons?	null		Is there a fire private fire brigade?		null	
requency of training red	ceived by the private fire br	igade:		null			
ype of public fire depar	tment:	null		Distance:		null	
xposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?					
escribe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):	null				
s there a body of water i	nearby?	null	Descri	ntion:	null		

Description:

Description:

null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

						Page 3
			Pr	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - MISSOULA		
Property:	Lewis and Clark Villages U	Init E				
Property Address:	3000 S Higgins MISSOUL	A				
Property ID:	329					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	18215	
Year built:		2004		Number of stories:	3	
Construction of roof:		null		Construction of floors:	null	
Construction of exterio	r walls:	null		Construction of interior walls:	null	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Res Apt	t Complex		
Provide a brief descript	ion of operations:		null			
Storage height of warehoused products:			null			
Are flammable and combustible liquids stored in a cut-off room?		null				
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	null			
Protection:						
Are there any automatic	c sprinklers?	Υ		What are the design densities for each area?		null
The water supply for au	itomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null
Indicate the Alarm Cov	erages provided for your fac	cility:				
Are alarms connected t	o a constantly attended loc	ation?		null		
Is there a watchman se	rvice?	null		What is the frequency of rounds?		null
Are watchman recording	g rounds?					
Are there any fire exting	guishers?	null		Are they serviced annually?		null
Are there any hose stat	ions?	null		Is there a fire private fire brigade?		null
Frequency of training r	eceived by the private fire b	rigade:		null		
Type of public fire depart	artment:	null		Distance:		null
Exposure:						
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?				
Describe the Occupano	y of those buildings(s) near	by (within 100 feet):	null			
Is there a body of water	nearby?	null	Descrip	otion:	null	
How far is the body of v	vater from major buildings?		null			

Description:

Description:

null

null

Previous history of flooding?

Any property damage losses in the past 3 years: null

null

							Page 3
			Prope	rty Detail Form			
Agency:	UNIVERSITY SYSTI	EM / UNIVERSITY SYSTEM, UN	NIVERSITY OF MONTAN	NA - MISSOULA			
Property:	Lewis and Clark Villa	ages Unit F					
Property Address:	3000 S. Higgins MIS	SOULA					
Property ID:	330						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	18215		
ear built:		2004		Number of stories:	3		
Construction of roof:		null		Construction of floors:	null		
Construction of exterio	or walls:	null		Construction of interior walls:	null		
Oo major interior maso	onry walls (fire walls) ex	xtend above the roofline?		null			
Occupancy:							
Occupancy Type:			Res Apt Co	mplex			
Provide a brief descrip	tion of operations:		null				
Storage height of ware	housed products:		null				
Are flammable and combustible liquids stored in a cut-off room?			null				
Safegaurds taken for th	ne storage and dispens	sing of flammable liquids:	null				
Protection:							
Are there any automati	c sprinklers?	Υ	Wh	at are the design densities for each area?		null	
The water supply for a	utomatic sprinklers is?	•	Ho	w many hydrants are located within 500 feet of buildir	ıgs?	null	
ndicate the Alarm Cov	erages provided for yo	our facility:					
Are alarms connected	to a constantly attende	ed location?	null				
s there a watchman se	rvice?	null	Wh	at is the frequency of rounds?		null	
Are watchman recordir	ng rounds?						
Are there any fire extin	guishers?	null	Are	they serviced annually?		null	
Are there any hose sta	tions?	null	ls t	here a fire private fire brigade?		null	
requency of training r	eceived by the private	fire brigade:	null				
Type of public fire depart	artment:	null	Dis	tance:		null	
Exposure:							
How many buildings(ne	ot part of Account) are	within 100 feet of insured buil	ldings?				
Describe the Occupand	cy of those buildings(s	) nearby (within 100 feet):	null				
s there a body of wate	r nearby?	null	Description	ı:	null		

Description:

Description:

null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

			Pro	perty De	etail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MI	SSOULA		
Property:	Lewis and Clark Villages Ur	nit G					
Property Address:	3000 S. Higgins MISSOUL	A					
Property ID:	331						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	18215	
Year built:		2004			Number of stories:	3	
Construction of roof:		Other			Construction of floors:	Poured Concre	ete
Construction of exterior v	valls:	Wood Frame			Construction of interior walls:	Gypsum Board	1
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			N		
Occupancy:							
Occupancy Type:			Res Apt	Complex			
Provide a brief descriptio	n of operations:		Apartme	nt housing	g complex for students		
Storage height of wareho	used products:		0				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A				
Protection:							
Are there any automatic s	sprinklers?	Υ	,	What are	the design densities for each area?		
The water supply for auto	omatic sprinklers is?	Public	1	How man	y hydrants are located within 500 feet of buildings?		2
Indicate the Alarm Covera	ages provided for your fac	ility:		Fire Pump	Alarms, Smoke Detectors, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	tion?	,	Υ			
Is there a watchman servi	ice?	Υ	,	What is th	ne frequency of rounds?		campus police 24/7
Are watchman recording	rounds?		ļ	N			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose station	ns?	N	1	ls there a	fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	igade:					
Type of public fire depart	ment:	Paid		Distance:			under 1 mile
Exposure:							
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	oy (within 100 feet):					
Is there a body of water n	earby?	N	Descript	tion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descript	tion:			
Any property damage los	ses in the past 3 years:	N	Descript	tion:			

						- 3
			Prop	perty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, UNIVERSITY	OF MONTA	ANA - MISSOULA		
Property:	Lewis and Clark Villages U	nit I				
Property Address:	3000 S. Higgins MISSOUL	A				
Property ID:	333					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	18215	
Year built:		2004		Number of stories:	3	
Construction of roof:		Other		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior masoni	y walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Res Apt C	Complex		
Provide a brief description	on of operations:		Apartment	t housing complex for students		
Storage height of wareho	oused products:		0			
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	Υ	W	hat are the design densities for each area?		
The water supply for auto	omatic sprinklers is?	Public	Н	low many hydrants are located within 500 feet of buildings?	2	
Indicate the Alarm Cover	ages provided for your fac	ility:	Fi	ire Pump Alarms, Smoke Detectors, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	ation?	Y			
ls there a watchman serv	ice?	Υ	W	hat is the frequency of rounds?	campus police 24/7	
Are watchman recording	rounds?		N	l'		
Are there any fire extingu	iishers?	Υ	Α	re they serviced annually?	Υ	
Are there any hose static	ons?	N	Is	s there a fire private fire brigade?	N	
Frequency of training red	eived by the private fire b	rigade:				
Type of public fire depart	ment:	Paid	D	istance:	under 1 mile	
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	blank			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
ls there a body of water r	nearby?	N	Description	on:		
How far is the body of wa	ater from major buildings?					
Previous history of flood	ing?	N	Description	on:		
Any property damage los	sses in the past 3 years:	N	Description	on:		

			Pr	operty D	etail Form			
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - M	IISSOULA			
Property:	Lewis and Clark Villages Ur	nit J						
Property Address:	3000 S. Higgins MISSOULA	4						
Property ID:	334							
Construction:								
Total number of insured l	buildings:	1			Total square footage of insured buildings:	18215		_
Year built:		2004			Number of stories:	3		
Construction of roof:		Other			Construction of floors:	Poured Conc	rete	
Construction of exterior v	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			N			
Occupancy:								
Occupancy Type:			Res Apt	t Complex				
Provide a brief descriptio	n of operations:		Apartme	ent housin	g complex for students			
Storage height of wareho	used products:		0					
Are flammable and comb	ustible liquids stored in a d	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?			_
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings	?	2	
Indicate the Alarm Cover	ages provided for your faci	lity:		Smoke D	etectors, Sprinkler Waterflow, Fire Pump Alarms			
Are alarms connected to	a constantly attended loca	tion?		Υ				
ls there a watchman serv	ice?	Υ		What is t	the frequency of rounds?		Campus police 24/7	
Are watchman recording	rounds?			N				
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N		Is there a	a fire private fire brigade?		N	
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire depart	ment:	Paid		Distance	:		under 1 mile	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) nearl	y (within 100 feet):						
ls there a body of water n	earby?	N	Descrip	otion:				
How far is the body of wa	ter from major buildings?							
Previous history of flood	ing?	N	Descrip	otion:				
Any property damage los	ses in the past 3 years:	N	Descrip	otion:				

			Pro	operty D	etail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - M	IISSOULA		
Property:	Lewis and Clark Villages U	nit K					
Property Address:	3000 S. Higgins MISSOUL	A					
Property ID:	335						
Construction:							
Total number of insured	buildings:	1			Total square footage of insured buildings:	18215	
Year built:		2004			Number of stories:	3	
Construction of roof:		Other			Construction of floors:	Poured Concr	rete
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Gypsum Boar	rd
Do major interior masoni	y walls (fire walls) extend	above the roofline?			N		
Occupancy:							
Occupancy Type:			Res Apt	Complex			
Provide a brief description	on of operations:		Apartme	ent housin	g complex for students		
Storage height of wareho	oused products:		0				
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?	<b>?</b>	2
Indicate the Alarm Cover	ages provided for your fac	ility:		Fire Pum	p Alarms, Smoke Detectors, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	ition?		N			
ls there a watchman serv	rice?	N		What is t	he frequency of rounds?		campus police 24/7
Are watchman recording	rounds?						
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ
Are there any hose statio	ons?	N		Is there a	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	rigade:					
Type of public fire depart	ment:	Paid		Distance	:		under 1 mile
Exposure:							
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
ls there a body of water r	nearby?	N	Descrip	tion:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Descrip	tion:			
Any property damage los	sses in the past 3 years:	N	Descrip	tion:			

0/03/02 WATER DAMAGE DUE TO FROZEN SPRINKLER LINE

						1 age 3
			P	roperty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UI	NIVERSITY - BOZEMAN		
Property:	LEWIS HALL					
Property Address:	West Garfield Street (no of	ficial address) BOZEMAN				
Property ID:	103					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	46233	
Year built:		1923		Number of stories:	4	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concre	ete
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	i
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Labora	itory		
Provide a brief description	on of operations:		OFFIC	ES/CLASSROOMS		
Storage height of warehoused products:			N/A			
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N/A			
Safegaurds taken for the storage and dispensing of flammable liquids:		flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		0.20/1500 803 gpm, 50.5 psi, 165 temp
The water supply for auto	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	<b>?</b>	5
Indicate the Alarm Cover	rages provided for your fac	ility:		Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Valv	ve Tamper, Sprir	nkler Waterflow
Are alarms connected to	a constantly attended loca	ation?		Υ		
Is there a watchman serv	vice?	Υ		What is the frequency of rounds?		AVERAGE 4 PER NIGHT
Are watchman recording	rounds?			N		
Are there any fire extingu	uishers?	Υ		Are they serviced annually?		Υ
Are there any hose static	ons?	N		Is there a fire private fire brigade?		N
Frequency of training red	ceived by the private fire br	igade:				
Type of public fire depart	tment:	Paid		Distance:		.75 MILES
Exposure:						
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water i	nearby?	N	Descri	ption:		
How far is the body of wa	ater from major buildings?					
Previous history of flood	ling?	N	Descri	ption:		

Description:

Any property damage losses in the past 3 years: Y

		<b>Property Detail Form</b>
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE	UNIVERSITY - NORTHERN
Property:	Lewistown	

Property Address:	773 Airport Road LEWISTOWN

37 **Property ID:** 

O 1-		
Conetr	шап	nn:

Total number of insured buildings: 1 Total square footage of insured buildings: 15232

Year built: 1978 2 Number of stories:

Reinforced Concrete Construction of roof: Construction of floors: Reinforced Concrete

Construction of exterior walls: Tilt-Up Concrete Construction of interior walls: Gypsum Board

Do major interior masonry walls (fire walls) extend above the roofline?

#### Occupancy:

**Occupancy Type:** State University

Provide a brief description of operations: classrooms/office

Storage height of warehoused products: n/a

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids: N/A

## Protection:

Ν Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? How many hydrants are located within 500 feet of buildings?

Indicate the Alarm Coverages provided for your facility: **Smoke Detectors** 

Are alarms connected to a constantly attended location?

Is there a watchman service? Υ What is the frequency of rounds? every 24 hours

Υ

Are watchman recording rounds?

Are there any fire extinguishers? Are they serviced annually?

Are there any hose stations? Ν Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: 2 miles

## Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Ν Description: Any property damage losses in the past 3 years: Description:

			Pro	operty D	etail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UN	IVERSITY	'- NORTHERN			
Property:	Lewistown - Shop							
Property Address:	773 Airport Road LEWISTO	OWN						
Property ID:	38							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	6000		
Year built:		1960			Number of stories:	1		
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Poured Concre	ete	
Construction of exterior	walls:	Corrugated Metal Panel			Construction of interior walls:	No Interior Wa	alls	
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			N			
Occupancy:								
Occupancy Type:			State Ur	niversity				
Provide a brief description	on of operations:		shop cla	ssroom				
Storage height of wareho	oused products:		n/a					
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How man	ny hydrants are located within 500 feet of buildings?		1	
Indicate the Alarm Cover	ages provided for your fac	ility:		Smoke De	etectors			
Are alarms connected to	a constantly attended loca	tion?		N				
ls there a watchman serv	ice?	Υ		What is t	he frequency of rounds?		every 24 hours	
Are watchman recording	rounds?			Υ				
Are there any fire extingu	iishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	eived by the private fire br	igade:						
Type of public fire depart	ment:	Paid		Distance	:		2 miles	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
ls there a body of water r	nearby?	N	Descrip	tion:				
How far is the body of wa	eter from major buildings?							
Previous history of flood	ing?	N	Descrip	tion:				
Any property damage los	ses in the past 3 years:	N	Descrip	tion:				

							Page 35
			Pro	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / I	JNIVERSITY SYSTEM, MONTANA S	STATE UNIV	/ERSITY - NORTHERN			
Property:	Lewistown - Vehicle Cold	Storage Buildings					
Property Address:	773 Airport Road LEWIST	OWN					
Property ID:	39						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	2700		
Year built:		1995		Number of stories:	1		
Construction of roof:		Reinforced Concrete		Construction of floors:	Reinforced Co	oncrete	
Construction of exterio	or walls:	Tilt-Up Concrete		Construction of interior walls:	No Interior Wa	alls	
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Garage, \	/ehicle Storage			
Provide a brief descrip	tion of operations:		storage (i	nclu 5 cars of OPI)			
Storage height of ware	housed products:		4'				
Are flammable and cor	nbustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for t	he storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automat	c sprinklers?	N	V	What are the design densities for each area?			
The water supply for a	utomatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings	s?	1	
Indicate the Alarm Cov	erages provided for your fa	cility:	S	Smoke Detectors			
Are alarms connected	to a constantly attended loc	ation?	n	null			
ls there a watchman se	ervice?	Υ	V	What is the frequency of rounds?		every 24 hours	
Are watchman recordi	ng rounds?		Y	′			
Are there any fire extin	guishers?	Υ	A	Are they serviced annually?		Υ	
Are there any hose sta	tions?	N	ls	s there a fire private fire brigade?		N	
Frequency of training	received by the private fire b	origade:					
Type of public fire dep	artment:	Paid	D	Distance:		2 miles	
Exposure:							
How many buildings(n	ot part of Account) are with	n 100 feet of insured buildings?	0				
Describe the Occupan	cy of those buildings(s) nea	rby (within 100 feet):					
Is there a body of wate	r nearby?	N	Descripti	ion:			
How far is the body of	water from major buildings'	?					
Previous history of flo	oding?	N	Descripti	ion:			
Any property damage	losses in the past 3 years:	N	Descripti	ion:			

						Page	355
			Pro	pperty Detail Form			
Agency:	UNIVERSITY SYSTEM / UN	IIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MISSOULA			
Property:	Liberal Arts						
Property Address:	725 Daly Avenue MISSOUL	A					
Property ID:	20						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	01083		
Year built:		1953		Number of stories: 4			
Construction of roof:		null		Construction of floors:	ull		
Construction of exterior	walls:	null		Construction of interior walls:	ull		
Do major interior masonr	y walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			State Un	iversity			
Provide a brief description	on of operations:		null				
Storage height of wareho	oused products:		null				
Are flammable and comb	ustible liquids stored in a c	ut-off room?	null				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?		null	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null	
Indicate the Alarm Cover	ages provided for your facil	ity:					
Are alarms connected to	a constantly attended locat	ion?		null			
Is there a watchman serv	ice?	null		What is the frequency of rounds?		null	
Are watchman recording	rounds?						
Are there any fire extingu	uishers?	null		Are they serviced annually?		null	
Are there any hose statio	ons?	null		Is there a fire private fire brigade?		null	
Frequency of training rec	eived by the private fire bri	gade:		null			

## **Exposure:** How many buildings(not part of Account) are within 100 feet of insured buildings?

Type of public fire department:

Previous history of flooding?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Description:

Is there a body of water nearby? null

How far is the body of water from major buildings?

null

null

Any property damage losses in the past 3 years:

Description:

null

null

Description:

Distance:

null null null

null

	Property Detail Form
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BILLINGS
Property:	Liberal Arts Building
Property Address:	1500 University Drive BILLINGS

**Property ID:** 600000781

_				
~~	nst	7.11	~11	٥n
υu	поц	ш	ыı	VΠ

Total number of insured buildings: 1 Total square footage of insured buildings: 96746

Year built: Number of stories: 8

Construction of roof: Poured Concrete Construction of floors: Poured Concrete

Construction of exterior walls: Masonry Construction of interior walls: Masonry w/ Fire Doors

Do major interior masonry walls (fire walls) extend above the roofline?

#### Occupancy:

Occupancy Type: State University

Provide a brief description of operations: education, classrooms

Storage height of warehoused products: 0

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids:

#### Protection:

Are there any automatic sprinklers? Y What are the design densities for each area?

The water supply for automatic sprinklers is? Public How many hydrants are located within 500 feet of buildings? 2

Indicate the Alarm Coverages provided for your facility: Sprinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors

Are alarms connected to a constantly attended location?

Is there a watchman service?

Y

What is the frequency of rounds?

daily

Are watchman recording rounds?

Are there any fire extinguishers?

Y

Are they serviced annually?

Y

Are there any hose stations?

Y

Is there a fire private fire brigade?

N

0

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: 1 to 2 miles

### Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Y Description: irrigation ditch

How far is the body of water from major buildings? 500 feet

Previous history of flooding? N Description:

Any property damage losses in the past 3 years: N Description:

						Page :
			Prop	erty Detail Form		
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSIT	Y OF MONTA	NA - WESTERN		
Property:	Library Administration					
Property Address:	710 S. Atlantic DILLON					
Property ID:	24					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	38935	
fear built:		1969		Number of stories:	2	
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete	
Construction of exterio	r walls:	Reinforced Concrete		Construction of interior walls:	Masonry w/ Fire Doors	3
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			State Univ	rersity		
Provide a brief descript	ion of operations:		OFFICES/	LIBRARY		
Storage height of wareh	noused products:		N/A			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	Υ	w	hat are the design densities for each area?	BASEN	MENT ONLY
The water supply for au	tomatic sprinklers is?		He	ow many hydrants are located within 500 feet of buildings	? 4	
ndicate the Alarm Cove	erages provided for your fa	cility:				
Are alarms connected t	o a constantly attended loc	ation?	Υ			
s there a watchman se	rvice?	Υ	w	hat is the frequency of rounds?	HOUR	
Are watchman recordin	g rounds?		Υ			
Are there any fire exting	guishers?	Υ	A	re they serviced annually?	Υ	
Are there any hose stat	ions?	N	Is	there a fire private fire brigade?	null	
requency of training re	eceived by the private fire b	rigade:				
Гуре of public fire depa	rtment:	Voluntary	Di	istance:	12 BLC	OCKS
Exposure:						
low many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0			
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):				
s there a body of water	nearby?	Υ	Description	on:	BEAVERHEAD RIVER	₹

1 MILE

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

							. age ee
			Prop	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIV	/ERSITY - NORTHERN			
Property:	Library Building						
Property Address:	MSU-Northern 180 College	e Road West HAVRE					
Property ID:	35						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	31134		
Year built:		1987		Number of stories:	2		
Construction of roof:		Poured Concrete		Construction of floors:	Poured Cond	crete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	Gypsum Boa	ard	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Library				
Provide a brief descripti	on of operations:		University	/ Library			
Storage height of wareh	oused products:		Bookstack	ks 7'			
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N	v	What are the design densities for each area?		n/a	
The water supply for aut	omatic sprinklers is?		н	low many hydrants are located within 500 feet of building	gs?	2	
Indicate the Alarm Cove	rages provided for your fac	cility:	S	Smoke Detectors			
Are alarms connected to	a constantly attended loc	ation?	N	N			
ls there a watchman ser	vice?	Υ	v	What is the frequency of rounds?		every 24 hours	
Are watchman recording	g rounds?		Υ	(			
Are there any fire exting	uishers?	Υ	A	Are they serviced annually?		Υ	
Are there any hose stati	ons?	N	ls	s there a fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:					
Type of public fire depar	rtment:	Paid	D	Distance:		1 mile	
Exposure:							
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water	nearby?	N	Descripti	ion:			
How far is the body of w	ater from major buildings?						
Previous history of flood	ding?	N	Descripti	ion:			
Any property damage lo	sses in the past 3 years:	N	Descripti	ion:			

							Page 38
			Pr	operty Detail Form			
agency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, MO	NTANA TECH OF	THE UM			
Property:	Library Building & Auditor	ium Building (joined)					
roperty Address:	1300 W. Park Street BUT	TE					
roperty ID:	113, 114						
Construction:							
otal number of insured	l buildings:	1		Total square footage of insured buildings:	39013		
ear built:		1977		Number of stories:	2		
Construction of roof:		Other		Construction of floors:	Other		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry		
o major interior mason	nry walls (fire walls) extend	l above the roofline?		null			
Occupancy:							
Occupancy Type:		State U	State University				
Provide a brief description of operations:		Office, I	Office, library, classrooms, stage				
storage height of warehoused products:		N/A					
are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
afegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?		115 psi static, 75 residl	
he water supply for au	tomatic sprinklers is?	Private		How many hydrants are located within 500 feet of building	ıgs?	10	
ndicate the Alarm Coverages provided for your facility:			Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
are alarms connected to	a constantly attended loc	cation?		Υ			
s there a watchman ser	vice?	Υ		What is the frequency of rounds?		2 per shift	
are watchman recording	g rounds?			Υ			
are there any fire exting	juishers?	Υ		Are they serviced annually?		Υ	
are there any hose stati	ons?	N		Is there a fire private fire brigade?		N	
requency of training re	eceived by the private fire b	origade:					
ype of public fire depar	rtment:	Paid		Distance:		0.86 miles	

# **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Ν

Description:

Any property damage losses in the past 3 years: N

Description:

Description:

	Property De	tail Form
UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE (	UNIVERSITY -	BILLINGS
L'honor Olonor an Bullellan		

Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERS
Property:	Library Classroom Building

**Property Address:** 1500 University Drive BILLINGS

Do major interior masonry walls (fire walls) extend above the roofline?

600000882 **Property ID:** 

$\sim$			
-0	nstr		on
		иси	

Total number of insured buildings: 1 Total square footage of insured buildings: 85801

Year built: 3 1968 Number of stories:

**Poured Concrete** Construction of roof: **Poured Concrete** Construction of floors:

Construction of exterior walls: Masonry Construction of interior walls: Masonry

#### Occupancy:

Protection:

**Occupancy Type:** State University

Provide a brief description of operations: education

Storage height of warehoused products: 0

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids:

Ν Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? **Public** How many hydrants are located within 500 feet of buildings? 2

Indicate the Alarm Coverages provided for your facility: Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow

Are alarms connected to a constantly attended location? Υ

Is there a watchman service? Υ What is the frequency of rounds? daily

Are watchman recording rounds?

Are there any fire extinguishers? Are they serviced annually?

Are there any hose stations? Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Type of public fire department: 1 to 2 miles Paid Distance:

#### Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Description: irrigation ditch

How far is the body of water from major buildings? 500

Previous history of flooding? Ν Description:

Description: Any property damage losses in the past 3 years:

Drabar	tu Data	il Form
	IV DETA	

Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S		TY - BOZEMAN		
Property:	LINFIELD HALL					
Property Address:	South 11th Avenue (no offi	cial address) BOZEMAN				
Property ID:	104101					
Construction:						
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	49058	
Year built:		1909		Number of stories:	4	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concre	te
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State University	1		
Provide a brief descriptio	n of operations:		OFFICES/CLAS	SSROOMS/LABS		
Storage height of wareho	used products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ				
Protection:						
Are there any automatic s	sprinklers?	Υ	What a	are the design densities for each area?		
The water supply for auto	omatic sprinklers is?		How m	nany hydrants are located within 500 feet of buildings?		9
Indicate the Alarm Covera	ages provided for your fac	ility:	Smoke	Detectors		
Are alarms connected to	a constantly attended loca	ation?	Υ			
Is there a watchman serv	ice?	Υ	What i	s the frequency of rounds?		AVERAGE 4 PER NIGHT
Are watchman recording	rounds?		N			
Are there any fire extingu	ishers?	Υ	Are the	ey serviced annually?		Υ
Are there any hose statio	ns?	N	Is there	e a fire private fire brigade?		N
Frequency of training rec	eived by the private fire b	rigade:				
Type of public fire depart	ment:	Paid	Distan	ce:		9 MILES
Exposure:						
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water n	earby?	N	Description:			
How far is the body of wa	ter from major buildings?					
Previous history of floodi	ing?	N	Description:			
Any property damage los	ses in the past 3 years:	Y	Description:		12/29/03 WATE SPRINKLER LI	R DAMAGE DUE TO FROZEN NE

						Page 362
			Prope	erty Detail Form		
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, MONTANA S	STATE UNIVE	RSITY - NORTHERN		
Property:	MacKenzie Hall					
Property Address:	MSU-Northern - 1200 Butt	rey Drive South HAVRE				
Property ID:	34					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	43678	
Year built:		1971		Number of stories:	4	
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Door	rs
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Res Apt Cor	mplex		
Provide a brief description	on of operations:		dorm rooms	5		
Storage height of wareho	oused products:		n/a			
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N	Wh	at are the design densities for each area?		
The water supply for aut	omatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?	2	
Indicate the Alarm Cover	rages provided for your fac	cility:	Sm	oke Detectors		
Are alarms connected to	a constantly attended loc	ation?	N			
Is there a watchman serv	vice?	Υ	Wh	at is the frequency of rounds?	every	24 hours
Are watchman recording	rounds?		Υ			
Are there any fire exting	uishers?	Υ	Are	they serviced annually?	Υ	
Are there any hose static	ons?	N	ls t	here a fire private fire brigade?	N	
Frequency of training red	ceived by the private fire b	rigade:				
Type of public fire depar	tment:	Paid	Dis	tance:	1 mile	•
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water	nearby?	N	Description	n:		
How far is the body of wa	ater from major buildings?					
Previous history of flood	ling?	N	Description	n:		
Any property damage los	sses in the past 3 years:	N	Description	1:		

			Property I	Detail Form		
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA ST	TATE UNIVERSIT	Y - BOZEMAN		
Property:	MADISON HALL					
Property Address:	West Garfield (no official ad	ddress) BOZEMAN				
Property ID:	334					
Construction:						
Total number of insured l	ouildings:	1		Total square footage of insured buildings:	30034	
Year built:		1998		Number of stories:	3	
Construction of roof:		Other		Construction of floors:	Poured Concre	ete
Construction of exterior v	walls:	Other		Construction of interior walls:	Gypsum Board	l
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Res Apt Comple	x		
Provide a brief descriptio	n of operations:		STUDENT DOR	M		
Storage height of wareho	used products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A				
Protection:						
Are there any automatic s	sprinklers?	Υ	What ar	e the design densities for each area?		PER NFPA 13
The water supply for auto	omatic sprinklers is?	Public	How ma	any hydrants are located within 500 feet of buildings?		8
Indicate the Alarm Covera	ages provided for your fac	eility:	Sprinkle	r Valve Tamper, Smoke Detectors, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	ation?	Υ			
Is there a watchman serv	ice?	Υ	What is	the frequency of rounds?		3-4 TIMES PER NIGHT
Are watchman recording	rounds?		Υ			
Are there any fire extingu	ishers?	Υ	Are the	y serviced annually?		Υ
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	rigade:				
Type of public fire depart	ment:	Paid	Distanc	e:		1.23 MILES
Exposure:						
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water n	earby?	N	Description:			
How far is the body of wa	ter from major buildings?					
Previous history of floodi	ing?	N	Description:			
Any property damage los	ses in the past 3 years:	N	Description:			

	Property Detail Form
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, GREAT FALLS COLLEGE MONTANA STATE UNIVERSITY
Property:	Main Building
Property Address:	2100 16th Ave S GREAT FALLS

1

1976

Steel Deck

Υ

**Public** 

Paid

Ν

Tilt-Up Concrete

Total square footage of insured buildings:

Number of stories:

COLLEGE SITE/OFFICES/CLASSROOMS

State University

N/A

Υ

0

Description:

Description:

Description:

Construction of floors:

Construction of interior walls:

What are the design densities for each area?

(Motion Detection), Sprinkler Waterflow

What is the frequency of rounds?

Is there a fire private fire brigade?

Are they serviced annually?

Distance:

How many hydrants are located within 500 feet of buildings?

180175

Reinforced Concrete

15SF

hourly

Ν

LOCAL/WITHIN CITY

6

Gypsum Board

2

Burglar Alarms (Beams), Burglar Alarms (Door Contacts), Sprinkler Valve Tamper, Smoke Detectors, Burglar Alarms

Property ID:

Year built:

Occupancy:
Occupancy Type:

Protection:

Construction:

Construction of roof:

Total number of insured buildings:

Construction of exterior walls:

Provide a brief description of operations:

Storage height of warehoused products:

Are there any automatic sprinklers?

Is there a watchman service?

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

Exposure:

Are watchman recording rounds?

Are there any fire extinguishers?

The water supply for automatic sprinklers is?

Indicate the Alarm Coverages provided for your facility:

Are alarms connected to a constantly attended location?

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

850

Do major interior masonry walls (fire walls) extend above the roofline?

Are flammable and combustible liquids stored in a cut-off room?

Safegaurds taken for the storage and dispensing of flammable liquids:

BEAVERHEAD RIVER

						Page 3
			Property	Detail Form		
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSITY	OF MONTANA -	WESTERN		
Property:	Main Hall Building					
Property Address:	710 S. Atlantic DILLON					
Property ID:	1					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	76626	
Year built:		1896		Number of stories:	4	
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			State University			
Provide a brief description of operations:		OFFICES/CLAS	SROOMS			
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for th	ne storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	c sprinklers?	N	What a	re the design densities for each area?		
The water supply for au	utomatic sprinklers is?		How ma	any hydrants are located within 500 feet of buildings?	4	
Indicate the Alarm Cove	erages provided for your fac	cility:				
Are alarms connected t	to a constantly attended loca	ation?	null			
Is there a watchman se	rvice?	Υ	What is	s the frequency of rounds?		
Are watchman recording	ng rounds?		Υ			
Are there any fire exting	guishers?	Υ	Are the	y serviced annually?	Υ	
Are there any hose stat	tions?	N	Is there	e a fire private fire brigade?	null	
Frequency of training re	eceived by the private fire b	rigade:				
Type of public fire depart	artment:	Voluntary	Distanc	ce:	12 BLOCKS	
Exposure:						
How many buildings(no	ot part of Account) are within	n 100 feet of insured buildings?	0			
Describe the Occupano	y of those buildings(s) near	by (within 100 feet):				

Description:

Description:

Description:

1 MILE

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

			Prope	rty Detail Form			
gency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, MONTANA T	ECH OF THE	ИМ			
Property:	Main Hall-H						
roperty Address:	1300 W. Park Street BUTTE	<u> </u>					
Property ID:	103						
Construction:							
otal number of insured	buildings:	1		Total square footage of insured buildings:	37794		
ear built:		1896		Number of stories:	3		
Construction of roof:		Other		Construction of floors:	null		
Construction of exterior	walls:	Other		Construction of interior walls:	null		
o major interior masonr	y walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			State Unive	rsity			
Provide a brief description	on of operations:		Classrooms	& labs			
Storage height of wareho	oused products:		N/A				
are flammable and comb	ustible liquids stored in a c	cut-off room?	N				
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ				
Protection:							
are there any automatic	sprinklers?	N	Wh	at are the design densities for each area?			
he water supply for auto	omatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?		6	
ndicate the Alarm Cover	ages provided for your faci	lity:	Sm	oke Detectors			
are alarms connected to	a constantly attended loca	tion?	Υ				
s there a watchman serv	rice?	Υ	Wh	at is the frequency of rounds?		2 per shift	
are watchman recording	rounds?		Υ				
are there any fire extingu	iishers?	Υ	Are	they serviced annually?		Υ	
are there any hose statio	ons?	N	ls t	here a fire private fire brigade?		N	
requency of training rec	eived by the private fire br	gade:					
ype of public fire depart	ment:	Paid	Dis	tance:		0.86 miles	
xposure:							

## Haw many

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Description:

How far is the body of water from major buildings?

Is there a body of water nearby?

Previous history of flooding? N Description:

Any property damage losses in the past 3 years:  $\,\,$  N  $\,\,$  Description:

Ν

							Page 367
			Pro	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / I	JNIVERSITY SYSTEM, UNIVI	ERSITY OF MONT	ANA - MISSOULA			
Property:	Mansfield Library						
Property Address:	910 McLeod Avenue MISS	SOULA					
Property ID:	92						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	216157		
Year built:		1973		Number of stories:	3		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
Oo major interior mason	ry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State Uni	versity			
Provide a brief descripti	on of operations:		null				
Storage height of wareh	oused products:		null				
Are flammable and com	bustible liquids stored in a	cut-off room?	null				
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	Υ	V	What are the design densities for each area?		null	
The water supply for au	tomatic sprinklers is?		ŀ	How many hydrants are located within 500 feet of buildir	ıgs?	null	
ndicate the Alarm Cove	rages provided for your fa	cility:					
Are alarms connected to	a constantly attended loc	ation?	r	null			
s there a watchman ser	vice?	null	V	What is the frequency of rounds?		null	
Are watchman recording	g rounds?						
Are there any fire exting	uishers?	null	A	Are they serviced annually?		null	
Are there any hose stati	ons?	null	I:	s there a fire private fire brigade?		null	
requency of training re	ceived by the private fire b	origade:	r	null			
Гуре of public fire depar	rtment:	null	Γ	Distance:		null	
Exposure:							
	t part of Account) are withi	in 100 feet of insured buildin	gs?				
Describe the Occupancy	of those buildings(s) nea	rby (within 100 feet):	null				
s there a body of water	nearby?	null	Descript	ion:	null		

null

Description:

Description:

null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

			Property D	Petail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVERSIT	/ - BOZEMAN		
Property:	MARGA HOSAEUS FITNE	SS CENTER				
Property Address:	West Grant Street (no offic	ial address) BOZEMAN				
Property ID:	123					
Construction:						
Total number of insured l	buildings:	1		Total square footage of insured buildings:	165090	
Year built:		1973		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Co	ncrete
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Masonry w/ Fi	re Doors
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State University			
Provide a brief descriptio	n of operations:		OFFICES/CLASS	ROOMS/GYM/MULTI-CARE CENTER/POOL		
Storage height of wareho	used products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A				
Protection:						
Are there any automatic s	sprinklers?	Υ	What are	the design densities for each area?		PER NFPA 13 BASEMENT ONLY
The water supply for auto	omatic sprinklers is?	Public	How ma	ny hydrants are located within 500 feet of buildings?		6
Indicate the Alarm Covera	ages provided for your fac	ility.	Sprinkler	Waterflow, Smoke Detectors, Sprinkler Valve Tamper		
	agos protraca for your fac	anty.		Tratement, emone Betestere, epinnaer vario ramper		
	a constantly attended loca	-	Υ	Tracemon, emote Beleaters, epininal valve rampor		
	a constantly attended loca	-	•	the frequency of rounds?		AVERAGE 4 PER NIGHT
Are alarms connected to	a constantly attended loca	ation?	•	·		AVERAGE 4 PER NIGHT
Are alarms connected to Is there a watchman serv	a constantly attended localice?	ation?	What is	·		AVERAGE 4 PER NIGHT
Are alarms connected to Is there a watchman serv Are watchman recording	a constantly attended localice? rounds? iishers?	ation?	What is N Are they	the frequency of rounds?		
Are alarms connected to Is there a watchman serv Are watchman recording Are there any fire extingu Are there any hose statio	a constantly attended localice? rounds? iishers?	Y Y N	What is N Are they	the frequency of rounds? serviced annually?		Υ
Are alarms connected to Is there a watchman serv Are watchman recording Are there any fire extingu Are there any hose statio	a constantly attended localice? rounds? sishers? ns? seived by the private fire be	Y Y N	What is N Are they	the frequency of rounds? serviced annually? a fire private fire brigade?		Υ
Are alarms connected to Is there a watchman servi Are watchman recording Are there any fire extingu Are there any hose statio Frequency of training rec	a constantly attended localice? rounds? sishers? ns? seived by the private fire be	ation? Y Y N rigade:	What is N Are they Is there	the frequency of rounds? serviced annually? a fire private fire brigade?		Y N
Are alarms connected to Is there a watchman serving Are watchman recording Are there any fire extingulare there any hose station Frequency of training recording training recording to public fire depart Exposure:	a constantly attended localice? rounds? sishers? ns? seived by the private fire butter.	ation? Y Y N rigade:	What is N Are they Is there	the frequency of rounds? serviced annually? a fire private fire brigade?		Y N
Are alarms connected to Is there a watchman serv Are watchman recording Are there any fire extingu Are there any hose statio Frequency of training recording type of public fire depart Exposure:  How many buildings(not	a constantly attended localice? rounds? sishers? ns? seived by the private fire butter.	Y Y N rigade: Paid 100 feet of insured buildings?	What is N Are they Is there	the frequency of rounds? serviced annually? a fire private fire brigade?		Y N
Are alarms connected to Is there a watchman serv Are watchman recording Are there any fire extingu Are there any hose statio Frequency of training recording type of public fire depart Exposure:  How many buildings(not	a constantly attended localice? rounds? sishers? ns? seived by the private fire be ment: part of Account) are within of those buildings(s) near	Y Y N rigade: Paid 100 feet of insured buildings?	What is N Are they Is there	the frequency of rounds? serviced annually? a fire private fire brigade?		Y N
Are alarms connected to Is there a watchman serving Are watchman recording Are there any fire extingulare there any hose station Frequency of training recording training recording for public fire depart Exposure:  How many buildings(not poscribe the Occupancy Is there a body of water not provided to the poscribe the Occupancy Is there a body of water not provided to the provided	a constantly attended localice? rounds? sishers? ns? seived by the private fire be ment: part of Account) are within of those buildings(s) near	Y  Y  N  rigade:  Paid  100 feet of insured buildings?  by (within 100 feet):  N	What is a N Are they Is there	the frequency of rounds? serviced annually? a fire private fire brigade?		Y N
Are alarms connected to Is there a watchman serving Are watchman recording Are there any fire extingulare there any hose station Frequency of training recording training recording for public fire depart Exposure:  How many buildings(not poscribe the Occupancy Is there a body of water not provided to the poscribe the Occupancy Is there a body of water not provided to the provided	a constantly attended localice? rounds? sishers? ns? seived by the private fire be ment: part of Account) are within of those buildings(s) near searby? ster from major buildings?	Y  Y  N  rigade:  Paid  100 feet of insured buildings?  by (within 100 feet):  N	What is a N Are they Is there	the frequency of rounds? serviced annually? a fire private fire brigade?		Y N

			Pro	perty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNI	VERSITY - BOZEMAN		
Property:	MARSH LABORATORY					
Property Address:	1911 WEST LINCOLN STR	REET BOZEMAN				
Property ID:	116					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	31013	
Year built:		1961		Number of stories:	1	
Construction of roof:		Other		Construction of floors:	Reinforced Co	oncrete
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Boar	d
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Laborato	ry		
Provide a brief descript	tion of operations:		OFFICES	S/LABS		
Storage height of warel	housed products:		N/A			
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for th	ne storage and dispensing of	f flammable liquids:	Υ			
Protection:						
Are there any automati	c sprinklers?	Υ	,	What are the design densities for each area?		
The water supply for au	tomatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?	•	3
Indicate the Alarm Cov	erages provided for your fac	ility:	5	Smoke Detectors, Burglar Alarms (Door Contacts)		
Are alarms connected t	o a constantly attended loca	ation?	•	Y		
Is there a watchman se	rvice?	Υ	,	What is the frequency of rounds?		AVERAGE 4 PER NIGHT
Are watchman recording	g rounds?		1	N		
Are there any fire exting	guishers?	Υ	1	Are they serviced annually?		Υ
Are there any hose stat	ions?	N	ı	s there a fire private fire brigade?		N
Frequency of training r	eceived by the private fire b	rigade:				
Type of public fire depart	artment:	Paid	I	Distance:		.79 MILES
Exposure:						
How many buildings(no	ot part of Account) are withir	n 100 feet of insured buildings?	0			
Describe the Occupand	y of those buildings(s) near	by (within 100 feet):				
Is there a body of water	r nearby?	N	Descript	ion:		
How far is the body of	water from major buildings?					
Previous history of floo	oding?	N	Descript	ion:		
Any property damage le	osses in the past 3 years:	Y	Descript	ion:	11/4/03 WATE SPRINKLER	ER DAMAGE DUE TO FROZEN LINE

							Page 370
			Pro	pperty Detail Form			
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MISSOULA			
Property:	Mathematics						
Property Address:	1255 Mansfield Avenue MIS	SOULA					
Property ID:	003						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	21390		
Year built:		1903		Number of stories:	3		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
Do major interior masonr	y walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			State Un	niversity			
Provide a brief description	on of operations:		null				
Storage height of wareho	oused products:		null				
Are flammable and comb	ustible liquids stored in a c	ut-off room?	null				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?		null	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings	?	null	
ndicate the Alarm Cover	ages provided for your facil	lity:					
Are alarms connected to	a constantly attended locat	ion?		null			
s there a watchman serv	rice?	null		What is the frequency of rounds?		null	
Are watchman recording	rounds?						
Are there any fire extingu	uishers?	null		Are they serviced annually?		null	
Are there any hose statio	ons?	null		Is there a fire private fire brigade?		null	
requency of training rec	eived by the private fire bri	gade:		null			
Type of public fire depart	ment:	null		Distance:		null	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?					

Description: Is there a body of water nearby?

null

How far is the body of water from major buildings?

Previous history of flooding? null

Any property damage losses in the past 3 years:

Description:

null

null

Description: null

null

							Page :
			Р	roperty Detail Form			
Agency:	UNIVERSITY SYSTEM	/ UNIVERSITY SYSTEM, UNIVERSIT	Y OF MOI	NTANA - WESTERN			
Property:	Matthews Hall						
Property Address:	710 S. Atlantic DILLON						
Property ID:	6						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	66091		
Year built:		1919		Number of stories:	3		
Construction of roof:		Wood Joists		Construction of floors:	Poured Concre	ete	
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Masonry		
Do major interior maso	onry walls (fire walls) exter	nd above the roofline?		Υ			
Occupancy:							
Occupancy Type:			Res Ap	ot Complex			
Provide a brief descrip	tion of operations:		DORM	S/FOOD SERVICE/MEETING ROOMS			
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	he storage and dispensing	of flammable liquids:	N/A				
Protection:							
Are there any automati	c sprinklers?	Υ		What are the design densities for each area?			
The water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings	.?	4	
Indicate the Alarm Cov	erages provided for your	facility:		Smoke Detectors			
Are alarms connected	to a constantly attended lo	ocation?		Υ			
Is there a watchman se	ervice?	Υ		What is the frequency of rounds?		HOUR	
Are watchman recording	ng rounds?			Υ			
Are there any fire extin	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose sta	tions?	N		Is there a fire private fire brigade?		null	
Frequency of training i	received by the private fire	brigade:					
Type of public fire dep	artment:	Voluntary		Distance:		12 BLOCKS	
Exposure:							
How many buildings(n	ot part of Account) are wit	hin 100 feet of insured buildings?	0				
Describe the Occupant	cy of those buildings(s) ne	earby (within 100 feet):					
Is there a body of wate	r nearby?	Υ	Descri	ption:	BEAVERHEAD	O RIVER	

1 MILE

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

null

			Proper	ty Detail Form				
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVER	SITY - BOZEMAN				
Property:	MCCALL HALL							
Property Address:	South11th Avenue (no offic	cial address) BOZEMAN						
Property ID:	112							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	10528			
Year built:		1952		Number of stories:	1			
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Con	ncrete		
Construction of exterior v	valls:	Masonry		Construction of interior walls:	Gypsum Board			
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N				
Occupancy:								
Occupancy Type:			Laboratory					
Provide a brief description	n of operations:		OFFICES & I	OFFICES & LABS				
Storage height of warehoused products:		N/A	J/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:			Υ					
Protection:								
Are there any automatic s	prinklers?	N	Wha	at are the design densities for each area?				
The water supply for auto	matic sprinklers is?		How	many hydrants are located within 500 feet of buildings?		7		
Indicate the Alarm Covera	iges provided for your faci	ility:						
Are alarms connected to	a constantly attended loca	ition?	N					
ls there a watchman servi	ce?	Υ	Wha	at is the frequency of rounds?		AVERAGE 4 PER WEEK		
Are watchman recording	rounds?		N					
Are there any fire extingu	ishers?	Υ	Are	they serviced annually?		Υ		
Are there any hose station	ns?	N	ls th	ere a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire departi	ment:	Paid	Dista	ance:		1.09 MILES		
Exposure:								
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	earby?	N	Description:	:				
How far is the body of wa	ter from major buildings?							
Previous history of floodi	ng?	N	Description:	:				
Any property damage los	ses in the past 3 years:	N	Description:	:				

						Page 3
			Proper	ty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, UNIVERSIT	TY OF MONTANA	A - MISSOULA		
Property:	McGill Hall					
Property Address:	920 Van Buren Street MIS	SOULA				
Property ID:	21					
Construction:						
Total number of insured I	buildings:	1		Total square footage of insured buildings:	66158	
Year built:		1953		Number of stories:	2	
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete	
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State Univers	sity		
Provide a brief descriptio	on of operations:		Offices/classr	rooms		
Storage height of wareho	oused products:		0			
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic s	sprinklers?	N	Wha	t are the design densities for each area?		
The water supply for auto	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings	<b>?</b> 1	
ndicate the Alarm Cover	ages provided for your fac	cility:	Smo	ke Detectors		

Υ Are alarms connected to a constantly attended location?

Is there a watchman service? What is the frequency of rounds? Campus police 24/7

Are watchman recording rounds?

Are there any fire extinguishers? Are they serviced annually?

Are there any hose stations? Ν Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: under 1 mile

Is there a body of water nearby?

Exposure:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How many buildings(not part of Account) are within 100 feet of insured buildings?

Description:

blank

How far is the body of water from major buildings?

Ν

Previous history of flooding? Ν Description: Any property damage losses in the past 3 years:

	Property Detail Form
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BILLINGS
Property:	McMullen Hall
Property Address:	1500 University Drive BILLINGS

1

1935

Wood Joists

Υ

Ν

Paid

Ν

**Public** 

Masonry

Total square footage of insured buildings:

Number of stories:

State University

Υ

Distance:

education

0

0

Description:

Description:

Description:

200 feet

N/A

Construction of floors:

Construction of interior walls:

What are the design densities for each area?

What is the frequency of rounds?

Is there a fire private fire brigade?

Are they serviced annually?

How many hydrants are located within 500 feet of buildings?

Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow

53891

Masonry

**Poured Concrete** 

2

daily

Ν

irrigation ditch

1 to 2 miles

6

600000896/897

Do major interior masonry walls (fire walls) extend above the roofline?

Are flammable and combustible liquids stored in a cut-off room?

Safegaurds taken for the storage and dispensing of flammable liquids:

Property ID:

Construction:

Year built:

Occupancy:
Occupancy Type:

Protection:

Exposure:

Construction of roof:

Total number of insured buildings:

Construction of exterior walls:

Provide a brief description of operations:

Storage height of warehoused products:

Are there any automatic sprinklers?

Is there a watchman service?

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

Are watchman recording rounds?

Are there any fire extinguishers?

The water supply for automatic sprinklers is?

Indicate the Alarm Coverages provided for your facility:

Are alarms connected to a constantly attended location?

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

			Prope	erty Detail Form				
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - NORTHERN							
Property:	Metals Technology Building							
Property Address:	MSU-Northern - 100 College	e Road East HAVRE						
Property ID:	5							
Construction:								
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	11211			
Year built:		1944		Number of stories:	1			
Construction of roof:		Other		Construction of floors:	Poured Concre	ete		
Construction of exterior v	valls:	Other		Construction of interior walls:	Gypsum Board	d		
Do major interior masonry	y walls (fire walls) extend a	bove the roofline?		N				
Occupancy:								
Occupancy Type:			Laboratory					
Provide a brief description	n of operations:		labs					
Storage height of wareho	used products:		n/a	n/a				
Are flammable and combustible liquids stored in a cut-off room?			N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic s	prinklers?	N	Wł	hat are the design densities for each area?		n/a		
The water supply for auto	matic sprinklers is?		Но	ow many hydrants are located within 500 feet of buildings?	1	2		
Indicate the Alarm Covera	ages provided for your faci	lity:						
Are alarms connected to	a constantly attended loca	tion?	N					
Is there a watchman servi	ce?	Υ	What is the frequency of rounds?			Every 24 hours		
Are watchman recording	rounds?		Υ					
Are there any fire extingu	ishers?	Υ	Arc	e they serviced annually?		Υ		
Are there any hose station	ns?	N	Is	there a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire bri	igade:						
Type of public fire departs	ment:	Paid	Dis	stance:		1 mile		
Exposure:								
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearb	y (within 100 feet):						
Is there a body of water n	earby?	N	Description	n:				
How far is the body of wa	ter from major buildings?							
Previous history of floodi	ng?	N	Description	n:				
Any property damage los	ses in the past 3 years:	N	Description	n:				

							Page 37
			Pı	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, MONTANA T	ECH OF	THE UM			
Property:	MGMB Billings Office						
Property Address:	107 Grand Ave. BILLINGS						
Property ID:							
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	6026		
Year built:		1984		Number of stories:	2		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
Oo major interior mason	ry walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			Office				
Provide a brief description	on of operations:		blank				
Storage height of wareho	oused products:		blank				
Are flammable and comb	oustible liquids stored in a c	ut-off room?	null				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?			
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		blank	
ndicate the Alarm Cover	ages provided for your faci	lity:		blank			
Are alarms connected to	a constantly attended locat	ion?		null			
s there a watchman serv	vice?	null		What is the frequency of rounds?			
Are watchman recording	rounds?						
Are there any fire exting	uishers?	null		Are they serviced annually?		null	
Are there any hose station	ons?	null		Is there a fire private fire brigade?		null	
requency of training red	ceived by the private fire bri	gade:					
Гуре of public fire depar	tment:	null		Distance:		blank	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Ossumeney	of these buildings(s) nearb	v /within 100 foot).					

Is there a body of water nearby? null Description:

How far is the body of water from major buildings?

Previous history of flooding?

null Any property damage losses in the past 3 years: null

Description:

						- 3	
			Proper	rty Detail Form			
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, MONTANA T	ECH OF THE	UM			
Property:	Mill Building-H						
Property Address:	1300 W. Park Street BUTTE	<u> </u>					
Property ID:	109						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	16813		
Year built:		1908		Number of stories:	2		
Construction of roof:		Other		Construction of floors:	null		
Construction of exterior	walls:	Other		Construction of interior walls:	null		
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		null			
Occupancy:							
Occupancy Type:			State Univers	sity			
Provide a brief description of operations:			Bookstore &	study			
Storage height of warehoused products:			N/A				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	Υ	Wha	at are the design densities for each area?		101 psi static 45 residul	
The water supply for auto	omatic sprinklers is?	Private	How	many hydrants are located within 500 feet of buildings	?	7	
Indicate the Alarm Cover	ages provided for your faci	ility:	Spri	Sprinkler Waterflow, Fire Pump Alarms, Smoke Detectors, Sprinkler Valve Tamper			
Are alarms connected to	a constantly attended loca	tion?	Υ				
Is there a watchman serv	ice?	Υ	Wha	at is the frequency of rounds?		2 per shift	
Are watchman recording	rounds?		Υ				
Are there any fire extingu	iishers?	Υ	Are	they serviced annually?		null	
Are there any hose statio	ons?	N	Is th	nere a fire private fire brigade?		N	
Frequency of training red	eived by the private fire br	igade:					
Type of public fire depart	ment:	Paid	Dist	ance:		0.86 miles	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):					

Description:

Description:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Ν

							- 3
			Pro	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UN	IVERSITY - BOZEMAN			
Property:	MILLER DINING HALL						
Property Address:	West Grant Street (no offic	ial address) BOZEMAN					
Property ID:	341						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	53505		
Year built:		1964		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	<sup>-</sup> d	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State Ur	niversity			
Occupancy Type: Provide a brief description of operations: Storage height of warehoused products: Are flammable and combustible liquids stored in a cut-off room?			FOOD S	SERVICE/CONFRENCE ROOMS			
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A					
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?		PER NFPA 13	
The water supply for auto	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	?	9	
ndicate the Alarm Cover	ages provided for your fac	ility:		Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected to	a constantly attended loca	ation?		Υ			
s there a watchman serv	rice?	N		What is the frequency of rounds?			
Are watchman recording	rounds?			N			
Are there any fire extingu	uishers?	Υ		Are they serviced annually?		Υ	
Are there any hose static	ons?	N		Is there a fire private fire brigade?		N	
requency of training red	ceived by the private fire b	rigade:					
Гуре of public fire depart	tment:	Paid		Distance:		.97 MILES	
Exposure:							
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
s there a body of water r	nearby?	N	Descrip	otion:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Descrip	otion:			
Any property damage los	sses in the past 3 years:	N	Descrip	otion:			

			Pr	operty D	etail Form		
Agency:	UNIVERSITY SYSTEM / UNIVERSITY / UNIVERSITY SYSTEM / UNIVERSITY SYSTEM / UNIVERSITY / UNIVERSITY / UNIVERSITY / UNIVERSITY / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - M	IISSOULA		
Property:	Miller Hall						
Property Address:	1330 Arthur Avenue MISSC	DULA					
Property ID:	108						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	84615	
Year built:		1965			Number of stories:	5	
Construction of roof:		Steel Deck			Construction of floors:	Poured Concre	ete
Construction of exterior w	valls:	Masonry			Construction of interior walls:	Gypsum Board	i
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			N		
Occupancy:							
Occupancy Type:			State U	niversity			
Provide a brief description	n of operations:		Dorm				
Storage height of warehoused products:			0				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	sprinklers?	Υ		What are	the design densities for each area?		0.1
The water supply for auto	matic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?		2
Indicate the Alarm Covera	ages provided for your faci	ility:	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow				
Are alarms connected to a	a constantly attended loca	ition?		Υ			
Is there a watchman servi	ice?	Υ		What is t	the frequency of rounds?		Campus police
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose station	ns?	N		Is there a	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	rigade:					
Type of public fire departs	ment:	Paid		Distance	:		under 1 mile
Exposure:							
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) nearb	by (within 100 feet):					
Is there a body of water n	earby?	N	Descrip	otion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descrip	otion:			
Any property damage los	ses in the past 3 years:	N	Descrip	otion:			

					etail Form			
Agency:		NIVERSITY SYSTEM, MONTANA ST	TATE UNI\	VERSITY	- BOZEMAN			
Property:	MILLER PAVILION							
Property Address:	West of South 19th Avenue	e & Lincoln Street BOZEMAN						
Property ID:	432							
Construction:								
Total number of insured l	buildings:	1			Total square footage of insured buildings:	23286		
fear built:		1968			Number of stories:	1		
Construction of roof:		Steel Deck			Construction of floors:	Poured Concr	rete	
Construction of exterior v	walls:	Corrugated Metal Panel			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			N			
Occupancy:								
Occupancy Type:			Other					
Provide a brief description	on of operations:		Livestock	event ce	enter			
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	N	V	What are	the design densities for each area?		no sprinklers	
The water supply for auto	omatic sprinklers is?		H	How man	y hydrants are located within 500 feet of buildings?	•	1	
ndicate the Alarm Cover	ages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	tion?	١	N				
s there a watchman serv	rice?	N	V	What is tl	he frequency of rounds?			
Are watchman recording	rounds?		١	N				
Are there any fire extingu	iishers?	Υ	A	Are they	serviced annually?		Υ	
Are there any hose statio	ns?	N	l:	s there a	fire private fire brigade?		N	
requency of training rec	eived by the private fire br	igade:						
Гуре of public fire depart	ment:	Paid		Distance:	:		2.25 miles	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):						
s there a body of water n	nearby?	N	Descript	ion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descript	ion:				
Any property damage los	ses in the past 3 years:	N	Descript	ion:				

							Page 38
			P	roperty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA T	TECH OF	THE UM			
Property:	Mining Geology Building (M	1&G)					
Property Address:	1300 W. Park Street BUTT	E					
Property ID:	115						
Construction:							
Total number of insured	l buildings:	1		Total square footage of insured buildings:	39536		
Year built:		1972		Number of stories:	4		
Construction of roof:		Other		Construction of floors:	Other		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	d	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State U	Iniversity			
Provide a brief description of operations:			Offices	, classrooms, labs			
Storage height of warehoused products:			N/a				
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	Υ				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	ı	8	
Indicate the Alarm Cove	rages provided for your fac	ility:		Smoke Detectors			
Are alarms connected to	o a constantly attended loca	ation?		Υ			
Is there a watchman ser	vice?	Υ		What is the frequency of rounds?		2 per shift	
Are watchman recording	g rounds?			Υ			
Are there any fire exting	uishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:					
Type of public fire depart	rtment:	Paid		Distance:		0.86 miles	
Exposure:							
How many buildings(no	t part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):					
Is there a body of water	nearby?	N	Descri	ption:			

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

			Pı	roperty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, GREAT FALL	S COLLI	EGE MONTANA STATE UNIVERSITY		
Property:	Mobile Welding Lab					
Property Address:	2100 16th Ave S GREAT F	ALLS				
Property ID:						
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	315	
Year built:		2015		Number of stories:	1	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			Trailer			
Provide a brief description	on of operations:		blank			
Storage height of wareho	used products:		blank			
Are flammable and comb	ustible liquids stored in a	cut-off room?	null			
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings	?	blank
Indicate the Alarm Cover	ages provided for your fac	ility:		blank		
Are alarms connected to	a constantly attended loca	ition?		null		
ls there a watchman serv	ice?	null		What is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire extingu	ishers?	null		Are they serviced annually?		null
Are there any hose statio	ns?	null		Is there a fire private fire brigade?		null
Frequency of training rec	eived by the private fire b	igade:				
Type of public fire depart	ment:	null		Distance:		blank
Exposure:						
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	blank			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water r	nearby?	null	Descri	ption:		
How far is the body of wa	ater from major buildings?					
Previous history of flood	ing?	null	Descri	ption:		
Any property damage los	ses in the past 3 years:	null	Descri	ption:		

	Property Detail Form
UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE	UNIVERSITY - BOZEMAN
MONTANA HALL	
West Garfield (no official address) BOZEMAN	

Property	ID:	101

## Construction:

Occupancy: **Occupancy Type:** 

Year built:

**Property Address:** 

Construction of roof:

Agency: Property:

Total number of insured buildings: 1

1896

Construction of exterior walls: Masonry

Do major interior masonry walls (fire walls) extend above the roofline?

Wood Joists

Office

N/A

Provide a brief description of operations: **OFFICES** 

Storage height of warehoused products:

Ν

Υ

Ν

Paid

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids: N/A

## Protection: Are there any automatic sprinklers?

The water supply for automatic sprinklers is?

Indicate the Alarm Coverages provided for your facility:

Are alarms connected to a constantly attended location? Is there a watchman service?

Are watchman recording rounds?

Are there any fire extinguishers?

Are there any hose stations?

Frequency of training received by the private fire brigade:

Type of public fire department: Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Is there a body of water nearby? Ν How far is the body of water from major buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Previous history of flooding?

Any property damage losses in the past 3 years:

Ν

Description:

0

Description: 3/25/03 WATER DAMAGE DUE TO FROZEN

How many hydrants are located within 500 feet of buildings? 5 Smoke Detectors

Total square footage of insured buildings:

Number of stories:

Construction of floors:

Construction of interior walls:

What are the design densities for each area?

40989

Wood Timber

Gypsum Board

**AVERAGE 4 PER NIGHT** 

Υ

Ν

SPRINKLER LINE

**1.18 MILES** 

What is the frequency of rounds?

Are they serviced annually?

Is there a fire private fire brigade?

Distance:

							Page 384	
			Pro	pperty Detail Form				
Agency:	UNIVERSITY SYSTEM / I	JNIVERSITY SYSTEM, MONTANA S	STATE UNI	VERSITY - NORTHERN				
Property:	Morgan Hall							
Property Address:	MSU-Northern - 1110 But	rey Drive HAVRE						
Property ID:	12							
Construction:								
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	48872			
Year built:		1957		Number of stories:	3			
Construction of roof:		Other		Construction of floors:	Reinforced C	oncrete		
Construction of exteri	or walls:	Other		Construction of interior walls:	Gypsum Boa	rd		
Do major interior mas	onry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:		Res Apt	Complex					
Provide a brief description of operations:		student o	udent dorm					
Storage height of warehoused products:		n/a						
Are flammable and co	Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automat	cic sprinklers?	N		What are the design densities for each area?		n/a		
The water supply for a	utomatic sprinklers is?			How many hydrants are located within 500 feet of building	s?	2		
Indicate the Alarm Co	verages provided for your fa	cility:	Smoke Detectors					
Are alarms connected	to a constantly attended loc	ation?		N				
Is there a watchman s	ervice?	Υ		What is the frequency of rounds?		every 24 hours		
Are watchman recordi	ng rounds?			Υ				
Are there any fire exti	nguishers?	Υ		Are they serviced annually?		Υ		
Are there any hose sta	ations?	N		Is there a fire private fire brigade?		N		
Frequency of training	received by the private fire b	rigade:						
Type of public fire dep	partment:	Paid		Distance:		1 mile		
Exposure:								
How many buildings(r	not part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupan	cy of those buildings(s) nea	rby (within 100 feet):						
Is there a body of water	er nearby?	N	Descrip	tion:				
How far is the body of	water from major buildings?	•						
Previous history of flo	oding?	N	Descrip	tion:				
Any property damage	losses in the past 3 years:	N	Descrip	tion:				

						- 3
			Pr	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA TE	ECH OF	THE UM		
Property:	Museum Building-H					
Property Address:	1300 W. Park Street BUTT	E				
Property ID:	104					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	28194	
Year built:		1940		Number of stories:	3	
Construction of roof:		Other		Construction of floors:	null	
Construction of exterior	walls:	Masonry		Construction of interior walls:	null	
Do major interior masonr	ry walls (fire walls) extend a	above the roofline?		null		
Occupancy:						
Occupancy Type:			Museun	n		
Provide a brief description of operations:			Classro	oms, museum		
Storage height of warehoused products:			N/A			
Are flammable and combustible liquids stored in a cut-off room?		N				
Safegaurds taken for the storage and dispensing of flammable liquids:		flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?		
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		6
Indicate the Alarm Cover	ages provided for your fac	ility:		Smoke Detectors		
Are alarms connected to	a constantly attended loca	ition?		Υ		
Is there a watchman serv	rice?	Υ		What is the frequency of rounds?		2 per shift
Are watchman recording	rounds?					
Are there any fire extingu	uishers?	null		Are they serviced annually?		null
Are there any hose statio	ons?	null		Is there a fire private fire brigade?		null
Frequency of training red	ceived by the private fire br	igade:				
Type of public fire depart	tment:	Paid		Distance:		0.86 miles
Exposure:						
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):				
Is there a body of water r	nearby?	N	Descrip	otion:		

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

4/2002 WATER DAMAGE DUE TO FROZEN SPRINKLER LINE

					Page 3		
			Prop	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, MONTANA S	STATE UNIV	/ERSITY - BOZEMAN			
Property:	MUSEUM OF THE ROCK	ES					
Property Address:	600 KAGY BOULEVARD I	BOZEMAN					
Property ID:	121						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	103408		
Year built:		1987		Number of stories:	3		
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete		
Construction of exterio	or walls:	Wood Frame		Construction of interior walls:	Masonry w/ Fire Doors		
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:		Museum					
Provide a brief description of operations:			PUBLIC N	MUSEUM & DISPLAYS			
Storage height of warehoused products:			N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ					
Protection:							
Are there any automati	c sprinklers?	Υ	v	Vhat are the design densities for each area?	PER NFPA 13		
The water supply for a	utomatic sprinklers is?	Public	н	low many hydrants are located within 500 feet of buildings?	? 4		
Indicate the Alarm Cov	erages provided for your fac	cility:	B V	Burglar Alarms (Door Contacts), Sprinkler Waterflow, Burglar Alarms (Motion Detection), Smoke Detectors, Sprin Valve Tamper			
Are alarms connected	to a constantly attended loc	ation?	Y	′			
Is there a watchman se	ervice?	Υ	v	What is the frequency of rounds?	HOURLY		
Are watchman recording	ng rounds?		N	N			
Are there any fire extin	guishers?	Υ	A	Are they serviced annually?	Υ		
Are there any hose sta	tions?	N	ls	s there a fire private fire brigade?	N		
Frequency of training r	eceived by the private fire b	rigade:					
Type of public fire dep	artment:	Paid	D	Distance:	1.85 MILES		
Exposure:							
How many buildings(ne	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupand	cy of those buildings(s) near	by (within 100 feet):					
Is there a body of water	r nearby?	N	Descripti	ion:			
How far is the body of	water from major buildings?						

Description:

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: Y

Ν

								- 3
			Pr	operty D	etail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSIT	Y OF MON	ITANA - M	IISSOULA			
Property:	Music Hall							
Property Address:	930 Maurice Avenue MISS	SOULA						
Property ID:	018							
Construction:								
Total number of insure	d buildings:	1			Total square footage of insured buildings:	41046		
Year built:		1953			Number of stories:	2		
Construction of roof:		Poured Concrete			Construction of floors:	Poured Concr	rete	
Construction of exterio	r walls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonry walls (fire walls) extend above the roofline?				N				
Occupancy:								
Occupancy Type:			State U	niversity				
Provide a brief description of operations:		Offices.	classroom	s				
Storage height of warehoused products:		0						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automati	c sprinklers?	N		What are	the design densities for each area?		no sprinklers	
The water supply for au	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?			3	
Indicate the Alarm Cov	erages provided for your fa	cility:	Smoke Detectors					
Are alarms connected t	o a constantly attended loc	ation?		Υ				
Is there a watchman se	rvice?	Υ		What is t	he frequency of rounds?		Campus police 24/7	
Are watchman recordir	g rounds?			Υ				
Are there any fire extin	guishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stat	ions?	N		Is there a	a fire private fire brigade?		N	
Frequency of training r	eceived by the private fire b	rigade:						
Type of public fire depart	artment:	Paid		Distance	:		under 1 mile	
Exposure:								
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupano	y of those buildings(s) nea	rby (within 100 feet):						
Is there a body of water	r nearby?	N	Descrip	tion:				
How far is the body of	water from major buildings?	?						
Previous history of floo	oding?	N	Descrip	tion:				
Any property damage l	osses in the past 3 years:	N	Descrip	tion:				

	Property Detail Form									
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MSU, AGRICU	JLTURAI	L EXPERIMENT STATION						
Property:	NARC Feed Bin 3340 Whe	atland								
Property Address:	3711 Assinniboine Rd. HAV	/RE								
Property ID:										
Construction:										
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	601					
Year built:		1994		Number of stories:	1					
Construction of roof:		null		Construction of floors:	null					
Construction of exterior w	valls:	null		Construction of interior walls:	null					
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		null						
Occupancy:										
Occupancy Type:			Granary	/						
Provide a brief description	n of operations:		blank							
Storage height of wareho	used products:		blank							
Are flammable and combi	ustible liquids stored in a	cut-off room?	null							
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null							
Protection:										
Are there any automatic s	prinklers?	N		What are the design densities for each area?						
The water supply for auto	matic sprinklers is?			How many hydrants are located within 500 feet of building	ıs?	blank				
Indicate the Alarm Covera	ges provided for your fac	ility:	blank							
Are alarms connected to	a constantly attended loca	tion?		null						
Is there a watchman servi	ce?	null		What is the frequency of rounds?						
Are watchman recording	rounds?									
Are there any fire extingu	ishers?	null		Are they serviced annually?		null				
Are there any hose station	ns?	null		Is there a fire private fire brigade?		null				
Frequency of training rec	eived by the private fire br	igade:								
Type of public fire departs	ment:	null		Distance:		blank				
Exposure:										
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	blank							
Describe the Occupancy	of those buildings(s) near	oy (within 100 feet):								
Is there a body of water n	earby?	null	Descrip	otion:						
How far is the body of wa	ter from major buildings?									
Previous history of floodi	ng?	null	Descrip	otion:						
Any property damage los	ses in the past 3 years:	null	Descrip	otion:						

								Page 3
			Р	operty Detail Form				
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, UNIVERSIT	Y OF MO	ITANA - MISSOULA				
Property:	Native American Center (Pa	ayne Family)						
Property Address:	1210 Maurice MISSOULA							
Property ID:	44							
Construction:								
Γotal number of insure	d buildings:	1		Total square footage of	insured buildings:	28194		
Year built:		2010		Number of stories:		2		
Construction of roof:		null		Construction of floors:		null		
Construction of exterio	r walls:	null		Construction of interior	walls:	null		
Do major interior maso	nry walls (fire walls) extend a	above the roofline?		null				
Occupancy:								
Occupancy Type:			State l	niversity				
Provide a brief descrip	tion of operations:		null					
Storage height of ware	housed products:		null					
Are flammable and con	nbustible liquids stored in a	cut-off room?	null					
Safegaurds taken for th	ne storage and dispensing of	flammable liquids:	null					
Protection:								
Are there any automati	c sprinklers?	Υ		What are the design densities for	each area?	1	null	
The water supply for au	utomatic sprinklers is?			How many hydrants are located v	within 500 feet of buildings	?	null	
ndicate the Alarm Cov	erages provided for your fac	ility:						
Are alarms connected t	to a constantly attended loca	tion?		null				
s there a watchman se	rvice?	null		What is the frequency of rounds?	?	ı	null	
Are watchman recordir	ng rounds?							
Are there any fire extin	guishers?	null		Are they serviced annually?		I	null	
Are there any hose stat	tions?	null		Is there a fire private fire brigade	?	I	null	
requency of training r	eceived by the private fire br	igade:		null				
Type of public fire depart	artment:	null		Distance:			null	
Exposure:								
How many buildings(no	ot part of Account) are within	100 feet of insured buildings?						
escribe the Occupancy of those buildings(s) nearby (within 100 feet):			null					

Description:

Is there a body of water nearby? null

How far is the body of water from major buildings?

Previous history of flooding? null

Any property damage losses in the past 3 years:

null

Description: null null

null

						ı ago v	
			Pr	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / UN	IIVERSITY SYSTEM, MONTANA T	ECH OF	THE UM			
Property:	Natural Resource Research	Center Building (NRRC)					
Property Address:	1300 West Park St. BUTTE						
Property ID:	143						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	31016		
Year built:		2017		Number of stories:	3		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
Do major interior mason	ry walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			Laborat	ory			
Provide a brief description	on of operations:		blank				
Storage height of wareho	oused products:		blank				
Are flammable and comb	oustible liquids stored in a c	ut-off room?	null				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?			
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		blank	
Indicate the Alarm Cover	rages provided for your facil	lity:		blank			
Are alarms connected to	a constantly attended locat	ion?		null			
Is there a watchman serv	vice?	null		What is the frequency of rounds?			
Are watchman recording	rounds?						
Are there any fire exting	uishers?	null		Are they serviced annually?		null	
Are there any hose static	ons?	null		Is there a fire private fire brigade?		null	
Frequency of training red	ceived by the private fire bri	gade:					
Type of public fire depar	tment:	null		Distance:		blank	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) nearb	y (within 100 feet):					

Description:

Description:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

						Page 3
			Pro	perty Detail Form		
Agency:	UNIVERSITY SYSTEM	M / UNIVERSITY SYSTEM, UNIV	ERSITY OF MONT	ANA - MISSOULA		
Property:	Natural Science Annex	x				
Property Address:	1040 Madiline Ave. MI	ISSOULA				
Property ID:	015					
Construction:						
Total number of insur	ed buildings:	1		Total square footage of insured buildings:	4890	
Year built:		1938		Number of stories:	3	
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete	
Construction of exteri	or walls:	Masonry		Construction of interior walls:	Other	
Do major interior mas	onry walls (fire walls) ext	end above the roofline?		N		
Occupancy:						
Occupancy Type:			State Un	versity		
Provide a brief description of operations:			Offices/c	lassrooms		
Storage height of warehoused products:		0				
Are flammable and co	mbustible liquids stored	in a cut-off room?	N/A			
Safegaurds taken for	the storage and dispensi	ng of flammable liquids:	N/A			
Protection:						
Are there any automa	tic sprinklers?	N	,	Nhat are the design densities for each area?	no sprinklers	
The water supply for a	automatic sprinklers is?		1	How many hydrants are located within 500 feet of buildings?	4	
Indicate the Alarm Co	verages provided for you	r facility:	;	Smoke Detectors		
Are alarms connected	l to a constantly attended	location?	,	<b>(</b>		
Is there a watchman s	ervice?	Υ	,	What is the frequency of rounds?	Campus police 24/7	
Are watchman record	ing rounds?		,	1		
Are there any fire exti	nguishers?	Υ		Are they serviced annually?	Υ	
Are there any hose sta	ations?	N	1	s there a fire private fire brigade?	N	
Frequency of training	received by the private fi	re brigade:				
Type of public fire dep	partment:	Paid		Distance:	blank	
Exposure:						

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Ν Any property damage losses in the past 3 years: N Description:

Description:

					Pa	age 39
			Pro	pperty Detail Form		
gency:	UNIVERSITY SYSTEM	/ UNIVERSITY SYSTEM, UNIV	ERSITY OF MON	TANA - MISSOULA		
Property:	Natural Sciences (Botar	ny Building)				
roperty Address:	1040 Madeline Avenue	MISSOULA				
Property ID:	005					
Construction:						
otal number of insure	d buildings:	1		Total square footage of insured buildings:	23070	
ear built:		1919		Number of stories:	3	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Other	
o major interior masonry walls (fire walls) extend above the roofline?				null		
Occupancy:						
Occupancy Type:			State Ur	niversity		
Provide a brief description of operations:			Higher e	d classrooms, offices & labs		
Storage height of warel	noused products:		0			
are flammable and com	nbustible liquids stored in	a cut-off room?	N/A			
afegaurds taken for th	ne storage and dispensing	g of flammable liquids:	N/A			
Protection:						
are there any automatic	c sprinklers?	N		What are the design densities for each area?	no sprinklers	
he water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of building	gs? 2	
ndicate the Alarm Cove	erages provided for your	facility:		Smoke Detectors		
are alarms connected t	o a constantly attended I	ocation?		null		
s there a watchman se	rvice?	Υ		What is the frequency of rounds?		
are watchman recordin	g rounds?			N		
are there any fire exting	guishers?	Υ		Are they serviced annually?	Υ	
are there any hose stat	ions?	N		Is there a fire private fire brigade?	N	
requency of training re	eceived by the private fire	e brigade:				
ype of public fire depart	artment:	Paid		Distance:	blank	

# **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Any property damage losses in the past 3 years: N

Ν

Description:

Description:

			Proper	ty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVER	SITY - BOZEMAN			
Property:	NELSON STORY TOWER	APARTMENTS					
Property Address:	101 Nelson Story BOZEMA	۸N					
Property ID:	521						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	36794		
Year built:		1968		Number of stories:	9		
Construction of roof:		Poured Concrete		Construction of floors:	Poured Conci	rete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Boar	rd	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Res Apt Com	plex			
Provide a brief description	n of operations:		STUDENT D	ORM			
Storage height of wareho	used products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A					
Protection:							
Are there any automatic	sprinklers?	Υ	Wha	t are the design densities for each area?		PER NFPA 13	
The water supply for auto	omatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings	?	11	
ndicate the Alarm Cover	ages provided for your fac	ility:	Smo	ke Detectors, Sprinkler Waterflow, Sprinkler Valve Tamper			
Are alarms connected to	a constantly attended loca	ition?	Υ				
s there a watchman serv	ice?	N	Wha	t is the frequency of rounds?			
Are watchman recording	rounds?		N				
Are there any fire extingu	ishers?	Υ	Are t	they serviced annually?		Υ	
Are there any hose statio	ns?	N	Is the	ere a fire private fire brigade?		N	
requency of training rec	eived by the private fire br	rigade:					
Гуре of public fire depart	ment:	Paid	Dista	ance:		0.66	
Exposure:							
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
s there a body of water n	earby?	N	Description:				
How far is the body of wa	ter from major buildings?						
Previous history of flood	ing?	N	Description:				
Any property damage los	ses in the past 3 years:	N	Description:				

								Page 3
			Pr	operty D	Detail Form			
Agency:	UNIVERSITY SYSTEM / UNI	VERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - N	MISSOULA			
Property:	North Corbin							
Property Address:	1025 Maurice Avenue MISSO	DULA						
Property ID:	106							
Construction:								
Total number of insured	buildings: 1				Total square footage of insured buildings:	14858		
Year built:	1	956			Number of stories:	4		
Construction of roof:	n	ull			Construction of floors:	null		
Construction of exterior	walls: n	ull			Construction of interior walls:	null		
Do major interior masonr	y walls (fire walls) extend ab	ove the roofline?			null			
Occupancy:								
Occupancy Type:			State U	niversity				
Provide a brief description	on of operations:		null					
Storage height of wareho	oused products:		null					
Are flammable and comb	ustible liquids stored in a cu	it-off room?	null					
Safegaurds taken for the	storage and dispensing of fl	ammable liquids:	null					
Protection:								
Are there any automatic	sprinklers?	N		What are	e the design densities for each area?		null	
The water supply for auto	omatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?		null	
ndicate the Alarm Cover	ages provided for your facili	ty:						
Are alarms connected to	a constantly attended location	on?		null				
s there a watchman serv	rice?	null		What is	the frequency of rounds?		null	
Are watchman recording	rounds?							
Are there any fire extingu	iishers?	null		Are they	serviced annually?		null	
Are there any hose statio	ons?	null		Is there	a fire private fire brigade?		null	
requency of training rec	eived by the private fire brig	ade:		null				
Type of public fire depart	ment:	null		Distance	9:		null	
Exposure:								
How many buildings(not	part of Account) are within 1	00 feet of insured buildings?						

Description:

Is there a body of water nearby? null

How far is the body of water from major buildings?

Previous history of flooding?

null

Any property damage losses in the past 3 years:

Description:

null

null

Description:

null null

			Pro	perty Detail Form			
Agency:	JNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN						
Property:	NORTH HEDGES RESIDENCE HALL						
Property Address:	West Grant Street (no official address) BOZEMAN						
Property ID:	343						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	137722		
Year built:		1965		Number of stories:	11		
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete		
Construction of exterior walls:		Masonry		Construction of interior walls:	Masonry		
Do major interior masonry walls (fire walls) extend above the roofline?			N				
Occupancy:							
Occupancy Type:		Res Apt (	Complex				
Provide a brief description of operations:			STUDENT DORM				
Storage height of warehoused products:			N/A				
Are flammable and combustible liquids stored in a cut-off room?			N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A				
Protection:							
Are there any automatic s	prinklers?	Υ	\	What are the design densities for each area?		PER NFPA 13	
The water supply for automatic sprinklers is?		Public	ŀ	How many hydrants are located within 500 feet of buildings?	•	10	
Indicate the Alarm Coverages provided for your facility:			5	Sprinkler Waterflow, Sprinkler Valve Tamper, Smoke Detectors			
Are alarms connected to a constantly attended location?			1	N			
Is there a watchman servi	ce?	Υ	1	What is the frequency of rounds?		3-4 TIMES PER NIGHT	
Are watchman recording	rounds?		`	Y			
Are there any fire extingui	ishers?	Υ	,	Are they serviced annually?		Υ	
Are there any hose station	ns?	N	ı	s there a fire private fire brigade?		N	
Frequency of training reco	eived by the private fire br	igade:					
Type of public fire departi	ment:	Paid	I	Distance:		.92 MILES	
Exposure:							
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water nearby?		Descript	ion:				
How far is the body of war	ter from major buildings?						
Previous history of floodi	y of flooding?		Descript	ion:			
Any property damage losses in the past 3 years: Y		Description:		6/21/02 WATER DAMAGE DUE TO FROZEN SPRINKLER LINE			

						r age s			
			Proper	ty Detail Form					
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA								
Property:	North Underground Lect. Hall								
Property Address:	1340 Mansfield Ave. MISSOL	JLA							
Property ID:	98								
Construction:									
Total number of insured buildings:				Total square footage of insured buildings:	9260				
Year built:	1	999		Number of stories:	1				
Construction of roof:	n	ull		Construction of floors:	null				
Construction of exterior	walls: n	ull		Construction of interior walls:	null				
Do major interior masonry walls (fire walls) extend above the roofline?		ove the roofline?		null					
Occupancy:									
Occupancy Type:			State Univers	sity					
Provide a brief description of operations:			null						
Storage height of warehoused products:			null						
Are flammable and combustible liquids stored in a cut-off room?			null						
Safegaurds taken for the storage and dispensing of flammable liquids:			null						
Protection:									
Are there any automatic	sprinklers?	Υ	Wha	t are the design densities for each area?		null			
The water supply for auto	omatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?		null			
Indicate the Alarm Cover	rages provided for your facilit	ty:							
Are alarms connected to a constantly attended location?			null						
Is there a watchman serv	vice?	null	Wha	t is the frequency of rounds?		null			
Are watchman recording	rounds?								
Are there any fire extingu	uishers?	null	Are	they serviced annually?		null			
Are there any hose static	ons?	null	ls th	ere a fire private fire brigade?		null			
Frequency of training received by the private fire brigade:			null						
Type of public fire depart	tment:	null	Dista	ance:		null			
Exposure:									
How many buildings(not	part of Account) are within 1	00 feet of insured buildings?							

null

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Description: null

How far is the body of water from major buildings?

Previous history of flooding? Description: null null

null

null

Any property damage losses in the past 3 years: Description: null

							Page
			Property I	Detail Form			
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, UNIVERSITY	OF MONTANA - V	WESTERN			
Property:	Old Library Building						
Property Address:	710 S. Atlantic DILLON						
Property ID:	2						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	19292		
Year built:		1924		Number of stories:	3		
Construction of roof:		Other		Construction of floors:	null		
Construction of exterio	r walls:	Masonry		Construction of interior walls:	null		
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State University				
Provide a brief descripe	tion of operations:		OFFICES/CLASS	SROOMS			
Storage height of ware	noused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for th	ne storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automati	c sprinklers?	N	What are	e the design densities for each area?			
The water supply for au	utomatic sprinklers is?		How ma	ny hydrants are located within 500 feet of buildings?	?	3	
Indicate the Alarm Cov	erages provided for your fac	cility:					
Are alarms connected to	o a constantly attended loc	ation?	null				
Is there a watchman se	rvice?	Υ	What is	the frequency of rounds?		HOUR	
Are watchman recording	g rounds?		Υ				
Are there any fire extin	guishers?	Υ	Are they	y serviced annually?		Υ	
Are there any hose stat	ions?	null	Is there	a fire private fire brigade?		null	
Frequency of training r	eceived by the private fire b	rigade:					
Type of public fire depart	artment:	Voluntary	Distance	e:		12 BLOCKS	
Exposure:							
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupano	y of those buildings(s) near	by (within 100 feet):					
Is there a body of water	r nearby?	Υ	Description:		BEAVERHEA	D RIVER	
How far is the body of	water from major buildings?		1 MILE				
Previous history of floo	oding?	N	Description:				

Any property damage losses in the past 3 years: N

			Property	Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVERSIT	Y - BOZEMAN			
Property:	OSCAR THOMAS NUTRIT	ION CENTER					
Property Address:	West of South 19th Avenue	& Lincoln Street BOZEMAN					
Property ID:	434						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	7262		
Year built:		1968		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Poured Concr	rete	
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Masonry		
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Laboratory				
Provide a brief description	on of operations:		Administration, t	esting laboratory			
Storage height of wareho	oused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ					
Protection:							
Are there any automatic	sprinklers?	N	What a	re the design densities for each area?		no sprinkler	
The water supply for auto	omatic sprinklers is?		How ma	any hydrants are located within 500 feet of buildings?	?	1	
ndicate the Alarm Cover	ages provided for your fac	ility:					
ndicate the Alarm Coverages provided for your facility:  Are alarms connected to a constantly attended location?							
		tion?	null				
	a constantly attended loca	tion? N		the frequency of rounds?			
Are alarms connected to	a constantly attended loca			the frequency of rounds?			
Are alarms connected to s there a watchman serv	a constantly attended locarice?		<b>W</b> hat is	the frequency of rounds? y serviced annually?		Υ	
Are alarms connected to s there a watchman serv Are watchman recording	a constantly attended loca rice? rounds? uishers?	N	What is N Are the			Y N	
Are alarms connected to s there a watchman serv Are watchman recording Are there any fire extingu Are there any hose station	a constantly attended loca rice? rounds? uishers?	N Y N	What is N Are the	y serviced annually?			
Are alarms connected to s there a watchman serv Are watchman recording Are there any fire extingu Are there any hose station	a constantly attended locatice? rounds? uishers? ons? ceived by the private fire br	N Y N	What is N Are the	y serviced annually? a fire private fire brigade?			
Are alarms connected to set there a watchman serve Are watchman recording Are there any fire extingue Are there any hose stations requency of training recording and the set t	a constantly attended locatice? rounds? uishers? ons? ceived by the private fire br	N Y N igade:	What is N Are the Is there	y serviced annually? a fire private fire brigade?		N	
Are alarms connected to s there a watchman serve Are watchman recording Are there any fire extingue Are there any hose station of training recording of training recording of the depart of public fire depart of the same are supposure:	a constantly attended loca vice? rounds? uishers? ons? ceived by the private fire br tment:	N Y N igade:	What is N Are the Is there	y serviced annually? a fire private fire brigade?		N	
Are alarms connected to s there a watchman serve Are watchman recording Are there any fire extinguare there any hose station requency of training recording to the public fire depart exposure:  How many buildings(not	a constantly attended loca vice? rounds? uishers? ons? ceived by the private fire br tment:	N Y N igade: Paid 100 feet of insured buildings?	What is N Are the Is there	y serviced annually? a fire private fire brigade?		N	
Are alarms connected to s there a watchman serve Are watchman recording Are there any fire extinguare there any hose station requency of training recording to the public fire depart exposure:  How many buildings(not	a constantly attended localice? rounds? uishers? ons? ceived by the private fire britment: part of Account) are within of those buildings(s) near	N Y N igade: Paid 100 feet of insured buildings?	What is N Are the Is there	y serviced annually? a fire private fire brigade?		N	
Are alarms connected to s there a watchman serve Are watchman recording Are there any fire extinguare there any hose station requency of training recording public fire departed by the way buildings and the control of	a constantly attended localice? rounds? uishers? ons? ceived by the private fire britment: part of Account) are within of those buildings(s) near	N Y N igade: Paid 100 feet of insured buildings? by (within 100 feet):	What is  N  Are the Is there  Distance	y serviced annually? a fire private fire brigade?		N	
Are alarms connected to s there a watchman serve Are watchman recording Are there any fire extinguare there any hose station requency of training recording public fire departed by the way buildings and the control of	a constantly attended localize? rounds? uishers? ons? ceived by the private fire britment: part of Account) are within of those buildings(s) nearlinearby? atter from major buildings?	N Y N igade: Paid 100 feet of insured buildings? by (within 100 feet):	What is  N  Are the Is there  Distance	y serviced annually? a fire private fire brigade?		N	

			Pro	perty De	etail Form		
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MI	SSOULA		
Property:	Pantzer Hall Dormitory						
Property Address:	615 Keith Avenue MISSOU	LA					
Property ID:	111						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	81333	
Year built:		1996			Number of stories:	4	
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Poured Concre	ete
Construction of exterior	valls:	Masonry			Construction of interior walls:	Gypsum Board	3
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			N		
Occupancy:							
Occupancy Type:			Res Apt	Complex			
Provide a brief descriptio	n of operations:		Student	dorm			
Storage height of wareho	used products:		0				
Are flammable and combustible liquids stored in a cut-off room?		N					
Safegaurds taken for the storage and dispensing of flammable liquids:		N					
Protection:							
Are there any automatic s	sprinklers?	Υ		What are	the design densities for each area?		0.1
The water supply for auto	matic sprinklers is?	Public		How man	y hydrants are located within 500 feet of buildings?		2
Indicate the Alarm Covera	ages provided for your faci	ility:		Smoke De	etectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	tion?		Υ			
Is there a watchman serv	ice?	Υ		What is th	ne frequency of rounds?		Campus police 24/7
Are watchman recording	rounds?			Υ			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose statio	ns?	N		ls there a	fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	igade:					
Type of public fire depart	ment:	Paid		Distance:			under 1 mile
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank				
Describe the Occupancy	of those buildings(s) nearb	oy (within 100 feet):					
Is there a body of water n	earby?	N	Descrip	tion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descrip	tion:			
Any property damage los	ses in the past 3 years:	null	Descrip	tion:			

						Page 4
			Pı	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	STATE UN	NIVERSITY - BILLINGS		
Property:	Parking Garage & Sky Brid	ge (sprinklered)				
Property Address:	1500 University Drive BILL	NGS				
Property ID:	600008331					
Construction:						
Γotal number of insured	buildings:	1		Total square footage of insured buildings: 17	7160	
Year built:		1998		Number of stories: 5		
Construction of roof:		Reinforced Concrete		Construction of floors: Re	einforced Concrete	
Construction of exterior	walls:	Reinforced Concrete		Construction of interior walls:	asonry	
Oo major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Garage	e, Vehicle Storage		
Provide a brief description of operations:			vehicle	parking		
Storage height of warehoused products:		0				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the	e storage and dispensing of	flammable liquids:	Υ			
Protection:						
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?	no sprinklers	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	1	
ndicate the Alarm Cove	rages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	tion?		null		
s there a watchman ser	vice?	Υ		What is the frequency of rounds?	daily	
Are watchman recording	g rounds?			N		
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
Are there any hose stati	ons?	N		Is there a fire private fire brigade?	N	
requency of training re	ceived by the private fire br	igade:				
Гуре of public fire depar	rtment:	Paid		Distance:	1 to 2 miles	
Exposure:						
How many buildings(no	part of Account) are withir	100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	oy (within 100 feet):				
s there a body of water	nearby?	Υ	Descri	ption: irri	gation ditch	

50 feet

Description:

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

Previous history of flooding?

			Prope	rty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MONTAN	IA - MISSOULA		
Property:	Parking Structure					
Property Address:	35 Campus Drive MISSOU	LA				
Property ID:	87					
Construction:						
Total number of insured I	buildings:	1		Total square footage of insured buildings:	99330	
Year built:		1996		Number of stories:	3	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior v	walls:	null		Construction of interior walls:	null	
Do major interior masonr	y walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			State Univer	rsity		
Provide a brief descriptio	on of operations:		null			
Storage height of wareho	oused products:		null			
Are flammable and combustible liquids stored in a cut-off room?		null				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	N	Wha	at are the design densities for each area?		null
The water supply for auto	omatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings?		null
Indicate the Alarm Cover	ages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ation?	null			
ls there a watchman serv	ice?	null	Wha	at is the frequency of rounds?		null
Are watchman recording	rounds?					
Are there any fire extingu	ishers?	null	Are	they serviced annually?		null
Are there any hose statio	ns?	null	ls th	here a fire private fire brigade?		null
Frequency of training rec	eived by the private fire b	rigade:	null			
Type of public fire depart	ment:	null	Dist	tance:		null
Exposure:						
How many buildings(not	part of Account) are withir	100 feet of insured buildings?				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	null			
Is there a body of water n	nearby?	null	Description	:	null	
How far is the body of wa	ater from major buildings?		null			
Previous history of flood	ing?	null	Description	:	null	
Any property damage los	ses in the past 3 years:	null	Description	:	null	

							Page 4
			Prop	erty Detail Form			
Agency:	UNIVERSITY SYSTEM	M / UNIVERSITY SYSTEM, UN	IVERSITY OF MONTA	NA - MISSOULA			
Property:	Performing Arts & Rac	lio Television					
Property Address:	735 S 6th Street East	MISSOULA					
Property ID:	96						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	69176		
Year built:		1984		Number of stories:	1		
Construction of roof:		null		Construction of floors:	null		
Construction of exterio	or walls:	null		Construction of interior walls:	null		
Do major interior maso	onry walls (fire walls) ext	end above the roofline?		null			
Occupancy:							
Occupancy Type:			State Univ	ersity			
Provide a brief descrip	tion of operations:		null				
Storage height of ware	housed products:		null				
Are flammable and cor	nbustible liquids stored	in a cut-off room?	null				
Safegaurds taken for the	he storage and dispensi	ng of flammable liquids:	null				
Protection:							
Are there any automati	c sprinklers?	Υ	w	hat are the design densities for each area?		null	
The water supply for a	utomatic sprinklers is?		Н	ow many hydrants are located within 500 feet of buildir	ıgs?	null	
Indicate the Alarm Cov	erages provided for you	r facility:					
Are alarms connected	to a constantly attended	location?	nı	ıll			
Is there a watchman se	ervice?	null	w	hat is the frequency of rounds?		null	
Are watchman recording	ng rounds?						
Are there any fire extin	guishers?	null	Α	re they serviced annually?		null	
Are there any hose sta	tions?	null	Is	there a fire private fire brigade?		null	
Frequency of training r	eceived by the private fi	re brigade:	nı	ıll			
Type of public fire depart	artment:	null	D	stance:		null	
Exposure:							
How many buildings(n	ot part of Account) are w	vithin 100 feet of insured build	dings?				
Describe the Occupand	cy of those buildings(s)	nearby (within 100 feet):	null				

Description:

Description:

null

null

null

null

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

								1 ago 10
			Prop	perty De	etail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIV	/ERSITY	- NORTHERN			
Property:	Pershing Hall							
Property Address:	MSU-Northern - 1200 SUE	B Drive HAVRE						
Property ID:	2							
Construction:								
Total number of insured	l buildings:	1			Total square footage of insured buildings:	14360		
Year built:		1933			Number of stories:	3		
Construction of roof:		Other			Construction of floors:	Reinforced C	oncrete	
Construction of exterior	walls:	Other			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masor	nry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Laborator	ry				
Provide a brief descripti	ion of operations:		classroom	ns/labs/of	ffice			
Storage height of wareh	oused products:		n/a					
Are flammable and combustible liquids stored in a cut-off room?		Υ						
Safegaurds taken for the	e storage and dispensing o	of flammable liquids:	Υ					
Protection:								
Are there any automatic	sprinklers?	N	V	What are	the design densities for each area?		n/a	
The water supply for au	tomatic sprinklers is?		н	low man	y hydrants are located within 500 feet of buildings	?	2	
Indicate the Alarm Cove	rages provided for your fa	cility:	S	Smoke De	etectors			
Are alarms connected to	o a constantly attended loc	ation?	N	١				
ls there a watchman ser	vice?	Υ	V	What is th	ne frequency of rounds?		every 24 hours	
Are watchman recording	g rounds?		Y	1				
Are there any fire exting	juishers?	Υ	A	Are they s	serviced annually?		Υ	
Are there any hose stati	ons?	N	ls	s there a	fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:						
Type of public fire depa	rtment:	Paid	D	Distance:	:		1 mile	
Exposure:								
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupancy	y of those buildings(s) near	rby (within 100 feet):						
ls there a body of water	nearby?	N	Descripti	ion:				
How far is the body of w	vater from major buildings?	•						
Previous history of floo	ding?	N	Descripti	ion:				
Any property damage lo	osses in the past 3 years:	N	Descripti	ion:				

						1 490 10 1
			Prope	erty Detail Form		
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, MONTANA S	TATE UNIVE	RSITY - BOZEMAN		
Property:	PETER KOCH TOWER AF	PARTMENTS				
Property Address:	101 Peter Koch Street BO	ZEMAN				
Property ID:	520					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	36794	
Year built:		1968		Number of stories:	9	
Construction of roof:		Poured Concrete		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Res Apt Co	omplex		
Provide a brief descripti	on of operations:		STUDENT	DORM		
Storage height of wareh	oused products:		N/A			
Are flammable and com	oustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	Υ	Wh	nat are the design densities for each area?	PER NFPA 13	
The water supply for aut	omatic sprinklers is?	Public	Но	w many hydrants are located within 500 feet of buildings	? 14	
Indicate the Alarm Cove	rages provided for your fac	cility:	Spi	rinkler Valve Tamper, Sprinkler Waterflow, Smoke Detectors		
Are alarms connected to	a constantly attended loca	ation?	Υ			
ls there a watchman ser	vice?	null	Wh	nat is the frequency of rounds?		
Are watchman recording	rounds?					
Are there any fire exting	uishers?	Υ	Are	e they serviced annually?	Υ	
Are there any hose stati	ons?	N	ls t	there a fire private fire brigade?	N	
Frequency of training re	ceived by the private fire b	rigade:				
Type of public fire depar	tment:	Paid	Dis	stance:	.63 MILES	
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water	nearby?	N	Description	n:		
How far is the body of w	ater from major buildings?					
Previous history of flood	ling?	N	Description	n:		
Any property damage lo	sses in the past 3 years:	N	Description	n:		

	Property Detail Form
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BILLINGS
Property:	Petro/Rimrock/SUB Complex
Property Address:	1500 University Drive RILLINGS

C O	nstr	nct	ıon

Total number of insured buildings: 1 Total square footage of insured buildings: 273692 Year built: 1962 Number of stories:

**Poured Concrete** Construction of roof: Steel Deck Construction of floors:

Construction of exterior walls: Masonry Construction of interior walls: Masonry w/ Fire Doors

## Occupancy:

**Occupancy Type:** State University

Provide a brief description of operations: dormitory

Storage height of warehoused products: 0

Do major interior masonry walls (fire walls) extend above the roofline?

Are flammable and combustible liquids stored in a cut-off room? N/A

Safegaurds taken for the storage and dispensing of flammable liquids:

### Protection:

Υ Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? **Public** How many hydrants are located within 500 feet of buildings? 2

Indicate the Alarm Coverages provided for your facility: Sprinkler Valve Tamper, Sprinkler Waterflow

Are alarms connected to a constantly attended location?

Is there a watchman service? Υ What is the frequency of rounds? daily

Are watchman recording rounds?

Are there any fire extinguishers? Are they serviced annually? null

Are there any hose stations? Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Type of public fire department: 1 to 2 miles Paid Distance:

### Exposure:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How many buildings(not part of Account) are within 100 feet of insured buildings?

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Ν Description: Description:

Any property damage losses in the past 3 years:

							Page	4
			Pr	operty D	Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	NTANA - M	MISSOULA			
Property:	Phyllis J. Washington Educ	cation Center						
Property Address:	745 Eddy MISSOULA							
Property ID:	016							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	66905		
Year built:		2009			Number of stories:	3		
Construction of roof:		null			Construction of floors:	null		
Construction of exterior	walls:	null			Construction of interior walls:	null		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			null			
Occupancy:								
Occupancy Type:			State U	niversity				
Provide a brief description	on of operations:		null					
Storage height of wareho	oused products:		null					
Are flammable and comb	oustible liquids stored in a	cut-off room?	null					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	e the design densities for each area?		null	
The water supply for aut	omatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?	?	null	
Indicate the Alarm Cover	rages provided for your fac	ility:						
Are alarms connected to	a constantly attended loca	ition?		null				
Is there a watchman serv	vice?	null		What is	the frequency of rounds?		null	
Are watchman recording	rounds?							
Are there any fire exting	uishers?	null		Are they	serviced annually?		null	
Are there any hose static	ons?	null		Is there	a fire private fire brigade?		null	
Frequency of training red	ceived by the private fire br	rigade:		null				
Type of public fire depar	tment:	null		Distance	e:		null	
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?						-

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Description:

Is there a body of water nearby? null

How far is the body of water from major buildings? Previous history of flooding?

Any property damage losses in the past 3 years:

null

Description:

Description:

null

null

null null

			Pro	operty D	etail Form				
Agency:	UNIVERSITY SYSTEM / UNIVERSITY / UNIVERSITY SYSTEM / UNIVERSITY SYSTEM / UNIVERSITY / UNIVERSITY / UNIVERSITY / UNIVERSITY / U	NIVERSITY SYSTEM, MONTANA ST	ATE UN	IVERSITY	- BILLINGS				
Property:	Phys Plant - 324 N Rim Ter	r							
Property Address:	324 N. Rim Terrrace BILLIN	IGS							
Property ID:	600000909/2192								
Construction:									
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	16384			
Year built:		1979			Number of stories:	1			
Construction of roof:		Concrete Panels			Construction of floors:	Poured Concre	ete		
Construction of exterior w	valls:	Tilt-Up Concrete			Construction of interior walls:	Masonry			
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			N				
Occupancy:									
Occupancy Type:			State Ur	niversity					
Provide a brief description	n of operations:		mainten	naintenance shops					
Storage height of warehoused products:		0							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ						
Protection:									
Are there any automatic s	prinklers?	N		What are	the design densities for each area?		no sprinklers		
The water supply for auto	matic sprinklers is?			How man	y hydrants are located within 500 feet of buildings?		1		
Indicate the Alarm Covera	ages provided for your faci	ility:							
Are alarms connected to a	a constantly attended loca	tion?		N					
ls there a watchman servi	ce?	Υ		What is th	ne frequency of rounds?		daily		
Are watchman recording	rounds?			N					
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose station	ns?	N		Is there a	fire private fire brigade?		N		
Frequency of training reco	eived by the private fire br	igade:							
Type of public fire departi	ment:	Paid		Distance			1 to 2 miles		
Exposure:									
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearb	y (within 100 feet):							
Is there a body of water no	earby?	N	Descrip	tion:					
How far is the body of war	ter from major buildings?								
Previous history of floodi	ng?	N	Descrip	tion:					
Any property damage loss	ses in the past 3 years:	N	Descrip	tion:					

						Page 40	
			Property	Detail Form			
Agency:	UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, MONTANA	STATE UNIVERSI	TY - BILLINGS			
Property:	Physical Ed Building						
Property Address:	1500 University Drive BIL	LINGS					
Property ID:	600000888/11730						
Construction:							
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	105395		
Year built:		1961		Number of stories:	3		
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete		
Construction of exteri	or walls:	Masonry		Construction of interior walls:	Masonry		
Do major interior mas	onry walls (fire walls) extend	d above the roofline?		N			
Occupancy:							
Occupancy Type:			State University				
Provide a brief descrip	otion of operations:		education				
Storage height of warehoused products:		0					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for t	the storage and dispensing	of flammable liquids:	Υ				
Protection:							
Are there any automat	ic sprinklers?	Υ	What a	re the design densities for each area?			
The water supply for a	utomatic sprinklers is?	Public	How m	any hydrants are located within 500 feet of building	gs? 2		
Indicate the Alarm Co	verages provided for your fa	cility:	Smoke Detectors, Sprinkler Waterflow, Sprinkler Valve Tamper, Burglar Alarms (Door Contacts)				
Are alarms connected	to a constantly attended loc	cation?	Υ				
Is there a watchman s	ervice?	Υ	What is	s the frequency of rounds?	daily		
Are watchman recordi	ng rounds?		N				
Are there any fire exti	nguishers?	Υ	Are the	ey serviced annually?	Υ		
Are there any hose sta	ations?	Υ	Is there	e a fire private fire brigade?	N		
Frequency of training	received by the private fire	origade:					
Type of public fire dep	partment:	Paid	Distan	ce:	1 to 2 miles		
Exposure:							
How many buildings(r	not part of Account) are with	in 100 feet of insured buildings?	1				
Describe the Occupan	cy of those buildings(s) nea	rby (within 100 feet):	residential				
Is there a body of water	er nearby?	Υ	Description:		irrigation ditch		
How far is the body of	water from major buildings	?	200 feet				
Previous history of flo	oding?	N	Description:				
Any property damage	losses in the past 3 years:	N	Description:				

							Page
			Pro	pperty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSIT	Y OF MON	TANA - WESTERN			
Property:	Physical Ed Building						
Property Address:	710 S. Atlantic DILLON						
Property ID:	23						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	73240		
Year built:		1975		Number of stories:	3		
Construction of roof:		Other		Construction of floors:	Poured Concre	ete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Masonry		
Do major interior masonry walls (fire walls) extend above the roofline?			Υ				
Occupancy:							
Occupancy: Occupancy Type:		State Un	iversity				
Provide a brief description of operations:		GYMNA	SIUM				
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automati	c sprinklers?	N	,	What are the design densities for each area?			
The water supply for au	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	?	5	
Indicate the Alarm Cov	erages provided for your fa	cility:		Smoke Detectors			
Are alarms connected to	to a constantly attended loc	ation?		Y			
Is there a watchman se	rvice?	Υ	,	What is the frequency of rounds?		HOUR	
Are watchman recording	ng rounds?			Y			
Are there any fire extin	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stat	tions?	N		Is there a fire private fire brigade?		null	
Frequency of training r	eceived by the private fire b	rigade:					
Type of public fire depart	artment:	Voluntary		Distance:		12 BLOCKS	
Exposure:							
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupano	cy of those buildings(s) near	rby (within 100 feet):					
Is there a body of water	r nearby?	Υ	Descript	tion:	BEAVERHEAD	D RIVER	

1 MILE

Description:

Description:

Ν

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Previous history of flooding?

								Page 41
			Pı	roperty [	Detail Form			
Agency:	UNIVERSITY SYSTEM / I	JNIVERSITY SYSTEM, MONTANA S	STATE UN	NIVERSIT'	Y - NORTHERN			
Property:	Physical Plant Building							
Property Address:	MSU-Northern - 300 13th	Street West HAVRE						
Property ID:	28							
Construction:								
Total number of insure	d buildings:	1			Total square footage of insured buildings:	5642		
Year built:		1967			Number of stories:	2		
Construction of roof:		Other			Construction of floors:	Other		
Construction of exterio	r walls:	Masonry			Construction of interior walls:	Gypsum Boa	rd	
Do major interior maso	nry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Garage	e, Service	Center			
Provide a brief descrip	tion of operations:		garage	/shop/offic	e			
Storage height of ware	housed products:		n/a					
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	Υ					
Protection:								
Are there any automati	c sprinklers?	N		What are	e the design densities for each area?		partial/shop area	
The water supply for au	utomatic sprinklers is?	Private		How ma	ny hydrants are located within 500 feet of buildings	s?	1	
Indicate the Alarm Cov	erages provided for your fa	cility:		Smoke D	Detectors			
Are alarms connected t	to a constantly attended loc	ation?		N				
ls there a watchman se	rvice?	Υ		What is	the frequency of rounds?		every 24 hours	
Are watchman recordir	ng rounds?			Υ				
Are there any fire extin	guishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stat	tions?	N		Is there	a fire private fire brigade?		N	
Frequency of training r	eceived by the private fire b	rigade:						
Type of public fire depa	artment:	Paid		Distance	e:		1 mile	
Exposure:								
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	2					
Describe the Occupand	cy of those buildings(s) nea	rby (within 100 feet):	shed/po	olebarn				
Is there a body of water	r nearby?	N	Descri	ption:				
How far is the body of	water from major buildings?	?						
Previous history of floo	oding?	N	Descri	ption:				
Any property damage l	osses in the past 3 years:	N	Descri	ption:				

						Page 4
			Pro	operty Detail Form		
gency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSIT	TY OF MON	TANA - MISSOULA		
roperty:	Physical Plant Building					
roperty Address:	12 Campus Drive MISSOL	JLA				
roperty ID:	32					
onstruction:						
otal number of insured	buildings:	1		Total square footage of insured buildings:	50897	
ear built:		1968		Number of stories:	1	
onstruction of roof:		Other		Construction of floors:	Poured Concrete	
onstruction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ Fire Doors	
o major interior mason	ry walls (fire walls) extend	above the roofline?		N		
ccupancy:						
ccupancy Type:			State Ur	niversity		
rovide a brief description	on of operations:		Facilities	s maintenance shops, offices, mail room & Office of Public Safety		
torage height of wareh	oused products:		0			
re flammable and comb	oustible liquids stored in a	cut-off room?	N/A			
afegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ			
rotection:						
re there any automatic	sprinklers?	Υ		What are the design densities for each area?		
he water supply for aut	omatic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings?	2	
dicate the Alarm Cove	rages provided for your fac	cility:		Smoke Detectors		
re alarms connected to	a constantly attended loc	ation?		Υ		
there a watchman serv	vice?	Υ		What is the frequency of rounds?	Campus police 24/7	
re watchman recording	g rounds?			Υ		
re there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
re there any hose static	ons?	N		Is there a fire private fire brigade?	N	
requency of training re	ceived by the private fire b	rigade:				
ype of public fire depar	tment:	Paid		Distance:	under 1 mile	
xposure:						

# Llaur many h

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

How far is the body of water from major buildings?

Previous history of flooding?

Any property damage losses in the past 3 years: N

N Description:

Description:

Description:

					Page	412
			Property	Detail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVERSIT	TY - BOZEMAN		
Property:	PLANT BIOSCIENCE BUIL	LDING				
Property Address:	South 11th Avenue (no offi	cial address) BOZEMAN				
Property ID:	400					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	50929	
Year built:		1999		Number of stories:	4	
Construction of roof:		Other		Construction of floors:	Reinforced Concrete	
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Laboratory			
Provide a brief description	on of operations:		RESEARCH OF	FICES/LABS		
Storage height of warehoused products:		N/A				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ				
Protection:						
Are there any automatic	sprinklers?	Υ	What a	re the design densities for each area?	PER NFPA 13	
The water supply for auto	omatic sprinklers is?	Public	How ma	any hydrants are located within 500 feet of buildings?	? 8	
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke	Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected to	a constantly attended loca	ation?	Υ			
Is there a watchman serv	rice?	Υ	What is	the frequency of rounds?	AVERAGE 4 PER NIGHT	
Are watchman recording	rounds?		N			
Are there any fire extingu	uishers?	Υ	Are the	y serviced annually?	Υ	
Are there any hose static	ons?	N	Is there	a fire private fire brigade?	N	
Frequency of training red	ceived by the private fire b	rigade:				
Type of public fire depart	tment:	Paid	Distanc	ee:	.88 MILES	
Exposure:						
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				
Is there a body of water r	nearby?	N	Description:			
How far is the body of wa	ater from major buildings?					
Previous history of flood	ing?	N	Description:			
Any property damage los	sses in the past 3 years:	Υ	Description:		10/21/02 - WATER DAMAGE/FROZEN SPRINKL LINE, 4/21/01 WATER DAMAGE CAUSING EQUIPMENT TO BE EXPOSED	ER

<b>Property</b>	/ Dotail	Earm
	/ Detall	<b>(0)</b>

			Pro	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	STATE UNI	VERSITY - BOZEMAN			
Property:	PLANT GROWTH CENTE	₹					
Property Address:	South 11th Avenue (no offi	cial address) BOZEMAN					
Property ID:	401						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	68286		
Year built:		1986		Number of stories:	2		
Construction of roof:	oof: Steel Deck			Construction of floors:	Reinforced Co	ncrete	
Construction of exterior w	nstruction of exterior walls: Masonry			Construction of interior walls: Masonry		re Doors	
Do major interior masonry	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Laborato	ory			
Provide a brief description of operations:		OFFICE	OFFICES/LABS/GREENHOUSE/CLASSROOMS				
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	storage and dispensing o	flammable liquids:	Υ				
Protection:							
Are there any automatic s	prinklers?	Υ	,	What are the design densities for each area?		PER NFPA 13	
The water supply for auto	matic sprinklers is?	Public		How many hydrants are located within 500 feet of buildings	?	8	
Indicate the Alarm Covera	nges provided for your fac	ility:	Burglar Alarms (Door Contacts), Sprinkler Waterflow, Smoke Detectors, Sprinkler Valve Tamper				
Are alarms connected to a	a constantly attended loca	ntion?		Υ			
Is there a watchman servi	ce?	Υ	,	What is the frequency of rounds?		AVERAGE 4 PER NIGHT	
Are watchman recording	rounds?			N			
Are there any fire extingui	ishers?	Υ		Are they serviced annually?		Υ	
Are there any hose station	ns?	N		Is there a fire private fire brigade?		N	
Frequency of training reco	eived by the private fire b	igade:					
Type of public fire departi	ment:	Paid		Distance:		.9 MILES	
Exposure:							
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water no	earby?	N	Descript	tion:			
How far is the body of war	ter from major buildings?						
Previous history of floodi	ng?	N	Descript	tion:			
Any property damage loss	ses in the past 3 years:	Y	Descript	tion:	9/19/02 WATE SPRINKLER L	R DAMAGE DUE TO FROZEN LINE	

			Property	y Detail Form					
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVERS	SITY - BOZEMAN					
Property:	PLEW BUILDING								
Property Address:	West Grant Street (no offici	al address) BOZEMAN							
Property ID:	316								
Construction:									
Total number of insured b	buildings:	1		Total square footage of insured buildings:	18086				
Year built:		1952		Number of stories:	2				
Construction of roof:		Other		Construction of floors:	Wood Timber				
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Gypsum Board	i			
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		N					
Occupancy:									
Occupancy Type:			Office						
Provide a brief descriptio	n of operations:		OFFICES/SHO	DFFICES/SHOPS/STORE					
Storage height of warehoused products:		6'8"							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A							
Protection:									
Are there any automatic s	sprinklers?	N	What	are the design densities for each area?		1 NEAR DUST COLLECTION			
The water supply for auto	omatic sprinklers is?	Public	How I	many hydrants are located within 500 feet of buildings	?	3			
Indicate the Alarm Covera	ages provided for your fac	ility:	Sprink	der Waterflow					
Are alarms connected to	a constantly attended loca	tion?	N						
Is there a watchman serv	ice?	Υ	What	is the frequency of rounds?		AVERAGE 4 PER NIGHT			
Are watchman recording	rounds?		N						
Are there any fire extingu	ishers?	Υ	Are th	ney serviced annually?		Υ			
Are there any hose statio	ns?	N	Is the	re a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid	Dista	nce:		1.41 MILES			
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	3						
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):	RESIDENTIAL	-					
Is there a body of water n	earby?	N	Description:						
How far is the body of wa	ter from major buildings?								
Previous history of floodi	ing?	N	Description:						
Any property damage los	ses in the past 3 years:	N	Description:						

								i ago i i	
			Pro	perty Deta	ail Form				
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MONTANA S	TATE UNI\	IVERSITY -	BILLINGS				
Property:	Poly Building								
Property Address:	1500 University Drive BILL	INGS							
Property ID:									
Construction:									
Total number of insured	buildings:	1		To	otal square footage of insured buildings:	4263			
Year built:		1988		N	lumber of stories:	2			
Construction of roof:		null		C	construction of floors:	null			
Construction of exterior	walls:	null		C	construction of interior walls:	null			
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N	l				
Occupancy:									
Occupancy Type:			State Uni	niversity					
Occupancy Type: Provide a brief description of operations: Storage height of warehoused products:			education	education					
Storage height of wareh	oused products:		0						
Are flammable and combustible liquids stored in a cut-off room?		null							
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	Υ						
Protection:									
Are there any automatic	sprinklers?	N	V	What are th	ne design densities for each area?				
The water supply for au	tomatic sprinklers is?		H	How many	hydrants are located within 500 feet of buildings?		blank		
Indicate the Alarm Cove	rages provided for your fac	cility:	b	blank					
Are alarms connected to	a constantly attended loc	ation?	١	N					
Is there a watchman ser	vice?	Υ	V	What is the	e frequency of rounds?		daily		
Are watchman recording	g rounds?		١	N					
Are there any fire exting	uishers?	Υ	A	Are they se	erviced annually?		Υ		
Are there any hose stati	ons?	N	ls	Is there a fi	ire private fire brigade?		N		
Frequency of training re	ceived by the private fire b	rigade:	١	N					
Type of public fire depa	rtment:	Paid		Distance:			1 to 2 miles		
Exposure:									
How many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	1						
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):	commerc	cial					
Is there a body of water	nearby?	Υ	Descripti	tion:		irrigation ditch			
How far is the body of w	rater from major buildings?		200 feet						
Previous history of floo	ding?	null	Descripti	tion:					
Any property damage lo	sses in the past 3 years:	N	Descripti	tion:					

Flathead Lake

					Pa	ige 4
			Pro	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MISSOULA		
Property:	Prescott Center Cafeteria					
Property Address:	32125 Bio Station Lane PC	DLSON				
Property ID:	573					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	6113	
Year built:		1985		Number of stories:	2	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:		State Un	niversity			
Provide a brief description of operations:			Cafeteria	a-higher ed research station -serves faculty, staff & students		
Storage height of warehoused products:			0			
Are flammable and combustible liquids stored in a cut-off room?		N				
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automatic	sprinklers?	N		What are the design densities for each area?	no sprinklers	
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	1	
Indicate the Alarm Cove	rages provided for your fac	cility:		Smoke Detectors		
Are alarms connected to	a constantly attended loca	ation?		Υ		
Is there a watchman serv	vice?	Υ		What is the frequency of rounds?		
Are watchman recording	g rounds?			N		
Are there any fire exting	uishers?	Υ		Are they serviced annually?	Υ	
Are there any hose static	ons?	N		Is there a fire private fire brigade?	N	
Frequency of training re	ceived by the private fire b	rigade:				
Type of public fire depar	rtment:	Voluntary		Distance:	on-site	
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0			
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):				

Description:

Description:

Description:

550 yards

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

							. ago .
			Pro	operty Detail Form			
gency:	UNIVERSITY SYSTEM / UN	IIVERSITY SYSTEM, MONTANA T	ECH OF T	THE UM			
roperty:	Prospector Hall (Student Re	sidence-West)-H					
roperty Address:	1301 W. Park Street BUTTE						
roperty ID:	118						
construction:							
otal number of insured l	buildings:	1		Total square footage of insured buildings:	46809		
ear built:		1935		Number of stories:	4		
construction of roof:	1	Other		Construction of floors:	null		
construction of exterior	walls:	Other		Construction of interior walls:	null		
o major interior masonr	y walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			Res Apt	Complex			
rovide a brief description	on of operations:		Student	residence hall			
torage height of wareho	oused products:		N/A				
are flammable and comb	ustible liquids stored in a c	ut-off room?	N/A				
afegaurds taken for the	storage and dispensing of	lammable liquids:	N/A				
Protection:							
re there any automatic	sprinklers?	N		What are the design densities for each area?		110 psi static 65 residl	
he water supply for auto	omatic sprinklers is?	Private		How many hydrants are located within 500 feet of buildings?	?	6	
ndicate the Alarm Cover	ages provided for your facil	ity:		Fire Pump Alarms, Smoke Detectors, Sprinkler Valve Tamper, Sprinkler	prinkler Waterflo	W	
re alarms connected to	a constantly attended locat	ion?		Υ			
s there a watchman serv	rice?	Υ		What is the frequency of rounds?		2 per shift	
re watchman recording	rounds?			Υ			
are there any fire extingu	iishers?	Υ		Are they serviced annually?		Υ	
re there any hose statio	ons?	N		Is there a fire private fire brigade?		N	
requency of training rec	eived by the private fire bri	gade:					
ype of public fire depart	ment:	Paid		Distance:		0.86 miles	
exposure:							
low many buildings(not	part of Account) are within	100 feet of insured buildings?	0				

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

		Prop	perty Detail Form					
Agency: UNIVERSITY SYSTEM /	UNIVERSITY SYSTEM, MONTANA S	STATE UNIVE	ERSITY - NORTHERN					
Property: Pump House								
Property Address: MSU-Northern - 200 13th	Street HAVRE							
Property ID:								
Construction:								
Total number of insured buildings:	1		Total square footage of insured buildings:	100				
Year built:	1985		Number of stories:	1				
Construction of roof:	Other		Construction of floors:	Poured Concre	ete			
Construction of exterior walls:	Wood Frame		Construction of interior walls:	No Interior Wa	alls			
Do major interior masonry walls (fire walls) extend	d above the roofline?		N					
Occupancy:								
Оссирапсу Туре:		Pump Hou	ise					
Provide a brief description of operations:		well pump	well pump for football field					
Storage height of warehoused products:		n/a						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:								
Protection:								
Are there any automatic sprinklers?	N	w	hat are the design densities for each area?					
The water supply for automatic sprinklers is?		Н	ow many hydrants are located within 500 feet of buildings?		1			
Indicate the Alarm Coverages provided for your fa	acility:							
Are alarms connected to a constantly attended loo	cation?	N						
Is there a watchman service?	Υ	W	hat is the frequency of rounds?		every 24 hours			
Are watchman recording rounds?		N						
Are there any fire extinguishers?	N	Ar	re they serviced annually?		N			
Are there any hose stations?	N	Is	there a fire private fire brigade?		N			
Frequency of training received by the private fire I	brigade:							
Type of public fire department:	Paid	Di	istance:		1 mile			
Exposure:								
How many buildings(not part of Account) are with	in 100 feet of insured buildings?	0						
Describe the Occupancy of those buildings(s) nea	arby (within 100 feet):							
Is there a body of water nearby?	N	Description	on:					
How far is the body of water from major buildings	?							
Previous history of flooding?	N	Description	on:					
Any property damage losses in the past 3 years:	N	Description	on:					

			Property	Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UNIVERSI	TY - BOZEMAN				
Property:	REID HALL							
Property Address:	West Garfield Street (no of	ficial address) BOZEMAN						
Property ID:	115							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	90982			
Year built:		1959		Number of stories:	4			
Construction of roof:		Poured Concrete		Construction of floors:	Reinforced Cor	ncrete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry			
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			State University	,				
Provide a brief description	on of operations:		OFFICES/CLAS	OFFICES/CLASSROOMS				
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	N	What a	re the design densities for each area?				
The water supply for aut	omatic sprinklers is?		How m	any hydrants are located within 500 feet of buildings?	<b>?</b>	8		
Indicate the Alarm Cover	ages provided for your fac	ility:	Smoke	Detectors				
Are alarms connected to	a constantly attended loca	ition?	Υ					
Is there a watchman serv	rice?	Υ	What is	s the frequency of rounds?		AVERAGE 4 PER NIGHT		
Are watchman recording	rounds?		N					
Are there any fire exting	uishers?	Υ	Are the	ey serviced annually?		Υ		
Are there any hose static	ons?	N	Is there	e a fire private fire brigade?		N		
Frequency of training re-	ceived by the private fire b	igade:						
Type of public fire depar	tment:	Paid	Distan	ce:		1.14 MILES		
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Description:					
How far is the body of w	ater from major buildings?							
Previous history of flood	ling?	N	Description:					
Any property damage lo	sses in the past 3 years:	N	Description:					

Property Detail Form	
INIIVEDSITY - BOZEMAN	ı

			Pr	operty D	etail Form		
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA ST	TATE UN	IIVERSITY	- BOZEMAN		
Property:	RENNE LIBRARY						
Property Address:	West Garfield Street (no off	ficial address) BOZEMAN					
Property ID:	111						
Construction:							
Total number of insured	buildings:	1			Total square footage of insured buildings:	158813	
Year built:		1949			Number of stories:	4	
Construction of roof:		Reinforced Concrete			Construction of floors:	Reinforced Cor	ncrete
Construction of exterior	walls:	Glass and Steel Curtain			Construction of interior walls:	Masonry w/ Fir	e Doors
Do major interior masoni	ry walls (fire walls) extend a	above the roofline?			N		
Occupancy:							
Occupancy Type:			Library				
Provide a brief description	on of operations:		LIBRAR	RY/OFFICE	S/COMPUTING CENTER		
Storage height of warehoused products:			N/A				
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		PER NFPA 13
The water supply for auto	omatic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?		6
Indicate the Alarm Cover	ages provided for your fac	ility:	Burglar Alarms (Door Contacts), Sprinkler Waterflow, Smoke Detectors, Sprinkler Valve Tamper				
Are alarms connected to	a constantly attended loca	ition?		Υ			
Is there a watchman serv	rice?	Υ		What is t	he frequency of rounds?		AVERAGE 4 PER NIGHT
Are watchman recording	rounds?			N			
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ
Are there any hose static	ons?	N		Is there a	fire private fire brigade?		N
Frequency of training red	ceived by the private fire br	igade:					
Type of public fire depart	tment:	Paid		Distance	:		1.21 MILES
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):					
Is there a body of water r	nearby?	N	Descrip	otion:			
How far is the body of wa	ater from major buildings?						
Previous history of flood	ing?	N	Descrip	otion:			
Any property damage los	sses in the past 3 years:	Υ	Descrip	otion:			R DAMAGE DUE TO FROZEN INE - 12/24/02 LARGE FOUNTAIN DR LEAKING

			Pr	operty D	etail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UN	IIVERSITY	/ - BOZEMAN			
Property:	ROBERTS HALL							
Property Address:	West Garfield Street (no of	ficial address) BOZEMAN						
Property ID:	107							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	76057		
Year built:		1922			Number of stories:	4		
Construction of roof:		Wood Joists			Construction of floors:	Reinforced Co	oncrete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Gypsum Boar	rd	
Do major interior masoni	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			State U	niversity				
Provide a brief description	on of operations:		OFFICE	S/CLASS	ROOMS			
Storage height of warehoused products:			N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	N		What are	the design densities for each area?			
The water supply for auto	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?	?	4	
Indicate the Alarm Cover	ages provided for your fac	ility:		Burglar A	larms (Door Contacts), Smoke Detectors			
Are alarms connected to	a constantly attended loca	ation?		Υ				
ls there a watchman serv	rice?	Υ		What is t	the frequency of rounds?		AVERAGE 4 PER NIGHT	
Are watchman recording	rounds?			N				
Are there any fire extingu	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N	
Frequency of training red	ceived by the private fire b	rigade:						
Type of public fire depart	tment:	Paid		Distance	:		1.34 MILES	
Exposure:								
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	2					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	RESIDE	NTAL				
Is there a body of water r	nearby?	N	Descrip	otion:				
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Descrip	otion:				
Any property damage los	sses in the past 3 years:	N	Descrip	tion:				

						r age -
			Prop	perty Detail Form		
gency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	STATE UNIV	/ERSITY - BOZEMAN		
Property:	ROMNEY HALL					
Property Address:	West Grant Street (no office	ial address) BOZEMAN				
Property ID:	105					
Construction:						
otal number of insured	buildings:	1		Total square footage of insured buildings:	59260	
ear built:		1922		Number of stories:	4	
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concrete	е
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry	
o major interior mason	ry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief description	on of operations:		OFFICES	/GYM/POOL/CLASSROOMS		
storage height of wareho	oused products:		N/A			
are flammable and comb	oustible liquids stored in a	cut-off room?	N/A			
afegaurds taken for the	storage and dispensing of	flammable liquids:	N/A			
Protection:						
are there any automatic	sprinklers?	N	W	What are the design densities for each area?		
he water supply for aut	omatic sprinklers is?		н	low many hydrants are located within 500 feet of buildings?	5	5
ndicate the Alarm Cove	rages provided for your fac	ility:				
are alarms connected to	a constantly attended loca	ation?	N	l .		
s there a watchman serv	vice?	Υ	W	What is the frequency of rounds?	A	AVERAGE 4 PER NIGHT
are watchman recording	rounds?		N	l .		
are there any fire exting	uishers?	Υ	Α	are they serviced annually?	Y	<b>(</b>
are there any hose station	ons?	N	Is	s there a fire private fire brigade?	N	١
requency of training re	ceived by the private fire br	rigade:				
ype of public fire depar	tment:	Paid	D	Distance:	1	.25 MILES
xposure:						
·			·		·	

How many buildings(not part of Account) are within 100 feet of insured buildings? 0 Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Description:

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Description:

Any property damage losses in the past 3 years: N

Description:

							1 age 42	
			Prop	erty Detail Form				
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIVE	ERSITY - BOZEMAN				
Property:	ROSKIE RESIDENCE HA	LL						
Property Address:	West Grant Street (no office	cial address) BOZEMAN						
Property ID:	344							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	92491			
Year built:		1966		Number of stories:	11			
Construction of roof:		Poured Concrete		Construction of floors:	Poured Conci	rete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry			
Do major interior mason	ry walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Res Apt Co	omplex				
Provide a brief description of operations:		STUDENT	STUDENT DORM					
Storage height of warehoused products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?		N/A						
Safegaurds taken for the storage and dispensing of flammable liquids:		N/A						
Protection:								
Are there any automatic	sprinklers?	Υ	WI	hat are the design densities for each area?		PER NFPA 13		
The water supply for aut	omatic sprinklers is?		Ho	ow many hydrants are located within 500 feet of buildings	6			
Indicate the Alarm Cover	rages provided for your fac	cility:	Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loc	ation?	Υ					
Is there a watchman serv	vice?	Υ	WI	hat is the frequency of rounds?		3-4 TIMES PER NIGHT		
Are watchman recording	rounds?		Υ					
Are there any fire exting	uishers?	Υ	Ar	re they serviced annually?		N		
Are there any hose static	ons?	N	Is	there a fire private fire brigade?		null		
Frequency of training re-	ceived by the private fire b	rigade:						
Type of public fire depar	tment:	Paid	Di	stance:		1.18 MILES		
Exposure:								
How many buildings(not	part of Account) are withi	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Descriptio	on:				
How far is the body of w	ater from major buildings?							
Previous history of floor	ling?	N	Descriptio	on:				
Any property damage los	sses in the past 3 years:	N	Descriptio	on:				

hail damage to liability vehicles

					Page 4
			ı	Property Detail Form	
Agency:	UNIVERSITY SYSTEM / I	UNIVERSITY SYSTEM, MONTA	NA STATE (	JNIVERSITY - BOZEMAN	
Property:	ROY E. HUFFMAN BUILD	DING			
Property Address:	South 7th Avenue (no office	cial address) BOZEMAN			
Property ID:	441				
Construction:					
Total number of insure	d buildings:	1		Total square footage of insured buildings:	8843
Year built:		1969		Number of stories:	1
Construction of roof:		Wood Joists		Construction of floors:	Reinforced Concrete
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Masonry w/ Openings
Do major interior masonry walls (fire walls) extend above the roofline?				N	
Occupancy:					
Occupancy Type:			Police	e Station	
Provide a brief description of operations:			Admi	nistration, research labs, private police station	
Storage height of warehoused products:			N/A		
Are flammable and combustible liquids stored in a cut-off room?		N/A			
Safegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A		
Protection:					
Are there any automati	c sprinklers?	N		What are the design densities for each area?	no psrinklers
The water supply for au	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	2
Indicate the Alarm Cov	erages provided for your fa	cility:		Smoke Detectors	
Are alarms connected t	to a constantly attended loc	eation?		Υ	
Is there a watchman se	rvice?	Υ		What is the frequency of rounds?	
Are watchman recording	ng rounds?			N	
Are there any fire extin	guishers?	Υ		Are they serviced annually?	Υ
Are there any hose stat	tions?	N		Is there a fire private fire brigade?	N
Frequency of training r	eceived by the private fire b	origade:			
Type of public fire depart	artment:	Paid		Distance:	1.50 miles
Exposure:					
How many buildings(no	ot part of Account) are with	in 100 feet of insured buildings	<b>s?</b> 0		
Describe the Occupano	cy of those buildings(s) nea	rby (within 100 feet):			

Description:

Description:

Description:

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: Y

Ν

Ν

			Droport	/ Detail Form					
A goney:	LINIIVEDSITY SYSTEM / LI	NIVERSITY SYSTEM, UNIVERSITY							
Agency: Property:	Schreiber Gym	NIVERSITI STSTEM, UNIVERSITI	OF WONTANA	- MIGGOULA					
Property Address:	950 Keith Avenue MISSOL	ПΔ							
Property ID:	008	LA .							
Construction:	000								
Total number of insured I	huildings:	1		Total square footage of insured buildings:	39204				
Year built:	ounumgo.	1922		Number of stories:	1				
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:	Poured Concre	ete			
Construction of exterior v	walls:	Masonry		Construction of interior walls:	Other				
	y walls (fire walls) extend	•		N	<b>C</b>				
Occupancy:	y traile (in a traile) externa								
Occupancy Type:			State Universit	V					
Provide a brief descriptio	n of operations:			Offices, classrooms, gymnasium					
Storage height of warehoused products:		0							
Are flammable and combustible liquids stored in a cut-off room?		N/A							
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A						
Protection:									
Are there any automatic s	sprinklers?	N	What	are the design densities for each area?		no sprinklers			
The water supply for auto	omatic sprinklers is?		How r	nany hydrants are located within 500 feet of buildings?	•	4			
Indicate the Alarm Cover	ages provided for your fac	ility:							
Are alarms connected to	a constantly attended loca	ition?	Υ						
Is there a watchman serv	ice?	Υ	What	is the frequency of rounds?					
Are watchman recording	rounds?		Υ						
Are there any fire extingu	ishers?	Υ	Are th	ey serviced annually?		Υ			
Are there any hose statio	ns?	N	Is the	re a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid	Distar	nce:		under 1 mile			
Exposure:									
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water n	earby?	N	Description:						
How far is the body of wa	ter from major buildings?								
Previous history of flood	ing?	N	Description:						
Any property damage los	ses in the past 3 years:	N	Description:						

	Property Detail Form								
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA TE	ECH OF T	HE UM					
Property:	Science & Engineering Buil	ding (S&E)-H							
Property Address:	1300 W. Park Street BUTTI	E							
Property ID:	101								
Construction:									
Total number of insured I	ouildings:	1		Total square footage of insured buildings:	35094				
Year built:		1925		Number of stories:	3				
Construction of roof:		Other		Construction of floors:	null				
Construction of exterior	walls:	Other		Construction of interior walls:	null				
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		null					
Occupancy:									
Occupancy Type:			State Un	State University					
Provide a brief description of operations:			Classroo	ms & labs					
Storage height of warehoused products:			N/A						
Are flammable and combustible liquids stored in a cut-off room?		N							
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ						
Protection:									
Are there any automatic s	sprinklers?	N	,	What are the design densities for each area?					
The water supply for auto	omatic sprinklers is?		ı	How many hydrants are located within 500 feet of buildings?		8			
Indicate the Alarm Covera	ages provided for your fac	ility:	;	Smoke Detectors					
Are alarms connected to	a constantly attended loca	tion?	,	Y					
Is there a watchman serv	ice?	Υ	,	What is the frequency of rounds?		2 per shift			
Are watchman recording	rounds?		,	Υ					
Are there any fire extingu	ishers?	Υ		Are they serviced annually?		Υ			
Are there any hose statio	ns?	N	ļ	Is there a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid		Distance:		0.86			
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank						
Describe the Occupancy	of those buildings(s) near	oy (within 100 feet):							
Is there a body of water n	earby?	N	Descript	tion:					

Description:

Description:

Ν

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Previous history of flooding?

							Page 4
			Pro	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MISSOULA			
Property:	Science Complex - Charles	H. Clapp Bldg.					
Property Address:	845 Keith Avenue MISSOU	LA					
Property ID:	34						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	104662		
Year built:		1971		Number of stories:	4		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
Do major interior mason	ry walls (fire walls) extend a	bove the roofline?		null			
Occupancy:							
Occupancy Type:			State Ur	niversity			
Provide a brief descripti	on of operations:		null				
Storage height of warehoused products:			null				
Are flammable and com	oustible liquids stored in a c	cut-off room?	null				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	N		What are the design densities for each area?	ı	null	
Γhe water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	ı	null	
ndicate the Alarm Cove	rages provided for your faci	lity:					
Are alarms connected to	a constantly attended loca	tion?		null			
s there a watchman ser	vice?	null		What is the frequency of rounds?	I	null	
Are watchman recording	rounds?						
Are there any fire exting	uishers?	null		Are they serviced annually?	I	null	
Are there any hose stati	ons?	null		Is there a fire private fire brigade?	I	null	
requency of training re	ceived by the private fire br	igade:		null			
Type of public fire depar	tment:	null		Distance:	1	null	
Exposure:							
How many buildings(not	part of Account) are within	100 feet of insured buildings?					
Describe the Occupancy	of those buildings(s) nearb	y (within 100 feet):	null				
s there a body of water	nearby?	null	Descrip	ition:	null		
How far is the body of w	ater from major buildings?		null				

Description:

null

null

Previous history of flooding?

Any property damage losses in the past 3 years:

						1 490 12
			Proper	ty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MONTANA S	STATE UNIVER	SITY - BILLINGS		
Property:	Science Hall					
Property Address:	1500 University Drive BILL	INGS				
Property ID:	600000894/895					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	58837	
Year built:		1947		Number of stories:	3	
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			Laboratory			
Provide a brief descript	ion of operations:		education			
Storage height of warehoused products:		0				
Are flammable and combustible liquids stored in a cut-off room?		N/A				
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	Υ			
Protection:						
Are there any automatic	c sprinklers?	Υ	Wha	t are the design densities for each area?		
The water supply for au	tomatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	2	
Indicate the Alarm Cov	erages provided for your fac	cility:	Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected t	o a constantly attended loc	ation?	Υ			
Is there a watchman se	rvice?	Υ	Wha	t is the frequency of rounds?	daily	
Are watchman recording	g rounds?		N			
Are there any fire exting	guishers?	Υ	Are t	they serviced annually?	Υ	
Are there any hose stat	ions?	Υ	Is the	ere a fire private fire brigade?	N	
Frequency of training r	eceived by the private fire b	rigade:				
Type of public fire depart	artment:	Paid	Dista	ance:	1 to 2 miles	
Exposure:						
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0			
Describe the Occupano	y of those buildings(s) near	by (within 100 feet):				
Is there a body of water	nearby?	Υ	Description:		irrigation ditch	
How far is the body of v	water from major buildings?		200 feet			
Previous history of floo	ding?	N	Description:			
Any property damage l	osses in the past 3 years:	N	Description:			

							Page 4	
			Р	roperty Detail Form				
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA							
Property:	Sisson Apartments	Sisson Apartments						
Property Address:	1900 Maurice Avenue MIS	SOULA						
Property ID:	201							
Construction:								
Total number of insure	d buildings:	1		Total square footage of insured buildings:	77292			
Year built:		1957		Number of stories:	3			
Construction of roof:		null		Construction of floors:	null			
Construction of exterio	r walls:	null		Construction of interior walls:	null			
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null				
Occupancy:								
Occupancy Type:			Res Ap	ot Complex				
			null					
Storage height of warehoused products:			null					
Are flammable and combustible liquids stored in a cut-off room?			null					
Safegaurds taken for the storage and dispensing of flammable liquids:			null					
Protection:								
Are there any automatic	c sprinklers?	N		What are the design densities for each area?		null		
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null		
Indicate the Alarm Coverages provided for your facility:								
Are alarms connected to a constantly attended location?				null				
Is there a watchman se	rvice?	null		What is the frequency of rounds?		null		
Are watchman recording	g rounds?							
Are there any fire exting	guishers?	null		Are they serviced annually?		null		
Are there any hose stat	ions?	null		Is there a fire private fire brigade?		null		
Frequency of training received by the private fire brigade:			null					
Type of public fire depart	artment:	null		Distance:		null		
Exposure:								
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?						
Describe the Occupancy of those buildings(s) nearby (within 100 feet):			null					

Description: Is there a body of water nearby? null null

How far is the body of water from major buildings? null

Previous history of flooding? Description: null null

Any property damage losses in the past 3 years: null Description: null

							Page 4	
			P	roperty Detail Form				
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA							
Property:	Skaggs Building	Skaggs Building						
Property Address:	1325 Mansfield Avenue MIS	SSOULA						
Property ID:	93							
Construction:								
Total number of insured	l buildings:	1		Total square footage of insured buildings:	155356			
Year built:		1981		Number of stories:	4			
Construction of roof:		null		Construction of floors:	null			
Construction of exterior	walls:	null		Construction of interior walls:	null			
Do major interior masor	nry walls (fire walls) extend a	above the roofline?		null				
Occupancy:								
Occupancy Type:			State L	Iniversity				
Provide a brief description of operations:			null					
Storage height of warehoused products:			null					
Are flammable and combustible liquids stored in a cut-off room?			null					
Safegaurds taken for the storage and dispensing of flammable liquids:			null					
Protection:								
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		null		
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null		
Indicate the Alarm Coverages provided for your facility:								
Are alarms connected to a constantly attended location?				null				
Is there a watchman ser	vice?	null		What is the frequency of rounds?		null		
Are watchman recording	g rounds?							
Are there any fire exting	juishers?	null		Are they serviced annually?		null		
Are there any hose stati	ons?	null		Is there a fire private fire brigade?		null		
Frequency of training received by the private fire brigade:			null					
Type of public fire depart	rtment:	null		Distance:		null		
Exposure:								
How many buildings(no	t part of Account) are within	100 feet of insured buildings?						
Describe the Occupancy of those buildings(s) nearby (within 100 feet):			null					

Previous history of flooding?

Description:

Is there a body of water nearby? null

How far is the body of water from major buildings?

null

Any property damage losses in the past 3 years:

Description:

null

Description:

null null

					9			
			Property	Detail Form				
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOULA							
Property:	Social Science							
Property Address:	1010 Mansfield Avenue MISSOULA							
Property ID:	006							
Construction:								
Total number of insured buildings: 1			Total square footage of insured buildings:	81700				
Year built: 1921		1921		Number of stories:	4			
Construction of roof:	Construction of roof: Poured Concrete			Construction of floors:	Poured Concrete			
Construction of exterior	walls:	Masonry		Construction of interior walls:	Gypsum Board			
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			State University					
Provide a brief description	on of operations:		Offices, classroom					
Storage height of wareho	oused products:		0					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the storage and dispensing of flammable liquids:			N/A					
Protection:								
Are there any automatic	sprinklers?	N	What ar	re the design densities for each area?	0.1			
The water supply for auto	omatic sprinklers is?	Public	How ma	any hydrants are located within 500 feet of buildings?	2			
Indicate the Alarm Coverages provided for your facility:			Sprinkler Waterflow, Burglar Alarms (Door Contacts), Sprinkler Valve Tamper, Smoke Detectors					
Are alarms connected to a constantly attended location?			Υ					
Is there a watchman serv	ice?	Υ	What is	the frequency of rounds?	Campus police 24/7			
Are watchman recording	rounds?		Υ					
Are there any fire extingu	ishers?	Υ	Are the	y serviced annually?	Υ			
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?	N			
Frequency of training red	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid	Distanc	e:	under 1 mile			
Exposure:								
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	blank					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Description:					
How far is the body of wa	ater from major buildings?							
Previous history of flood	ing?	N	Description:					
Any property damage los	ses in the past 3 years:	N	Description:					

						- 3 -		
			Prop	erty Detail Form				
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE UNIVERSITY - BOZEMAN							
Property:	SOUTH HEDGES RESIDE	NCE HALL						
Property Address:	West Grant Street (no offici	ial address) BOZEMAN						
Property ID:	340							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	135347			
Year built:		1965		Number of stories:	11			
Construction of roof:		Steel Deck		Construction of floors: Poure		te		
Construction of exterior	walls:	Masonry		Construction of interior walls: Masonry w/ Opening		enings		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Res Apt Complex					
Provide a brief description	on of operations:		STUDENT DORM					
Storage height of wareho	oused products:		N/A					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A					
Protection:								
Are there any automatic s	sprinklers?	Υ	W	hat are the design densities for each area?		PER NFPA13		
The water supply for auto	omatic sprinklers is?	Public	Но	ow many hydrants are located within 500 feet of buildings?		8		
Indicate the Alarm Coverages provided for your facility:		Sn	noke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow					
Are alarms connected to a constantly attended location?			Υ					
Is there a watchman serv	rice?	Υ	W	hat is the frequency of rounds?		3-4 TIMES PER NIGHT		
Are watchman recording	rounds?		Υ					
Are there any fire extingu	uishers?	Υ	Ar	e they serviced annually?		Υ		
Are there any hose statio	ons?	N	Is	there a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	rigade:						
Type of public fire depart	ment:	Paid	Di	stance:		1.02 MILES		
Exposure:								
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water nearby?		Descriptio	on:					
How far is the body of wa	ater from major buildings?							
Previous history of flooding?		Description:						
Any property damage los	sses in the past 3 years:	N	Descriptio	n:				

no sprinklers

	Property Detail Fo
Agency:	UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, UNIVERSITY OF MONTANA - MISSOUL
Property:	Stone Hall (old Journalism)

**Property Address:** 825 McLeod Avenue MISSOULA

012 **Property ID:** 

Construction				
	L.V.	13.77		1
	CUI	P-14E-	Tall I	

Total number of insured buildings: 1 Total square footage of insured buildings: 32671

Year built: 1937 3 Number of stories:

**Poured Concrete** Construction of roof: Wood Joists Construction of floors:

Construction of exterior walls: Masonry Construction of interior walls: Other

Do major interior masonry walls (fire walls) extend above the roofline?

### Occupancy:

Protection:

**Occupancy Type:** State University

Provide a brief description of operations: Offices, classrooms

Storage height of warehoused products: 0

Are flammable and combustible liquids stored in a cut-off room? Ν

Safegaurds taken for the storage and dispensing of flammable liquids:

Are there any automatic sprinklers?

The water supply for automatic sprinklers is? How many hydrants are located within 500 feet of buildings?

Indicate the Alarm Coverages provided for your facility: **Smoke Detectors** 

Ν

Are alarms connected to a constantly attended location?

Is there a watchman service? Υ What is the frequency of rounds? Campus police 24/7

What are the design densities for each area?

Are watchman recording rounds?

Are there any fire extinguishers? Are they serviced annually?

Are there any hose stations? Ν Is there a fire private fire brigade? Ν

Frequency of training received by the private fire brigade:

Type of public fire department: Paid Distance: under 1 mile

## Exposure:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν Description:

How far is the body of water from major buildings?

Previous history of flooding? Ν Description: Any property damage losses in the past 3 years:

Description:

			Pro	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / UI	NIVERSITY SYSTEM, GREAT FALLS	S COLLE	GE MONTANA STATE UNIVERSITY			
Property:	Storage						
Property Address:	2100 16th Ave S GREAT F	ALLS					
Property ID:							
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured	buildings:	2000	
Year built:		2004		Number of stories:		1	
Construction of roof:		Steel Deck w/ Fasterners		Construction of floors:		Reinforced Cor	ncrete
Construction of exterior v	valls:	Corrugated Metal Panel		Construction of interior walls:		Gypsum Board	I
Do major interior masonry	y walls (fire walls) extend a	above the roofline?		N			
Occupancy:							
Occupancy Type:			Storage				
Provide a brief descriptio	n of operations:		equipme	nt storage			
Storage height of wareho	used products:		N/A				
Are flammable and combustible liquids stored in a cut-off room? N/A			N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	Υ				
Protection:							
Are there any automatic s	sprinklers?	N		What are the design densities for each a	ea?		none
The water supply for auto	matic sprinklers is?			How many hydrants are located within 50	00 feet of buildings?		4
Indicate the Alarm Covera	ages provided for your faci	ility:					
Are alarms connected to	a constantly attended loca	tion?		null			
Is there a watchman servi	ice?	Υ		What is the frequency of rounds?			hourly
Are watchman recording	rounds?			(			
Are there any fire extingu	ishers?	Υ		Are they serviced annually?			Υ
Are there any hose station	ns?	N		s there a fire private fire brigade?			N
Frequency of training rec	eived by the private fire br	igade:		N/A			
Type of public fire depart	ment:	Paid		Distance:			Local/Within city
Exposure:							
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) neark	y (within 100 feet):	N/A				
Is there a body of water n	earby?	N	Descrip	ion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descrip	ion:			
Any property damage los	ses in the past 3 years:	N	Descrip	ion:			

	<b>Property Detail Form</b>
UNIVERSITY SYSTEM / UNIVERSITY SYSTEM, MONTANA STATE	UNIVERSITY - BOZEMA
STRAND UNION BUILDING	

**Property Address:** 

Storage height of warehoused products:

West Grant Street (no official address) BOZEMAN

304 **Property ID:** 

Agency:

Property:

Total number of insured buildings: 1 Total square footage of insured buildings: 274751 Year built: 1939 Number of stories:

Construction of roof: Wood Joists Construction of floors: Poured Concrete

Construction of exterior walls: Masonry Construction of interior walls: Gypsum Board

N/A

Do major interior masonry walls (fire walls) extend above the roofline?

#### Occupancy:

**Occupancy Type:** State University

Provide a brief description of operations: OFFICES/THEATER/REC CENTER/CONFRENCE SER./BOOKSTORE

Are flammable and combustible liquids stored in a cut-off room? Ν

Safegaurds taken for the storage and dispensing of flammable liquids:

## Protection:

Υ PER NFPA 13 Are there any automatic sprinklers? What are the design densities for each area?

The water supply for automatic sprinklers is? **Public** How many hydrants are located within 500 feet of buildings? 7

Indicate the Alarm Coverages provided for your facility: Smoke Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow

Are alarms connected to a constantly attended location? Υ

Is there a watchman service? Υ What is the frequency of rounds? **OCCUPIED 24 HOURS** 

Are watchman recording rounds?

Are there any fire extinguishers? Υ Are they serviced annually?

Are there any hose stations? Is there a fire private fire brigade? Ν null

0

Frequency of training received by the private fire brigade:

**1.34 MILES** Type of public fire department: Paid Distance:

Exposure:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

How many buildings(not part of Account) are within 100 feet of insured buildings?

Is there a body of water nearby? Ν Description:

Ν

How far is the body of water from major buildings?

Previous history of flooding?

Description:

Any property damage losses in the past 3 years:

Description:

3/19/03 WATER DAMAGE DUE TO FROZEN SPRINKLER LINE/8/16/02 PROPYLENE GLYCOL LEAKED FROM HEATING SYSTE

						Page 4
			Pr	operty Detail Form		
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - MISSOULA		
Property:	Student Recreation Center					
Property Address:	800 Van Buren MISSOULA	A				
Property ID:	29					
Construction:						
Total number of insured	buildings:	1		Total square footage of insured buildings:	80297	
Year built:		2001		Number of stories:	2	
Construction of roof:		null		Construction of floors:	null	
Construction of exterior	walls:	null		Construction of interior walls:	null	
Do major interior mason	ry walls (fire walls) extend	above the roofline?		null		
Occupancy:						
Occupancy Type:			State U	niversity		
Provide a brief description	on of operations:		null			
Storage height of wareho	oused products:		null			
Are flammable and comb	oustible liquids stored in a	cut-off room?	null			
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	null			
Protection:						
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		null
The water supply for aut	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		null
Indicate the Alarm Cover	rages provided for your fac	ility:				
Are alarms connected to	a constantly attended loca	ation?		null		
Is there a watchman serv	vice?	null		What is the frequency of rounds?		null
Are watchman recording	rounds?					
Are there any fire exting	uishers?	null		Are they serviced annually?		null
Are there any hose static	ons?	null		Is there a fire private fire brigade?		null
Frequency of training re-	ceived by the private fire b	rigade:		null		
Type of public fire depar	tment:	null		Distance:		null
Exposure:						
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	null			
Is there a body of water	nearby?	null	Descrip	otion:	null	

null

Description:

Description:

null

null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

								- 3	
			Pr	operty D	etail Form				
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA S	TATE UN	IIVERSITY	/ - NORTHERN				
Property:	Student Union								
Property Address:	MSU-Northern 1150 - A S	UB Drive HAVRE							
Property ID:	22								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	29323			
Year built:		1960			Number of stories:	2			
Construction of roof:		Other			Construction of floors:	Poured Conci	rete		
Construction of exterior	walls:	Masonry			Construction of interior walls:	Masonry			
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			State U	niversity					
Provide a brief description	on of operations:		meet/sc	cial/office	/bookstore				
Storage height of warehoused products:			booksto	bookstore shelves 7'					
Are flammable and comb	oustible liquids stored in a	cut-off room?	N/A						
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		partial-basement rec area		
The water supply for auto	omatic sprinklers is?	Public		How man	ny hydrants are located within 500 feet of buildings?	<b>&gt;</b>	1		
Indicate the Alarm Cover	ages provided for your fac	ility:		Smoke D	etectors, Sprinkler Waterflow				
Are alarms connected to	a constantly attended loca	ation?		N					
ls there a watchman serv	rice?	Υ		What is t	the frequency of rounds?		every 24 hours		
Are watchman recording	rounds?			Υ					
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N		
Frequency of training red	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Paid		Distance	e:		1 mile		
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water r	nearby?	N	Descrip	otion:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ling?	N	Descrip	otion:					
Any property damage los	sses in the past 3 years:	N	Descrip	otion:					

							- 3 -	
			Prope	rty Detail Form				
gency:	UNIVERSITY SYSTEM / UN	NIVERSITY SYSTEM, MONTANA T	ECH OF THE	UM				
roperty:	Student Union Building							
roperty Address:	1300 W. Park Street BUTTE							
roperty ID:	111							
Construction:								
otal number of insured l	buildings:	1		Total square footage of insured buildings:	43322			
ear built:		1960		Number of stories:	2			
Construction of roof:		Steel Deck		Construction of floors:	Other			
construction of exterior v	walls:	Masonry		Construction of interior walls:	Masonry			
o major interior masonr	y walls (fire walls) extend a	bove the roofline?		null				
Occupancy:								
ccupancy Type:			State Univer	sity				
rovide a brief descriptio	on of operations:		Sution unin,	dining svcs/hall, meeting rooms				
torage height of wareho	oused products:		N/A					
re flammable and combustible liquids stored in a cut-off room?			N					
afegaurds taken for the	storage and dispensing of	flammable liquids:	Υ					
Protection:								
re there any automatic s	sprinklers?	N	Wha	at are the design densities for each area?				
he water supply for auto	omatic sprinklers is?		Hov	v many hydrants are located within 500 feet of buildings?	?	10		
ndicate the Alarm Cover	ages provided for your faci	lity:	Smo	oke Detectors				
are alarms connected to	a constantly attended locat	ion?	Υ					
s there a watchman serv	ice?	Υ	Wha	at is the frequency of rounds?		2 per shift		
re watchman recording	rounds?		Υ					
are there any fire extingu	iishers?	Υ	Are	they serviced annually?		Υ		
are there any hose statio	ns?	N	ls th	nere a fire private fire brigade?		N		
requency of training rec	eived by the private fire bri	gade:						
ype of public fire depart	ment:	Paid	Dist	ance:		0.86 miles		
xposure:								

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Any property damage losses in the past 3 years: N

Ν

Description:

Description:

Description:

						i ago io
			Proper	ty Detail Form		
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSITY	Y OF MONTANA	A - WESTERN		
Property:	Student Union Building					
Property Address:	710 S. Atlantic DILLON					
Property ID:	12					
Construction:						
Total number of insure	d buildings:	1		Total square footage of insured buildings:	15530	
Year built:		1958		Number of stories:	1	
Construction of roof:		Concrete Panels		Construction of floors:	Reinforced Concrete	
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Masonry w/ Openings	
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N		
Occupancy:						
Occupancy Type:			State Univers	ity		
Provide a brief descrip	tion of operations:		Offices, resta	urant, stores, radio station		
Storage height of ware	housed products:		N/A			
Are flammable and co	nbustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for t	he storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automat	c sprinklers?	N	Wha	t are the design densities for each area?		
The water supply for a	utomatic sprinklers is?	Public	How	many hydrants are located within 500 feet of buildings?	? 3	
Indicate the Alarm Cov	erages provided for your fa	cility:				
Are alarms connected	to a constantly attended loc	ation?	Υ			
Is there a watchman se	ervice?	Υ	Wha	t is the frequency of rounds?	Hourly	
Are watchman recordi	ng rounds?		Υ			
Are there any fire extir	guishers?	Υ	Are t	they serviced annually?	Υ	
Are there any hose sta	tions?	N	Is the	ere a fire private fire brigade?	N	
Frequency of training	received by the private fire b	rigade:				
Type of public fire dep	artment:	Voluntary	Dista	ance:	> 1 Mile	
Exposure:						
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	blank			
Describe the Occupan-	cy of those buildings(s) near	by (within 100 feet):				
Is there a body of water	r nearby?	N	Description:		Beaverhead River	
How far is the body of	water from major buildings?	•	< 1 mile			
Previous history of flo	oding?	N	Description:			
Any property damage	losses in the past 3 years:	N	Description:			

							. ago
			Pro	pperty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNI\	VERSITY - BOZEMAN			
Property:	SWINGLE HEALTH CENT	ER					
Property Address:	South 7th Avenue (no office	cial address) BOZEMAN					
Property ID:	346						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	22213		
Year built:		1957		Number of stories:	2		
Construction of roof:		Poured Concrete		Construction of floors:	Poured Cond	crete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Boa	ard	
Do major interior maso	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Clinics				
Provide a brief descript	ion of operations:		STUDEN	NT HEALTH CENTER			
Storage height of warel	noused products:		N/A				
Are flammable and com	nbustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automatic	c sprinklers?	N	V	What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?		H	How many hydrants are located within 500 feet of build	ings?	5	
Indicate the Alarm Cove	erages provided for your fa	cility:					
Are alarms connected t	o a constantly attended loc	ation?	١	N			
Is there a watchman se	rvice?	Υ	V	What is the frequency of rounds?		AVERAGE 4 PER NIGHT	
Are watchman recordin	g rounds?		١	N			
Are there any fire exting	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stat	ions?	N	l:	Is there a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:					
Type of public fire depart	artment:	Paid		Distance:		1.44 MILES	
Exposure:							
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupanc	y of those buildings(s) near	by (within 100 feet):					
Is there a body of water	nearby?	N	Descript	tion:			
How far is the body of v	water from major buildings?						
Previous history of floo	ding?	N	Descript	tion:			
Any property damage lo	osses in the past 3 years:	N	Descript	tion:			

						Page 44
			Property I	Detail Form		
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, UNIVERSIT	Y OF MONTANA - \	VESTERN		
Property:	Swysgood Technology Ce	nter (STC)				
Property Address:	710 South Atlantic DILLON	I				
Property ID:	51080					
Construction:						
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	24361	
Year built:		2002		Number of stories:	2	
Construction of roof:		Steel Deck		Construction of floors:	Poured Concrete	
Construction of exteri	or walls:	Masonry		Construction of interior walls:	Gypsum Board	
Do major interior mas	onry walls (fire walls) extend	above the roofline?		Υ		
Occupancy:						
Occupancy Type:			State University			
Provide a brief descrip	otion of operations:		CLASSROOMS/	RESOURCE CENTER		
Storage height of war	ehoused products:		N/A			
Are flammable and co	mbustible liquids stored in a	cut-off room?	N/A			
Safegaurds taken for t	the storage and dispensing o	f flammable liquids:	N/A			
Protection:						
Are there any automat	ic sprinklers?	Υ	What ar	e the design densities for each area?		
The water supply for a	utomatic sprinklers is?	Public	How ma	ny hydrants are located within 500 feet of buildings?	? 5	
Indicate the Alarm Co	verages provided for your fac	cility:	Smoke [	Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow		
Are alarms connected	to a constantly attended loc	ation?	Υ			
Is there a watchman s	ervice?	Υ	What is	the frequency of rounds?	HOUR	
Are watchman recordi	ng rounds?		Υ			
Are there any fire exti	nguishers?	Υ	Are they	y serviced annually?	Υ	
Are there any hose sta	ations?	N	Is there	a fire private fire brigade?	N	
Frequency of training	received by the private fire b	rigade:				
Type of public fire dep	partment:	Voluntary	Distanc	e:	12 BLOCKS	
Exposure:						
How many buildings(r	not part of Account) are withi	n 100 feet of insured buildings?	2			
Describe the Occupan	cy of those buildings(s) near	by (within 100 feet):	LIBRARY/CLASS	SROOMS		
Is there a body of wate	er nearby?	Υ	Description:			
How far is the body of	water from major buildings?		1 MILE			
Previous history of flo	oding?	N	Description:			
Any property damage	losses in the past 3 years:	N	Description:			

			Pr	operty D	etail Form		
Agency:	UNIVERSITY SYSTEM / UNIVERSITY / UNIVERSITY SYSTEM / UNIVERSITY / UNIVERSITY / UNIVERSITY / UNIVERSITY / U	NIVERSITY SYSTEM, MONTANA ST	TATE UN	IIVERSITY	′ - BOZEMAN		
Property:	TAYLOR HALL						
Property Address:	South 11th Avenue (no office	cial address) BOZEMAN					
Property ID:	108						
Construction:							
Total number of insured b	ouildings:	1			Total square footage of insured buildings:	9936	
Year built:		1896			Number of stories:	3	
Construction of roof:		Wood Joists			Construction of floors:	Poured Concre	ete
Construction of exterior v	valls:	Tilt-Up Concrete			Construction of interior walls:	Gypsum Board	d
Do major interior masonry	y walls (fire walls) extend a	above the roofline?			N		
Occupancy:							
Occupancy Type:			Office				
Provide a brief description	n of operations:		Offices				
Storage height of wareho	used products:		N/A				
Are flammable and combi	ustible liquids stored in a d	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A				
Protection:							
Are there any automatic s	prinklers?	Υ		What are	the design densities for each area?		140' sq/sprinkler
The water supply for auto	matic sprinklers is?	Public		How mar	ny hydrants are located within 500 feet of buildings?		2
Indicate the Alarm Covera	ages provided for your faci	ility:		Sprinkler	Waterflow, Sprinkler Valve Tamper, Smoke Detectors		
Are alarms connected to	a constantly attended loca	tion?		Υ			
Is there a watchman servi	ce?	N		What is t	he frequency of rounds?		
Are watchman recording	rounds?			N			
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ
Are there any hose station	ns?	N		Is there a	a fire private fire brigade?		N
Frequency of training rec	eived by the private fire br	igade:					
Type of public fire departi	ment:	Paid		Distance	:		1/25 miles
Exposure:							
How many buildings(not p	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) nearb	oy (within 100 feet):					
Is there a body of water n	earby?	N	Descrip	otion:			
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Descrip	otion:			
Any property damage los	ses in the past 3 years:	N	Descrip	otion:			

							Page 4
			F	Property Detail Form			
gency:	UNIVERSITY SYSTEM / L	UNIVERSITY SYSTEM, MONTANA	STATE L	JNIVERSITY - NORTHERN			
Property:	Tiber 2 bedroom home						
roperty Address:	206 Tiber Drive HAVRE						
Property ID:	13E						
Construction:							
otal number of insure	d buildings:	1		Total square footage of insured buildings:	660		
ear built:		1957		Number of stories:			
construction of roof:		Other		Construction of floors:	Vood Timber		
construction of exterio	r walls:	Wood Frame		Construction of interior walls:	Other		
o major interior maso	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Cotta	ges/Residential			
Provide a brief descrip	tion of operations:		reside	ential			
storage height of ware	housed products:		n/a				
are flammable and con	nbustible liquids stored in a	cut-off room?	N/A				
afegaurds taken for th	ne storage and dispensing o	of flammable liquids:	N/A				
Protection:							
are there any automati	c sprinklers?	N		What are the design densities for each area?		n/a	
he water supply for au	utomatic sprinklers is?			How many hydrants are located within 500 feet of buildings?		1	
ndicate the Alarm Cov	erages provided for your fa	cility:		Smoke Detectors			
are alarms connected t	to a constantly attended loc	eation?		N			
s there a watchman se	rvice?	Υ		What is the frequency of rounds?		every 24 hours	
are watchman recordin	ng rounds?			Y			
are there any fire extin	guishers?	Υ		Are they serviced annually?		Υ	
are there any hose stat	tions?	N		Is there a fire private fire brigade?		N	
requency of training r	eceived by the private fire b	origade:					
ype of public fire depart	artment:	Paid		Distance:		1 mile	
xposure:							
low many buildings(no	ot part of Account) are withi	in 100 feet of insured buildings?	0				
escribe the Occupand	cy of those buildings(s) nea	rby (within 100 feet):					
s there a body of water	r nearby?	N	Desci	ription:			

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

Ν

							i ago i		
			Property	Detail Form					
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	TATE UNIVERSI	TY - NORTHERN					
Property:	Tiber 2 bedroom house								
Property Address:	208 Tiber Drive HAVRE								
Property ID:	13F								
Construction:									
Total number of insure	d buildings:	1		Total square footage of insured buildings:	660				
Year built:		1957		Number of stories:	1				
Construction of roof:		Other		Construction of floors:	Wood Timber				
Construction of exterio	r walls:	Wood Frame		Construction of interior walls:	Other				
Do major interior masonry walls (fire walls) extend above the roofline?				N					
Occupancy:									
Occupancy Type:			Cottages/Resid	ential					
Provide a brief descript	ion of operations:		residential						
Storage height of warel	noused products:		n/a						
Are flammable and con	nbustible liquids stored in a	cut-off room?	N/A						
Safegaurds taken for th	Safegaurds taken for the storage and dispensing of flammable liquids:  N/A								
Protection:									
Are there any automatic	c sprinklers?	N	What a	re the design densities for each area?					
The water supply for au	tomatic sprinklers is?		How m	any hydrants are located within 500 feet of buildings?	>	1			
Indicate the Alarm Cov	erages provided for your fac	cility:	Smoke	Detectors					
Are alarms connected t	o a constantly attended loc	ation?	N						
Is there a watchman se	rvice?	Υ	What i	s the frequency of rounds?		every 24 hours			
Are watchman recording	g rounds?		Υ						
Are there any fire exting	guishers?	Υ	Are the	ey serviced annually?		Υ			
Are there any hose stat	ions?	N	Is there	e a fire private fire brigade?		N			
Frequency of training r	eceived by the private fire b	rigade:							
Type of public fire depart	artment:	Paid	Distan	ce:		1 mile			
Exposure:									
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0						
Describe the Occupano	y of those buildings(s) near	rby (within 100 feet):							
Is there a body of water	nearby?	N	Description:						
How far is the body of	vater from major buildings?	•							
Previous history of floo	oding?	N	Description:						
Any property damage le	osses in the past 3 years:	N	Description:						

	Property Detail Form								
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVE	ERSITY - NORTHERN					
Property:	Tiber 2 bedroom house								
Property Address:	210 Tiber Drive HAVRE								
Property ID:	13G								
Construction:									
Total number of insured	buildings:	1		Total square footage of insured buildings:	660				
Year built:		1957		Number of stories:	1				
Construction of roof:		Other		Construction of floors:	Wood Timber				
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Other				
Do major interior masonry walls (fire walls) extend above the roofline?				N					
Occupancy:									
Occupancy Type:			Cottages/F	Residential					
Provide a brief description	on of operations:		residential						
Storage height of warehoused products:									
Are flammable and combustible liquids stored in a cut-off room?  N/A									
Safegaurds taken for the	Safegaurds taken for the storage and dispensing of flammable liquids: N/A								
Protection:									
Are there any automatic s	sprinklers?	N	W	hat are the design densities for each area?					
The water supply for auto	omatic sprinklers is?		Н	ow many hydrants are located within 500 feet of buildings?		0			
Indicate the Alarm Cover	ages provided for your fac	ility:	Sr	moke Detectors					
Are alarms connected to	a constantly attended loca	ition?	N						
Is there a watchman serv	ice?	Υ	W	hat is the frequency of rounds?		every 24 hours			
Are watchman recording	rounds?		Υ						
Are there any fire extingu	iishers?	Υ	Aı	re they serviced annually?		Υ			
Are there any hose statio	ns?	N	Is	there a fire private fire brigade?		N			
Frequency of training rec	eived by the private fire b	rigade:							
Type of public fire depart	ment:	Paid	Di	istance:		1 mile			
Exposure:									
How many buildings(not	How many buildings(not part of Account) are within 100 feet of insured buildings? 0								
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):							
Is there a body of water n	nearby?	N	Description	on:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Description	on:					

Any property damage losses in the past 3 years: N

							Page 4
			Р	Property Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA	STATE U	INIVERSITY - NORTHERN			
Property:	Tiber One Bedroom						
Property Address:	204 Tiber Drive HAVRE						
Property ID:	13C						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	566		
fear built:		1957		Number of stories:	1		
Construction of roof:		Other		Construction of floors:	Wood Timber	r	
Construction of exterio	r walls:	Wood Frame		Construction of interior walls:	Other		
Oo major interior maso	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Cottag	ges/Residential			
Provide a brief descript	ion of operations:		reside	ential			
Storage height of wareh	noused products:		n/a				
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automation	sprinklers?	N		What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?			How many hydrants are located within 500 feet of building	gs?	1	
ndicate the Alarm Cove	erages provided for your fa	cility:		Smoke Detectors			
Are alarms connected t	o a constantly attended loc	ation?		N			
s there a watchman se	rvice?	Υ		What is the frequency of rounds?		every 24 hours	
Are watchman recordin	g rounds?			Y			
Are there any fire exting	guishers?	Υ		Are they serviced annually?		Υ	
Are there any hose stat	ions?	N		Is there a fire private fire brigade?		N	
requency of training re	eceived by the private fire b	rigade:					
Гуре of public fire depa	rtment:	Paid		Distance:		1 mile	
Exposure:							
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupanc	y of those buildings(s) nea	rby (within 100 feet):					
s there a body of water	nearby?	N	Descri	ription:			

Description:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:  $\ \ N$ 

Ν

							Page 4
			Prop	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA S	TATE UNIV	ERSITY - NORTHERN			
Property:	Tiber One Bedroom						
Property Address:	202 Tiber Drive HAVRE						
Property ID:	13B						
Construction:							
Total number of insured	l buildings:	1		Total square footage of insured buildings:	566		
Year built:		1957		Number of stories:	1		
Construction of roof:		Other		Construction of floors:	Wood Timber		
Construction of exterior	walls:	Wood Frame		Construction of interior walls:	Other		
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Cottages/F	Residential			
Provide a brief descripti	ion of operations:		residential				
Storage height of warehoused products:			n/a				
Are flammable and combustible liquids stored in a cut-off room?							
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automatic	sprinklers?	N	w	hat are the design densities for each area?			
The water supply for au	tomatic sprinklers is?		H	ow many hydrants are located within 500 feet of buildings?	?	1	
Indicate the Alarm Cove	rages provided for your fac	cility:	Sı	moke Detectors			
Are alarms connected to	o a constantly attended loca	ation?	N				
Is there a watchman ser	vice?	Υ	w	hat is the frequency of rounds?		every 24 hours	
Are watchman recording	g rounds?		Υ				
Are there any fire exting	juishers?	Υ	Α	re they serviced annually?		Υ	
Are there any hose stati	ons?	N	Is	there a fire private fire brigade?		N	
Frequency of training re	eceived by the private fire b	rigade:					
Type of public fire depart	rtment:	Paid	D	istance:		1 mile	
Exposure:							
How many buildings(no	t part of Account) are within	n 100 feet of insured buildings?	0				
Describe the Occupancy	y of those buildings(s) near	by (within 100 feet):					
Is there a body of water	nearby?	N	Description	on:			

Description:

Ν

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

								- 3 -
			Р	roperty [	Detail Form			
gency:	UNIVERSITY SYSTEM / U	JNIVERSITY SYSTEM, MONTANA S	STATE UI	NIVERSIT	Y - NORTHERN			
Property:	Tiber One Bedroom							
roperty Address:	200 Tiber Drive HAVRE							
Property ID:	13A							
Construction:								
otal number of insured	l buildings:	1			Total square footage of insured buildings:	566		
ear built:		1957			Number of stories:	1		
Construction of roof:		Other			Construction of floors:	Wood Timber		
Construction of exterior	walls:	Wood Frame			Construction of interior walls:	Other		
o major interior masor	nry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			Cottag	es/Resider	ntial			
Provide a brief descript	ion of operations:		resider	ntial				
Storage height of wareh	oused products:		n/a					
are flammable and com	bustible liquids stored in a	cut-off room?	N/A					
afegaurds taken for the	e storage and dispensing o	of flammable liquids:	N/A					
Protection:								
are there any automatic	sprinklers?	N		What are	e the design densities for each area?			
he water supply for au	tomatic sprinklers is?			How ma	ny hydrants are located within 500 feet of buildings?		1	
ndicate the Alarm Cove	rages provided for your fa	cility:		Smoke D	Detectors			
are alarms connected to	o a constantly attended loc	ation?		null				
s there a watchman ser	vice?	Υ		What is	the frequency of rounds?		eveery 24 hours	
are watchman recording	g rounds?			Υ				
are there any fire exting	juishers?	Υ		Are they	serviced annually?		Υ	
are there any hose stati	ons?	N		Is there	a fire private fire brigade?		N	
requency of training re	eceived by the private fire b	origade:						
ype of public fire depa	rtment:	Paid		Distance	9:		1 mile	
xposure:								
low many buildings(no	t part of Account) are withi	n 100 feet of insured buildings?	0					
escribe the Occupancy	y of those buildings(s) nea	rby (within 100 feet):						
s there a body of water	nearby?	N	Descri	ption:				
low far is the body of w	ater from major buildings?	?						

Description:

Previous history of flooding?

Any property damage losses in the past 3 years: N

Ν

							Page 4
			Propert	ty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIVER	SITY - NORTHERN			
Property:	Tiber One Bedroom						
Property Address:	212 Tiber Drive HAVRE						
Property ID:	13D						
Construction:							
Total number of insure	ed buildings:	1		Total square footage of insured buildings:	533		•
Year built:		1957		Number of stories:	1		
Construction of roof:		Other		Construction of floors:	Wood Timber		
Construction of exterio	or walls:	Wood Frame		Construction of interior walls:	Other		
Do major interior maso	onry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Cottages/Res	idential			
Provide a brief descrip	otion of operations:		residential				
Storage height of ware	ehoused products:		n/a				
Are flammable and cor	mbustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for t	he storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automat	ic sprinklers?	N	Wha	t are the design densities for each area?			
The water supply for a	utomatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	?	0	
Indicate the Alarm Cov	verages provided for your fa	cility:	Smol	ke Detectors			
Are alarms connected	to a constantly attended loc	ation?	N				
Is there a watchman se	ervice?	Υ	Wha	t is the frequency of rounds?		every 24 hours	
Are watchman recordi	ng rounds?		Υ				
Are there any fire extir	nguishers?	Υ	Are t	hey serviced annually?		Υ	
Are there any hose sta	ations?	N	Is the	ere a fire private fire brigade?		N	
Frequency of training	received by the private fire b	origade:					
Type of public fire dep	partment:	Paid	Dista	ance:		1 mile	
Exposure:							
How many buildings(n	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupan	cy of those buildings(s) nea	rby (within 100 feet):					
Is there a body of water	er nearby?	N	Description:				
How far is the body of	water from major buildings?	?					
Previous history of flo	oding?	N	Description:				

Any property damage losses in the past 3 years: N

Property Detail Form								
Agency:	UNIVERSITY SYSTEM / U	INIVERSITY SYSTEM, MONTANA S	TATE UNIVERSIT	TY - BOZEMAN				
Property:	TIETZ HALL							
Property Address:	East of South 11th Avenue	(no official address) BOZEMAN						
Property ID:	133							
Construction:								
Total number of insured	buildings:	1		Total square footage of insured buildings:	20471			
Year built:		1985		Number of stories:	1			
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Co	oncrete		
Construction of exterior	walls:	Masonry		Construction of interior walls:	Masonry w/ F	ire Doors		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		N				
Occupancy:								
Occupancy Type:			Laboratory					
Provide a brief description	on of operations:		RESEARCH OF	FICES/LABS				
Storage height of wareho	used products:		N/A					
Are flammable and comb	ustible liquids stored in a	cut-off room?	N/A					
Safegaurds taken for the storage and dispensing of flammable liquids: N/A								
Protection:								
Are there any automatic	sprinklers?	Υ	What ar	re the design densities for each area?		PER NFPA 13		
The water supply for auto	omatic sprinklers is?	Public	How ma	any hydrants are located within 500 feet of buildings	?	6		
Indicate the Alarm Cover	ages provided for your fac	sility:	Sprinkle	er Valve Tamper, Smoke Detectors, Burglar Alarms (Doo	r Contacts), Spr	inkler Waterflow		
Are alarms connected to	a constantly attended loca	ation?	Υ					
Is there a watchman serv	ice?	Υ	What is	the frequency of rounds?		AVERAGE 4 NIGHT		
Are watchman recording	rounds?							
Are there any fire extingu	ishers?	Υ	Are the	y serviced annually?		Υ		
Are there any hose statio	ns?	N	Is there	a fire private fire brigade?		N		
Frequency of training red	eived by the private fire b	rigade:						
Type of public fire depart	ment:	Paid	Distanc	ee:		.99 MILES		
Exposure:								
How many buildings(not	part of Account) are withir	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water r	nearby?	N	Description:					
How far is the body of wa	nter from major buildings?							
Previous history of flood	ing?	N	Description:					
Any property damage los	ses in the past 3 years:	Y	Description:		10/2/02 WATE LINE	ER DAMAGE FROZEN SPRINKLER		

							Page 45
			Property	Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIVERSI	TY - BILLINGS			
Property:	Townhomes (student hous	sing) 32 Mountain View					
Property Address:	32 Mountain View BILLING	GS					
Property ID:	600008333						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	9712		
Year built:		1970		Number of stories:	2		
Construction of roof:		Wood Joists		Construction of floors:	Poured Concrete		
Construction of exterio	r walls:	Wood Frame		Construction of interior walls:	Gypsum Board		
Do major interior maso	nry walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			Cottages/Resid	ential			
Provide a brief descript	ion of operations:		student housing				
Storage height of warel	noused products:		0				
Are flammable and con	nbustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for th	e storage and dispensing o	of flammable liquids:	N/A				
Protection:							
Are there any automatic	c sprinklers?	Υ	What a	re the design densities for each area?			
The water supply for au	tomatic sprinklers is?	Public	How m	any hydrants are located within 500 feet of buildings?	1		
Indicate the Alarm Cov	erages provided for your fa	cility:	Smoke	Detectors, Sprinkler Valve Tamper, Sprinkler Waterflow			
Are alarms connected t	o a constantly attended loc	ation?	Υ				
Is there a watchman se	rvice?	Υ	What is	s the frequency of rounds?	da	aily	
Are watchman recording	g rounds?		N				
Are there any fire exting	guishers?	Υ	Are the	ey serviced annually?	Υ		
Are there any hose stat	ions?	N	Is there	e a fire private fire brigade?	N		
Frequency of training r	eceived by the private fire b	rigade:					
Type of public fire depart	artment:	Paid	Distan	ce:	1 1	to 2 miles	
Exposure:							
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	1				
Describe the Occupano	y of those buildings(s) near	rby (within 100 feet):	private residence	ee e			
Is there a body of water	nearby?	Υ	Description:		irrigation ditch		
How far is the body of	water from major buildings?	•	200 feet				
Previous history of floo	ding?	N	Description:				
Any property damage l	osses in the past 3 years:	N	Description:				

			Pro	perty D	etail Form				
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - M	IISSOULA				
Property:	Trade & Technology I								
Property Address:	3639 S Ave W. MISSOULA	Ą							
Property ID:	452								
Construction:									
Total number of insured	buildings:	1			Total square footage of insured buildings:	30412			
Year built:		1972			Number of stories:	2			
Construction of roof:		Steel Deck w/ Fasterners			Construction of floors:	Poured Conc	rete		
Construction of exterior	walls:	Glass and Steel Curtain			Construction of interior walls:	Gypsum Boar	rd		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N				
Occupancy:									
Occupancy Type:			State Un	niversity					
Provide a brief description	on of operations:		Offices/c	lassroom	as				
Storage height of wareho	oused products:		0						
Are flammable and comb	oustible liquids stored in a	cut-off room?	N						
Safegaurds taken for the	storage and dispensing o	f flammable liquids:	Υ						
Protection:									
Are there any automatic	sprinklers?	N	,	What are	the design densities for each area?		no sprinklers		
The water supply for aut	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings	?	0		
Indicate the Alarm Cover	ages provided for your fac	cility:		Smoke D	etectors				
Are alarms connected to	a constantly attended loca	ation?		Υ					
ls there a watchman serv	rice?	Υ	,	What is t	the frequency of rounds?		Campus police 24/7		
Are watchman recording	rounds?			Υ					
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose static	ons?	N		Is there a	a fire private fire brigade?		N		
Frequency of training red	ceived by the private fire b	rigade:							
Type of public fire depar	tment:	Paid		Distance	ı:		between 1 & 2 miles		
Exposure:									
How many buildings(not	part of Account) are within	n 100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) near	rby (within 100 feet):							
ls there a body of water i	nearby?	N	Descript	tion:					
low far is the body of water from major buildings?									
Previous history of flood	ling?	N	Descript	tion:					
Any property damage los	sses in the past 3 years:	N	Descript	tion:					

			Pro	operty D	etail Form					
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - M	ISSOULA					
Property:	Trade & Technology II									
Property Address:	3639 S Ave W. MISSOULA	1								
Property ID:	453									
Construction:										
Total number of insured I	buildings:	1			Total square footage of insured buildings:	34340				
Year built:		1977			Number of stories:	1				
Construction of roof:		Steel Deck			Construction of floors:	Poured Concr	rete			
Construction of exterior v	walls:	null			Construction of interior walls:	null				
Do major interior masonr	y walls (fire walls) extend	above the roofline?			null					
Occupancy:										
Occupancy Type:			State Ur	niversity						
Provide a brief descriptio	n of operations:		Classroo	oms/office	s/shops					
Storage height of wareho	used products:		0							
Are flammable and comb	ustible liquids stored in a	cut-off room?	N							
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	Υ							
Protection:										
Are there any automatic s	sprinklers?	N		What are	the design densities for each area?		no sprinklers			
The water supply for auto	omatic sprinklers is?			How mar	ny hydrants are located within 500 feet of buildings?		0			
Indicate the Alarm Cover	ages provided for your fac	ility:								
Are alarms connected to	a constantly attended loca	ation?		N						
Is there a watchman serv	ice?	Υ		What is t	he frequency of rounds?		Campus police 24/7			
Are watchman recording	rounds?			Υ						
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ			
Are there any hose statio	ns?	N		Is there a	ifire private fire brigade?		N			
Frequency of training rec	eived by the private fire b	rigade:								
Type of public fire depart	ment:	Paid		Distance	:		under 1 mile			
Exposure:										
How many buildings(not	part of Account) are withir	100 feet of insured buildings?	0							
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):								
Is there a body of water n	earby?	N	Descrip	tion:						
How far is the body of wa	How far is the body of water from major buildings?									
Previous history of flood	ing?	N	Descrip	tion:						
Any property damage los	ses in the past 3 years:	N	Descrip	tion:						

	Property Detail Form								
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, GREAT FALLS	S COLLEG	GE MONTA	ANA STATE UNIVERSITY				
Property:	Trades Building								
Property Address:	2100 16th Ave S GREAT F	ALLS							
Property ID:	850								
Construction:									
Total number of insured b	ouildings:	1		т	Total square footage of insured buildings:	12000			
Year built:		2008		N	Number of stories:	2			
Construction of roof:		Steel Deck w/ Fasterners		C	Construction of floors:	Reinforced Co	oncrete		
Construction of exterior v	valls:	Masonry		C	Construction of interior walls:	Masonry w/ Fi	re Doors		
Do major interior masonr	y walls (fire walls) extend a	above the roofline?		Y	(				
Occupancy:									
Occupancy Type:			State Uni	iversity					
Provide a brief descriptio	n of operations:		classroom	ms & workiı	ng area for carpentry and welding classes				
Storage height of wareho	used products:		N/A						
Are flammable and combustible liquids stored in a cut-off room?									
Safegaurds taken for the storage and dispensing of flammable liquids:									
Protection:									
Are there any automatic s	sprinklers?	Υ	V	What are tl	he design densities for each area?		15 SF		
The water supply for auto	matic sprinklers is?	Public	F	How many	hydrants are located within 500 feet of buildings?		4		
Indicate the Alarm Covera	ages provided for your fac	ility:	Burglar Alarms (Motion Detection), Smoke Detectors, Sprinkler Valve Tamper						
Are alarms connected to	a constantly attended loca	ition?	Y	Υ					
Is there a watchman servi	ice?	Υ	V	What is the	e frequency of rounds?		hourly		
Are watchman recording	rounds?		Y	Υ					
Are there any fire extingu	ishers?	Υ	A	Are they se	erviced annually?		Υ		
Are there any hose statio	ns?	N	ls	ls there a f	ire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	igade:	N	N/A					
Type of public fire depart	ment:	Paid	С	Distance:			Local/Within City		
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0						
Describe the Occupancy	of those buildings(s) nearl	by (within 100 feet):	N/A						
Is there a body of water n	earby?	N	Descripti	tion:		N/A			
How far is the body of wa	ter from major buildings?		N/A						
Previous history of floodi	ng?	N	Descripti	tion:		N/A			
Any property damage los	ses in the past 3 years:	N	Descripti	tion:		N/A			

Dec'07- broken water pipe

							Page 4
			Pro	perty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, MON	ITANA STATE UNIV	/ERSITY - NORTHERN			
Property:	Trades Lab						
Property Address:	MSU-Northern 1121 Buttre	y Drive HAVRE					
Property ID:	24						
Construction:							
Total number of insured	d buildings:	1		Total square footage of insured buildings:	3382		
ear built:		1960		Number of stories:	2		
Construction of roof:		Other		Construction of floors:	Other		
Construction of exterior	r walls:	Wood Frame		Construction of interior walls:	Gypsum Boa	rd	
Do major interior masor	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Other				
Provide a brief descript	ion of operations:		lab for plu	mb/elect/const			
Storage height of wareh	noused products:		n/a				
Are flammable and com	bustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for th	e storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automation	sprinklers?	N	v	What are the design densities for each area?			
The water supply for au	tomatic sprinklers is?		H	low many hydrants are located within 500 feet of buildi	ngs?	1	
ndicate the Alarm Cove	erages provided for your fac	cility:	S	Smoke Detectors			
Are alarms connected to	o a constantly attended loca	ation?	N	I			
s there a watchman ser	rvice?	Υ	v	What is the frequency of rounds?		every 24 hours	
Are watchman recordin	g rounds?		Y	,			
Are there any fire exting	guishers?	Υ	A	re they serviced annually?		Υ	
Are there any hose stat	ions?	N	ls	s there a fire private fire brigade?		N	
requency of training re	eceived by the private fire b	rigade:					
Гуре of public fire depa	rtment:	Paid		Distance:		1 mile	
Exposure:							
low many buildings(no	ot part of Account) are within	n 100 feet of insured buildi	nas? 0				

Description:

Description:

Description:

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Ν

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: Y

			Proper	ty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, MONTANA S	TATE UNIVER	SITY - BOZEMAN			
Property:	TRAPHAGEN HALL						
Property Address:	West of South 11th Avenue	e (no official address) BOZEMAN					
Property ID:	102						
Construction:							
Total number of insured b	ouildings:	1		Total square footage of insured buildings:	37234		
Year built:		1920		Number of stories:	4		
Construction of roof:		Wood Joists		Construction of floors:	Poured Concr	rete	
Construction of exterior w	valls:	Masonry		Construction of interior walls:	Gypsum Boar	d	
Do major interior masonry	y walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			State Univers	sity			
Provide a brief description	n of operations:		OFFICES/CL	ASSROOMS			
Storage height of wareho	used products:		N/A				
Are flammable and combu	ustible liquids stored in a	cut-off room?	N/A				
Safegaurds taken for the	storage and dispensing of	f flammable liquids:	N/A				
Protection:							
Are there any automatic s	prinklers?	N	Wha	t are the design densities for each area?			
The water supply for auto	matic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	?	6	
Indicate the Alarm Covera	iges provided for your fac	ility:					
Are alarms connected to a	a constantly attended loca	ation?	N				
ls there a watchman servi	ce?	Υ	Wha	t is the frequency of rounds?		AVERAGE 4 PER NIGHT	
Are watchman recording	rounds?		N				
Are there any fire extingu	ishers?	Υ	Are t	they serviced annually?		Υ	
Are there any hose station	ns?	N	Is the	ere a fire private fire brigade?		N	
Frequency of training reco	eived by the private fire br	rigade:					
Type of public fire departi	ment:	Paid	Dista	ance:		1.17 MILES	
Exposure:							
How many buildings(not រុ	part of Account) are within	100 feet of insured buildings?	0				
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):					
Is there a body of water no	earby?	N	Description:				
How far is the body of wa	ter from major buildings?						
Previous history of floodi	ng?	N	Description:				
Any property damage los	ses in the past 3 years:	N	Description:				

								- 3
			Pr	operty D	etail Form			
Agency:	UNIVERSITY SYSTEM / L	INIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - M	ISSOULA			
Property:	Turner Hall							
Property Address:	1105 Maurice Aveneu MIS	SOULA						
Property ID:	103							
Construction:								
Total number of insured	buildings:	1			Total square footage of insured buildings:	35012		
Year built:		1938			Number of stories:	3		
Construction of roof:		Wood Joists			Construction of floors:	Poured Concre	ete	
Construction of exterior	walls:	Masonry			Construction of interior walls:	Other		
Do major interior mason	ry walls (fire walls) extend	above the roofline?			N			
Occupancy:								
Occupancy Type:			State U	niversity				
Provide a brief descripti	on of operations:		Student	hall				
Storage height of warehoused products:		0						
Are flammable and combustible liquids stored in a cut-off room?		N						
Safegaurds taken for the	e storage and dispensing o	f flammable liquids:	N/A					
Protection:								
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?		0.1	
The water supply for aut	tomatic sprinklers is?	Public		How man	y hydrants are located within 500 feet of buildings?	<b>?</b>	2	
Indicate the Alarm Cove	rages provided for your fac	sility:	Burglar Alarms (Door Contacts), Smoke Detectors, Sprinkler Waterflow					
Are alarms connected to	a constantly attended loca	ation?		Υ				
Is there a watchman ser	vice?	Υ		What is t	he frequency of rounds?		Campus police 24/7	
Are watchman recording	g rounds?			Υ				
Are there any fire exting	uishers?	Υ		Are they	serviced annually?		Υ	
Are there any hose stati	ons?	N		Is there a	fire private fire brigade?		N	
Frequency of training re	ceived by the private fire b	rigade:						
Type of public fire depart	rtment:	Paid		Distance	:		under 1 mile	
Exposure:								
How many buildings(no	t part of Account) are within	n 100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water	nearby?	N	Descrip	tion:				
How far is the body of w	rater from major buildings?							
Previous history of floor	ding?	N	Descrip	tion:				
Any property damage lo	sses in the past 3 years:	N	Descrip	tion:				

						Page	: 4
			Pro	operty Detail Form			
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	TANA - MISSOULA			
Property:	University Center						
Property Address:	915 Daly Avenue MISSOU	LA					
Property ID:	91						
Construction:							
Total number of insured	buildings:	1		Total square footage of insured buildings:	187396		
Year built:		1969		Number of stories:	3		
Construction of roof:		null		Construction of floors:	null		
Construction of exterior	walls:	null		Construction of interior walls:	null		
Do major interior masonr	y walls (fire walls) extend	above the roofline?		null			
Occupancy:							
Occupancy Type:			State Ur	niversity			
Provide a brief description	on of operations:		null				
Storage height of warehoused products:		null					
Are flammable and combustible liquids stored in a cut-off room?		null					
Safegaurds taken for the	storage and dispensing of	flammable liquids:	null				
Protection:							
Are there any automatic	sprinklers?	Υ		What are the design densities for each area?		null	
The water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	•	null	
Indicate the Alarm Cover	ages provided for your fac	ility:					
Are alarms connected to	a constantly attended loca	ition?		null			
Is there a watchman serv	ice?	null		What is the frequency of rounds?		null	
Are watchman recording	rounds?						
Are there any fire extingu	ishers?	null		Are they serviced annually?		null	
Are there any hose statio	ns?	null		Is there a fire private fire brigade?		null	
Frequency of training red	eived by the private fire b	rigade:		null			
Type of public fire depart	ment:	null		Distance:		null	
Exposure:							
How many buildings(not	part of Account) are withir	100 feet of insured buildings?					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):	null				
Is there a body of water r	nearby?	null	Descrip	otion:	null		

null

Description:

Description:

null

null

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: null

null

							Page 4
			Pr	operty Detail Form			
gency:	UNIVERSITY SYSTEM / UNI	VERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - MISSOULA			
roperty:	University Hall						
roperty Address:	900 University Avenue MISS	OULA					
roperty ID:	001						
Construction:							
otal number of insured I	buildings: 1			Total square footage of insured buildings: 36	6088		
ear built:	1	898		Number of stories: 3			
Construction of roof:	n	ull		Construction of floors:	ull		
Construction of exterior	walls: n	ull		Construction of interior walls:	ull		
o major interior masonr	y walls (fire walls) extend ab	ove the roofline?		null			
Occupancy:							
Occupancy Type:			State U	niversity			
Provide a brief description	on of operations:		null				
Provide a brief description of operations: Storage height of warehoused products:			null				
are flammable and comb	ustible liquids stored in a cu	t-off room?	null				
afegaurds taken for the	storage and dispensing of f	ammable liquids:	null				
Protection:							
are there any automatic	sprinklers?	N		What are the design densities for each area?	r	null	
he water supply for auto	omatic sprinklers is?			How many hydrants are located within 500 feet of buildings?	r	null	
ndicate the Alarm Cover	ages provided for your facili	ty:					
are alarms connected to	a constantly attended location	on?		null			
s there a watchman serv	ice?	null		What is the frequency of rounds?	r	null	
are watchman recording	rounds?						
are there any fire extingu	ishers?	null		Are they serviced annually?	r	null	
are there any hose statio	ns?	null		Is there a fire private fire brigade?	r	null	
requency of training rec	eived by the private fire brig	ade:		null			
ype of public fire depart	ment:	null		Distance:	r	null	
xposure:							
low many buildings(not	part of Account) are within 1	00 feet of insured buildings?					
escribe the Occupancy	of those buildings(s) nearby	(within 100 feet):	null				

Description:

Description:

null

null

null

null

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years:

null

null

			Pr	operty D	etail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY	OF MON	ITANA - M	IISSOULA				
Property:	Urey Lecture Hall								
Property Address:	1340 Mansfield Avenue MIS	SSOULA							
Property ID:	94								
Construction:									
Total number of insured l	buildings:	1			Total square footage of insured buildings:	9780			
Year built:		1980			Number of stories:	1			
Construction of roof:		Reinforced Concrete			Construction of floors:	Reinforced Co	oncrete		
Construction of exterior v	walls:	Reinforced Concrete			Construction of interior walls:	Gypsum Boar	rd		
Do major interior masonr	y walls (fire walls) extend a	above the roofline?			null				
Occupancy:									
Occupancy Type:			State U	niversity					
Provide a brief descriptio	on of operations:		Lecture	Lecture hall/classrooms					
Storage height of warehoused products:		0							
Are flammable and combustible liquids stored in a cut-off room?		N							
Safegaurds taken for the	storage and dispensing of	flammable liquids:	N/A						
Protection:									
Are there any automatic	sprinklers?	Υ		What are	the design densities for each area?				
The water supply for auto	omatic sprinklers is?			How mai	ny hydrants are located within 500 feet of buildings?	•	1		
Indicate the Alarm Cover	ages provided for your fac	ility:		Sprinkler	Waterflow				
Are alarms connected to	a constantly attended loca	tion?		Υ					
ls there a watchman serv	ice?	Υ		What is t	the frequency of rounds?		Campus police 24/7		
Are watchman recording	rounds?			Υ					
Are there any fire extingu	ishers?	Υ		Are they	serviced annually?		Υ		
Are there any hose statio	ns?	N		Is there a	a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	igade:							
Type of public fire depart	ment:	Paid		Distance	:		under 1 mile		
Exposure:									
How many buildings(not	part of Account) are within	100 feet of insured buildings?	blank						
Describe the Occupancy	of those buildings(s) nearl	oy (within 100 feet):							
Is there a body of water n	nearby?	N	Descrip	otion:					
How far is the body of wa	ater from major buildings?								
Previous history of flood	ing?	N	Descrip	otion:					
Any property damage los	ses in the past 3 years:	N	Descrip	otion:					

			Prop	perty Detail Form				
Agency:	UNIVERSITY SYSTEM / U	NIVERSITY SYSTEM, UNIVERSITY (	OF MONTA	ANA - MISSOULA				
Property:	Vehicle Storage Building							
Property Address:	32 Campus Dr. MISSOUL	A						
Property ID:	35							
Construction:								
Total number of insured l	buildings:	1		Total square footage of insured buildings:	9710			
Year built:		1965		Number of stories:	1			
Construction of roof:		Steel Deck		Construction of floors:	Poured Concre	rete		
Construction of exterior	walls:	Corrugated Metal Panel		Construction of interior walls:	Other			
Do major interior masonr	y walls (fire walls) extend	above the roofline?		null				
Occupancy:								
Occupancy Type:			Storage					
Provide a brief descriptio	n of operations:		Vehicle re	Vehicle repair center, transport svcs rental dispatch				
Storage height of wareho	used products:		0					
Are flammable and combustible liquids stored in a cut-off room?		cut-off room?	N					
Safegaurds taken for the storage and dispensing of flammable liquids:		Υ						
Protection:								
Are there any automatic s	sprinklers?	N	W	hat are the design densities for each area?		no sprinklers		
The water supply for auto	omatic sprinklers is?		н	ow many hydrants are located within 500 feet of buildings?		1		
Indicate the Alarm Covera	ages provided for your fac	ility:	S	moke Detectors				
Are alarms connected to	a constantly attended loca	ition?	N					
Is there a watchman serv	ice?	Υ	W	/hat is the frequency of rounds?		campus police 24/7		
Are watchman recording	rounds?		N					
Are there any fire extingu	ishers?	Υ	Α	re they serviced annually?		Υ		
Are there any hose statio	ns?	N	Is	there a fire private fire brigade?		N		
Frequency of training rec	eived by the private fire br	igade:						
Type of public fire depart	ment:	Paid	D	istance:		under 1 mile		
Exposure:								
How many buildings(not	part of Account) are within	100 feet of insured buildings?	0					
Describe the Occupancy	of those buildings(s) near	by (within 100 feet):						
Is there a body of water n	earby?	Υ	Description	on:	Clark Fork Riv	/er		
How far is the body of wa	ter from major buildings?		500-700 fe	eet				
Previous history of floodi	ing?	N	Description	on:				
Any property damage los	ses in the past 3 years:	N	Description	on:				

						Page 46
			Prope	rty Detail Form		
gency:	UNIVERSITY SYSTEM	/ UNIVERSITY SYSTEM, MON	TANA STATE UNIVE	RSITY - BOZEMAN		
Property:	VISUAL COMMUNICAT	TONS BUILDING				
roperty Address:	West Grant (no official a	address) BOZEMAN				
Property ID:	132					
Construction:						
otal number of insure	d buildings:	1		Total square footage of insured buildings:	43081	
ear built:		1983		Number of stories:	3	
construction of roof:		Steel Deck		Construction of floors:	Reinforced Concrete	
Construction of exterio	or walls:	Masonry		Construction of interior walls:	Gypsum Board	
o major interior maso	onry walls (fire walls) exter	nd above the roofline?		N		
Occupancy:						
Occupancy Type:			State Unive	rsity		
Provide a brief description of operations:		OFFICES/C	LASSROOMS			
storage height of ware	housed products:		N/A			
are flammable and cor	nbustible liquids stored in	a cut-off room?	N/A			
afegaurds taken for tl	ne storage and dispensing	g of flammable liquids:	N/A			
Protection:						
are there any automati	c sprinklers?	N	Wh	at are the design densities for each area?		
he water supply for a	utomatic sprinklers is?		Hov	w many hydrants are located within 500 feet of buildings	<b>6</b>	
ndicate the Alarm Cov	erages provided for your	facility:				
are alarms connected	to a constantly attended lo	ocation?	N			
s there a watchman se	ervice?	Υ	Wh	at is the frequency of rounds?	AVERAGE	4 PER NIGHT
are watchman recording	ng rounds?		N			
are there any fire extin	guishers?	Υ	Are	they serviced annually?	Υ	
are there any hose sta	tions?	N	ls t	here a fire private fire brigade?	N	
requency of training r	eceived by the private fire	e brigade:				
ype of public fire dep	artment:	Paid	Dis	tance:	1.09 MILES	3

# **Exposure:**

How many buildings(not part of Account) are within 100 feet of insured buildings? 0

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby? Ν

How far is the body of water from major buildings?

Previous history of flooding?

Any property damage losses in the past 3 years: N

Description: Description:

Description:

Clark Fork River

							Page 4
			Prope	rty Detail Form			
gency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, UNIVE	RSITY OF MONTAN	NA - MISSOULA			
roperty:	Warehouse #25						
roperty Address:	10 Campus Drive MISSOL	JLA					
roperty ID:	25						
Construction:							
otal number of insured	d buildings:	1		Total square footage of insured buildings:	16800		
ear built:		1955		Number of stories:	1		
Construction of roof:		Steel Deck		Construction of floors:	Poured Concre	ete	
Construction of exterior	r walls:	Wood Frame		Construction of interior walls:	null		
o major interior masor	nry walls (fire walls) extend	above the roofline?		N			
Occupancy:							
Occupancy Type:			Storage				
Provide a brief descripti	ion of operations:		Storage				
Storage height of wareh	noused products:		0				
are flammable and com	bustible liquids stored in a	cut-off room?	N				
afegaurds taken for the	e storage and dispensing o	of flammable liquids:	Υ				
Protection:							
are there any automatic	sprinklers?	N	Wh	at are the design densities for each area?		no sprinklers	
he water supply for au	tomatic sprinklers is?		Но	w many hydrants are located within 500 feet of buildings	?	blank	
ndicate the Alarm Cove	erages provided for your fa	cility:					
are alarms connected to	o a constantly attended loc	ation?	N				
s there a watchman ser	rvice?	N	Wh	at is the frequency of rounds?		Campus police 24/7	
are watchman recording	g rounds?		N				
are there any fire exting	guishers?	Υ	Are	they serviced annually?		Υ	
are there any hose stati	ions?	N	ls t	here a fire private fire brigade?		null	
requency of training re	eceived by the private fire b	rigade:					
ype of public fire depa	rtment:	Paid	Dis	tance:		under 1 mile	
vnosura:							

0

Description:

500-700 yards

Description:

Description:

How many buildings(not part of Account) are within 100 feet of insured buildings?

Ν

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Is there a body of water nearby?

Previous history of flooding?

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

						r age 40	
			Proper	rty Detail Form			
Agency:	UNIVERSITY SYSTEM / L	JNIVERSITY SYSTEM, MONTANA S	STATE UNIVER	RSITY - BOZEMAN			
Property:	WILSON HALL						
Property Address:	West Garfield Street (no o	fficial address) BOZEMAN					
Property ID:	129						
Construction:							
Total number of insure	d buildings:	1		Total square footage of insured buildings:	80153		
Year built:		1974		Number of stories:	2		
Construction of roof:		Steel Deck		Construction of floors:	Reinforced Cond	crete	
Construction of exterio	r walls:	Masonry		Construction of interior walls:	Gypsum Board		
Do major interior masonry walls (fire walls) extend above the roofline?			N				
Occupancy:							
Occupancy Type:			State Univers	sity			
Provide a brief description of operations:		OFFICES/CL	OFFICES/CLASSROOMS				
Storage height of warehoused products:		N/A					
Are flammable and combustible liquids stored in a cut-off room?		N/A					
Safegaurds taken for the	ne storage and dispensing o	f flammable liquids:	N/A				
Protection:							
Are there any automati	c sprinklers?	N	Wha	at are the design densities for each area?			
The water supply for a	utomatic sprinklers is?		How	many hydrants are located within 500 feet of buildings?	5	j.	
Indicate the Alarm Cov	erages provided for your fa	cility:	Smo	oke Detectors			
Are alarms connected	to a constantly attended loc	ation?	Υ				
Is there a watchman se	rvice?	Υ	Wha	at is the frequency of rounds?	Д	AVERAGE 4 PER NIGHT	
Are watchman recording	ng rounds?		N				
Are there any fire extin	guishers?	Υ	Are	they serviced annually?	Y	′	
Are there any hose star	tions?	N	Is th	ere a fire private fire brigade?	Ν	<b>J</b>	
Frequency of training r	eceived by the private fire b	rigade:					
Type of public fire depart	artment:	Paid	Dist	ance:		93 MILES	
Exposure:							
How many buildings(no	ot part of Account) are withi	n 100 feet of insured buildings?	0				
Describe the Occupand	cy of those buildings(s) near	by (within 100 feet):					
Is there a body of wate	r nearby?	N	Description:	:			
How far is the body of	water from major buildings?	•					
Previous history of floo	oding?	N	Description:	:			
Any property damage I	osses in the past 3 years:	N	Description:	:			

Ν

.93 miles

						Page 46
			Prop	erty Detail Form		
Agency:	UNIVERSITY SYSTEM	/ UNIVERSITY SYSTEM, MONT	ANA STATE UNIVE	ERSITY - BOZEMAN		
Property:	WOOL LAB					
Property Address:	South 11th Avenue (no	o official address) BOZEMAN				
Property ID:	405					
Construction:						
Total number of insured	d buildings:	1		Total square footage of insured buildings:	7449	
Year built:		1947		Number of stories:	1	
Construction of roof:		Wood Joists		Construction of floors:	Wood Timber	
Construction of exterio	r walls:	Wood Frame		Construction of interior walls:	Gypsum Board	
Do major interior masor	nry walls (fire walls) ext	end above the roofline?		N		
Occupancy:						
Occupancy Type:			Office			
Provide a brief descript	ion of operations:		Administra	tion		
Storage height of wareh	noused products:		N/A			
Are flammable and com	nbustible liquids stored	in a cut-off room?	N/A			
Safegaurds taken for th	e storage and dispensi	ng of flammable liquids:	N/A			
Protection:						
Are there any automatic	c sprinklers?	N	w	hat are the design densities for each area?	no sprinklers	
The water supply for au	tomatic sprinklers is?		Ho	ow many hydrants are located within 500 feet of building	gs? 3	
Indicate the Alarm Cove	erages provided for you	r facility:				
Are alarms connected t	o a constantly attended	location?	nu	II		
Is there a watchman ser	rvice?	N	w	hat is the frequency of rounds?		
Are watchman recordin	g rounds?		N			
Are there any fire exting	guishers?	Υ	Ar	e they serviced annually?	Υ	

Is there a fire private fire brigade?

Distance:

0

Description:

Description:

Description:

Are there any hose stations?

Type of public fire department:

Is there a body of water nearby?

Previous history of flooding?

Exposure:

Frequency of training received by the private fire brigade:

How far is the body of water from major buildings?

Any property damage losses in the past 3 years: N

How many buildings(not part of Account) are within 100 feet of insured buildings?

Describe the Occupancy of those buildings(s) nearby (within 100 feet):

Ν

Paid

Ν

Ν